










































	<p><b>БПЗ-001</b></p> <p> <math>F \text{ см}^2 = 17.202</math>  <math>Q \text{ кг.} = 4.662</math>  <math>D \text{ оп.мм} = 163.0</math>  <math>P \text{ н.мм} = 323.14</math>  <math>P \text{ вн.мм} = 380</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-0006</b></p> <p> <math>F \text{ см}^2 = 0.88</math>  <math>Q \text{ кг.} = 0.238</math>  <math>D \text{ оп.мм} = 16</math>  <math>P \text{ н.мм} = 50.3</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-0002</b></p> <p> <math>F \text{ см}^2 = 4.3</math>  <math>Q \text{ кг.} = 1.65</math>  <math>D \text{ оп.мм} = 68</math>  <math>P \text{ н.мм} = 180.1</math>  <math>P \text{ вн.мм} = 160.1</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-0007</b></p> <p> <math>F \text{ см}^2 = 15.81</math>  <math>Q \text{ кг.} = 4.285</math>  <math>D \text{ оп.мм} = 129</math>  <math>P \text{ н.мм} = 494</math>  <math>P \text{ вн.мм} = 375</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-0003</b></p> <p> <math>F \text{ см}^2 = 2.895</math>  <math>Q \text{ кг.} = 0.785</math>  <math>D \text{ оп.мм} = 50</math>  <math>P \text{ н.мм} = 171.5</math>  <math>P \text{ вн.мм} = 118.3</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0008</b></p> <p> <math>F \text{ см}^2 = 18.67</math>  <math>Q \text{ кг.} = 5.059</math>  <math>D \text{ оп.мм} = 140</math>  <math>P \text{ н.мм} = 545</math>  <math>P \text{ вн.мм} = 411</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-0004</b></p> <p> <math>F \text{ см}^2 = 4.235</math>  <math>Q \text{ кг.} = 1.148</math>  <math>D \text{ оп.мм} = 96.1</math>  <math>P \text{ н.мм} = 212.3</math>  <math>P \text{ вн.мм} = 124</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0009</b></p> <p> <math>F \text{ см}^2 = 3.922</math>  <math>Q \text{ кг.} = 1.062</math>  <math>D \text{ оп.мм} = 74</math>  <math>P \text{ н.мм} = 263</math>  <math>P \text{ вн.мм} = 151</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-0005</b></p> <p> <math>F \text{ см}^2 = 8.63</math>  <math>Q \text{ кг.} = 2.339</math>  <math>D \text{ оп.мм} = 128.0</math>  <math>P \text{ н.мм} = 472.8</math>  <math>P \text{ вн.мм} = 361.3</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0010</b></p> <p> <math>F \text{ см}^2 = 3.562</math>  <math>Q \text{ кг.} = 0.965</math>  <math>D \text{ оп.мм} = 63</math>  <math>P \text{ н.мм} = 222</math>  <math>P \text{ вн.мм} = 145</math>  Гр. сл. = V  Точн. = П </p>











	<p><b>БПЗ-0011</b></p> <p> <math>F \text{ см}^2 = 1.413</math>  <math>Q \text{ кг.} = 0.383</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 101</math>  <math>P \text{ вн.мм} = 30</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-0016</b></p> <p> <math>F \text{ см}^2 = 4.175</math>  <math>Q \text{ кг.} = 1.128</math>  <math>D \text{ оп.мм} = 79</math>  <math>P \text{ н.мм} = 293</math>  <math>P \text{ вн.мм} = 145</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-0012</b></p> <p> <math>F \text{ см}^2 = 3.266</math>  <math>Q \text{ кг.} = 0.885</math>  <math>D \text{ оп.мм} = 43</math>  <math>P \text{ н.мм} = 143</math>  <math>P \text{ вн.мм} = 121</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-017</b></p> <p> <math>F \text{ см}^2 = 8.275</math>  <math>Q \text{ кг.} = 2.243</math>  <math>D \text{ оп.мм} = 90.0</math>  <math>P \text{ н.мм} = 276.0</math>  <math>P \text{ вн.мм} = 198.0</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-0013</b></p> <p> <math>F \text{ см}^2 = 5.337</math>  <math>Q \text{ кг.} = 1.446</math>  <math>D \text{ оп.мм} = 146</math>  <math>P \text{ н.мм} = 334</math>  <math>P \text{ вн.мм} = 211.4</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-018</b></p> <p> <math>F \text{ см}^2 = 21.195</math>  <math>Q \text{ кг.} = 5.744</math>  <math>D \text{ оп.мм} = 140.0</math>  <math>P \text{ н.мм} = 439.8</math>  <math>P \text{ вн.мм} = 408.4</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-0014</b></p> <p> <math>F \text{ см}^2 = 7.290</math>  <math>Q \text{ кг.} = 1.968</math>  <math>D \text{ оп.мм} = 127</math>  <math>P \text{ н.мм} = 438</math>  <math>P \text{ вн.мм} = 301</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-0019</b></p> <p> <math>F \text{ см}^2 = 3.351</math>  <math>Q \text{ кг.} = 0.908</math>  <math>D \text{ оп.мм} = 92</math>  <math>P \text{ н.мм} = 266</math>  <math>P \text{ вн.мм} = 103</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-0015</b></p> <p> <math>F \text{ см}^2 = 3.131</math>  <math>Q \text{ кг.} = 0.845</math>  <math>D \text{ оп.мм} = 85</math>  <math>P \text{ н.мм} = 236</math>  <math>P \text{ вн.мм} = 103</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-0020</b></p> <p> <math>F \text{ см}^2 = 2.455</math>  <math>Q \text{ кг.} = 0.663</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 165</math>  <math>P \text{ вн.мм} = 91</math>  Гр. сл. = V  Точн. = П </p>










	<p><b>БПЗ-0021</b></p> <p> <math>F_{\text{см}} = 2.632</math>  <math>Q_{\text{кз.}} = 0.713</math>  <math>D_{\text{оп.мм}} = 40</math>  <math>P_{\text{н.мм}} = 195</math>  <math>P_{\text{вн.мм}} = 71</math>  <math>\Gamma_{\text{р. сл.}} = V</math>  <math>\text{Точн.} = П</math> </p>		
			<p><b>БПЗ-0027</b></p> <p> <math>F_{\text{см}^2} = 2.133</math>  <math>Q_{\text{кз.}} = 0.578</math>  <math>D_{\text{оп.мм}} = 64</math>  <math>P_{\text{н.мм}} = 214</math>  <math>P_{\text{вн.мм}} = 42</math>  <math>\Gamma_{\text{р. сл.}} = V</math>  <math>\text{Точн.} = П</math> </p>
			<p><b>БПЗ-0028</b></p> <p> <math>F_{\text{см}^2} = 6.47</math>  <math>Q_{\text{кз.}} = 1.753</math>  <math>D_{\text{оп.мм}} = 106.0</math>  <math>P_{\text{н.мм}} = 355.5</math>  <math>P_{\text{вн.мм}} = 210.9</math>  <math>\Gamma_{\text{р. сл.}} = VI</math>  <math>\text{Точн.} = П</math> </p>
			<p><b>БПЗ-0029</b></p> <p> <math>F_{\text{см}^2} = 4.951</math>  <math>Q_{\text{кз.}} = 1.342</math>  <math>D_{\text{оп.мм}} = 78</math>  <math>P_{\text{н.мм}} = 173.4</math>  <math>P_{\text{вн.мм}} = 155.1</math>  <math>\Gamma_{\text{р. сл.}} = \text{Особ.}</math>  <math>\text{Точн.} = П</math> </p>
			<p><b>БПЗ-030</b></p> <p> <math>F_{\text{см}^2} = 3.238</math>  <math>Q_{\text{кз.}} = 0.877</math>  <math>D_{\text{оп.мм}} = 42.4</math>  <math>P_{\text{н.мм}} = 277.3</math>  <math>P_{\text{вн.мм}} = 40.0</math>  <math>\Gamma_{\text{р. сл.}} = IV</math>  <math>\text{Точн.} = Н</math> </p>










	<b>БПЗ-031</b> $F_{\text{см}} = 4.05$ $Q_{\text{кг.}} = 1.098$ $D_{\text{оп.мм}} = 58.5$ $P_{\text{н.мм}} = 142$ $P_{\text{вн.мм}} = 113$ Гр. сл. = IV Точн. = II		<b>БПЗ-0036</b> $F_{\text{см}^2} = 1.750$ $Q_{\text{кг.}} = 0.474$ $D_{\text{оп.мм}} = 56.2$ $P_{\text{н.мм}} = 146.9$ $P_{\text{вн.мм}} = 81.5$ Гр. сл. = VI Точн. = П
	<b>БПЗ-032</b> $F_{\text{см}} = 0.692$ $Q_{\text{кг.}} = 0.187$ $D_{\text{оп.мм}} = 27.2$ $P_{\text{н.мм}} = 78.2$ $P_{\text{вн.мм}} = 33.6$ Гр. сл. = IV Точн. = II		<b>БПЗ-0037</b> $F_{\text{см}^2} = 1.89$ $Q_{\text{кг.}} = 0.512$ $D_{\text{оп.мм}} = 61.2$ $P_{\text{н.мм}} = 157.8$ $P_{\text{вн.мм}} = 91.5$ Гр. сл. = VI Точн. = П
	<b>БПЗ-033</b> $F_{\text{см}^2} = 2.54$ $Q_{\text{кг.}} = 0.688$ $D_{\text{оп.мм}} = 30.0$ $P_{\text{н.мм}} = 94.3$ $P_{\text{вн.мм}} = 75.4$ Гр. сл. = IV Точн. = П		
	<b>БПЗ-034</b> $F_{\text{см}^2} = 8.605$ $Q_{\text{кг.}} = 2.332$ $D_{\text{оп.мм}} = 121.8$ $P_{\text{н.мм}} = 409.9$ $P_{\text{вн.мм}} = 263.7$ Гр. сл. = VI Точн. = П		<b>БПЗ-039</b> $F_{\text{см}^2} = 3.24$ $Q_{\text{кг.}} = 0.878$ $D_{\text{оп.мм}} = 43.3$ $P_{\text{н.мм}} = 116.6$ $P_{\text{вн.мм}} = 92.57$ Гр. сл. = IV Точн. = H
	<b>БПЗ-0035</b> $F_{\text{см}^2} = 5.932$ $Q_{\text{кг.}} = 1.608$ $D_{\text{оп.мм}} = 38.0$ $P_{\text{н.мм}} = 119.4$ $P_{\text{вн.мм}} = 81.7$ Гр. сл. = I Точн. = П		<b>БПЗ-0040</b> $F_{\text{см}^2} = 3.200$ $Q_{\text{кг.}} = 0.867$ $D_{\text{оп.мм}} = 87.8$ $P_{\text{н.мм}} = 260.2$ $P_{\text{вн.мм}} = 163.5$ Гр. сл. = IV Точн. = П




















	<b>БПЗ-041</b> $F \text{ см}^2 = 3.8$ $Q \text{ кг.} = 1.1$ $D \text{ оп.мм} = 107.4$ $P \text{ н.мм} = 300.2$ $P \text{ вн.мм} = 203.5$ Гр. сл. = IV Точн. = П		<b>БПЗ-046</b> $F \text{ см}^2 = 2.505$ $Q \text{ кг.} = 0.679$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 28.27$ Гр. сл. = III Точн. = Н
	<b>БПЗ-042</b> $F \text{ см}^2 = 6.716$ $Q \text{ кг.} = 1.82$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 94.3$ $P \text{ вн.мм} = 20.1$ Гр. сл. = IV Точн. = П		<b>БПЗ-047</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ $P \text{ вн.мм} = 0$ Гр. сл. = III Точн. = Н
	<b>БПЗ-043</b> $F \text{ см}^2 = 2.463$ $Q \text{ кг.} = 0.667$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 134$ $P \text{ вн.мм} = 127.7$ Гр. сл. = IV Точн. = Н		<b>БПЗ-0048</b> $F \text{ см}^2 = 3.607$ $Q \text{ кг.} = 0.977$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 111.9$ $P \text{ вн.мм} = 105.6$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-044</b> $F \text{ см}^2 = 2.17$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 109.8$ $P \text{ вн.мм} = 121.9$ Гр. сл. = VI Точн. = Н		<b>БПЗ-0049</b> $F \text{ см}^2 = 7.930$ $Q \text{ кг.} = 2.149$ $D \text{ оп.мм} = 159.0$ $P \text{ н.мм} = 437.1$ $P \text{ вн.мм} = 356.0$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0045</b> $F \text{ см}^2 = 6.418$ $Q \text{ кг.} = 1.739$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 275.2$ $P \text{ вн.мм} = 316.9$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-050</b> $F \text{ см}^2 = 7.7$ $Q \text{ кг.} = 2.087$ $D \text{ оп.мм} = 87.3$ $P \text{ н.мм} = 230$ $P \text{ вн.мм} = 198$ Гр. сл. = IV Точн. = П










	<b>БПЗ-0051</b> $F \text{ см}^2 = 3.200$ $Q \text{ кг.} = 0.867$ $D \text{ оп.мм} = 65.5$ $P \text{ н.мм} = 179.2$ $P \text{ вн.мм} = 140.9$ Гр. сл. = V Точн. = П		<b>БПЗ-0056</b> $F \text{ см}^2 = 6.100$ $Q \text{ кг.} = 1.653$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 212.2$ $P \text{ вн.мм} = 126.0$ Гр. сл. = IV Точн. = П
	<b>БПЗ-0052</b> $F \text{ см}^2 = 13.480$ $Q \text{ кг.} = 3.653$ $D \text{ оп.мм} = 81.0$ $P \text{ н.мм} = 349.7$ $P \text{ вн.мм} = 60.3$ Гр. сл. = VI Точн. = П		<b>БПЗ-0057</b> $F \text{ см}^2 = 2.750$ $Q \text{ кг.} = 0.745$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 188.5$ $P \text{ вн.мм} = 179.1$ Гр. сл. = IV Точн. = Н
	<b>БПЗ-0053</b> $F \text{ см}^2 = 19.28$ $Q \text{ кг.} = 5.225$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 157.1$ $P \text{ вн.мм} = 21.05$ Гр. сл. = II Точн. = П		<b>БПЗ-0058</b> $F \text{ см}^2 = 4.190$ $Q \text{ кг.} = 1.135$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 166.5$ $P \text{ вн.мм} = 112.5$ Гр. сл. = IV Точн. = П
	<b>БПЗ-0054</b> $F \text{ см}^2 = 9.56$ $Q \text{ кг.} = 2.591$ $D \text{ оп.мм} = 136.0$ $P \text{ н.мм} = 318.4$ $P \text{ вн.мм} = 296.8$ Гр. сл. = IV Точн. = Н		<b>БПЗ-0059</b> $F \text{ см}^2 = 7.700$ $Q \text{ кг.} = 2.087$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 310.0$ $P \text{ вн.мм} = 288.0$ Гр. сл. = III Точн. = Н
	<b>БПЗ-0055</b> $F \text{ см}^2 = 0.819$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 37.7$ $P \text{ вн.мм} = 19.8$ Гр. сл. = III Точн. = Н		<b>БПЗ-0060</b> $F \text{ см}^2 = 5.183$ $Q \text{ кг.} = 1.405$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 119.4$ $P \text{ вн.мм} = 87.9$ Гр. сл. = IV Точн. = Н











	<b>БПЗ-0061</b> $F \text{ см}^2 = 0.840$ $Q \text{ кг.} = 0.228$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 73.7$ $P \text{ вн.мм} = 66.2$ Гр. сл. = IV Точн. = Н		<b>БПЗ-066</b> $F \text{ см}^2 = 7.28$ $Q \text{ кг.} = 1.973$ $D \text{ оп.мм} = 89.4$ $P \text{ н.мм} = 338.2$ $P \text{ вн.мм} = 229$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0062</b> $F \text{ см}^2 = 2.360$ $Q \text{ кг.} = 0.640$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 193.2$ $P \text{ вн.мм} = 97.0$ Гр. сл. = VI Точн. = П		<b>БПЗ-067</b> $F \text{ см}^2 = 11.110$ $Q \text{ кг.} = 3.011$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 397.3$ $P \text{ вн.мм} = 255.7$ Гр. сл. = 0соб. Точн. = Н
			<b>БПЗ-068</b> $F \text{ см}^2 = 9.28$ $Q \text{ кг.} = 2.515$ $D \text{ оп.мм} = 126.5$ $P \text{ н.мм} = 418.2$ $P \text{ вн.мм} = 309$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0064</b> $F \text{ см}^2 = 5.010$ $Q \text{ кг.} = 1.358$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 203.7$ $P \text{ вн.мм} = 96.9$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-069</b> $F \text{ см}^2 = 7.99$ $Q \text{ кг.} = 2.165$ $D \text{ оп.мм} = 117.0$ $P \text{ н.мм} = 290$ $P \text{ вн.мм} = 259$ Гр. сл. = IV Точн. = П
	<b>БПЗ-065</b> $F \text{ см}^2 = 1.413$ $Q \text{ кг.} = 0.383$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 56.55$ $P \text{ вн.мм} = 37.7$ Гр. сл. = II Точн. = Н		<b>БПЗ-070</b> $F \text{ см}^2 = 2.060$ $Q \text{ кг.} = 0.558$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 165.0$ $P \text{ вн.мм} = 32.0$ Гр. сл. = 0соб. Точн. = Т

	<b>БПЗ-071</b> $F \text{ см}^2 = 1.758$ $Q \text{ кг.} = 0.476$ $D \text{ оп.мм} = 22.7$ $P \text{ н.мм} = 64$ $P \text{ вн.мм} = 31.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-0076</b> $F \text{ см}^2 = 0.298$ $Q \text{ кг.} = 0.081$ $D \text{ оп.мм} = 8.1$ $P \text{ н.мм} = 24.3$ $P \text{ вн.мм} = 12.6$ Гр. сл. = V Точн. = Н
	<b>БПЗ-072</b> $F \text{ см}^2 = 1.99$ $Q \text{ кг.} = 0.539$ $D \text{ оп.мм} = 22.7$ $P \text{ н.мм} = 64$ $P \text{ вн.мм} = 26.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-0077</b> $F \text{ см}^2 = 0.382$ $Q \text{ кг.} = 0.104$ $D \text{ оп.мм} = 11.0$ $P \text{ н.мм} = 34.6$ $P \text{ вн.мм} = 26.8$ Гр. сл. = IV Точн. = Н
	<b>БПЗ-0073</b> $F \text{ см}^2 = 1.945$ $Q \text{ кг.} = 0.527$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 171.5$ $P \text{ вн.мм} = 83.4$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-078</b> $F \text{ см}^2 = 6.640$ $Q \text{ кг.} = 1.8$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 166.0$ $P \text{ вн.мм} = 271.0$ Гр. сл. = IV Точн. = Т
			<b>БПЗ-079</b> $F \text{ см}^2 = 3.757$ $Q \text{ кг.} = 1.018$ $D \text{ оп.мм} = 38.7$ $P \text{ н.мм} = 157.2$ $P \text{ вн.мм} = 81.79$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0075</b> $F \text{ см}^2 = 3.519$ $Q \text{ кг.} = 0.954$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 100.5$ $P \text{ вн.мм} = 75.4$ Гр. сл. = IV Точн. = Н		<b>БПЗ-080</b> $F \text{ см}^2 = 1.72$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 60.3$ $P \text{ вн.мм} = 26.7$ Гр. сл. = IV Точн. = П











	<p><b>БПЗ-081-01</b></p> <p> <math>F \text{ см}^2 = 2.453</math>  <math>Q \text{ кг.} = 0.665</math>  <math>D \text{ оп.мм} = 20.0</math>  <math>P \text{ н.мм} = 67.26</math>  <math>P \text{ вн.мм} = 25.13</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-086</b></p> <p> <math>F \text{ см}^2 = 2.827</math>  <math>Q \text{ кг.} = 0.766</math>  <math>D \text{ оп.мм} = 47.0</math>  <math>P \text{ н.мм} = 135.1</math>  <math>P \text{ вн.мм} = 147.7</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-082</b></p> <p> <math>F \text{ см}^2 = 9.620</math>  <math>Q \text{ кг.} = 2.607</math>  <math>D \text{ оп.мм} = 162.8</math>  <math>P \text{ н.мм} = 380.4</math>  <math>P \text{ вн.мм} = 359.6</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-087</b></p> <p> <math>F \text{ см}^2 = 2.730</math>  <math>Q \text{ кг.} = 0.740</math>  <math>D \text{ оп.мм} = 24.0</math>  <math>P \text{ н.мм} = 162.0</math>  <math>P \text{ вн.мм} = 28.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-083</b></p> <p> <math>F \text{ см}^2 = 4.480</math>  <math>Q \text{ кг.} = 1.2</math>  <math>D \text{ оп.мм} = 51.6</math>  <math>P \text{ н.мм} = 144.8</math>  <math>P \text{ вн.мм} = 120.8</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-0088</b></p> <p> <math>F \text{ см}^2 = 18.830</math>  <math>Q \text{ кг.} = 5.103</math>  <math>D \text{ оп.мм} = 107.6</math>  <math>P \text{ н.мм} = 398.5</math>  <math>P \text{ вн.мм} = 353.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-084</b></p> <p> <math>F \text{ см}^2 = 8.77</math>  <math>Q \text{ кг.} = 2.377</math>  <math>D \text{ оп.мм} = 128.0</math>  <math>P \text{ н.мм} = 534.7</math>  <math>P \text{ вн.мм} = 294.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-089</b></p> <p> <math>F \text{ см}^2 = 19.200</math>  <math>Q \text{ кг.} = 5.203</math>  <math>D \text{ оп.мм} = 60.0</math>  <math>P \text{ н.мм} = 188.5</math>  <math>P \text{ вн.мм} = 106.8</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-085</b></p> <p> <math>F \text{ см}^2 = 11.784</math>  <math>Q \text{ кг.} = 3.193</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 251.3</math>  <math>P \text{ вн.мм} = 219.9</math>  Гр. сл. = III  Точн. = Т </p>		<p><b>БПЗ-0090</b></p> <p> <math>F \text{ см}^2 = 30.290</math>  <math>Q \text{ кг.} = 8.209</math>  <math>D \text{ оп.мм} = 152.0</math>  <math>P \text{ н.мм} = 457.4</math>  <math>P \text{ вн.мм} = 296.9</math>  Гр. сл. = 0соб.  Точн. = П </p>








	<b>БПЗ-091</b> F см <sup>2</sup> = 3.39 Q кз. = 0.919 D оп.мм= 46.7 P н.мм = 121.1 P в.н.мм= 161 Гр. сл. = VI Точн. = П		<b>БПЗ-096-01</b> F см <sup>2</sup> = 2.640 Q кз. = 0.715 D оп.мм= 25.0 P н.мм = 78.5 P в.н.мм= 53.4 Гр. сл. = II Точн. = Н
	<b>БПЗ-0092</b> F см <sup>2</sup> = 29.600 Q кз. = 8.022 D оп.мм= 194.0 P н.мм = 503.0 P в.н.мм= 334.5 Гр. сл. = Особ. Точн. = П		<b>БПЗ-097</b> F см <sup>2</sup> = 2.04 Q кз. = 0.553 D оп.мм= 26.0 P н.мм = 100.8 P в.н.мм= 56.55 Гр. сл. = IV Точн. = Н
			<b>БПЗ-098</b> F см <sup>2</sup> = 3.16 Q кз. = 0.856 D оп.мм= 38.0 P н.мм = 152.1 P в.н.мм= 94.25 Гр. сл. = IV Точн. = Н
	<b>БПЗ-0095</b> F см <sup>2</sup> = 30.241 Q кз. = 8.195 D оп.мм= 180.2 P н.мм = 522.7 P в.н.мм= 321.0 Гр. сл. = Особ. Точн. = П		<b>БПЗ-0100</b> F см <sup>2</sup> = 37.790 Q кз. = 10.241 D оп.мм= 185.0 P н.мм = 532.7 P в.н.мм= 427.7 Гр. сл. = Особ. Точн. = П









	<p><b>БПЗ-0101</b></p> <p> <math>F \text{ см}^2 = 15.493</math>  <math>Q \text{ кг.} = 4.199</math>  <math>D \text{ оп.мм} = 158.2</math>  <math>P \text{ н.мм} = 435.8</math>  <math>P \text{ вн.мм} = 224.4</math>  Гр. сл. = 0соб.  Точн. = П </p>		
	<p><b>БПЗ-0102</b></p> <p> <math>F \text{ см}^2 = 1.383</math>  <math>Q \text{ кг.} = 0.375</math>  <math>D \text{ оп.мм} = 45.3</math>  <math>P \text{ н.мм} = 140.2</math>  <math>P \text{ вн.мм} = 90.4</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-107</b></p> <p> <math>F \text{ см}^2 = 3.93</math>  <math>Q \text{ кг.} = 1.065</math>  <math>D \text{ оп.мм} = 56.5</math>  <math>P \text{ н.мм} = 203.0</math>  <math>P \text{ вн.мм} = 130.0</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-103</b></p> <p> <math>F \text{ см}^2 = 1.287</math>  <math>Q \text{ кг.} = 0.349</math>  <math>D \text{ оп.мм} = 17.0</math>  <math>P \text{ н.мм} = 48</math>  <math>P \text{ вн.мм} = 13.8</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-108</b></p> <p> <math>F \text{ см}^2 = 0.978</math>  <math>Q \text{ кг.} = 0.265</math>  <math>D \text{ оп.мм} = 12.0</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ вн.мм} = 13.8</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-0104</b></p> <p> <math>F \text{ см}^2 = 3.520</math>  <math>Q \text{ кг.} = 0.954</math>  <math>D \text{ оп.мм} = 83.0</math>  <math>P \text{ н.мм} = 307.1</math>  <math>P \text{ вн.мм} = 189.3</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-0109</b></p> <p> <math>F \text{ см}^2 = 2.549</math>  <math>Q \text{ кг.} = 0.691</math>  <math>D \text{ оп.мм} = 36.4</math>  <math>P \text{ н.мм} = 116.0</math>  <math>P \text{ вн.мм} = 76.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-105-01</b></p> <p> <math>F \text{ см}^2 = 2.92</math>  <math>Q \text{ кг.} = 0.791</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 165.4</math>  <math>P \text{ вн.мм} = 49.5</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-0110</b></p> <p> <math>F \text{ см}^2 = 1.576</math>  <math>Q \text{ кг.} = 0.427</math>  <math>D \text{ оп.мм} = 33.0</math>  <math>P \text{ н.мм} = 151.3</math>  <math>P \text{ вн.мм} = 58.3</math>  Гр. сл. = VI  Точн. = П </p>











	<b>БПЗ-0111</b> $F \text{ см}^2 = 7.870$ $Q \text{ кг.} = 2.133$ $D \text{ оп.мм} = 165.0$ $P \text{ н.мм} = 542.9$ $P \text{ вн.мм} = 192.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-116</b> $F \text{ см}^2 = 15.300$ $Q \text{ кг.} = 4.146$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 182.0$ $P \text{ вн.мм} = 119.0$ Гр. сл. = I Точн. = Т
	<b>БПЗ-112</b> $F \text{ см}^2 = 6.960$ $Q \text{ кг.} = 1.886$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 299.0$ $P \text{ вн.мм} = 206.0$ Гр. сл. = VI Точн. = Т		<b>БПЗ-117</b> $F \text{ см}^2 = 14.130$ $Q \text{ кг.} = 3.829$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 172.7$ $P \text{ вн.мм} = 109.9$ Гр. сл. = I Точн. = Т
	<b>БПЗ-0113</b> $F \text{ см}^2 = 48.000$ $Q \text{ кг.} = 13.008$ $D \text{ оп.мм} = 111.6$ $P \text{ н.мм} = 421.2$ $P \text{ вн.мм} = 182.3$ Гр. сл. = V Точн. = П		<b>БПЗ-118</b> $F \text{ см}^2 = 12.560$ $Q \text{ кг.} = 3.404$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 157.0$ $P \text{ вн.мм} = 94.2$ Гр. сл. = I Точн. = Т
	<b>БПЗ-114</b> $F \text{ см}^2 = 3.73$ $Q \text{ кг.} = 1.01$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 276.8$ $P \text{ вн.мм} = 103$ Гр. сл. = VI Точн. = П		<b>БПЗ-0119</b> $F \text{ см}^2 = 13.334$ $Q \text{ кг.} = 3.614$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 245.0$ $P \text{ вн.мм} = 223.3$ Гр. сл. = IV Точн. = П
	<b>БПЗ-115</b> $F \text{ см}^2 = 16.330$ $Q \text{ кг.} = 4.425$ $D \text{ оп.мм} = 62.0$ $P \text{ н.мм} = 195.0$ $P \text{ вн.мм} = 132.0$ Гр. сл. = I Точн. = Т		<b>БПЗ-120</b> $F \text{ см}^2 = 1.180$ $Q \text{ кг.} = 0.320$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 67.2$ $P \text{ вн.мм} = 51.2$ Гр. сл. = IV Точн. = П





















	<b>БПЗ-0121</b> $F \text{ см}^2 = 3.277$ $Q \text{ кг.} = 0.888$ $D \text{ оп.мм} = 77.0$ $P \text{ н.мм} = 249.2$ $P \text{ вн.мм} = 36.5$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-126</b> $F \text{ см}^2 = 1.680$ $Q \text{ кг.} = 0.46$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 108.0$ $P \text{ вн.мм} = 57.0$ Гр. сл. = IV Точн. = Т
	<b>БПЗ-122</b> $F \text{ см}^2 = 3.750$ $Q \text{ кг.} = 1.02$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 196.0$ $P \text{ вн.мм} = 180.0$ Гр. сл. = IV Точн. = Т		<b>БПЗ-127</b> $F \text{ см}^2 = 2.030$ $Q \text{ кг.} = 0.550$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 138.0$ $P \text{ вн.мм} = 87.0$ Гр. сл. = IV Точн. = Т
	<b>БПЗ-123</b> $F \text{ см}^2 = 4.230$ $Q \text{ кг.} = 1.15$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 180.0$ $P \text{ вн.мм} = 168.0$ Гр. сл. = IV Точн. = Т		<b>БПЗ-128</b> $F \text{ см}^2 = 9.700$ $Q \text{ кг.} = 2.63$ $D \text{ оп.мм} = 108.0$ $P \text{ н.мм} = 351.0$ $P \text{ вн.мм} = 228.0$ Гр. сл. = VI Точн. = Т
	<b>БПЗ-124</b> $F \text{ см}^2 = 8.120$ $Q \text{ кг.} = 2.2$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 295.0$ $P \text{ вн.мм} = 124.0$ Гр. сл. = VI Точн. = Т		<b>БПЗ-129</b> $F \text{ см}^2 = 12.070$ $Q \text{ кг.} = 3.27$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 296.0$ $P \text{ вн.мм} = 266.0$ Гр. сл. = V Точн. = Т
	<b>БПЗ-125</b> $F \text{ см}^2 = 1.480$ $Q \text{ кг.} = 0.402$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 102.0$ $P \text{ вн.мм} = 93.0$ Гр. сл. = IV Точн. = Т		<b>БПЗ-130</b> $F \text{ см}^2 = 3.860$ $Q \text{ кг.} = 1.04$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 218.0$ $P \text{ вн.мм} = 142.0$ Гр. сл. = VI Точн. = Т










	<p><b>БПЗ-131</b></p> <p> <math>F \text{ см}^2 = 4.36</math>  <math>Q \text{ кг.} = 1.182</math>  <math>D \text{ оп.мм} = 82.0</math>  <math>P \text{ н.мм} = 328.8</math>  <math>P \text{ вн.мм} = 123</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0136</b></p> <p> <math>F \text{ см}^2 = 3.450</math>  <math>Q \text{ кг.} = 0.935</math>  <math>D \text{ оп.мм} = 76.0</math>  <math>P \text{ н.мм} = 244.0</math>  <math>P \text{ вн.мм} = 62.9</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-132</b></p> <p> <math>F \text{ см}^2 = 11.500</math>  <math>Q \text{ кг.} = 3.12</math>  <math>D \text{ оп.мм} = 140.0</math>  <math>P \text{ н.мм} = 416.0</math>  <math>P \text{ вн.мм} = 307.0</math>  Гр. сл. = 0соб.  Точн. = Т </p>		<p><b>БПЗ-0137</b></p> <p> <math>F \text{ см}^2 = 2.227</math>  <math>Q \text{ кг.} = 0.604</math>  <math>D \text{ оп.мм} = 63.5</math>  <math>P \text{ н.мм} = 176.7</math>  <math>P \text{ вн.мм} = 85.2</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-133</b></p> <p> <math>F \text{ см}^2 = 7.650</math>  <math>Q \text{ кг.} = 2.07</math>  <math>D \text{ оп.мм} = 94.0</math>  <math>P \text{ н.мм} = 292.0</math>  <math>P \text{ вн.мм} = 206.0</math>  Гр. сл. = VI  Точн. = Т </p>		
	<p><b>БПЗ-134</b></p> <p> <math>F \text{ см}^2 = 8.950</math>  <math>Q \text{ кг.} = 2.42</math>  <math>D \text{ оп.мм} = 94.0</math>  <math>P \text{ н.мм} = 363.0</math>  <math>P \text{ вн.мм} = 210.0</math>  Гр. сл. = VI  Точн. = Т </p>		
	<p><b>БПЗ-135</b></p> <p> <math>F \text{ см}^2 = 7.060</math>  <math>Q \text{ кг.} = 1.91</math>  <math>D \text{ оп.мм} = 91.0</math>  <math>P \text{ н.мм} = 294.0</math>  <math>P \text{ вн.мм} = 219.0</math>  Гр. сл. = VI  Точн. = Т </p>		









			<b>БПЗ-146</b> $F \text{ см}^2 = 1.115$ $Q \text{ кг.} = 0.302$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 84.6$ $P \text{ вн.мм} = 0.0$ Гр. сл. = III Точн. = П
			<b>БПЗ-147</b> $F \text{ см}^2 = 4.740$ $Q \text{ кг.} = 1.285$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 171.0$ $P \text{ вн.мм} = 101.5$ Гр. сл. = V Точн. = Т
	<b>БПЗ-143</b> $F \text{ см}^2 = 22.75$ $Q \text{ кг.} = 6.16$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 239.0$ $P \text{ вн.мм} = 136.0$ Гр. сл. = VI Точн. = Т		<b>БПЗ-0148</b> $F \text{ см}^2 = 2.421$ $Q \text{ кг.} = 0.656$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 134.7$ $P \text{ вн.мм} = 63.7$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-144</b> $F \text{ см}^2 = 2.600$ $Q \text{ кг.} = 0.704$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 103.0$ $P \text{ вн.мм} = 38.0$ Гр. сл. = V Точн. = Т		<b>БПЗ-149</b> $F \text{ см}^2 = 2.217$ $Q \text{ кг.} = 0.601$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 61.7$ $P \text{ вн.мм} = 35.1$ Гр. сл. = II Точн. = П
	<b>БПЗ-145</b> $F \text{ см}^2 = 9.26$ $Q \text{ кг.} = 2.509$ $D \text{ оп.мм} = 127.0$ $P \text{ н.мм} = 455.6$ $P \text{ вн.мм} = 345.6$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-150</b> $F \text{ см}^2 = 4.55$ $Q \text{ кг.} = 1.233$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 347.87$ $P \text{ вн.мм} = 123$ Гр. сл. = VI Точн. = П

	<b>БПЗ-151</b> $F \text{ см}^2 = 2.789$ $Q \text{ кг.} = 0.756$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 21.05$ Гр. сл. = II Точн. = Н		<b>БПЗ-156</b> $F \text{ см}^2 = 8.820$ $Q \text{ кг.} = 2.390$ $D \text{ оп.мм} = 126.5$ $P \text{ н.мм} = 359.7$ $P \text{ вн.мм} = 315.0$ Гр. сл. = IV Точн. = П
	<b>БПЗ-152</b> $F \text{ см}^2 = 7.360$ $Q \text{ кг.} = 1.99$ $D \text{ оп.мм} = 95.3$ $P \text{ н.мм} = 302.5$ $P \text{ вн.мм} = 156.0$ Гр. сл. = V Точн. = Т		<b>БПЗ-157</b> $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.487$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 66.5$ $P \text{ вн.мм} = 46.0$ Гр. сл. = III Точн. = Н
	<b>БПЗ-0153</b> $F \text{ см}^2 = 2.519$ $Q \text{ кг.} = 0.683$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 194.0$ $P \text{ вн.мм} = 65.5$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-158</b> $F \text{ см}^2 = 9.150$ $Q \text{ кг.} = 2.480$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 346.0$ $P \text{ вн.мм} = 236.0$ Гр. сл. = IV Точн. = Т
	<b>БПЗ-0154</b> $F \text{ см}^2 = 4.036$ $Q \text{ кг.} = 1.094$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 183.2$ $P \text{ вн.мм} = 210.2$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-159</b> $F \text{ см}^2 = 7.540$ $Q \text{ кг.} = 2.043$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 343.0$ $P \text{ вн.мм} = 206.0$ Гр. сл. = VI Точн. = Т
	<b>БПЗ-155</b> $F \text{ см}^2 = 6.820$ $Q \text{ кг.} = 1.848$ $D \text{ оп.мм} = 89.4$ $P \text{ н.мм} = 278.7$ $P \text{ вн.мм} = 235.0$ Гр. сл. = IV Точн. = П		<b>БПЗ-160</b> $F \text{ см}^2 = 8.000$ $Q \text{ кг.} = 2.17$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 223.0$ $P \text{ вн.мм} = 144.0$ Гр. сл. = IV Точн. = Т









	<b>БПЗ-161</b> $F \text{ см}^2 = 8.310$ $Q \text{ кг.} = 2.252$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 251.0$ $P \text{ вн.мм} = 144.0$ Гр. сл. = IV Точн. = Т		<b>БПЗ-166</b> $F \text{ см}^2 = 2.680$ $Q \text{ кг.} = 0.725$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 167.0$ $P \text{ вн.мм} = 115.0$ Гр. сл. = 0соб. Точн. = Н
			<b>БПЗ-167</b> $F \text{ см}^2 = 2.380$ $Q \text{ кг.} = 0.64$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 143.0$ $P \text{ вн.мм} = 91.0$ Гр. сл. = 0соб. Точн. = Н
			<b>БПЗ-168</b> $F \text{ см}^2 = 7.800$ $Q \text{ кг.} = 2.114$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 237.0$ $P \text{ вн.мм} = 170.0$ Гр. сл. = V Точн. = Т
	<b>БПЗ-164</b> $F \text{ см}^2 = 13.07$ $Q \text{ кг.} = 3.54$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 265.0$ $P \text{ вн.мм} = 229.0$ Гр. сл. = III Точн. = Т		<b>БПЗ-169</b> $F \text{ см}^2 = 20.200$ $Q \text{ кг.} = 5.49$ $D \text{ оп.мм} = 134.0$ $P \text{ н.мм} = 440.0$ $P \text{ вн.мм} = 275.0$ Гр. сл. = VI Точн. = Т
	<b>БПЗ-165</b> $F \text{ см}^2 = 3.350$ $Q \text{ кг.} = 0.909$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 217.0$ $P \text{ вн.мм} = 126.0$ Гр. сл. = 0соб. Точн. = Н		<b>БПЗ-170</b> $F \text{ см}^2 = 3.420$ $Q \text{ кг.} = 0.93$ $D \text{ оп.мм} = 51.8$ $P \text{ н.мм} = 212.5$ $P \text{ вн.мм} = 106.0$ Гр. сл. = VI Точн. = Т










	<p><b>БПЗ-171</b></p> <p> <math>F \text{ см}^2 = 3.670</math>  <math>Q \text{ кг.} = 0.991</math>  <math>D \text{ оп.мм} = 51.8</math>  <math>P \text{ н.мм} = 236.5</math>  <math>P \text{ вн.мм} = 106.0</math>  Гр. сл. = VI  Точн. = Т </p>		<p><b>БПЗ-176</b></p> <p> <math>F \text{ см}^2 = 6.328</math>  <math>Q \text{ кг.} = 1.715</math>  <math>D \text{ оп.мм} = 99.4</math>  <math>P \text{ н.мм} = 326.3</math>  <math>P \text{ вн.мм} = 232.8</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-172</b></p> <p> <math>F \text{ см}^2 = 3.920</math>  <math>Q \text{ кг.} = 1.064</math>  <math>D \text{ оп.мм} = 51.8</math>  <math>P \text{ н.мм} = 260.5</math>  <math>P \text{ вн.мм} = 106.0</math>  Гр. сл. = VI  Точн. = Т </p>		<p><b>БПЗ-177</b></p> <p> <math>F \text{ см}^2 = 4.69</math>  <math>Q \text{ кг.} = 1.271</math>  <math>D \text{ оп.мм} = 56.4</math>  <math>P \text{ н.мм} = 257</math>  <math>P \text{ вн.мм} = 148.2</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-173</b></p> <p> <math>F \text{ см}^2 = 3.260</math>  <math>Q \text{ кг.} = 0.883</math>  <math>D \text{ оп.мм} = 38.3</math>  <math>P \text{ н.мм} = 256.0</math>  <math>P \text{ вн.мм} = 48.0</math>  Гр. сл. = V  Точн. = Т </p>		<p><b>БПЗ-178</b></p> <p> <math>F \text{ см}^2 = 1.040</math>  <math>Q \text{ кг.} = 0.282</math>  <math>D \text{ оп.мм} = 14.0</math>  <math>P \text{ н.мм} = 44.0</math>  <math>P \text{ вн.мм} = 25.1</math>  Гр. сл. = IV  Точн. = Т </p>
	<p><b>БПЗ-174</b></p> <p> <math>F \text{ см}^2 = 7.540</math>  <math>Q \text{ кг.} = 2.04</math>  <math>D \text{ оп.мм} = 70.7</math>  <math>P \text{ н.мм} = 557.5</math>  <math>P \text{ вн.мм} = 163.2</math>  Гр. сл. = 0соб.  Точн. = Т </p>		<p><b>БПЗ-179</b></p> <p> <math>F \text{ см}^2 = 1.370</math>  <math>Q \text{ кг.} = 0.371</math>  <math>D \text{ оп.мм} = 16.0</math>  <math>P \text{ н.мм} = 50.2</math>  <math>P \text{ вн.мм} = 28.3</math>  Гр. сл. = IV  Точн. = Т </p>
	<p><b>БПЗ-175</b></p> <p> <math>F \text{ см}^2 = 3.320</math>  <math>Q \text{ кг.} = 0.900</math>  <math>D \text{ оп.мм} = 38.3</math>  <math>P \text{ н.мм} = 260.0</math>  <math>P \text{ вн.мм} = 54.2</math>  Гр. сл. = 0соб.  Точн. = Т </p>		<p><b>БПЗ-180</b></p> <p> <math>F \text{ см}^2 = 1.600</math>  <math>Q \text{ кг.} = 0.434</math>  <math>D \text{ оп.мм} = 18.0</math>  <math>P \text{ н.мм} = 56.5</math>  <math>P \text{ вн.мм} = 34.5</math>  Гр. сл. = IV  Точн. = Т </p>











	<b>БПЗ-0181</b> $F \text{ см}^2 = 3.032$ $Q \text{ кг.} = 0.822$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 209.2$ $P \text{ вн.мм} = 94.0$ Гр. сл. = IV Точн. = П		<b>БПЗ-186</b> $F \text{ см}^2 = 2.760$ $Q \text{ кг.} = 0.748$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 81.6$ $P \text{ вн.мм} = 56.3$ Гр. сл. = II Точн. = Т
	<b>БПЗ-182</b> $F \text{ см}^2 = 1.810$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 40.8$ Гр. сл. = IV Точн. = Т		<b>БПЗ-187</b> $F \text{ см}^2 = 2.470$ $Q \text{ кг.} = 0.669$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 81.6$ $P \text{ вн.мм} = 59.7$ Гр. сл. = II Точн. = Т
	<b>БПЗ-183</b> $F \text{ см}^2 = 2.260$ $Q \text{ кг.} = 0.612$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 69.1$ $P \text{ вн.мм} = 44.0$ Гр. сл. = IV Точн. = Т		
	<b>БПЗ-184</b> $F \text{ см}^2 = 2.510$ $Q \text{ кг.} = 0.680$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 75.4$ $P \text{ вн.мм} = 50.2$ Гр. сл. = II Точн. = Т		<b>БПЗ-189</b> $F \text{ см}^2 = 2.6$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 152$ $P \text{ вн.мм} = 92$ Гр. сл. = V Точн. = П
	<b>БПЗ-185</b> $F \text{ см}^2 = 2.250$ $Q \text{ кг.} = 0.610$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 75.4$ $P \text{ вн.мм} = 53.4$ Гр. сл. = II Точн. = Т		<b>БПЗ-190</b> $F \text{ см}^2 = 16.300$ $Q \text{ кг.} = 4.42$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 303.0$ $P \text{ вн.мм} = 250.0$ Гр. сл. = 0соб. Точн. = Т











	<b>БПЗ-191</b> $F \text{ см}^2 = 1.65$ $Q \text{ кг.} = 0.447$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 104.7$ $P \text{ вн.мм} = 57.4$ Гр. сл. = IV Точн. = Н		<b>БПЗ-0196</b> $F \text{ см}^2 = 3.770$ $Q \text{ кг.} = 1.022$ $D \text{ оп.мм} = 43.4$ $P \text{ н.мм} = 309.4$ $P \text{ вн.мм} = 62.8$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-192</b> $F \text{ см}^2 = 22.560$ $Q \text{ кг.} = 6.114$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 219.9$ $P \text{ вн.мм} = 141.3$ Гр. сл. = II Точн. = Т		<b>БПЗ-0197</b> $F \text{ см}^2 = 3.440$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 36.4$ $P \text{ н.мм} = 92.0$ $P \text{ вн.мм} = 25.8$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-193</b> $F \text{ см}^2 = 7.037$ $Q \text{ кг.} = 1.907$ $D \text{ оп.мм} = 118.0$ $P \text{ н.мм} = 408.1$ $P \text{ вн.мм} = 301.6$ Гр. сл. = VI Точн. = П		
	<b>БПЗ-0194</b> $F \text{ см}^2 = 5.052$ $Q \text{ кг.} = 1.369$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 289.2$ $P \text{ вн.мм} = 194.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-199</b> $F \text{ см}^2 = 8.075$ $Q \text{ кг.} = 2.188$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 151.2$ $P \text{ вн.мм} = 112.7$ Гр. сл. = IV Точн. = П
			<b>БПЗ-200</b> $F \text{ см}^2 = 20.504$ $Q \text{ кг.} = 5.556$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 377.6$ $P \text{ вн.мм} = 341.8$ Гр. сл. = IV Точн. = П






















			<b>БПЗ-0206</b>
			$F \text{ см}^2 = 3.108$ $Q \text{ кг.} = 0.842$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 215.0$ $P \text{ вн.мм} = 190.3$ Гр. сл. = 0соб. Точн. = П
			<b>БПЗ-0207</b>
			$F \text{ см}^2 = 7.492$ $Q \text{ кг.} = 2.030$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 287.7$ $P \text{ вн.мм} = 280.6$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-203</b>		<b>БПЗ-208</b>
	$F \text{ см}^2 = 5.337$ $Q \text{ кг.} = 1.446$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 347.9$ $P \text{ вн.мм} = 182$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 12.060$ $Q \text{ кг.} = 3.268$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 307.1$ $P \text{ вн.мм} = 278.3$ Гр. сл. = VI Точн. = Т
	<b>БПЗ-204</b>		<b>БПЗ-209</b>
	$F \text{ см}^2 = 4.908$ $Q \text{ кг.} = 1.33$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 290.3$ $P \text{ вн.мм} = 182$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 3.220$ $Q \text{ кг.} = 0.873$ $D \text{ оп.мм} = 52.3$ $P \text{ н.мм} = 192.0$ $P \text{ вн.мм} = 118.0$ Гр. сл. = V Точн. = Т
	<b>БПЗ-205</b>		<b>БПЗ-210</b>
	$F \text{ см}^2 = 25.298$ $Q \text{ кг.} = 6.856$ $D \text{ оп.мм} = 148.0$ $P \text{ н.мм} = 397.4$ $P \text{ вн.мм} = 359.4$ Гр. сл. = VI Точн. = Н		$F \text{ см}^2 = 3.558$ $Q \text{ кг.} = 0.964$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 157.4$ $P \text{ вн.мм} = 82.0$ Гр. сл. = IV Точн. = П











	<p><b>БПЗ-211</b></p> <p> <math>F \text{ см}^2 = 8.090</math>  <math>Q \text{ кг.} = 2.192</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 173.0</math>  <math>P \text{ вн.мм} = 57.0</math>  Гр. сл. = IV  Точн. = Т </p>		<p><b>БПЗ-0216</b></p> <p> <math>F \text{ см}^2 = 12.400</math>  <math>Q \text{ кг.} = 3.360</math>  <math>D \text{ оп.мм} = 81.5</math>  <math>P \text{ н.мм} = 317.8</math>  <math>P \text{ вн.мм} = 139.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-212</b></p> <p> <math>F \text{ см}^2 = 1.805</math>  <math>Q \text{ кг.} = 0.489</math>  <math>D \text{ оп.мм} = 33.7</math>  <math>P \text{ н.мм} = 96.6</math>  <math>P \text{ вн.мм} = 84</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-217</b></p> <p> <math>F \text{ см}^2 = 3.612</math>  <math>Q \text{ кг.} = 0.979</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>P \text{ н.мм} = 126.2</math>  <math>P \text{ вн.мм} = 102.3</math>  Гр. сл. = VI  Точн. = Н </p>
	<p><b>БПЗ-0213</b></p> <p> <math>F \text{ см}^2 = 1.369</math>  <math>Q \text{ кг.} = 0.371</math>  <math>D \text{ оп.мм} = 35.4</math>  <math>P \text{ н.мм} = 159.0</math>  <math>P \text{ вн.мм} = 63.9</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-0218</b></p> <p> <math>F \text{ см}^2 = 2.227</math>  <math>Q \text{ кг.} = 0.604</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 129.3</math>  <math>P \text{ вн.мм} = 63.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-0214</b></p> <p> <math>F \text{ см}^2 = 1.547</math>  <math>Q \text{ кг.} = 0.419</math>  <math>D \text{ оп.мм} = 42.8</math>  <math>P \text{ н.мм} = 185.0</math>  <math>P \text{ вн.мм} = 74.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0219</b></p> <p> <math>F \text{ см}^2 = 2.544</math>  <math>Q \text{ кг.} = 0.689</math>  <math>D \text{ оп.мм} = 63.0</math>  <math>P \text{ н.мм} = 288.1</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-215</b></p> <p> <math>F \text{ см}^2 = 7.338</math>  <math>Q \text{ кг.} = 1.989</math>  <math>D \text{ оп.мм} = 60.0</math>  <math>P \text{ н.мм} = 541.5</math>  <math>P \text{ вн.мм} = 128.5</math>  Гр. сл. = 0соб.  Точн. = П </p>		











	<b>БПЗ-0221</b> $F \text{ см}^2 = 1.723$ $Q \text{ кг.} = 0.467$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 239.9$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-226</b> $F \text{ см}^2 = 2$ $Q \text{ кг.} = 0.54$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 232.0$ $P \text{ вн.мм} = 101.3$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-0222</b> $F \text{ см}^2 = 3.349$ $Q \text{ кг.} = 0.908$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 319.7$ $P \text{ вн.мм} = 124.0$ Гр. сл. = IV Точн. = П		<b>БПЗ-227</b> $F \text{ см}^2 = 2.68$ $Q \text{ кг.} = 0.726$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 306.5$ $P \text{ вн.мм} = 101.3$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-223</b> $F \text{ см}^2 = 1.820$ $Q \text{ кг.} = 0.493$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 97.3$ $P \text{ вн.мм} = 84.8$ Гр. сл. = III Точн. = Т		<b>БПЗ-228</b> $F \text{ см}^2 = 1.000$ $Q \text{ кг.} = 0.271$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 56.5$ $P \text{ вн.мм} = 44.0$ Гр. сл. = IV Точн. = Т
	<b>БПЗ-224</b> $F \text{ см}^2 = 8.441$ $Q \text{ кг.} = 2.288$ $D \text{ оп.мм} = 129.0$ $P \text{ н.мм} = 237.4$ $P \text{ вн.мм} = 521.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-229</b> $F \text{ см}^2 = 12.35$ $Q \text{ кг.} = 3.347$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 226.7$ $P \text{ вн.мм} = 100.9$ Гр. сл. = V Точн. = Н
	<b>БПЗ-0225</b> $F \text{ см}^2 = 5.372$ $Q \text{ кг.} = 1.456$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 227.7$ $P \text{ вн.мм} = 31.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-230</b> $F \text{ см}^2 = 1.16$ $Q \text{ кг.} = 0.314$ $D \text{ оп.мм} = 26.0$ $P \text{ н.мм} = 76.5$ $P \text{ вн.мм} = 28.3$ Гр. сл. = IV Точн. = Н

	<b>БПЗ-231</b> $F \text{ см}^2 = 6.870$ $Q \text{ кг.} = 1.858$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 416.0$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-236</b> $F \text{ см}^2 = 7.600$ $Q \text{ кг.} = 2.060$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.7$ $P \text{ вн.мм} = 78.5$ Гр. сл. = I Точн. = Т
	<b>БПЗ-232</b> $F \text{ см}^2 = 6.120$ $Q \text{ кг.} = 1.659$ $D \text{ оп.мм} = 59.0$ $P \text{ н.мм} = 324.0$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-237</b> $F \text{ см}^2 = 23.700$ $Q \text{ кг.} = 6.423$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 235.6$ $P \text{ вн.мм} = 160.0$ Гр. сл. = I Точн. = Т
	<b>БПЗ-233-01</b> $F \text{ см}^2 = 6.140$ $Q \text{ кг.} = 1.664$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 317.0$ $P \text{ вн.мм} = 237.0$ Гр. сл. = V Точн. = П		<b>БПЗ-238</b> $F \text{ см}^2 = 30.600$ $Q \text{ кг.} = 8.293$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 251.3$ $P \text{ вн.мм} = 157.1$ Гр. сл. = I Точн. = Т
	<b>БПЗ-234-01</b> $F \text{ см}^2 = 6.730$ $Q \text{ кг.} = 1.824$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 385.0$ $P \text{ вн.мм} = 228.0$ Гр. сл. = VI Точн. = П		<b>БПЗ-0239</b> $F \text{ см}^2 = 19.986$ $Q \text{ кг.} = 5.416$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 264.4$ $P \text{ вн.мм} = 62.8$ Гр. сл. = IV Точн. = Н
	<b>БПЗ-0235</b> $F \text{ см}^2 = 15.800$ $Q \text{ кг.} = 4.282$ $D \text{ оп.мм} = 114.0$ $P \text{ н.мм} = 289.9$ $P \text{ вн.мм} = 34.6$ Гр. сл. = IV Точн. = Н		<b>БПЗ-0240</b> $F \text{ см}^2 = 2.097$ $Q \text{ кг.} = 0.568$ $D \text{ оп.мм} = 42.8$ $P \text{ н.мм} = 212.5$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = П









	<b>БПЗ-0241</b> $F \text{ см}^2 = 1.916$ $Q \text{ кг.} = 0.519$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 183.2$ $P \text{ вн.мм} = 73.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-247</b> $F \text{ см}^2 = 7.780$ $Q \text{ кг.} = 2.178$ $D \text{ оп.мм} = 38.0$ $P \text{ н.мм} = 217.6$ $P \text{ вн.мм} = 30.7$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-242</b> $F \text{ см}^2 = 5.418$ $Q \text{ кг.} = 1.468$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 401$ $P \text{ вн.мм} = 148.5$ Гр. сл. = IV Точн. = П		<b>БПЗ-248</b> $F \text{ см}^2 = 1.823$ $Q \text{ кг.} = 0.494$ $D \text{ оп.мм} = 27.2$ $P \text{ н.мм} = 122.6$ $P \text{ вн.мм} = 0.0$ Гр. сл. = III Точн. = П
	<b>БПЗ-243</b> $F \text{ см}^2 = 6.53$ $Q \text{ кг.} = 1.77$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 293.2$ $P \text{ вн.мм} = 274.8$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-249</b> $F \text{ см}^2 = 2.950$ $Q \text{ кг.} = 0.799$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.6$ $P \text{ вн.мм} = 109.9$ Гр. сл. = III Точн. = Т
	<b>БПЗ-0244</b> $F \text{ см}^2 = 0.615$ $Q \text{ кг.} = 0.167$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 66.5$ $P \text{ вн.мм} = 26.8$ Гр. сл. = VI Точн. = Н		<b>БПЗ-250</b> $F \text{ см}^2 = 3.900$ $Q \text{ кг.} = 1.057$ $D \text{ оп.мм} = 120.5$ $P \text{ н.мм} = 268.3$ $P \text{ вн.мм} = 117.6$ Гр. сл. = 0соб. Точн. = Т
	<b>БПЗ-0245</b> $F \text{ см}^2 = 34.160$ $Q \text{ кг.} = 9.257$ $D \text{ оп.мм} = 173.0$ $P \text{ н.мм} = 642.1$ $P \text{ вн.мм} = 607.9$ Гр. сл. = VI Точн. = П		<b>БПЗ-250-01</b> $F \text{ см}^2 = 3.818$ $Q \text{ кг.} = 1.035$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 268.0$ $P \text{ вн.мм} = 115.0$ Гр. сл. = 0соб. Точн. = Н


	<b>БПЗ-251</b> $F \text{ см}^2 = 3.070$ $Q \text{ кг.} = 0.832$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 96.2$ $P \text{ вн.мм} = 116.5$ Гр. сл. = IV Точн. = П		
	<b>БПЗ-0252</b> $F \text{ см}^2 = 29.700$ $Q \text{ кг.} = 8.049$ $D \text{ оп.мм} = 187.0$ $P \text{ н.мм} = 571.4$ $P \text{ вн.мм} = 246.4$ Гр. сл. = VI Точн. = П		<b>БПЗ-257</b> $F \text{ см}^2 = 6.86$ $Q \text{ кг.} = 1.859$ $D \text{ оп.мм} = 91.7$ $P \text{ н.мм} = 343.2$ $P \text{ вн.мм} = 229.8$ Гр. сл. = VI Точн. = П
	<b>БПЗ-253</b> $F \text{ см}^2 = 48.800$ $Q \text{ кг.} = 13.225$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 318.0$ $P \text{ вн.мм} = 178.0$ Гр. сл. = IV Точн. = Т		<b>БПЗ-258</b> $F \text{ см}^2 = 7.910$ $Q \text{ кг.} = 2.144$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 256.1$ $P \text{ вн.мм} = 111.7$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-254</b> $F \text{ см}^2 = 13.35$ $Q \text{ кг.} = 3.618$ $D \text{ оп.мм} = 88.0$ $P \text{ н.мм} = 226.2$ $P \text{ вн.мм} = 94.2$ Гр. сл. = IV Точн. = П		<b>БПЗ-259</b> $F \text{ см}^2 = 8.300$ $Q \text{ кг.} = 2.249$ $D \text{ оп.мм} = 103.0$ $P \text{ н.мм} = 329.5$ $P \text{ вн.мм} = 161.0$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-255</b> $F \text{ см}^2 = 8.660$ $Q \text{ кг.} = 2.347$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 235.7$ $P \text{ вн.мм} = 198.0$ Гр. сл. = V Точн. = П		<b>БПЗ-260</b> $F \text{ см}^2 = 12.020$ $Q \text{ кг.} = 3.257$ $D \text{ оп.мм} = 118.0$ $P \text{ н.мм} = 385.0$ $P \text{ вн.мм} = 349.0$ Гр. сл. = VI Точн. = Н

	<p><b>БПЗ-0261</b></p> <p> <math>F \text{ см}^2 = 2.2</math>  <math>Q \text{ кг.} = 0.527</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 79.0</math>  <math>P \text{ вн.мм} = 67.9</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-266</b></p> <p> <math>F \text{ см}^2 = 4.018</math>  <math>Q \text{ кг.} = 1.089</math>  <math>D \text{ оп.мм} = 69.3</math>  <math>P \text{ н.мм} = 207.9</math>  <math>P \text{ вн.мм} = 194</math>  Гр. сл. = VI  Точн. = Н </p>
	<p><b>БПЗ-262-01</b></p> <p> <math>F \text{ см}^2 = 13.731</math>  <math>Q \text{ кг.} = 3.721</math>  <math>D \text{ оп.мм} = 87.6</math>  <math>P \text{ н.мм} = 551.7</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-0267</b></p> <p> <math>F \text{ см}^2 = 2.000</math>  <math>Q \text{ кг.} = 0.542</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>P \text{ н.мм} = 105.8</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-263-01</b></p> <p> <math>F \text{ см}^2 = 5.180</math>  <math>Q \text{ кг.} = 1.404</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 291.8</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-268</b></p> <p> <math>F \text{ см}^2 = 5.61</math>  <math>Q \text{ кг.} = 1.52</math>  <math>D \text{ оп.мм} = 83</math>  <math>P \text{ н.мм} = 280.4</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-264</b></p> <p> <math>F \text{ см}^2 = 14.840</math>  <math>Q \text{ кг.} = 4.022</math>  <math>D \text{ оп.мм} = 103.0</math>  <math>P \text{ н.мм} = 581.0</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-269</b></p> <p> <math>F \text{ см}^2 = 6.860</math>  <math>Q \text{ кг.} = 1.859</math>  <math>D \text{ оп.мм} = 105.0</math>  <math>P \text{ н.мм} = 337.8</math>  <math>P \text{ вн.мм} = 124.6</math>  Гр. сл. = VI  Точн. = Н </p>
	<p><b>БПЗ-265</b></p> <p> <math>F \text{ см}^2 = 9.670</math>  <math>Q \text{ кг.} = 2.621</math>  <math>D \text{ оп.мм} = 100.5</math>  <math>P \text{ н.мм} = 426.0</math>  <math>P \text{ вн.мм} = 111.0</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-270</b></p> <p> <math>F \text{ см}^2 = 2.470</math>  <math>Q \text{ кг.} = 0.669</math>  <math>D \text{ оп.мм} = 31.5</math>  <math>P \text{ н.мм} = 138.1</math>  <math>P \text{ вн.мм} = 75.4</math>  Гр. сл. = III  Точн. = Н </p>

	<b>БПЗ-271</b> $F \text{ см}^2 = 0.589$ $Q \text{ кг.} = 0.160$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 44.0$ $P \text{ вн.мм} = 34.5$ Гр. сл. = IV Точн. = П		<b>БПЗ-276</b> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 39.0$ $P \text{ н.мм} = 146.0$ $P \text{ вн.мм} = 89.0$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-272</b> $F \text{ см}^2 = 0.960$ $Q \text{ кг.} = 0.260$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 69.1$ $P \text{ вн.мм} = 59.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-277</b> $F \text{ см}^2 = 3.880$ $Q \text{ кг.} = 1.051$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 168.0$ $P \text{ вн.мм} = 124.0$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-273</b> $F \text{ см}^2 = 0.780$ $Q \text{ кг.} = 0.211$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 56.5$ $P \text{ вн.мм} = 47.1$ Гр. сл. = IV Точн. = П		<b>БПЗ-278</b> $F \text{ см}^2 = 13.500$ $Q \text{ кг.} = 3.659$ $D \text{ оп.мм} = 151.0$ $P \text{ н.мм} = 428.0$ $P \text{ вн.мм} = 388.0$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-274</b> $F \text{ см}^2 = 5.230$ $Q \text{ кг.} = 1.417$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 303.0$ $P \text{ вн.мм} = 246.0$ Гр. сл. = VI Точн. = Н		<b>БПЗ-279</b> $F \text{ см}^2 = 3.972$ $Q \text{ кг.} = 1.076$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 306.8$ $P \text{ вн.мм} = 81.7$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-275</b> $F \text{ см}^2 = 6.100$ $Q \text{ кг.} = 1.653$ $D \text{ оп.мм} = 85.5$ $P \text{ н.мм} = 266.0$ $P \text{ вн.мм} = 209.0$ Гр. сл. = 0соб. Точн. = Н		<b>БПЗ-280</b> $F \text{ см}^2 = 6.510$ $Q \text{ кг.} = 1.764$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 200.0$ $P \text{ вн.мм} = 172.0$ Гр. сл. = IV Точн. = Н




	<p><b>БПЗ-281</b></p> <p> <math>F \text{ см}^2 = 3.840</math>  <math>Q \text{ кг.} = 1.041</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 200.0</math>  <math>P \text{ вн.мм} = 184.0</math>  Гр. сл. = VI  Точн. = Т </p>		<p><b>БПЗ-286</b></p> <p> <math>F \text{ см}^2 = 5.264</math>  <math>Q \text{ кг.} = 1.427</math>  <math>D \text{ оп.мм} = 90.5</math>  <math>P \text{ н.мм} = 387.3</math>  <math>P \text{ вн.мм} = 146.5</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-282</b></p> <p> <math>F \text{ см}^2 = 1.679</math>  <math>Q \text{ кг.} = 0.455</math>  <math>D \text{ оп.мм} = 41.0</math>  <math>P \text{ н.мм} = 116.6</math>  <math>P \text{ вн.мм} = 107.1</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-287</b></p> <p> <math>F \text{ см}^2 = 4.520</math>  <math>Q \text{ кг.} = 1.225</math>  <math>D \text{ оп.мм} = 72.0</math>  <math>P \text{ н.мм} = 332.0</math>  <math>P \text{ вн.мм} = 120.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-283</b></p> <p> <math>F \text{ см}^2 = 2.240</math>  <math>Q \text{ кг.} = 0.607</math>  <math>D \text{ оп.мм} = 44.0</math>  <math>P \text{ н.мм} = 120.0</math>  <math>P \text{ вн.мм} = 104.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-288</b></p> <p> <math>F \text{ см}^2 = 4.740</math>  <math>Q \text{ кг.} = 1.284</math>  <math>D \text{ оп.мм} = 61.5</math>  <math>P \text{ н.мм} = 163.5</math>  <math>P \text{ вн.мм} = 138.7</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-284</b></p> <p> <math>F \text{ см}^2 = 2.640</math>  <math>Q \text{ кг.} = 0.715</math>  <math>D \text{ оп.мм} = 51.0</math>  <math>P \text{ н.мм} = 140.0</math>  <math>P \text{ вн.мм} = 124.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-289</b></p> <p> <math>F \text{ см}^2 = 4.884</math>  <math>Q \text{ кг.} = 1.324</math>  <math>D \text{ оп.мм} = 71.0</math>  <math>P \text{ н.мм} = 394.8</math>  <math>P \text{ вн.мм} = 123</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-285</b></p> <p> <math>F \text{ см}^2 = 2.264</math>  <math>Q \text{ кг.} = 0.614</math>  <math>D \text{ оп.мм} = 47.0</math>  <math>P \text{ н.мм} = 205.5</math>  <math>P \text{ вн.мм} = 70.4</math>  Гр. сл. = IV  Точн. = П </p>		



БПЗ-291


$F \text{ см}^2 = 5.55$   
 $Q \text{ кг.} = 1.5$   
 $D \text{ оп.мм} = 60.0$   
 $P \text{ н.мм} = 188.7$   
 $P \text{ вн.мм} = 165.2$   
 Гр. сл. = IV  
 Точн. = Н

БПЗ-299














$F \text{ см}^2 = 0.952$   
 $Q \text{ кг.} = 0.258$   
 $D \text{ оп.мм} = 15.0$   
 $P \text{ н.мм} = 48.13$   
 $P \text{ вн.мм} = 17.28$   
 Гр. сл. = IV  
 Точн. = Н










БПЗ-300





















$F \text{ см}^2 = 7.910$   
 $Q \text{ кг.} = 2.144$   
 $D \text{ оп.мм} = 91.0$   
 $P \text{ н.мм} = 303.0$   
 $P \text{ вн.мм} = 226.0$   
 Гр. сл. = 0соб.  
 Точн. = Н

	<p><b>БПЗ-301</b></p> <p> <math>F \text{ см}^2 = 1.848</math>  <math>Q \text{ кг.} = 0.501</math>  <math>D \text{ оп.мм} = 52.3</math>  <math>P \text{ н.мм} = 118.1</math>  <math>P \text{ вн.мм} = 84.8</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-306</b></p> <p> <math>F \text{ см}^2 = 4.560</math>  <math>Q \text{ кг.} = 1.236</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>P \text{ н.мм} = 141.4</math>  <math>P \text{ вн.мм} = 119.4</math>  Гр. сл. = II  Точн. = Н </p>
	<p><b>БПЗ-302</b></p> <p> <math>F \text{ см}^2 = 11.160</math>  <math>Q \text{ кг.} = 3.024</math>  <math>D \text{ оп.мм} = 105.0</math>  <math>P \text{ н.мм} = 330.0</math>  <math>P \text{ вн.мм} = 308.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-307</b></p> <p> <math>F \text{ см}^2 = 3.570</math>  <math>Q \text{ кг.} = 0.967</math>  <math>D \text{ оп.мм} = 36.0</math>  <math>P \text{ н.мм} = 113.1</math>  <math>P \text{ вн.мм} = 91.1</math>  Гр. сл. = II  Точн. = Н </p>
			<p><b>БПЗ-308</b></p> <p> <math>F \text{ см}^2 = 3.665</math>  <math>Q \text{ кг.} = 0.993</math>  <math>D \text{ оп.мм} = 130</math>  <math>P \text{ н.мм} = 270.8</math>  <math>P \text{ вн.мм} = 194.4</math>  Гр. сл. = VI  Точн. = П </p>
			<p><b>БПЗ-309</b></p> <p> <math>F \text{ см}^2 = 5.920</math>  <math>Q \text{ кг.} = 1.604</math>  <math>D \text{ оп.мм} = 88.0</math>  <math>P \text{ н.мм} = 275.7</math>  <math>P \text{ вн.мм} = 299.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
			<p><b>БПЗ-310</b></p> <p> <math>F \text{ см}^2 = 10.200</math>  <math>Q \text{ кг.} = 2.766</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 219.8</math>  <math>P \text{ вн.мм} = 188.4</math>  Гр. сл. = II  Точн. = Н </p>

			<b>БПЗ-317</b> $F \text{ см}^2 = 6.240$ $Q \text{ кг.} = 1.691$ $D \text{ оп.мм} = 113.1$ $P \text{ н.мм} = 320.0$ $P \text{ вн.мм} = 304.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
			<b>БПЗ-318</b> $F \text{ см}^2 = 0.276$ $Q \text{ кг.} = 0.075$ $D \text{ оп.мм} = 7.0$ $P \text{ н.мм} = 22.3$ $P \text{ вн.мм} = 12.2$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{H}$
			<b>БПЗ-319</b> $F \text{ см}^2 = 0.461$ $Q \text{ кг.} = 0.125$ $D \text{ оп.мм} = 9.0$ $P \text{ н.мм} = 28.6$ $P \text{ вн.мм} = 15.4$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{H}$
			<b>БПЗ-320</b> $F \text{ см}^2 = 0.527$ $Q \text{ кг.} = 0.143$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 31.7$ $P \text{ вн.мм} = 18.5$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{H}$











	<b>БПЗ-321</b> $F \text{ см}^2 = 0.750$ $Q \text{ кг.} = 0.203$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 37.7$ $P \text{ вн.мм} = 21.9$ Гр. сл. = IV Точн. = Н		
	<b>БПЗ-322</b> $F \text{ см}^2 = 1.810$ $Q \text{ кг.} = 0.491$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 40.8$ Гр. сл. = III Точн. = Н		<b>БПЗ-327</b> $F \text{ см}^2 = 3.978$ $Q \text{ кг.} = 1.076$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 255.5$ $P \text{ вн.мм} = 158$ Гр. сл. = IV Точн. = П
	<b>БПЗ-323</b> $F \text{ см}^2 = 2.28$ $Q \text{ кг.} = 0.618$ $D \text{ оп.мм} = 36.5$ $P \text{ н.мм} = 99.6$ $P \text{ вн.мм} = 35.4$ Гр. сл. = IV Точн. = Н		<b>БПЗ-328</b> $F \text{ см}^2 = 4.458$ $Q \text{ кг.} = 1.241$ $D \text{ оп.мм} = 77.8$ $P \text{ н.мм} = 285.5$ $P \text{ вн.мм} = 188$ Гр. сл. = IV Точн. = П
	<b>БПЗ-324</b> $F \text{ см}^2 = 6.463$ $Q \text{ кг.} = 1.751$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 415.2$ $P \text{ вн.мм} = 172.8$ Гр. сл. = IV Точн. = П		<b>БПЗ-329</b> $F \text{ см}^2 = 4.907$ $Q \text{ кг.} = 1.33$ $D \text{ оп.мм} = 81.4$ $P \text{ н.мм} = 326.2$ $P \text{ вн.мм} = 188$ Гр. сл. = IV Точн. = П
	<b>БПЗ-325</b> $F \text{ см}^2 = 3.240$ $Q \text{ кг.} = 0.878$ $D \text{ оп.мм} = 80.5$ $P \text{ н.мм} = 233.0$ $P \text{ вн.мм} = 153.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-330</b> $F \text{ см}^2 = 0.589$ $Q \text{ кг.} = 0.160$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 44.0$ $P \text{ вн.мм} = 34.5$ Гр. сл. = IV Точн. = Н









	<p><b>БПЗ-331</b></p> <p> <math>F \text{ см}^2 = 3.640</math>  <math>Q \text{ кг.} = 0.986</math>  <math>D \text{ оп.мм} = 57.8</math>  <math>P \text{ н.мм} = 190.0</math>  <math>P \text{ вн.мм} = 72.3</math>  Гр. сл. = IV  Точн. = П </p>		
	<p><b>БПЗ-332</b></p> <p> <math>F \text{ см}^2 = 2.550</math>  <math>Q \text{ кг.} = 0.691</math>  <math>D \text{ оп.мм} = 55.4</math>  <math>P \text{ н.мм} = 184.4</math>  <math>P \text{ вн.мм} = 82.6</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-337</b></p> <p> <math>F \text{ см}^2 = 0.454</math>  <math>Q \text{ кг.} = 0.123</math>  <math>D \text{ оп.мм} = 10.0</math>  <math>P \text{ н.мм} = 31.7</math>  <math>P \text{ вн.мм} = 20.42</math>  Гр. сл. = II  Точн. = Н </p>
	<p><b>БПЗ-333</b></p> <p> <math>F \text{ см}^2 = 2.800</math>  <math>Q \text{ кг.} = 0.759</math>  <math>D \text{ оп.мм} = 63.2</math>  <math>P \text{ н.мм} = 200.4</math>  <math>P \text{ вн.мм} = 102.6</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-338</b></p> <p> <math>F \text{ см}^2 = 3.520</math>  <math>Q \text{ кг.} = 0.954</math>  <math>D \text{ оп.мм} = 27.0</math>  <math>P \text{ н.мм} = 85.1</math>  <math>P \text{ вн.мм} = 53.1</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-334</b></p> <p> <math>F \text{ см}^2 = 15.660</math>  <math>Q \text{ кг.} = 4.244</math>  <math>D \text{ оп.мм} = 39.7</math>  <math>P \text{ н.мм} = 210.0</math>  <math>P \text{ вн.мм} = 119.4</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-339</b></p> <p> <math>F \text{ см}^2 = 1.840</math>  <math>Q \text{ кг.} = 0.499</math>  <math>D \text{ оп.мм} = 36.0</math>  <math>P \text{ н.мм} = 100.0</math>  <math>P \text{ вн.мм} = 84.0</math>  Гр. сл. = V  Точн. = Н </p>
			<p><b>БПЗ-340</b></p> <p> <math>F \text{ см}^2 = 4.825</math>  <math>Q \text{ кг.} = 1.308</math>  <math>D \text{ оп.мм} = 103.0</math>  <math>P \text{ н.мм} = 246.6</math>  <math>P \text{ вн.мм} = 231.4</math>  Гр. сл. = 0соб.  Точн. = Н </p>










	<p><b>БПЗ-341</b></p> <p> <math>F \text{ см}^2 = 1.440</math>  <math>Q \text{ кг.} = 0.390</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 80.0</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = IV  Точн. = Особ. </p>		<p><b>БПЗ-346</b></p> <p> <math>F \text{ см}^2 = 2.440</math>  <math>Q \text{ кг.} = 0.661</math>  <math>D \text{ оп.мм} = 75.1</math>  <math>P \text{ н.мм} = 164.0</math>  <math>P \text{ вн.мм} = 131.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-342</b></p> <p> <math>F \text{ см}^2 = 9.292</math>  <math>Q \text{ кг.} = 2.518</math>  <math>D \text{ оп.мм} = 127.0</math>  <math>P \text{ н.мм} = 559.3</math>  <math>P \text{ вн.мм} = 369.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-347</b></p> <p> <math>F \text{ см}^2 = 2.240</math>  <math>Q \text{ кг.} = 0.607</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 119.2</math>  <math>P \text{ вн.мм} = 104.0</math>  Гр. сл. = V  Точн. = Особ. </p>
	<p><b>БПЗ-343</b></p> <p> <math>F \text{ см}^2 = 4.56</math>  <math>Q \text{ кг.} = 1.236</math>  <math>D \text{ оп.мм} = 80.3</math>  <math>P \text{ н.мм} = 374.0</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = Особ.  Точн. = П </p>		<p><b>БПЗ-348</b></p> <p> <math>F \text{ см}^2 = 1.182</math>  <math>Q \text{ кг.} = 0.320</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 79.5</math>  <math>P \text{ вн.мм} = 67.6</math>  Гр. сл. = VI  Точн. = Н </p>
	<p><b>БПЗ-344</b></p> <p> <math>F \text{ см}^2 = 5.250</math>  <math>Q \text{ кг.} = 1.423</math>  <math>D \text{ оп.мм} = 103.0</math>  <math>P \text{ н.мм} = 246.5</math>  <math>P \text{ вн.мм} = 227.4</math>  Гр. сл. = Особ.  Точн. = Особ. </p>		<p><b>БПЗ-349</b></p> <p> <math>F \text{ см}^2 = 3.240</math>  <math>Q \text{ кг.} = 0.878</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 119.1</math>  <math>P \text{ вн.мм} = 96.0</math>  Гр. сл. = III  Точн. = Особ. </p>
	<p><b>БПЗ-345</b></p> <p> <math>F \text{ см}^2 = 12.160</math>  <math>Q \text{ кг.} = 3.295</math>  <math>D \text{ оп.мм} = 100.0</math>  <math>P \text{ н.мм} = 665.5</math>  <math>P \text{ вн.мм} = 285.5</math>  Гр. сл. = Особ.  Точн. = Н </p>		<p><b>БПЗ-350</b></p> <p> <math>F \text{ см}^2 = 2.640</math>  <math>Q \text{ кг.} = 0.715</math>  <math>D \text{ оп.мм} = 47.9</math>  <math>P \text{ н.мм} = 182.0</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = Особ.  Точн. = П </p>











	<b>БПЗ-351</b> $F \text{ см}^2 = 2.880$ $Q \text{ кг.} = 0.780$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 206.0$ $P \text{ вн.мм} = 82.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-356</b> $F \text{ см}^2 = 3.230$ $Q \text{ кг.} = 0.875$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 85.9$ $P \text{ вн.мм} = 57.7$ Гр. сл. = III Точн. = Н
	<b>БПЗ-352</b> $F \text{ см}^2 = 3.120$ $Q \text{ кг.} = 0.846$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 230$ $P \text{ вн.мм} = 82.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-357</b> $F \text{ см}^2 = 5.580$ $Q \text{ кг.} = 1.512$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 127.4$ $P \text{ вн.мм} = 96.0$ Гр. сл. = III Точн. = Н
	<b>БПЗ-353</b> $F \text{ см}^2 = 0.640$ $Q \text{ кг.} = 0.173$ $D \text{ оп.мм} = 14.0$ $P \text{ н.мм} = 38.3$ $P \text{ вн.мм} = 25.7$ Гр. сл. = III Точн. = Н		<b>БПЗ-358</b> $F \text{ см}^2 = 5.825$ $Q \text{ кг.} = 1.579$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 116.0$ $P \text{ вн.мм} = 78.2$ Гр. сл. = III Точн. = Н
	<b>БПЗ-354</b> $F \text{ см}^2 = 1.100$ $Q \text{ кг.} = 0.298$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 51.7$ $P \text{ вн.мм} = 36.0$ Гр. сл. = III Точн. = Н		<b>БПЗ-359</b> $F \text{ см}^2 = 7.730$ $Q \text{ кг.} = 2.095$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 132.5$ $P \text{ вн.мм} = 88.5$ Гр. сл. = III Точн. = Н
	<b>БПЗ-355</b> $F \text{ см}^2 = 2.000$ $Q \text{ кг.} = 0.542$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 68.2$ $P \text{ вн.мм} = 46.3$ Гр. сл. = III Точн. = Н		<b>БПЗ-360</b> $F \text{ см}^2 = 9.910$ $Q \text{ кг.} = 2.686$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 149.0$ $P \text{ вн.мм} = 98.8$ Гр. сл. = III Точн. = Н























	<b>БПЗ-361</b> $F \text{ см}^2 = 12.360$ $Q \text{ кг.} = 3.350$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 165.6$ $P \text{ вн.мм} = 109.1$ Гр. сл. = III Точн. = Н		<b>БПЗ-366</b> $F \text{ см}^2 = 28.460$ $Q \text{ кг.} = 7.713$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 247.0$ $P \text{ вн.мм} = 159.0$ Гр. сл. = III Точн. = Н
	<b>БПЗ-362</b> $F \text{ см}^2 = 15.080$ $Q \text{ кг.} = 4.087$ $D \text{ оп.мм} = 66.0$ $P \text{ н.мм} = 182.0$ $P \text{ вн.мм} = 119.4$ Гр. сл. = III Точн. = Н		<b>БПЗ-367</b> $F \text{ см}^2 = 32.510$ $Q \text{ кг.} = 8.810$ $D \text{ оп.мм} = 96.0$ $P \text{ н.мм} = 263.8$ $P \text{ вн.мм} = 169.6$ Гр. сл. = III Точн. = Н
	<b>БПЗ-363</b> $F \text{ см}^2 = 18.050$ $Q \text{ кг.} = 4.892$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 198.7$ $P \text{ вн.мм} = 129.6$ Гр. сл. = III Точн. = Н		<b>БПЗ-368</b> $F \text{ см}^2 = 37.640$ $Q \text{ кг.} = 10.200$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 285.5$ $P \text{ вн.мм} = 185.0$ Гр. сл. = III Точн. = Н
	<b>БПЗ-364</b> $F \text{ см}^2 = 21.310$ $Q \text{ кг.} = 5.8$ $D \text{ оп.мм} = 78.0$ $P \text{ н.мм} = 215.3$ $P \text{ вн.мм} = 140.0$ Гр. сл. = III Точн. = Н		<b>БПЗ-369</b> $F \text{ см}^2 = 42.500$ $Q \text{ кг.} = 11.518$ $D \text{ оп.мм} = 110.0$ $P \text{ н.мм} = 303.2$ $P \text{ вн.мм} = 196.5$ Гр. сл. = III Точн. = Н
	<b>БПЗ-365</b> $F \text{ см}^2 = 24.700$ $Q \text{ кг.} = 6.7$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 230.7$ $P \text{ вн.мм} = 149.1$ Гр. сл. = III Точн. = Н		<b>БПЗ-370</b> $F \text{ см}^2 = 1.640$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм} = 34.5$ $P \text{ н.мм} = 90.1$ $P \text{ вн.мм} = 66.9$ Гр. сл. = V Точн. = Н











	<b>БПЗ-371</b> $F \text{ см}^2 = 7.850$ $Q \text{ кг.} = 2.13$ $D \text{ оп.мм} = 104.0$ $P \text{ н.мм} = 270.0$ $P \text{ вн.мм} = 227.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-376</b> $F \text{ см}^2 = 5.760$ $Q \text{ кг.} = 1.561$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 160.0$ $P \text{ вн.мм} = 128.0$ Гр. сл. = III Точн. = DIN
	<b>БПЗ-372</b> $F \text{ см}^2 = 26.200$ $Q \text{ кг.} = 7.100$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 226.5$ $P \text{ вн.мм} = 31.4$ Гр. сл. = IV Точн. = П		<b>БПЗ-377</b> $F \text{ см}^2 = 7.360$ $Q \text{ кг.} = 1.995$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ $P \text{ вн.мм} = 168.0$ Гр. сл. = III Точн. = DIN
	<b>БПЗ-373</b> $F \text{ см}^2 = 32.780$ $Q \text{ кг.} = 8.883$ $D \text{ оп.мм} = 116.0$ $P \text{ н.мм} = 238.6$ $P \text{ вн.мм} = 125.6$ Гр. сл. = III Точн. = Н		<b>БПЗ-378</b> $F \text{ см}^2 = 1.840$ $Q \text{ кг.} = 0.499$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 100.0$ $P \text{ вн.мм} = 84.0$ Гр. сл. = V Точн. = DIN
	<b>БПЗ-374</b> $F \text{ см}^2 = 52.350$ $Q \text{ кг.} = 14.187$ $D \text{ оп.мм} = 122.0$ $P \text{ н.мм} = 335.2$ $P \text{ вн.мм} = 215.9$ Гр. сл. = III Точн. = Н		
	<b>БПЗ-375</b> $F \text{ см}^2 = 3.810$ $Q \text{ кг.} = 1.033$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 136.6$ $P \text{ вн.мм} = 116.0$ Гр. сл. = III Точн. = DIN		










			<b>БПЗ-386</b> $F \text{ см}^2 = 15.360$ $Q \text{ кг.} = 4.163$ $D \text{ оп.мм} = 141.4$ $P \text{ н.мм} = 400.0$ $P \text{ вн.мм} = 368.0$ $\text{Гр. сл.} = V$ $\text{Точн.} = H$
	<b>БПЗ-382</b> $F \text{ см}^2 = 5.640$ $Q \text{ кг.} = 1.528$ $D \text{ оп.мм} = 70.7$ $P \text{ н.мм} = 200.0$ $P \text{ вн.мм} = 176.0$ $\text{Гр. сл.} = IV$ $\text{Точн.} = H$		<b>БПЗ-387</b> $F \text{ см}^2 = 3.240$ $Q \text{ кг.} = 0.878$ $D \text{ оп.мм} = 44.7$ $P \text{ н.мм} = 120.0$ $P \text{ вн.мм} = 96.0$ $\text{Гр. сл.} = III$ $\text{Точн.} = H$
	<b>БПЗ-383</b> $F \text{ см}^2 = 6.840$ $Q \text{ кг.} = 1.854$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ $P \text{ вн.мм} = 216.0$ $\text{Гр. сл.} = V$ $\text{Точн.} = H$		<b>БПЗ-388</b> $F \text{ см}^2 = 3.840$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 49.6$ $P \text{ н.мм} = 139.1$ $P \text{ вн.мм} = 116.0$ $\text{Гр. сл.} = III$ $\text{Точн.} = H$
	<b>БПЗ-384</b> $F \text{ см}^2 = 8.960$ $Q \text{ кг.} = 2.428$ $D \text{ оп.мм} = 84.9$ $P \text{ н.мм} = 240.0$ $P \text{ вн.мм} = 208.0$ $\text{Гр. сл.} = IV$ $\text{Точн.} = H$		<b>БПЗ-389</b> $F \text{ см}^2 = 2.640$ $Q \text{ кг.} = 0.715$ $D \text{ оп.мм} = 53.9$ $P \text{ н.мм} = 140.0$ $P \text{ вн.мм} = 124.0$ $\text{Гр. сл.} = VI$ $\text{Точн.} = H$
	<b>БПЗ-385</b> $F \text{ см}^2 = 12.160$ $Q \text{ кг.} = 3.295$ $D \text{ оп.мм} = 113.1$ $P \text{ н.мм} = 320.0$ $P \text{ вн.мм} = 288.0$ $\text{Гр. сл.} = V$ $\text{Точн.} = H$		<b>БПЗ-390</b> $F \text{ см}^2 = 3.040$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм} = 53.8$ $P \text{ н.мм} = 160.0$ $P \text{ вн.мм} = 144.0$ $\text{Гр. сл.} = VI$ $\text{Точн.} = H$

	<p><b>БПЗ-391</b></p> <p> <math>F \text{ см}^2 = 3.040</math>  <math>Q \text{ кг.} = 0.824</math>  <math>D \text{ оп.мм} = 63.2</math>  <math>P \text{ н.мм} = 160.0</math>  <math>P \text{ вн.мм} = 144.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-396</b></p> <p> <math>F \text{ см}^2 = 4.440</math>  <math>Q \text{ кг.} = 1.203</math>  <math>D \text{ оп.мм} = 58.3</math>  <math>P \text{ н.мм} = 160.0</math>  <math>P \text{ вн.мм} = 136.0</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-392</b></p> <p> <math>F \text{ см}^2 = 3.840</math>  <math>Q \text{ кг.} = 1.041</math>  <math>D \text{ оп.мм} = 72.1</math>  <math>P \text{ н.мм} = 200.0</math>  <math>P \text{ вн.мм} = 184.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-397</b></p> <p> <math>F \text{ см}^2 = 5.040</math>  <math>Q \text{ кг.} = 1.366</math>  <math>D \text{ оп.мм} = 67.1</math>  <math>P \text{ н.мм} = 180.0</math>  <math>P \text{ вн.мм} = 156.0</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-393</b></p> <p> <math>F \text{ см}^2 = 4.750</math>  <math>Q \text{ кг.} = 1.287</math>  <math>D \text{ оп.мм} = 72.1</math>  <math>P \text{ н.мм} = 200.0</math>  <math>P \text{ вн.мм} = 180.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-398</b></p> <p> <math>F \text{ см}^2 = 6.840</math>  <math>Q \text{ кг.} = 1.854</math>  <math>D \text{ оп.мм} = 89.4</math>  <math>P \text{ н.мм} = 240.0</math>  <math>P \text{ вн.мм} = 216.0</math>  Гр. сл. = V  Точн. = Н </p>
	<p><b>БПЗ-394</b></p> <p> <math>F \text{ см}^2 = 5.640</math>  <math>Q \text{ кг.} = 1.528</math>  <math>D \text{ оп.мм} = 72.1</math>  <math>P \text{ н.мм} = 200.0</math>  <math>P \text{ вн.мм} = 176.0</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-399</b></p> <p> <math>F \text{ см}^2 = 8.600</math>  <math>Q \text{ кг.} = 2.331</math>  <math>D \text{ оп.мм} = 89.4</math>  <math>P \text{ н.мм} = 240.0</math>  <math>P \text{ вн.мм} = 208.0</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-395</b></p> <p> <math>F \text{ см}^2 = 7.600</math>  <math>Q \text{ кг.} = 2.060</math>  <math>D \text{ оп.мм} = 72.1</math>  <math>P \text{ н.мм} = 200.0</math>  <math>P \text{ вн.мм} = 168.0</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-400</b></p> <p> <math>F \text{ см}^2 = 9.760</math>  <math>Q \text{ кг.} = 2.645</math>  <math>D \text{ оп.мм} = 94.3</math>  <math>P \text{ н.мм} = 260.0</math>  <math>P \text{ вн.мм} = 228.0</math>  Гр. сл. = IV  Точн. = Н </p>











	<p><b>БПЗ-401</b></p> <p> <math>F \text{ см}^2 = 10.560</math>  <math>Q \text{ кг.} = 2.862</math>  <math>D \text{ оп.мм} = 100.0</math>  <math>P \text{ н.мм} = 280.0</math>  <math>P \text{ вн.мм} = 248.0</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-406</b></p> <p> <math>F \text{ см}^2 = 2.550</math>  <math>Q \text{ кг.} = 0.691</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 94.2</math>  <math>P \text{ вн.мм} = 75.4</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-402</b></p> <p> <math>F \text{ см}^2 = 3.840</math>  <math>Q \text{ кг.} = 1.041</math>  <math>D \text{ оп.мм} = 82.3</math>  <math>P \text{ н.мм} = 199.2</math>  <math>P \text{ вн.мм} = 184.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-407</b></p> <p> <math>F \text{ см}^2 = 3.020</math>  <math>Q \text{ кг.} = 0.818</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 110.0</math>  <math>P \text{ вн.мм} = 91.1</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-403</b></p> <p> <math>F \text{ см}^2 = 4.640</math>  <math>Q \text{ кг.} = 1.257</math>  <math>D \text{ оп.мм} = 90.0</math>  <math>P \text{ н.мм} = 240.0</math>  <math>P \text{ вн.мм} = 224.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-408</b></p> <p> <math>F \text{ см}^2 = 1.600</math>  <math>Q \text{ кг.} = 0.434</math>  <math>D \text{ оп.мм} = 20.0</math>  <math>P \text{ н.мм} = 62.8</math>  <math>P \text{ вн.мм} = 44.0</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-404</b></p> <p> <math>F \text{ см}^2 = 6.240</math>  <math>Q \text{ кг.} = 1.691</math>  <math>D \text{ оп.мм} = 78.1</math>  <math>P \text{ н.мм} = 220.0</math>  <math>P \text{ вн.мм} = 196.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-409</b></p> <p> <math>F \text{ см}^2 = 2.940</math>  <math>Q \text{ кг.} = 0.797</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 125.6</math>  <math>P \text{ вн.мм} = 109.9</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-405</b></p> <p> <math>F \text{ см}^2 = 6.560</math>  <math>Q \text{ кг.} = 1.778</math>  <math>D \text{ оп.мм} = 64.0</math>  <math>P \text{ н.мм} = 180.0</math>  <math>P \text{ вн.мм} = 148.0</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-410</b></p> <p> <math>F \text{ см}^2 = 2.070</math>  <math>Q \text{ кг.} = 0.561</math>  <math>D \text{ оп.мм} = 25.0</math>  <math>P \text{ н.мм} = 78.5</math>  <math>P \text{ вн.мм} = 59.7</math>  Гр. сл. = III  Точн. = Н </p>











	<b>БПЗ-411</b> $F \text{ см}^2 = 3.470$ $Q \text{ кг.} = 0.940$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.7$ $P \text{ вн.мм} = 106.8$ Гр. сл. = III Точн. = Н		<b>БПЗ-416</b> $F \text{ см}^2 = 4.250$ $Q \text{ кг.} = 1.152$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 150.8$ $P \text{ вн.мм} = 131.9$ Гр. сл. = III Точн. = Н
	<b>БПЗ-412</b> $F \text{ см}^2 = 5.470$ $Q \text{ кг.} = 1.482$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.7$ $P \text{ вн.мм} = 94.2$ Гр. сл. = I Точн. = Н		<b>БПЗ-417</b> $F \text{ см}^2 = 7.300$ $Q \text{ кг.} = 1.978$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 251.3$ $P \text{ вн.мм} = 232.5$ Гр. сл. = V Точн. = Н
	<b>БПЗ-413</b> $F \text{ см}^2 = 4.400$ $Q \text{ кг.} = 1.192$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 157.0$ $P \text{ вн.мм} = 130.2$ Гр. сл. = III Точн. = Н		<b>БПЗ-418</b> $F \text{ см}^2 = 11.800$ $Q \text{ кг.} = 3.198$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 251.3$ $P \text{ вн.мм} = 219.9$ Гр. сл. = III Точн. = Н
	<b>БПЗ-414</b> $F \text{ см}^2 = 5.370$ $Q \text{ кг.} = 1.455$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 188.5$ $P \text{ вн.мм} = 169.6$ Гр. сл. = III Точн. = Н		<b>БПЗ-419</b> $F \text{ см}^2 = 18.100$ $Q \text{ кг.} = 4.905$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 251.3$ $P \text{ вн.мм} = 201.1$ Гр. сл. = II Точн. = Н
	<b>БПЗ-415</b> $F \text{ см}^2 = 8.640$ $Q \text{ кг.} = 2.341$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 188.5$ $P \text{ вн.мм} = 157.1$ Гр. сл. = II Точн. = Н		<b>БПЗ-420</b> $F \text{ см}^2 = 6.876$ $Q \text{ кг.} = 1.863$ $D \text{ оп.мм} = 76.0$ $P \text{ н.мм} = 238.7$ $P \text{ вн.мм} = 219.9$ Гр. сл. = III Точн. = Н











	<p><b>БПЗ-421</b></p> <p> <math>F \text{ см}^2 = 2.980</math>  <math>Q \text{ кг.} = 0.808</math>  <math>D \text{ оп.мм} = 24.0</math>  <math>P \text{ н.мм} = 75.36</math>  <math>P \text{ вн.мм} = 44.0</math>  Гр. сл. = I  Точн. = П </p>		<p><b>БПЗ-426</b></p> <p> <math>F \text{ см}^2 = 1.759</math>  <math>Q \text{ кг.} = 0.477</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 94.3</math>  <math>P \text{ вн.мм} = 81.7</math>  Гр. сл. = V  Точн. = 0соб. </p>
	<p><b>БПЗ-422</b></p> <p> <math>F \text{ см}^2 = 3.490</math>  <math>Q \text{ кг.} = 0.946</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 125.6</math>  <math>P \text{ вн.мм} = 106.8</math>  Гр. сл. = I  Точн. = П </p>		<p><b>БПЗ-427</b></p> <p> <math>F \text{ см}^2 = 3.220</math>  <math>Q \text{ кг.} = 0.874</math>  <math>D \text{ оп.мм} = 51.2</math>  <math>P \text{ н.мм} = 172.3</math>  <math>P \text{ вн.мм} = 147.3</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>
	<p><b>БПЗ-423</b></p> <p> <math>F \text{ см}^2 = 10.128</math>  <math>Q \text{ кг.} = 2.745</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 132.1</math>  <math>P \text{ вн.мм} = 68.8</math>  Гр. сл. = II  Точн. = П </p>		<p><b>БПЗ-428</b></p> <p> <math>F \text{ см}^2 = 1.860</math>  <math>Q \text{ кг.} = 0.504</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 116.0</math>  <math>P \text{ вн.мм} = 70.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-424</b></p> <p> <math>F \text{ см}^2 = 8.454</math>  <math>Q \text{ кг.} = 2.291</math>  <math>D \text{ оп.мм} = 58.0</math>  <math>P \text{ н.мм} = 182.4</math>  <math>P \text{ вн.мм} = 150.5</math>  Гр. сл. = II  Точн. = П </p>		<p><b>БПЗ-429</b></p> <p> <math>F \text{ см}^2 = 2.160</math>  <math>Q \text{ кг.} = 0.585</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 146.0</math>  <math>P \text{ вн.мм} = 70.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-425</b></p> <p> <math>F \text{ см}^2 = 10.310</math>  <math>Q \text{ кг.} = 2.794</math>  <math>D \text{ оп.мм} = 60.0</math>  <math>P \text{ н.мм} = 188.6</math>  <math>P \text{ вн.мм} = 150.5</math>  Гр. сл. = I  Точн. = П </p>		<p><b>БПЗ-430</b></p> <p> <math>F \text{ см}^2 = 2.776</math>  <math>Q \text{ кг.} = 0.752</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 188.4</math>  <math>P \text{ вн.мм} = 89.27</math>  Гр. сл. = VI  Точн. = П </p>











	<b>БПЗ-431</b> $F \text{ см}^2 = 2.170$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 114.8$ $P \text{ вн.мм} = 102.3$ Гр. сл. = V Точн. = Особ.		<b>БПЗ-436</b> $F \text{ см}^2 = 0.628$ $Q \text{ кг.} = 0.170$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 37.7$ $P \text{ вн.мм} = 25.1$ Гр. сл. = IV Точн. = Н
			<b>БПЗ-437</b> $F \text{ см}^2 = 7.823$ $Q \text{ кг.} = 2.12$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 270.2$ $P \text{ вн.мм} = 251.3$ Гр. сл. = III Точн. = Н
	<b>БПЗ-433</b> $F \text{ см}^2 = 9.250$ $Q \text{ кг.} = 2.507$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 371.0$ $P \text{ вн.мм} = 351.0$ Гр. сл. = Особ. Точн. = Н		<b>БПЗ-438</b> $F \text{ см}^2 = 2.796$ $Q \text{ кг.} = 0.758$ $D \text{ оп.мм} = 23.2$ $P \text{ н.мм} = 72.9$ $P \text{ вн.мм} = 42.4$ Гр. сл. = III Точн. = Н
	<b>БПЗ-434</b> $F \text{ см}^2 = 8.100$ $Q \text{ кг.} = 2.195$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 103.9$ $P \text{ вн.мм} = 53.0$ Гр. сл. = II Точн. = Н		<b>БПЗ-0439</b> $F \text{ см}^2 = 1.570$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 153.3$ $P \text{ вн.мм} = 81.3$ Гр. сл. = VI Точн. = П
	<b>БПЗ-435</b> $F \text{ см}^2 = 2.236$ $Q \text{ кг.} = 0.605$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 75.6$ $P \text{ вн.мм} = 59.4$ Гр. сл. = II Точн. = Н		<b>БПЗ-0440</b> $F \text{ см}^2 = 18.820$ $Q \text{ кг.} = 5.100$ $D \text{ оп.мм} = 162.0$ $P \text{ н.мм} = 727.7$ $P \text{ вн.мм} = 868.6$ Гр. сл. = Особ. Точн. = П























	<p><b>БПЗ-441</b></p> <p> <math>F \text{ см}^2 = 1.640</math>  <math>Q \text{ кг.} = 0.444</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 90.0</math>  <math>P \text{ вн.мм} = 74.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-446</b></p> <p> <math>F \text{ см}^2 = 2.811</math>  <math>Q \text{ кг.} = 0.762</math>  <math>D \text{ оп.мм} = 62.0</math>  <math>P \text{ н.мм} = 174.1</math>  <math>P \text{ вн.мм} = 129.4</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-442</b></p> <p> <math>F \text{ см}^2 = 2.040</math>  <math>Q \text{ кг.} = 0.553</math>  <math>D \text{ оп.мм} = 42.7</math>  <math>P \text{ н.мм} = 110.0</math>  <math>P \text{ вн.мм} = 94.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-447</b></p> <p> <math>F \text{ см}^2 = 1.554</math>  <math>Q \text{ кг.} = 0.421</math>  <math>D \text{ оп.мм} = 16.0</math>  <math>P \text{ н.мм} = 50.3</math>  <math>P \text{ вн.мм} = 33.8</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-443</b></p> <p> <math>F \text{ см}^2 = 11.360</math>  <math>Q \text{ кг.} = 3.079</math>  <math>D \text{ оп.мм} = 114.0</math>  <math>P \text{ н.мм} = 300.0</math>  <math>P \text{ вн.мм} = 268.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-0448</b></p> <p> <math>F \text{ см}^2 = 1.327</math>  <math>Q \text{ кг.} = 0.360</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 96.9</math>  <math>P \text{ вн.мм} = 78.5</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-444</b></p> <p> <math>F \text{ см}^2 = 10.560</math>  <math>Q \text{ кг.} = 2.862</math>  <math>D \text{ оп.мм} = 109.0</math>  <math>P \text{ н.мм} = 280.0</math>  <math>P \text{ вн.мм} = 218.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-449</b></p> <p> <math>F \text{ см}^2 = 1.240</math>  <math>Q \text{ кг.} = 0.336</math>  <math>D \text{ оп.мм} = 25.0</math>  <math>P \text{ н.мм} = 70.0</math>  <math>P \text{ вн.мм} = 54.0</math>  Гр. сл. = IV  Точн. = 0соб. </p>
	<p><b>БПЗ-445</b></p> <p> <math>F \text{ см}^2 = 12.160</math>  <math>Q \text{ кг.} = 3.295</math>  <math>D \text{ оп.мм} = 126.5</math>  <math>P \text{ н.мм} = 320.0</math>  <math>P \text{ вн.мм} = 288.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-450</b></p> <p> <math>F \text{ см}^2 = 1.640</math>  <math>Q \text{ кг.} = 0.444</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>P \text{ н.мм} = 90.0</math>  <math>P \text{ вн.мм} = 74.0</math>  Гр. сл. = V  Точн. = 0соб. </p>











	<b>БПЗ-451</b> $F \text{ см}^2 = 1.040$ $Q \text{ кг.} = 0.282$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 60.0$ $P \text{ вн.мм} = 44.0$ Гр. сл. = IV Точн. = Особ.		<b>БПЗ-456</b> $F \text{ см}^2 = 1.040$ $Q \text{ кг.} = 0.282$ $D \text{ оп.мм} = 21.2$ $P \text{ н.мм} = 60.0$ $P \text{ вн.мм} = 44.0$ Гр. сл. = IV Точн. = Особ.
	<b>БПЗ-452</b> $F \text{ см}^2 = 2.440$ $Q \text{ кг.} = 0.661$ $D \text{ оп.мм} = 47.2$ $P \text{ н.мм} = 130.0$ $P \text{ вн.мм} = 114.0$ Гр. сл. = V Точн. = Особ.		<b>БПЗ-457</b> $F \text{ см}^2 = 2.640$ $Q \text{ кг.} = 0.715$ $D \text{ оп.мм} = 49.5$ $P \text{ н.мм} = 140.0$ $P \text{ вн.мм} = 124.0$ Гр. сл. = V Точн. = Особ.
	<b>БПЗ-453</b> $F \text{ см}^2 = 3.640$ $Q \text{ кг.} = 0.986$ $D \text{ оп.мм} = 67.3$ $P \text{ н.мм} = 190.0$ $P \text{ вн.мм} = 174.0$ Гр. сл. = IV Точн. = Особ.		<b>БПЗ-458</b> $F \text{ см}^2 = 10.560$ $Q \text{ кг.} = 2.862$ $D \text{ оп.мм} = 99.0$ $P \text{ н.мм} = 280.0$ $P \text{ вн.мм} = 248.0$ Гр. сл. = IV Точн. = Особ.
	<b>БПЗ-454</b> $F \text{ см}^2 = 8.040$ $Q \text{ кг.} = 2.179$ $D \text{ оп.мм} = 107.7$ $P \text{ н.мм} = 280.0$ $P \text{ вн.мм} = 256.0$ Гр. сл. = VI Точн. = Особ.		<b>БПЗ-459</b> $F \text{ см}^2 = 9.240$ $Q \text{ кг.} = 2.504$ $D \text{ оп.мм} = 113.1$ $P \text{ н.мм} = 320.0$ $P \text{ вн.мм} = 296.0$ Гр. сл. = VI Точн. = Особ.
	<b>БПЗ-455</b> $F \text{ см}^2 = 4.250$ $Q \text{ кг.} = 1.152$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ $P \text{ вн.мм} = 160.0$ Гр. сл. = V Точн. = Особ.		<b>БПЗ-460</b> $F \text{ см}^2 = 1.130$ $Q \text{ кг.} = 0.306$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 50.3$ Гр. сл. = III Точн. = Особ.











	<p><b>БПЗ-461</b></p> <p> <math>F \text{ см}^2 = 1.450</math>  <math>Q \text{ кг.} = 0.393</math>  <math>D \text{ оп.мм} = 25.0</math>  <math>P \text{ н.мм} = 78.5</math>  <math>P \text{ вн.мм} = 66.0</math>  Гр. сл. = III  Точн. = 0соб. </p>		<p><b>БПЗ-466</b></p> <p> <math>F \text{ см}^2 = 7.069</math>  <math>Q \text{ кг.} = 1.916</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 157.0</math>  <math>P \text{ вн.мм} = 125.7</math>  Гр. сл. = II  Точн. = 0соб. </p>
	<p><b>БПЗ-462</b></p> <p> <math>F \text{ см}^2 = 2.390</math>  <math>Q \text{ кг.} = 0.648</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 125.7</math>  <math>P \text{ вн.мм} = 113.1</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-467</b></p> <p> <math>F \text{ см}^2 = 2.570</math>  <math>Q \text{ кг.} = 0.696</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 135.0</math>  <math>P \text{ вн.мм} = 122.5</math>  Гр. сл. = IV  Точн. = H </p>
	<p><b>БПЗ-463</b></p> <p> <math>F \text{ см}^2 = 3.020</math>  <math>Q \text{ кг.} = 0.819</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 157.0</math>  <math>P \text{ вн.мм} = 144.5</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-468</b></p> <p> <math>F \text{ см}^2 = 12.160</math>  <math>Q \text{ кг.} = 3.295</math>  <math>D \text{ оп.мм} = 116.6</math>  <math>P \text{ н.мм} = 320.0</math>  <math>P \text{ вн.мм} = 288.0</math>  Гр. сл. = V  Точн. = 0соб. </p>
	<p><b>БПЗ-464</b></p> <p> <math>F \text{ см}^2 = 4.520</math>  <math>Q \text{ кг.} = 1.225</math>  <math>D \text{ оп.мм} = 60.0</math>  <math>P \text{ н.мм} = 188.5</math>  <math>P \text{ вн.мм} = 172.8</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-469</b></p> <p> <math>F \text{ см}^2 = 5.280</math>  <math>Q \text{ кг.} = 1.431</math>  <math>D \text{ оп.мм} = 69.0</math>  <math>P \text{ н.мм} = 188.0</math>  <math>P \text{ вн.мм} = 164.0</math>  Гр. сл. = IV  Точн. = 0соб. </p>
	<p><b>БПЗ-465</b></p> <p> <math>F \text{ см}^2 = 13.760</math>  <math>Q \text{ кг.} = 3.729</math>  <math>D \text{ оп.мм} = 127.2</math>  <math>P \text{ н.мм} = 360.0</math>  <math>P \text{ вн.мм} = 328.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-470</b></p> <p> <math>F \text{ см}^2 = 4.960</math>  <math>Q \text{ кг.} = 1.344</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 140.0</math>  <math>P \text{ вн.мм} = 108.0</math>  Гр. сл. = III  Точн. = 0соб. </p>

	<b>БПЗ-471</b> $F \text{ см}^2 = 3.920$ $Q \text{ кг.} = 1.062$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 94.2$ $P \text{ вн.мм} = 62.8$ Гр. сл. = I Точн. = 0соб.		<b>БПЗ-476</b> $F \text{ см}^2 = 18.060$ $Q \text{ кг.} = 4.894$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 377.0$ $P \text{ вн.мм} = 345.6$ Гр. сл. = V Точн. = 0соб.
	<b>БПЗ-472</b> $F \text{ см}^2 = 3.140$ $Q \text{ кг.} = 0.851$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 78.5$ $P \text{ вн.мм} = 47.1$ Гр. сл. = I Точн. = 0соб.		<b>БПЗ-477</b> $F \text{ см}^2 = 6.710$ $Q \text{ кг.} = 1.818$ $D \text{ оп.мм} = 86.8$ $P \text{ н.мм} = 233.1$ $P \text{ вн.мм} = 214.3$ Гр. сл. = V Точн. = 0соб.
	<b>БПЗ-473</b> $F \text{ см}^2 = 2.360$ $Q \text{ кг.} = 0.640$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 31.4$ Гр. сл. = II Точн. = 0соб.		<b>БПЗ-478</b> $F \text{ см}^2 = 5.360$ $Q \text{ кг.} = 1.453$ $D \text{ оп.мм} = 68.3$ $P \text{ н.мм} = 191.4$ $P \text{ вн.мм} = 172.6$ Гр. сл. = IV Точн. = 0соб.
	<b>БПЗ-474</b> $F \text{ см}^2 = 4.720$ $Q \text{ кг.} = 1.279$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 110.0$ $P \text{ вн.мм} = 78.5$ Гр. сл. = I Точн. = 0соб.		<b>БПЗ-479</b> $F \text{ см}^2 = 5.510$ $Q \text{ кг.} = 1.493$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 193.1$ $P \text{ вн.мм} = 174.3$ Гр. сл. = IV Точн. = 0соб.
	<b>БПЗ-475</b> $F \text{ см}^2 = 14.920$ $Q \text{ кг.} = 4.043$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 314.2$ $P \text{ вн.мм} = 282.7$ Гр. сл. = IV Точн. = 0соб.		<b>БПЗ-480</b> $F \text{ см}^2 = 2.940$ $Q \text{ кг.} = 0.797$ $D \text{ оп.мм} = 55.4$ $P \text{ н.мм} = 153.1$ $P \text{ вн.мм} = 140.6$ Гр. сл. = VI Точн. = 0соб.










	<p><b>БПЗ-481</b></p> <p> <math>F \text{ см}^2 = 13.760</math>  <math>Q \text{ кг.} = 3.729</math>  <math>D \text{ оп.мм} = 134.2</math>  <math>P \text{ н.мм} = 360.0</math>  <math>P \text{ вн.мм} = 328.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-486</b></p> <p> <math>F \text{ см}^2 = 5.780</math>  <math>Q \text{ кг.} = 1.566</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 157.0</math>  <math>P \text{ вн.мм} = 132.0</math>  Гр. сл. = III  Точн. = 0соб. </p>
	<p><b>БПЗ-482</b></p> <p> <math>F \text{ см}^2 = 12.960</math>  <math>Q \text{ кг.} = 3.512</math>  <math>D \text{ оп.мм} = 130.0</math>  <math>P \text{ н.мм} = 340.0</math>  <math>P \text{ вн.мм} = 308.0</math>  Гр. сл. = V  Точн. = 0соб. </p>		<p><b>БПЗ-487</b></p> <p> <math>F \text{ см}^2 = 2.0</math>  <math>Q \text{ кг.} = 0.572</math>  <math>D \text{ оп.мм} = 79.0</math>  <math>P \text{ н.мм} = 176.4</math>  <math>P \text{ вн.мм} = 42.3</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-483</b></p> <p> <math>F \text{ см}^2 = 15.360</math>  <math>Q \text{ кг.} = 4.163</math>  <math>D \text{ оп.мм} = 158.1</math>  <math>P \text{ н.мм} = 400.0</math>  <math>P \text{ вн.мм} = 368.0</math>  Гр. сл. = IV  Точн. = 0соб. </p>		<p><b>БПЗ-488</b></p> <p> <math>F \text{ см}^2 = 2.640</math>  <math>Q \text{ кг.} = 0.715</math>  <math>D \text{ оп.мм} = 36.1</math>  <math>P \text{ н.мм} = 100.0</math>  <math>P \text{ вн.мм} = 76.0</math>  Гр. сл. = III  Точн. = 0соб. </p>
	<p><b>БПЗ-484</b></p> <p> <math>F \text{ см}^2 = 2.080</math>  <math>Q \text{ кг.} = 0.564</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 110.0</math>  <math>P \text{ вн.мм} = 97.4</math>  Гр. сл. = IV  Точн. = 0соб. </p>		<p><b>БПЗ-489</b></p> <p> <math>F \text{ см}^2 = 4.560</math>  <math>Q \text{ кг.} = 1.236</math>  <math>D \text{ оп.мм} = 101.6</math>  <math>P \text{ н.мм} = 236.0</math>  <math>P \text{ вн.мм} = 220.0</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>
	<p><b>БПЗ-485</b></p> <p> <math>F \text{ см}^2 = 3.731</math>  <math>Q \text{ кг.} = 1.011</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 157.1</math>  <math>P \text{ вн.мм} = 141.3</math>  Гр. сл. = IV  Точн. = 0соб. </p>		<p><b>БПЗ-490</b></p> <p> <math>F \text{ см}^2 = 0.548</math>  <math>Q \text{ кг.} = 0.149</math>  <math>D \text{ оп.мм} = 23.5</math>  <math>P \text{ н.мм} = 62.6</math>  <math>P \text{ вн.мм} = 42.0</math>  Гр. сл. = VI  Точн. = Н </p>










	<p><b>БПЗ-491</b></p> <p> <math>F \text{ см}^2 = 14.560</math>  <math>Q \text{ кг.} = 3.946</math>  <math>D \text{ оп.мм} = 155.2</math>  <math>P \text{ н.мм} = 380.0</math>  <math>P_{\text{вн.мм}} = 348.0</math>  Гр. сл. = V  Точн. = DIN </p>		<p><b>БПЗ-496</b></p> <p> <math>F \text{ см}^2 = 6.240</math>  <math>Q \text{ кг.} = 1.691</math>  <math>D \text{ оп.мм} = 95.4</math>  <math>P \text{ н.мм} = 220.0</math>  <math>P_{\text{вн.мм}} = 196.0</math>  Гр. сл. = V  Точн. = DIN </p>
	<p><b>БПЗ-492</b></p> <p> <math>F \text{ см}^2 = 2.560</math>  <math>Q \text{ кг.} = 0.694</math>  <math>D \text{ оп.мм} = 48.0</math>  <math>P \text{ н.мм} = 136.0</math>  <math>P_{\text{вн.мм}} = 120.0</math>  Гр. сл. = V  Точн. = DIN </p>		<p><b>БПЗ-497</b></p> <p> <math>F \text{ см}^2 = 6.310</math>  <math>Q \text{ кг.} = 1.710</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 219.9</math>  <math>P_{\text{вн.мм}} = 201.1</math>  Гр. сл. = V  Точн. = DIN </p>
	<p><b>БПЗ-493</b></p> <p> <math>F \text{ см}^2 = 3.720</math>  <math>Q \text{ кг.} = 1.008</math>  <math>D \text{ оп.мм} = 48.1</math>  <math>P \text{ н.мм} = 136.0</math>  <math>P_{\text{вн.мм}} = 112.0</math>  Гр. сл. = III  Точн. = DIN </p>		<p><b>БПЗ-498</b></p> <p> <math>F \text{ см}^2 = 18.76</math>  <math>Q \text{ кг.} = 5.084</math>  <math>D \text{ оп.мм} = 75.0</math>  <math>P \text{ н.мм} = 227</math>  <math>P_{\text{вн.мм}} = 98.9</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-494</b></p> <p> <math>F \text{ см}^2 = 11.640</math>  <math>Q \text{ кг.} = 3.154</math>  <math>D \text{ оп.мм} = 141.4</math>  <math>P \text{ н.мм} = 400.0</math>  <math>P_{\text{вн.мм}} = 376.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>		<p><b>БПЗ-499</b></p> <p> <math>F \text{ см}^2 = 6.240</math>  <math>Q \text{ кг.} = 1.691</math>  <math>D \text{ оп.мм} = 126.5</math>  <math>P \text{ н.мм} = 320.0</math>  <math>P_{\text{вн.мм}} = 304.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>
	<p><b>БПЗ-495</b></p> <p> <math>F \text{ см}^2 = 3.440</math>  <math>Q \text{ кг.} = 0.932</math>  <math>D \text{ оп.мм} = 67.0</math>  <math>P \text{ н.мм} = 180.0</math>  <math>P_{\text{вн.мм}} = 164.0</math>  Гр. сл. = VI  Точн. = DIN </p>		<p><b>БПЗ-500</b></p> <p> <math>F \text{ см}^2 = 7.840</math>  <math>Q \text{ кг.} = 2.125</math>  <math>D \text{ оп.мм} = 141.4</math>  <math>P \text{ н.мм} = 400.0</math>  <math>P_{\text{вн.мм}} = 384.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>











<b>Профиль заказчика</b> 	<b>БПЗ-501-3</b> $F \text{ см}^2 = 1.096$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм} = 35.5$ $P \text{ н.мм} = 91.2$ $P \text{ вн.мм} = 85.5$ Гр. сл. = 0соб. Точн. = 0соб.		<b>БПЗ-506</b> $F \text{ см}^2 = 1.677$ $Q \text{ кг.} = 0.454$ $D \text{ оп.мм} = 51.2$ $P \text{ н.мм} = 142.4$ $P \text{ вн.мм} = 76.3$ Гр. сл. = VI Точн. = П
	<b>БПЗ-502</b> $F \text{ см}^2 = 5.440$ $Q \text{ кг.} = 1.474$ $D \text{ оп.мм} = 121.6$ $P \text{ н.мм} = 280.0$ $P \text{ вн.мм} = 264.0$ Гр. сл. = 0соб. Точн. = DIN		<b>БПЗ-507</b> $F \text{ см}^2 = 1.874$ $Q \text{ кг.} = 0.508$ $D \text{ оп.мм} = 60.5$ $P \text{ н.мм} = 155.3$ $P \text{ вн.мм} = 103.2$ Гр. сл. = II Точн. = П
	<b>БПЗ-503</b> $F \text{ см}^2 = 5.150$ $Q \text{ кг.} = 1.396$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 141.4$ $P \text{ вн.мм} = 116.2$ Гр. сл. = II Точн. = DIN	<b>Профиль заказчика</b> 	<b>БПЗ-508</b> $F \text{ см}^2 = 2.972$ $Q \text{ кг.} = 0.805$ $D \text{ оп.мм} = 101.1$ $P \text{ н.мм} = 247.4$ $P \text{ вн.мм} = 224.4$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-504</b> $F \text{ см}^2 = 10.440$ $Q \text{ кг.} = 2.829$ $D \text{ оп.мм} = 134.0$ $P \text{ н.мм} = 360.0$ $P \text{ вн.мм} = 336.0$ Гр. сл. = 0соб. Точн. = DIN		<b>БПЗ-0509</b> $F \text{ см}^2 = 3.806$ $Q \text{ кг.} = 1.031$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 283.8$ $P \text{ вн.мм} = 85.7$ Гр. сл. = VI Точн. = П
	<b>БПЗ-505</b> $F \text{ см}^2 = 4.86$ $Q \text{ кг.} = 1.317$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 176.0$ $P \text{ вн.мм} = 129.7$ Гр. сл. = V Точн. = П		<b>БПЗ-510</b> $F \text{ см}^2 = 9.400$ $Q \text{ кг.} = 2.547$ $D \text{ оп.мм} = 149.0$ $P \text{ н.мм} = 367.0$ $P \text{ вн.мм} = 614.0$ Гр. сл. = 0соб. Точн. = DIN











	<p><b>БПЗ-0511</b></p> <p> <math>F \text{ см}^2 = 3.680</math>  <math>Q \text{ кг.} = 0.997</math>  <math>D \text{ оп.мм} = 75.1</math>  <math>P \text{ н.мм} = 204.4</math>  <math>P_{\text{вн.мм}} = 116.7</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-516</b></p> <p> <math>F \text{ см} = 4.28</math>  <math>Q \text{ кг.} = 1.16</math>  <math>D \text{ оп.мм} = 64</math>  <math>P \text{ н.мм} = 340.6</math>  <math>P_{\text{вн.мм}} = 0.6</math>  Гр. сл. = Особ.  Точн. = Н </p>
	<p><b>БПЗ-512</b></p> <p> <math>F \text{ см}^2 = 2.240</math>  <math>Q \text{ кг.} = 0.607</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 120.0</math>  <math>P_{\text{вн.мм}} = 104.0</math>  Гр. сл. = V  Точн. = DIN </p>		<p><b>БПЗ-517</b></p> <p> <math>F \text{ см}^2 = 5.231</math>  <math>Q \text{ кг.} = 1.418</math>  <math>D \text{ оп.мм} = 75.3</math>  <math>P \text{ н.мм} = 277.0</math>  <math>P_{\text{вн.мм}} = 209.0</math>  Гр. сл. = Особ.  Точн. = Н </p>
	<p><b>БПЗ-513</b></p> <p> <math>F \text{ см}^2 = 4.640</math>  <math>Q \text{ кг.} = 1.257</math>  <math>D \text{ оп.мм} = 102.0</math>  <math>P \text{ н.мм} = 240.0</math>  <math>P_{\text{вн.мм}} = 224.0</math>  Гр. сл. = Особ.  Точн. = DIN </p>		<p><b>БПЗ-518</b></p> <p> <math>F \text{ см}^2 = 5.340</math>  <math>Q \text{ кг.} = 1.447</math>  <math>D \text{ оп.мм} = 96.0</math>  <math>P \text{ н.мм} = 273.0</math>  <math>P_{\text{вн.мм}} = 260.0</math>  Гр. сл. = Особ.  Точн. = DIN </p>
	<p><b>БПЗ-514</b></p> <p> <math>F \text{ см}^2 = 5.940</math>  <math>Q \text{ кг.} = 1.610</math>  <math>D \text{ оп.мм} = 74.3</math>  <math>P \text{ н.мм} = 210.0</math>  <math>P_{\text{вн.мм}} = 186.0</math>  Гр. сл. = IV  Точн. = DIN </p>		<p><b>БПЗ-519-01</b></p> <p> <math>F \text{ см}^2 = 5.315</math>  <math>Q \text{ кг.} = 1.440</math>  <math>D \text{ оп.мм} = 65.0</math>  <math>P \text{ н.мм} = 258.1</math>  <math>P_{\text{вн.мм}} = 103.4</math>  Гр. сл. = V  Точн. = Н </p>
	<p><b>БПЗ-515</b></p> <p> <math>F \text{ см} = 3.38</math>  <math>Q \text{ кг.} = 0.916</math>  <math>D \text{ оп.мм} = 42</math>  <math>P \text{ н.мм} = 280</math>  <math>P_{\text{вн.мм}} = 10</math>  Гр. сл. = Особ.  Точн. = Н </p>		<p><b>БПЗ-520</b></p> <p> <math>F \text{ см}^2 = 1.554</math>  <math>Q \text{ кг.} = 0.421</math>  <math>D \text{ оп.мм} = 48.0</math>  <math>P \text{ н.мм} = 139.0</math>  <math>P_{\text{вн.мм}} = 67.0</math>  Гр. сл. = Особ.  Точн. = Н </p>





















	<b>БПЗ-521</b> $F \text{ см}^2 = 20.300$ $Q \text{ кг.} = 5.501$ $D \text{ оп.мм} = 57.4$ $P \text{ н.мм} = 229.9$ $P_{\text{вн.мм}} = 100.7$ Гр. сл. = 0соб. Точн. = DIN		<b>БПЗ-526</b> $F \text{ см}^2 = 3.890$ $Q \text{ кг.} = 1.054$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 88.0$ $P_{\text{вн.мм}} = 53.4$ Гр. сл. = II Точн. = Н
	<b>БПЗ-522</b> $F \text{ см}^2 = 4.620$ $Q \text{ кг.} = 1.252$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 78.5$ $P_{\text{вн.мм}} = 18.8$ Гр. сл. = I Точн. = Н		<b>БПЗ-527</b> $F \text{ см}^2 = 5.000$ $Q \text{ кг.} = 1.355$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 97.4$ $P_{\text{вн.мм}} = 56.6$ Гр. сл. = I Точн. = Н
	<b>БПЗ-523</b> $F \text{ см}^2 = 5.410$ $Q \text{ кг.} = 1.466$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 103.6$ $P_{\text{вн.мм}} = 62.8$ Гр. сл. = I Точн. = Н		<b>БПЗ-528</b> $F \text{ см}^2 = 3.950$ $Q \text{ кг.} = 1.070$ $D \text{ оп.мм} = 124.0$ $P \text{ н.мм} = 295.0$ $P_{\text{вн.мм}} = 25.0$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-524</b> $F \text{ см}^2 = 1.760$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 18.0$ $P \text{ н.мм} = 56.6$ $P_{\text{вн.мм}} = 31.4$ Гр. сл. = IV Точн. = Н		<b>БПЗ-0529</b> $F \text{ см}^2 = 3.670$ $Q \text{ кг.} = 0.995$ $D \text{ оп.мм} = 62.9$ $P \text{ н.мм} = 323.0$ $P_{\text{вн.мм}} = 55.9$ Гр. сл. = V Точн. = П
	<b>БПЗ-525</b> $F \text{ см}^2 = 1.711$ $Q \text{ кг.} = 0.464$ $D \text{ оп.мм} = 23.1$ $P \text{ н.мм} = 77.3$ $P_{\text{вн.мм}} = 34.7$ Гр. сл. = IV Точн. = П		











	<p><b>БПЗ-0531</b></p> <p> <math>F \text{ см}^2 = 5.284</math>  <math>Q \text{ кг.} = 1.432</math>  <math>D \text{ оп.мм} = 81.0</math>  <math>P \text{ н.мм} = 269.8</math>  <math>P \text{ вн.мм} = 257.2</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-536</b></p> <p> <math>F \text{ см}^2 = 2.000</math>  <math>Q \text{ кг.} = 0.542</math>  <math>D \text{ оп.мм} = 20.0</math>  <math>P \text{ н.мм} = 62.8</math>  <math>P \text{ вн.мм} = 70.6</math>  Гр. сл. = 0соб.  Точн. = Н </p>
	<p><b>БПЗ-0532</b></p> <p> <math>F \text{ см}^2 = 1.824</math>  <math>Q \text{ кг.} = 0.494</math>  <math>D \text{ оп.мм} = 36.1</math>  <math>P \text{ н.мм} = 130.5</math>  <math>P \text{ вн.мм} = 36.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0537</b></p> <p> <math>F \text{ см}^2 = 8.400</math>  <math>Q \text{ кг.} = 2.276</math>  <math>D \text{ оп.мм} = 143.0</math>  <math>P \text{ н.мм} = 336.8</math>  <math>P \text{ вн.мм} = 251.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-533</b></p> <p> <math>F \text{ см}^2 = 5.23</math>  <math>Q \text{ кг.} = 1.417</math>  <math>D \text{ оп.мм} = 61</math>  <math>P \text{ н.мм} = 245.7</math>  <math>P \text{ вн.мм} = 131.7</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-0538</b></p> <p> <math>F \text{ см}^2 = 2.980</math>  <math>Q \text{ кг.} = 0.808</math>  <math>D \text{ оп.мм} = 47.3</math>  <math>P \text{ н.мм} = 174.6</math>  <math>P \text{ вн.мм} = 102.2</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-0534</b></p> <p> <math>F \text{ см}^2 = 4.478</math>  <math>Q \text{ кг.} = 1.214</math>  <math>D \text{ оп.мм} = 44.0</math>  <math>P \text{ н.мм} = 197.4</math>  <math>P \text{ вн.мм} = 113.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-0539</b></p> <p> <math>F \text{ см}^2 = 2.084</math>  <math>Q \text{ кг.} = 0.565</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 143.4</math>  <math>P \text{ вн.мм} = 131.4</math>  Гр. сл. = IV  Точн. = П </p>
			<p><b>БПЗ-540</b></p> <p> <math>F \text{ см}^2 = 5.820</math>  <math>Q \text{ кг.} = 1.577</math>  <math>D \text{ оп.мм} = 74.0</math>  <math>P \text{ н.мм} = 324.5</math>  <math>P \text{ вн.мм} = 73.0</math>  Гр. сл. = IV  Точн. = DIN </p>











	<p><b>БПЗ-541</b></p> <p> <math>F \text{ см}^2 = 6.970</math>  <math>Q \text{ кг.} = 1.889</math>  <math>D \text{ оп.мм} = 160.7</math>  <math>P \text{ н.мм} = 510.5</math>  <math>P_{\text{вн.мм}} = 132.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-546</b></p> <p> <math>F \text{ см}^2 = 4.900</math>  <math>Q \text{ кг.} = 1.328</math>  <math>D \text{ оп.мм} = 32.0</math>  <math>P \text{ н.мм} = 100.5</math>  <math>P_{\text{вн.мм}} = 62.8</math>  Гр. сл. = I  Точн. = Н </p>
	<p><b>БПЗ-542</b></p> <p> <math>F \text{ см}^2 = 5.320</math>  <math>Q \text{ кг.} = 1.442</math>  <math>D \text{ оп.мм} = 43.3</math>  <math>P \text{ н.мм} = 353.5</math>  <math>P_{\text{вн.мм}} = 46.4</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-547</b></p> <p> <math>F \text{ см}^2 = 0.880</math>  <math>Q \text{ кг.} = 0.238</math>  <math>D \text{ оп.мм} = 16.0</math>  <math>P \text{ н.мм} = 50.3</math>  <math>P_{\text{вн.мм}} = 37.7</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-543</b></p> <p> <math>F \text{ см}^2 = 2.860</math>  <math>Q \text{ кг.} = 0.775</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 184.2</math>  <math>P_{\text{вн.мм}} = 96.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-548</b></p> <p> <math>F \text{ см}^2 = 1.260</math>  <math>Q \text{ кг.} = 0.341</math>  <math>D \text{ оп.мм} = 22.0</math>  <math>P \text{ н.мм} = 69.0</math>  <math>P_{\text{вн.мм}} = 56.6</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-544</b></p> <p> <math>F \text{ см}^2 = 2.190</math>  <math>Q \text{ кг.} = 0.593</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 131.5</math>  <math>P_{\text{вн.мм}} = 84.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-549</b></p> <p> <math>F \text{ см}^2 = 15.480</math>  <math>Q \text{ кг.} = 4.195</math>  <math>D \text{ оп.мм} = 111.8</math>  <math>P \text{ н.мм} = 337.4</math>  <math>P_{\text{вн.мм}} = 166.8</math>  Гр. сл. = VI  Точн. = Н </p>
	<p><b>БПЗ-545</b></p> <p> <math>F \text{ см}^2 = 3.020</math>  <math>Q \text{ кг.} = 0.818</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 225.5</math>  <math>P_{\text{вн.мм}} = 66.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-550</b></p> <p> <math>F \text{ см}^2 = 8.150</math>  <math>Q \text{ кг.} = 2.209</math>  <math>D \text{ оп.мм} = 92.7</math>  <math>P \text{ н.мм} = 328.2</math>  <math>P_{\text{вн.мм}} = 132.6</math>  Гр. сл. = VI  Точн. = Н </p>

	<b>БПЗ-551</b> $F \text{ см}^2 = 13.790$ $Q \text{ кг.} = 3.737$ $D \text{ оп.мм} = 169.0$ $P \text{ н.мм} = 446.1$ $P \text{ вн.мм} = 199.5$ Гр. сл. = VI Точн. = Н		<b>БПЗ-556</b> $F \text{ см}^2 = 1.310$ $Q \text{ кг.} = 0.355$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 78.5$ $P \text{ вн.мм} = 67.2$ Гр. сл. = V Точн. = Н
	<b>БПЗ-552</b> $F \text{ см}^2 = 3.644$ $Q \text{ кг.} = 0.988$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 188.5$ $P \text{ вн.мм} = 175.9$ Гр. сл. = VI Точн. = DIN		<b>БПЗ-0557</b> $F \text{ см}^2 = 3.260$ $Q \text{ кг.} = 0.883$ $D \text{ оп.мм} = 102.0$ $P \text{ н.мм} = 223.4$ $P \text{ вн.мм} = 198.3$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-0553</b> $F \text{ см}^2 = 1.323$ $Q \text{ кг.} = 0.359$ $D \text{ оп.мм} = 35.2$ $P \text{ н.мм} = 94.2$ $P \text{ вн.мм} = 82.2$ Гр. сл. = 0соб. Точн. = 0соб.		<b>БПЗ-558</b> $F \text{ см}^2 = 1.010$ $Q \text{ кг.} = 0.274$ $D \text{ оп.мм} = 38.6$ $P \text{ н.мм} = 116.3$ $P \text{ вн.мм} = 50.2$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-0554</b> $F \text{ см}^2 = 24.321$ $Q \text{ кг.} = 6.591$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 812.7$ $P \text{ вн.мм} = 78.5$ Гр. сл. = VI Точн. = П		<b>БПЗ-559</b> $F \text{ см}^2 = 2.430$ $Q \text{ кг.} = 0.659$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 192.8$ $P \text{ вн.мм} = 118.0$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-555</b> $F \text{ см}^2 = 1.110$ $Q \text{ кг.} = 0.301$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 74.8$ $P \text{ вн.мм} = 64.8$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-560</b> $F \text{ см}^2 = 2.191$ $Q \text{ кг.} = 0.594$ $D \text{ оп.мм} = 46.8$ $P \text{ н.мм} = 127.4$ $P \text{ вн.мм} = 115.6$ Гр. сл. = V Точн. = Н











	<p><b>БПЗ-561</b></p> <p> <math>F \text{ см}^2 = 30.630</math>  <math>Q \text{ кг.} = 8.301</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 251.3</math>  <math>P_{\text{вн.мм}} = 157.1</math>  Гр. сл. = I  Точн. = Н </p>		<p><b>БПЗ-566</b></p> <p> <math>F \text{ см}^2 = 5.236</math>  <math>Q \text{ кг.} = 1.419</math>  <math>D \text{ оп.мм} = 83.6</math>  <math>P \text{ н.мм} = 366.9</math>  <math>P_{\text{вн.мм}} = 188</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-562</b></p> <p> <math>F \text{ см}^2 = 34.560</math>  <math>Q \text{ кг.} = 9.366</math>  <math>D \text{ оп.мм} = 75.0</math>  <math>P \text{ н.мм} = 235.6</math>  <math>P_{\text{вн.мм}} = 109.9</math>  Гр. сл. = I  Точн. = Н </p>		<p><b>БПЗ-567</b></p> <p> <math>F \text{ см}^2 = 4.500</math>  <math>Q \text{ кг.} = 1.220</math>  <math>D \text{ оп.мм} = 74.3</math>  <math>P \text{ н.мм} = 190.0</math>  <math>P_{\text{вн.мм}} = 170.0</math>  Гр. сл. = IV  Точн. = DIN </p>
	<p><b>БПЗ-563</b></p> <p> <math>F \text{ см}^2 = 31.420</math>  <math>Q \text{ кг.} = 8.515</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 219.9</math>  <math>P_{\text{вн.мм}} = 94.3</math>  Гр. сл. = I  Точн. = Н </p>		<p><b>БПЗ-568</b></p> <p> <math>F \text{ см}^2 = 23.256</math>  <math>Q \text{ кг.} = 6.302</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 172.8</math>  <math>P_{\text{вн.мм}} = 25.1</math>  Гр. сл. = I  Точн. = П </p>
	<p><b>БПЗ-564</b></p> <p> <math>F \text{ см}^2 = 0.817</math>  <math>Q \text{ кг.} = 0.221</math>  <math>D \text{ оп.мм} = 15.0</math>  <math>P \text{ н.мм} = 47.1</math>  <math>P_{\text{вн.мм}} = 34.6</math>  Гр. сл. = III  Точн. = DIN </p>		<p><b>БПЗ-569</b></p> <p> <math>F \text{ см}^2 = 14.360</math>  <math>Q \text{ кг.} = 3.892</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>P \text{ н.мм} = 141.4</math>  <math>P_{\text{вн.мм}} = 43.9</math>  Гр. сл. = I  Точн. = П </p>
			<p><b>БПЗ-0570</b></p> <p> <math>F \text{ см}^2 = 1.739</math>  <math>Q \text{ кг.} = 0.471</math>  <math>D \text{ оп.мм} = 36.1</math>  <math>P \text{ н.мм} = 127.1</math>  <math>P_{\text{вн.мм}} = 34.6</math>  Гр. сл. = VI  Точн. = П </p>

	<b>БПЗ-571</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P_{\text{вн.мм}} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		<b>БПЗ-576</b> $F \text{ см}^2 = 6.560$ $Q \text{ кг.} = 1.778$ $D \text{ оп.мм} = 67.0$ $P \text{ н.мм} = 180.0$ $P_{\text{вн.мм}} = 148.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{DIN}$
	<b>БПЗ-572</b> $F \text{ см}^2 = 2.840$ $Q \text{ кг.} = 0.770$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 150.0$ $P_{\text{вн.мм}} = 134.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{DIN}$		<b>БПЗ-577</b> $F \text{ см}^2 = 4.240$ $Q \text{ кг.} = 1.149$ $D \text{ оп.мм} = 85.5$ $P \text{ н.мм} = 220.0$ $P_{\text{вн.мм}} = 204.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{DIN}$
	<b>БПЗ-573</b> $F \text{ см}^2 = 4.140$ $Q \text{ кг.} = 1.122$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 150.0$ $P_{\text{вн.мм}} = 126.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{DIN}$		<b>БПЗ-578</b> $F \text{ см}^2 = 1.831$ $Q \text{ кг.} = 0.496$ $D \text{ оп.мм} = 44.2$ $P \text{ н.мм} = 144.6$ $P_{\text{вн.мм}} = 90.4$ $\text{Гр. сл.} = 0 \text{соб.}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-574</b> $F \text{ см}^2 = 3.440$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ $P_{\text{вн.мм}} = 164.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{DIN}$		<b>БПЗ-579</b> $F \text{ см}^2 = 0.810$ $Q \text{ кг.} = 0.220$ $D \text{ оп.мм} = 22.4$ $P \text{ н.мм} = 60.0$ $P_{\text{вн.мм}} = 48.0$ $\text{Гр. сл.} = 0 \text{соб.}$ $\text{Точн.} = \text{DIN}$
	<b>БПЗ-575</b> $F \text{ см}^2 = 5.040$ $Q \text{ кг.} = 1.366$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ $P_{\text{вн.мм}} = 156.0$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{DIN}$		<b>БПЗ-580</b> $F \text{ см}^2 = 1.410$ $Q \text{ кг.} = 0.382$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 100.0$ $P_{\text{вн.мм}} = 88.0$ $\text{Гр. сл.} = 0 \text{соб.}$ $\text{Точн.} = \text{DIN}$

	<p><b>БПЗ-581</b></p> <p> <math>F \text{ см}^2 = 2.040</math>  <math>Q \text{ кг.} = 0.553</math>  <math>D \text{ оп.мм} = 40.3</math>  <math>P \text{ н.мм} = 110.0</math>  <math>P_{\text{вн.мм}} = 94.0</math>  Гр. сл. = IV  Точн. = DIN </p>		<p><b>БПЗ-586</b></p> <p> <math>F \text{ см}^2 = 3.360</math>  <math>Q \text{ кг.} = 0.911</math>  <math>D \text{ оп.мм} = 35.4</math>  <math>P \text{ н.мм} = 100.0</math>  <math>P_{\text{вн.мм}} = 68.0</math>  Гр. сл. = IV  Точн. = DIN </p>
	<p><b>БПЗ-582</b></p> <p> <math>F \text{ см}^2 = 2.240</math>  <math>Q \text{ кг.} = 0.607</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 120.0</math>  <math>P_{\text{вн.мм}} = 104.0</math>  Гр. сл. = IV  Точн. = DIN </p>		<p><b>БПЗ-587</b></p> <p> <math>F \text{ см}^2 = 1.710</math>  <math>Q \text{ кг.} = 0.463</math>  <math>D \text{ оп.мм} = 42.4</math>  <math>P \text{ н.мм} = 120.0</math>  <math>P_{\text{вн.мм}} = 108.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>
	<p><b>БПЗ-583</b></p> <p> <math>F \text{ см}^2 = 1.560</math>  <math>Q \text{ кг.} = 0.423</math>  <math>D \text{ оп.мм} = 39.0</math>  <math>P \text{ н.мм} = 110.0</math>  <math>P_{\text{вн.мм}} = 98.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>		<p><b>БПЗ-588</b></p> <p> <math>F \text{ см}^2 = 2.310</math>  <math>Q \text{ кг.} = 0.626</math>  <math>D \text{ оп.мм} = 56.6</math>  <math>P \text{ н.мм} = 160.0</math>  <math>P_{\text{вн.мм}} = 148.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>
	<p><b>БПЗ-584</b></p> <p> <math>F \text{ см}^2 = 1.410</math>  <math>Q \text{ кг.} = 0.382</math>  <math>D \text{ оп.мм} = 35.4</math>  <math>P \text{ н.мм} = 100.0</math>  <math>P_{\text{вн.мм}} = 88.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>		<p><b>БПЗ-589</b></p> <p> <math>F \text{ см}^2 = 10.180</math>  <math>Q \text{ кг.} = 2.759</math>  <math>D \text{ оп.мм} = 60.0</math>  <math>P \text{ н.мм} = 188.5</math>  <math>P_{\text{вн.мм}} = 150.8</math>  Гр. сл. = II  Точн. = DIN </p>
	<p><b>БПЗ-585</b></p> <p> <math>F \text{ см}^2 = 2.640</math>  <math>Q \text{ кг.} = 0.715</math>  <math>D \text{ оп.мм} = 35.4</math>  <math>P \text{ н.мм} = 100.0</math>  <math>P_{\text{вн.мм}} = 76.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>		<p><b>БПЗ-590</b></p> <p> <math>F \text{ см}^2 = 6.880</math>  <math>Q \text{ кг.} = 1.864</math>  <math>D \text{ оп.мм} = 76.0</math>  <math>P \text{ н.мм} = 238.8</math>  <math>P_{\text{вн.мм}} = 219.9</math>  Гр. сл. = V  Точн. = DIN </p>











	<p><b>БПЗ-591</b></p> <p> <math>F \text{ см}^2 = 0.637</math>  <math>Q \text{ кг.} = 0.173</math>  <math>D \text{ оп.мм} = 69.4</math>  <math>P \text{ н.мм} = 68.4</math>  <math>P \text{ вн.мм} = 33.40</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-596</b></p> <p> <math>F \text{ см}^2 = 3.687</math>  <math>Q \text{ кг.} = 0.999</math>  <math>D \text{ оп.мм} = 61.7</math>  <math>P \text{ н.мм} = 209.2</math>  <math>P \text{ вн.мм} = 243.9</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>
	<p><b>БПЗ-592</b></p> <p> <math>F \text{ см}^2 = 4.230</math>  <math>Q \text{ кг.} = 1.146</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 132.0</math>  <math>P \text{ вн.мм} = 110.0</math>  Гр. сл. = II  Точн. = DIN </p>		<p><b>БПЗ-597</b></p> <p> <math>F \text{ см}^2 = 3.882</math>  <math>Q \text{ кг.} = 1.052</math>  <math>D \text{ оп.мм} = 79.0</math>  <math>P \text{ н.мм} = 246.2</math>  <math>P \text{ вн.мм} = 246.5</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-593</b></p> <p> <math>F \text{ см}^2 = 5.91</math>  <math>Q \text{ кг.} = 1.601</math>  <math>D \text{ оп.мм} = 99.0</math>  <math>P \text{ н.мм} = 408.4</math>  <math>P \text{ вн.мм} = 275.8</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-598</b></p> <p> <math>F \text{ см}^2 = 2.780</math>  <math>Q \text{ кг.} = 0.753</math>  <math>D \text{ оп.мм} = 60.0</math>  <math>P \text{ н.мм} = 235.7</math>  <math>P \text{ вн.мм} = 94.4</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-594</b></p> <p> <math>F \text{ см}^2 = 2.243</math>  <math>Q \text{ кг.} = 0.608</math>  <math>D \text{ оп.мм} = 40.2</math>  <math>P \text{ н.мм} = 173.2</math>  <math>P \text{ вн.мм} = 78.9</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>		<p><b>БПЗ-599</b></p> <p> <math>F \text{ см}^2 = 2.345</math>  <math>Q \text{ кг.} = 0.635</math>  <math>D \text{ оп.мм} = 45.3</math>  <math>P \text{ н.мм} = 217.3</math>  <math>P \text{ вн.мм} = 70.9</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>
	<p><b>БПЗ-595</b></p> <p> <math>F \text{ см}^2 = 9.64</math>  <math>Q \text{ кг.} = 2.612</math>  <math>D \text{ оп.мм} = 128.0</math>  <math>P \text{ н.мм} = 526.4</math>  <math>P \text{ вн.мм} = 399.2</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-600</b></p> <p> <math>F \text{ см}^2 = 10.560</math>  <math>Q \text{ кг.} = 2.862</math>  <math>D \text{ оп.мм} = 72.1</math>  <math>P \text{ н.мм} = 200.0</math>  <math>P \text{ вн.мм} = 152.0</math>  Гр. сл. = III  Точн. = DIN </p>





















	<b>БПЗ-601</b> $F \text{ см}^2 = 3.589$ $Q \text{ кг.} = 0.973$ $D \text{ оп.мм} = 84.1$ $P \text{ н.мм} = 278.2$ $P \text{ вн.мм} = 93.4$ Гр. сл. = VI Точн. = П		<b>БПЗ-606</b> $F \text{ см}^2 = 7.190$ $Q \text{ кг.} = 1.948$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 323.9$ $P \text{ вн.мм} = 272.8$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-602</b> $F \text{ см}^2 = 3.174$ $Q \text{ кг.} = 0.86$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 199.4$ $P \text{ вн.мм} = 127.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-607</b> $F \text{ см}^2 = 1.970$ $Q \text{ кг.} = 0.534$ $D \text{ оп.мм} = 42.8$ $P \text{ н.мм} = 178.4$ $P \text{ вн.мм} = 86.55$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-603</b> $F \text{ см}^2 = 2.814$ $Q \text{ кг.} = 0.763$ $D \text{ оп.мм} = 43.6$ $P \text{ н.мм} = 181.4$ $P \text{ вн.мм} = 109.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-608</b> $F \text{ см}^2 = 6.790$ $Q \text{ кг.} = 1.840$ $D \text{ оп.мм} = 58.0$ $P \text{ н.мм} = 182.2$ $P \text{ вн.мм} = 157.1$ Гр. сл. = III Точн. = DIN
	<b>БПЗ-604</b> $F \text{ см}^2 = 2.702$ $Q \text{ кг.} = 0.732$ $D \text{ оп.мм} = 52.5$ $P \text{ н.мм} = 181.6$ $P \text{ вн.мм} = 84$ Гр. сл. = V Точн. = П		<b>БПЗ-609</b> $F \text{ см}^2 = 0.910$ $Q \text{ кг.} = 0.247$ $D \text{ оп.мм} = 15.0$ $P \text{ н.мм} = 66.8$ $P \text{ вн.мм} = 49.2$ Гр. сл. = V Точн. = П
	<b>БПЗ-605</b> $F \text{ см}^2 = 7.570$ $Q \text{ кг.} = 2.051$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 355.6$ $P \text{ вн.мм} = 273.0$ Гр. сл. = 0соб. Точн. = Н		<b>БПЗ-610</b> $F \text{ см}^2 = 18.410$ $Q \text{ кг.} = 4.989$ $D \text{ оп.мм} = 120.0$ $P \text{ н.мм} = 572.3$ $P \text{ вн.мм} = 351.1$ Гр. сл. = V Точн. = П










	<p><b>БПЗ-611</b></p> <p> <math>F \text{ см}^2 = 2.719</math>  <math>Q \text{ кг.} = 0.737</math>  <math>D \text{ оп.мм} = 47.0</math>  <math>P \text{ н.мм} = 134.7</math>  <math>P \text{ вн.мм} = 101.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-616</b></p> <p> <math>F \text{ см}^2 = 4.115</math>  <math>Q \text{ кг.} = 1.115</math>  <math>D \text{ оп.мм} = 25.0</math>  <math>P \text{ н.мм} = 78.5</math>  <math>P \text{ вн.мм} = 31.4</math>  Гр. сл. = I  Точн. = Н </p>
	<p><b>БПЗ-612</b></p> <p> <math>F \text{ см}^2 = 2.278</math>  <math>Q \text{ кг.} = 0.617</math>  <math>D \text{ оп.мм} = 41.0</math>  <math>P \text{ н.мм} = 158.4</math>  <math>P \text{ вн.мм} = 57.3</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-617</b></p> <p> <math>F \text{ см}^2 = 1.000</math>  <math>Q \text{ кг.} = 0.271</math>  <math>D \text{ оп.мм} = 13.0</math>  <math>P \text{ н.мм} = 40.8</math>  <math>P \text{ вн.мм} = 20.4</math>  Гр. сл. = II  Точн. = Н </p>
	<p><b>БПЗ-613</b></p> <p> <math>F \text{ см}^2 = 2.810</math>  <math>Q \text{ кг.} = 0.762</math>  <math>D \text{ оп.мм} = 45.2</math>  <math>P \text{ н.мм} = 167.4</math>  <math>P \text{ вн.мм} = 111.4</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-618</b></p> <p> <math>F \text{ см}^2 = 3.110</math>  <math>Q \text{ кг.} = 0.843</math>  <math>D \text{ оп.мм} = 51.0</math>  <math>P \text{ н.мм} = 267.5</math>  <math>P \text{ вн.мм} = 81.3</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-614</b></p> <p> <math>F \text{ см}^2 = 1.780</math>  <math>Q \text{ кг.} = 0.482</math>  <math>D \text{ оп.мм} = 31.5</math>  <math>P \text{ н.мм} = 125.8</math>  <math>P \text{ вн.мм} = 48.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-619</b></p> <p> <math>F \text{ см}^2 = 0.772</math>  <math>Q \text{ кг.} = 0.209</math>  <math>D \text{ оп.мм} = 21.0</math>  <math>P \text{ н.мм} = 56.6</math>  <math>P \text{ вн.мм} = 47.1</math>  Гр. сл. = VI  Точн. = DIN </p>
	<p><b>БПЗ-615</b></p> <p> <math>F \text{ см}^2 = 1.392</math>  <math>Q \text{ кг.} = 0.377</math>  <math>D \text{ оп.мм} = 27.7</math>  <math>P \text{ н.мм} = 76.3</math>  <math>P \text{ вн.мм} = 61.5</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-620</b></p> <p> <math>F \text{ см}^2 = 2.623</math>  <math>Q \text{ кг.} = 0.711</math>  <math>D \text{ оп.мм} = 68.4</math>  <math>P \text{ н.мм} = 243.8</math>  <math>P \text{ вн.мм} = 43.8</math>  Гр. сл. = VI  Точн. = Н </p>









Нет нормалли










	<p><b>БПЗ-0621</b></p> <p> <math>F \text{ см}^2 = 5.238</math>  <math>Q \text{ кг.} = 1.419</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-626</b></p> <p> <math>F \text{ см}^2 = 1.556</math>  <math>Q \text{ кг.} = 0.422</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 265.5</math>  <math>P \text{ вн.мм} = 0.0</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-622</b></p> <p> <math>F \text{ см}^2 = 4.495</math>  <math>Q \text{ кг.} = 1.218</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 273.7</math>  <math>P \text{ вн.мм} = 77.7</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-627</b></p> <p> <math>F \text{ см}^2 = 1.314</math>  <math>Q \text{ кг.} = 0.356</math>  <math>D \text{ оп.мм} = 33.0</math>  <math>P \text{ н.мм} = 122.0</math>  <math>P \text{ вн.мм} = 72.0</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-623</b></p> <p> <math>F \text{ см}^2 = 2.445</math>  <math>Q \text{ кг.} = 0.663</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 210.5</math>  <math>P \text{ вн.мм} = 81.3</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-628</b></p> <p> <math>F \text{ см}^2 = 0.977</math>  <math>Q \text{ кг.} = 0.265</math>  <math>D \text{ оп.мм} = 33</math>  <math>P \text{ н.мм} = 81</math>  <math>P \text{ вн.мм} = 72</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-624</b></p> <p> <math>F \text{ см}^2 = 3.970</math>  <math>Q \text{ кг.} = 1.076</math>  <math>D \text{ оп.мм} = 67.1</math>  <math>P \text{ н.мм} = 205.5</math>  <math>P \text{ вн.мм} = 192.2</math>  <math>\text{Гр. сл.} = \text{VI}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-629</b></p> <p> <math>F \text{ см}^2 = 1.646</math>  <math>Q \text{ кг.} = 0.446</math>  <math>D \text{ оп.мм} = 40.8</math>  <math>P \text{ н.мм} = 108.0</math>  <math>P \text{ вн.мм} = 145.1</math>  <math>\text{Гр. сл.} = 0 \text{ особ.}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-625</b></p> <p> <math>F \text{ см}^2 = 2.785</math>  <math>Q \text{ кг.} = 0.755</math>  <math>D \text{ оп.мм} = 120.0</math>  <math>P \text{ н.мм} = 256.5</math>  <math>P \text{ вн.мм} = 31.4</math>  <math>\text{Гр. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{Н}</math> </p>		<p><b>БПЗ-630</b></p> <p> <math>F \text{ см}^2 = 5.312</math>  <math>Q \text{ кг.} = 1.440</math>  <math>D \text{ оп.мм} = 54.5</math>  <math>P \text{ н.мм} = 214.3</math>  <math>P \text{ вн.мм} = 102.3</math>  <math>\text{Гр. сл.} = \text{VI}</math>  <math>\text{Точн.} = \text{П}</math> </p>

			БПЗ-636
			$F \text{ см}^2 = 5.680$ $Q \text{ кг.} = 1.539$ $D \text{ оп.мм} = 112.0$ $P \text{ н.мм} = 291.8$ $P \text{ вн.мм} = 275.8$ Гр. сл. = 0соб. Точн. = П
			БПЗ-637
			$F \text{ см}^2 = 4.795$ $Q \text{ кг.} = 1.299$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 304.4$ $P \text{ вн.мм} = 177.0$ Гр. сл. = 0соб. Точн. = П
	БПЗ-633		БПЗ-638
	$F \text{ см}^2 = 3.544$ $Q \text{ кг.} = 0.96$ $D \text{ оп.мм} = 52.5$ $P \text{ н.мм} = 288.2$ $P \text{ вн.мм} = 63.5$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 5.054$ $Q \text{ кг.} = 1.37$ $D \text{ оп.мм} = 85.3$ $P \text{ н.мм} = 358.5$ $P \text{ вн.мм} = 164.2$ Гр. сл. = VI Точн. = П
	БПЗ-634		БПЗ-639
	$F \text{ см}^2 = 0.760$ $Q \text{ кг.} = 0.206$ $D \text{ оп.мм} = 19.0$ $P \text{ н.мм} = 54.9$ $P \text{ вн.мм} = 45.5$ Гр. сл. = 0соб. Точн. = П		$F \text{ см}^2 = 5.054$ $Q \text{ кг.} = 1.37$ $D \text{ оп.мм} = 94.5$ $P \text{ н.мм} = 358.5$ $P \text{ вн.мм} = 164.2$ Гр. сл. = VI Точн. = П
	БПЗ-635		БПЗ-640
	$F \text{ см}^2 = 0.964$ $Q \text{ кг.} = 0.261$ $D \text{ оп.мм} = 34.2$ $P \text{ н.мм} = 81.7$ $P \text{ вн.мм} = 40.7$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 7.967$ $Q \text{ кг.} = 2.159$ $D \text{ оп.мм} = 127.8$ $P \text{ н.мм} = 443.3$ $P \text{ вн.мм} = 248$ Гр. сл. = VI Точн. = П











	<b>БПЗ-641</b> $F \text{ см}^2 = 4.473$ $Q \text{ кг.} = 1.212$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 284.8$ $P \text{ вн.мм} = 164.2$ Гр. сл. = VI Точн. = П		<b>БПЗ-646</b> $F \text{ см}^2 = 1.992$ $Q \text{ кг.} = 0.540$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 57.9$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-642</b> $F \text{ см}^2 = 20.974$ $Q \text{ кг.} = 5.684$ $D \text{ оп.мм} = 116.8$ $P \text{ н.мм} = 525.3$ $P \text{ вн.мм} = 237.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-647</b> $F \text{ см}^2 = 2.238$ $Q \text{ кг.} = 0.606$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 119.1$ $P \text{ вн.мм} = 104.0$ Гр. сл. = V Точн. = DIN
	<b>БПЗ-643</b> $F \text{ см}^2 = 3.049$ $Q \text{ кг.} = 0.826$ $D \text{ оп.мм} = 70.0$ $P \text{ н.мм} = 178.7$ $P \text{ вн.мм} = 147.4$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-648</b> $F \text{ см}^2 = 2.717$ $Q \text{ кг.} = 0.736$ $D \text{ оп.мм} = 51.4$ $P \text{ н.мм} = 204.9$ $P \text{ вн.мм} = 127.7$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-644</b> $F \text{ см}^2 = 15.740$ $Q \text{ кг.} = 4.266$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 269.4$ $P \text{ вн.мм} = 172.8$ Гр. сл. = I Точн. = Н		<b>БПЗ-649</b> $F \text{ см}^2 = 5.076$ $Q \text{ кг.} = 1.376$ $D \text{ оп.мм} = 54.9$ $P \text{ н.мм} = 156.6$ $P \text{ вн.мм} = 132.0$ Гр. сл. = III Точн. = DIN
	<b>БПЗ-645</b> $F \text{ см}^2 = 2.408$ $Q \text{ кг.} = 0.653$ $D \text{ оп.мм} = 60.4$ $P \text{ н.мм} = 160.5$ $P \text{ вн.мм} = 127.4$ Гр. сл. = VI Точн. = Н		<b>БПЗ-0650</b> $F \text{ см}^2 = 0.978$ $Q \text{ кг.} = 0.265$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 73.6$ $P \text{ вн.мм} = 62.1$ Гр. сл. = V Точн. = П








	<p><b>БПЗ-0651</b></p> <p> <math>F \text{ см}^2 = 1.030</math>  <math>Q \text{ кг.} = 0.279</math>  <math>D \text{ оп.мм} = 27.0</math>  <math>P \text{ н.мм} = 80.5</math>  <math>P \text{ вн.мм} = 67.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-656</b></p> <p> <math>F \text{ см}^2 = 3.420</math>  <math>Q \text{ кг.} = 0.927</math>  <math>D \text{ оп.мм} = 68.2</math>  <math>P \text{ н.мм} = 104.7</math>  <math>P \text{ вн.мм} = 327.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-652</b></p> <p> <math>F \text{ см}^2 = 1.242</math>  <math>Q \text{ кг.} = 0.337</math>  <math>D \text{ оп.мм} = 38.6</math>  <math>P \text{ н.мм} = 102.0</math>  <math>P \text{ вн.мм} = 77.0</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>		<p><b>БПЗ-657</b></p> <p> <math>F \text{ см}^2 = 0.283</math>  <math>Q \text{ кг.} = 0.077</math>  <math>D \text{ оп.мм} = 10.0</math>  <math>P \text{ н.мм} = 31.4</math>  <math>P \text{ вн.мм} = 25.1</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-653</b></p> <p> <math>F \text{ см}^2 = 1.040</math>  <math>Q \text{ кг.} = 0.282</math>  <math>D \text{ оп.мм} = 35.4</math>  <math>P \text{ н.мм} = 96.8</math>  <math>P \text{ вн.мм} = 62.5</math>  Гр. сл. = 0соб.  Точн. = 0соб. </p>		<p><b>БПЗ-658</b></p> <p> <math>F \text{ см}^2 = 0.495</math>  <math>Q \text{ кг.} = 0.134</math>  <math>D \text{ оп.мм} = 12.0</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ вн.мм} = 28.3</math>  Гр. сл. = V  Точн. = H </p>
	<p><b>БПЗ-654</b></p> <p> <math>F \text{ см}^2 = 34.880</math>  <math>Q \text{ кг.} = 9.452</math>  <math>D \text{ оп.мм} = 206.0</math>  <math>P \text{ н.мм} = 809.8</math>  <math>P \text{ вн.мм} = 384.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-659</b></p> <p> <math>F \text{ см}^2 = 3.880</math>  <math>Q \text{ кг.} = 1.051</math>  <math>D \text{ оп.мм} = 95.0</math>  <math>P \text{ н.мм} = 309.7</math>  <math>P \text{ вн.мм} = 90.4</math>  Гр. сл. = VI  Точн. = H </p>
	<p><b>БПЗ-655</b></p> <p> <math>F \text{ см}^2 = 30.100</math>  <math>Q \text{ кг.} = 8.157</math>  <math>D \text{ оп.мм} = 150.0</math>  <math>P \text{ н.мм} = 1024.0</math>  <math>P \text{ вн.мм} = 320.6</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-660</b></p> <p> <math>F \text{ см}^2 = 4.225</math>  <math>Q \text{ кг.} = 1.145</math>  <math>D \text{ оп.мм} = 66.4</math>  <math>P \text{ н.мм} = 308.5</math>  <math>P \text{ вн.мм} = 117.0</math>  Гр. сл. = VI  Точн. = H </p>











			<b>БПЗ-666</b> $F \text{ см}^2 = 2.290$ $Q \text{ кг.} = 0.621$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 157.1$ $P \text{ вн.мм} = 147.7$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-662</b> $F \text{ см}^2 = 3.620$ $Q \text{ кг.} = 0.981$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 289.0$ $P \text{ вн.мм} = 86.0$ Гр. сл. = VI Точн. = Н		<b>БПЗ-667</b> $F \text{ см}^2 = 0.740$ $Q \text{ кг.} = 0.201$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 54.9$ Гр. сл. = V Точн. = Н
	<b>БПЗ-663</b> $F \text{ см}^2 = 3.352$ $Q \text{ кг.} = 0.908$ $D \text{ оп.мм} = 57.3$ $P \text{ н.мм} = 263.7$ $P \text{ вн.мм} = 84.8$ Гр. сл. = VI Точн. = Н		<b>БПЗ-668</b> $F \text{ см}^2 = 0.820$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 69.1$ $P \text{ вн.мм} = 61.3$ Гр. сл. = V Точн. = Н
			<b>БПЗ-669</b> $F \text{ см}^2 = 3.379$ $Q \text{ кг.} = 0.916$ $D \text{ оп.мм} = 77.0$ $P \text{ н.мм} = 263.8$ $P \text{ вн.мм} = 114.9$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-665</b> $F \text{ см}^2 = 17.690$ $Q \text{ кг.} = 4.794$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 372.6$ $P \text{ вн.мм} = 410.0$ Гр. сл. = VI Точн. = Н		<b>БПЗ-670</b> $F \text{ см}^2 = 2.127$ $Q \text{ кг.} = 0.576$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 140.9$ $P \text{ вн.мм} = 88.0$ Гр. сл. = V Точн. = Н

	<p><b>БПЗ-671</b></p> <p> <math>F \text{ см}^2 = 2.361</math>  <math>Q \text{ кг.} = 0.640</math>  <math>D \text{ оп.мм} = 46.9</math>  <math>P \text{ н.мм} = 181.8</math>  <math>P \text{ вн.мм} = 88.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-676</b></p> <p> <math>F \text{ см}^2 = 2.551</math>  <math>Q \text{ кг.} = 0.691</math>  <math>D \text{ оп.мм} = 37.8</math>  <math>P \text{ н.мм} = 238.1</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-672</b></p> <p> <math>F \text{ см}^2 = 2.361</math>  <math>Q \text{ кг.} = 0.640</math>  <math>D \text{ оп.мм} = 46.9</math>  <math>P \text{ н.мм} = 181.8</math>  <math>P \text{ вн.мм} = 88.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-677</b></p> <p> <math>F \text{ см}^2 = 1.578</math>  <math>Q \text{ кг.} = 0.428</math>  <math>D \text{ оп.мм} = 25.8</math>  <math>P \text{ н.мм} = 147.6</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = VI  Точн. = П </p>
			<p><b>БПЗ-678</b></p> <p> <math>F \text{ см}^2 = 1.810</math>  <math>Q \text{ кг.} = 0.491</math>  <math>D \text{ оп.мм} = 36.2</math>  <math>P \text{ н.мм} = 128.1</math>  <math>P \text{ вн.мм} = 64.0</math>  Гр. сл. = VI  Точн. = Н </p>
	<p><b>БПЗ-674</b></p> <p> <math>F \text{ см}^2 = 8.750</math>  <math>Q \text{ кг.} = 2.371</math>  <math>D \text{ оп.мм} = 128.0</math>  <math>P \text{ н.мм} = 360.0</math>  <math>P \text{ вн.мм} = 340.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-679</b></p> <p> <math>F \text{ см}^2 = 3.216</math>  <math>Q \text{ кг.} = 0.872</math>  <math>D \text{ оп.мм} = 64.2</math>  <math>P \text{ н.мм} = 285.2</math>  <math>P \text{ вн.мм} = 114.1</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-675</b></p> <p> <math>F \text{ см}^2 = 6.840</math>  <math>Q \text{ кг.} = 1.854</math>  <math>D \text{ оп.мм} = 102.0</math>  <math>P \text{ н.мм} = 240.0</math>  <math>P \text{ вн.мм} = 216.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-680</b></p> <p> <math>F \text{ см}^2 = 3.224</math>  <math>Q \text{ кг.} = 0.874</math>  <math>D \text{ оп.мм} = 64.8</math>  <math>P \text{ н.мм} = 375.5</math>  <math>P \text{ вн.мм} = 48.7</math>  Гр. сл. = VI  Точн. = П </p>




	<b>БПЗ-681</b> $F \text{ см}^2 = 2.438$ $Q \text{ кг.} = 0.661$ $D \text{ оп.мм} = 47.6$ $P \text{ н.мм} = 260.6$ $P \text{ вн.мм} = 49.9$ Гр. сл. = V Точн. = П		<b>БПЗ-0686</b> $F \text{ см}^2 = 1.567$ $Q \text{ кг.} = 0.425$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 116.5$ $P \text{ вн.мм} = 103.2$ Гр. сл. = V Точн. = П
	<b>БПЗ-682</b> $F \text{ см}^2 = 1.382$ $Q \text{ кг.} = 0.375$ $D \text{ оп.мм} = 24.0$ $P \text{ н.мм} = 75.4$ $P \text{ вн.мм} = 62.8$ Гр. сл. = III Точн. = Н		<b>БПЗ-0687</b> $F \text{ см}^2 = 1.404$ $Q \text{ кг.} = 0.380$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 100.5$ $P \text{ вн.мм} = 92.7$ Гр. сл. = V Точн. = П
	<b>БПЗ-683</b> $F \text{ см}^2 = 1.711$ $Q \text{ кг.} = 0.464$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 256.0$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-688</b> $F \text{ см}^2 = 6.425$ $Q \text{ кг.} = 1.742$ $D \text{ оп.мм} = 116.0$ $P \text{ н.мм} = 298.8$ $P \text{ вн.мм} = 467.3$ Гр. сл. = 0соб. Точн. = Н
	<b>БПЗ-684</b> $F \text{ см}^2 = 2.970$ $Q \text{ кг.} = 0.805$ $D \text{ оп.мм} = 54.1$ $P \text{ н.мм} = 154.9$ $P \text{ вн.мм} = 142.3$ Гр. сл. = VI Точн. = DIN		<b>БПЗ-689</b> $F \text{ см}^2 = 12.000$ $Q \text{ кг.} = 3.252$ $D \text{ оп.мм} = 94.3$ $P \text{ н.мм} = 260.0$ $P \text{ вн.мм} = 220.0$ Гр. сл. = III Точн. = DIN
	<b>БПЗ-685</b> $F \text{ см}^2 = 9.240$ $Q \text{ кг.} = 2.504$ $D \text{ оп.мм} = 114.0$ $P \text{ н.мм} = 361.9$ $P \text{ вн.мм} = 286.9$ Гр. сл. = VI Точн. = Н		<b>БПЗ-690</b> $F \text{ см}^2 = 3.032$ $Q \text{ кг.} = 0.822$ $D \text{ оп.мм} = 56.6$ $P \text{ н.мм} = 237.2$ $P \text{ вн.мм} = 95.2$ Гр. сл. = V Точн. = П

	<p><b>БПЗ-691</b></p> <p> <math>F \text{ см}^2 = 2.330</math>  <math>Q \text{ кг.} = 0.631</math>  <math>D \text{ оп.мм} = 51.4</math>  <math>P \text{ н.мм} = 189.0</math>  <math>P \text{ вн.мм} = 71.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-696</b></p> <p> <math>F \text{ см}^2 = 5.213</math>  <math>Q \text{ кг.} = 1.413</math>  <math>D \text{ оп.мм} = 66.0</math>  <math>P \text{ н.мм} = 145.0</math>  <math>P \text{ вн.мм} = 153.5</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-692</b></p> <p> <math>F \text{ см}^2 = 2.301</math>  <math>Q \text{ кг.} = 0.531</math>  <math>D \text{ оп.мм} = 38.7</math>  <math>P \text{ н.мм} = 165.3</math>  <math>P \text{ вн.мм} = 71.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-697</b></p> <p> <math>F \text{ см}^2 = 28.190</math>  <math>Q \text{ кг.} = 7.639</math>  <math>D \text{ оп.мм} = 110.0</math>  <math>P \text{ н.мм} = 405.7</math>  <math>P \text{ вн.мм} = 31.4</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-693</b></p> <p> <math>F \text{ см}^2 = 2.510</math>  <math>Q \text{ кг.} = 0.680</math>  <math>D \text{ оп.мм} = 53.2</math>  <math>P \text{ н.мм} = 205.8</math>  <math>P \text{ вн.мм} = 71.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-698</b></p> <p> <math>F \text{ см}^2 = 1.317</math>  <math>Q \text{ кг.} = 0.357</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 253.3</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
			<p><b>БПЗ-700</b></p> <p> <math>F \text{ см}^2 = 64.254</math>  <math>Q \text{ кг.} = 17.413</math>  <math>D \text{ оп.мм} = 113.0</math>  <math>P \text{ н.мм} = 344.3</math>  <math>P \text{ вн.мм} = 186.9</math>  Гр. сл. = 0соб.  Точн. = П </p>


	<p><b>БПЗ-701</b></p> <p> <math>F \text{ см}^2 = 57.85</math>  <math>Q \text{ кг.} = 15.68</math>  <math>D \text{ оп.мм} = 111.8</math>  <math>P \text{ н.мм} = 332.3</math>  <math>P \text{ вн.мм} = 183.1</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-706</b></p> <p> <math>F \text{ см}^2 = 6.406</math>  <math>Q \text{ кг.} = 1.736</math>  <math>D \text{ оп.мм} = 121.5</math>  <math>P \text{ н.мм} = 446.0</math>  <math>P \text{ вн.мм} = 224.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-702</b></p> <p> <math>F \text{ см}^2 = 3.905</math>  <math>Q \text{ кг.} = 1.058</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 110.4</math>  <math>P \text{ вн.мм} = 95.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		
	<p><b>БПЗ-703</b></p> <p> <math>F \text{ см}^2 = 3.210</math>  <math>Q \text{ кг.} = 0.870</math>  <math>D \text{ оп.мм} = 76.2</math>  <math>P \text{ н.мм} = 314.0</math>  <math>P \text{ вн.мм} = 114.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-708</b></p> <p> <math>F \text{ см}^2 = 3.980</math>  <math>Q \text{ кг.} = 1.079</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 112.0</math>  <math>P \text{ вн.мм} = 100.5</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-704</b></p> <p> <math>F \text{ см}^2 = 2.855</math>  <math>Q \text{ кг.} = 0.774</math>  <math>D \text{ оп.мм} = 66.1</math>  <math>P \text{ н.мм} = 265.0</math>  <math>P \text{ вн.мм} = 108.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-709</b></p> <p> <math>F \text{ см}^2 = 20.421</math>  <math>Q \text{ кг.} = 5.534</math>  <math>D \text{ оп.мм} = 75.0</math>  <math>P \text{ н.мм} = 235.6</math>  <math>P \text{ вн.мм} = 172.8</math>  Гр. сл. = I  Точн. = Н </p>
	<p><b>БПЗ-705</b></p> <p> <math>F \text{ см}^2 = 3.340</math>  <math>Q \text{ кг.} = 0.905</math>  <math>D \text{ оп.мм} = 67.0</math>  <math>P \text{ н.мм} = 327.0</math>  <math>P \text{ вн.мм} = 108.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-710</b></p> <p> <math>F \text{ см}^2 = 59.100</math>  <math>Q \text{ кг.} = 16.016</math>  <math>D \text{ оп.мм} = 105.0</math>  <math>P \text{ н.мм} = 334.2</math>  <math>P \text{ вн.мм} = 183.7</math>  Гр. сл. = 0соб.  Точн. = П </p>

БПЗ-711




$F \text{ см}^2 = 10.489$   
 $Q \text{ кг.} = 2.843$   
 $D \text{ оп.мм} = 151.0$   
 $P \text{ н.мм} = 311.0$   
 $P \text{ вн.мм} = 222.7$   
 Гр. сл. = 0соб.  
 Точн. = П

БПЗ-717












$F \text{ см}^2 = 3.884$   
 $Q \text{ кг.} = 1.053$   
 $D \text{ оп.мм} = 61.1$   
 $P \text{ н.мм} = 277.8$   
 $P \text{ вн.мм} = 127.3$   
 Гр. сл. = VI  
 Точн. = П











БПЗ-718





















$F \text{ см}^2 = 3.365$   
 $Q \text{ кг.} = 0.912$   
 $D \text{ оп.мм} = 62.5$   
 $P \text{ н.мм} = 267.7$   
 $P \text{ вн.мм} = 119.8$   
 Гр. сл. = VI  
 Точн. = П










			<p><b>БПЗ-726</b></p> <p> <math>F \text{ см}^2 = 2.687</math>  <math>Q \text{ кг.} = 0.728</math>  <math>D \text{ оп.мм} = 38.3</math>  <math>P \text{ н.мм} = 262.8</math>  <math>P \text{ вн.мм} = 48.0</math>  Гр. сл. = III  Точн. = П </p>
			<p><b>БПЗ-727</b></p> <p> <math>F \text{ см}^2 = 6.942</math>  <math>Q \text{ кг.} = 1.881</math>  <math>D \text{ оп.мм} = 180.8</math>  <math>P \text{ н.мм} = 596.0</math>  <math>P \text{ вн.мм} = 164.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
			<p><b>БПЗ-728</b></p> <p> <math>F \text{ см}^2 = 3.060</math>  <math>Q \text{ кг.} = 0.829</math>  <math>D \text{ оп.мм} = 45.3</math>  <math>P \text{ н.мм} = 242.0</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-724</b></p> <p> <math>F \text{ см}^2 = 2.021</math>  <math>Q \text{ кг.} = 0.548</math>  <math>D \text{ оп.мм} = 46.6</math>  <math>P \text{ н.мм} = 178.0</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = III  Точн. = П </p>		
	<p><b>БПЗ-725</b></p> <p> <math>F \text{ см}^2 = 2.171</math>  <math>Q \text{ кг.} = 0.588</math>  <math>D \text{ оп.мм} = 46.6</math>  <math>P \text{ н.мм} = 198.0</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = III  Точн. = П </p>		











	<b>БПЗ-731</b> $F \text{ см}^2 = 405.5$ $Q \text{ кг.} = 109.89$ $D \text{ оп.мм} = 79.0$ $P \text{ н.мм} = 246.4$ $P \text{ вн.мм} = 234.7$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-736</b> $F \text{ см}^2 = 2.600$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм} = 42.3$ $P \text{ н.мм} = 205.6$ $P \text{ вн.мм} = 91.4$ Гр. сл. = V Точн. = Н
	<b>БПЗ-732</b> $F \text{ см}^2 = 3.789$ $Q \text{ кг.} = 1.027$ $D \text{ оп.мм} = 59.9$ $P \text{ н.мм} = 210.8$ $P \text{ вн.мм} = 240.4$ Гр. сл. = 0соб. Точн. = 0соб.		<b>БПЗ-737</b> $F \text{ см}^2 = 2.509$ $Q \text{ кг.} = 0.680$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 200.4$ $P \text{ вн.мм} = 85.6$ Гр. сл. = VI Точн. = П
	<b>БПЗ-733</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ $P \text{ вн.мм} = 0$ Гр. сл. = 0соб. Точн. = 0соб.		<b>БПЗ-738</b> $F \text{ см}^2 = 3.490$ $Q \text{ кг.} = 0.946$ $D \text{ оп.мм} = 63.1$ $P \text{ н.мм} = 267.8$ $P \text{ вн.мм} = 112.3$ Гр. сл. = V Точн. = Н
	<b>БПЗ-734</b> $F \text{ см}^2 = 3.267$ $Q \text{ кг.} = 0.885$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 169.7$ $P \text{ вн.мм} = 157.1$ Гр. сл. = V Точн. = DIN		<b>БПЗ-739</b> $F \text{ см}^2 = 3.440$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 180.0$ $P \text{ вн.мм} = 164.0$ Гр. сл. = VI Точн. = DIN
	<b>БПЗ-735</b> $F \text{ см}^2 = 4.524$ $Q \text{ кг.} = 1.226$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 125.7$ $P \text{ вн.мм} = 100.5$ Гр. сл. = II Точн. = DIN		<b>БПЗ-740</b> $F \text{ см}^2 = 2.795$ $Q \text{ кг.} = 0.757$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 245.2$ $P \text{ вн.мм} = 37.7$ Гр. сл. = 0соб. Точн. = П










	<p><b>БПЗ-741</b></p> <p> <math>F \text{ см}^2 = 3.961</math>  <math>Q \text{ кг.} = 1.073</math>  <math>D \text{ оп.мм} = 78.1</math>  <math>P \text{ н.мм} = 356.0</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-746</b></p> <p> <math>F \text{ см}^2 = 1.599</math>  <math>Q \text{ кг.} = 0.433</math>  <math>D \text{ оп.мм} = 46.0</math>  <math>P \text{ н.мм} = 118.7</math>  <math>P \text{ вн.мм} = 82.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-742</b></p> <p> <math>F \text{ см}^2 = 4.840</math>  <math>Q \text{ кг.} = 1.312</math>  <math>D \text{ оп.мм} = 103.0</math>  <math>P \text{ н.мм} = 250.0</math>  <math>P \text{ вн.мм} = 234.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>		<p><b>БПЗ-747</b></p> <p> <math>F \text{ см}^2 = 1.380</math>  <math>Q \text{ кг.} = 0.374</math>  <math>D \text{ оп.мм} = 38.4</math>  <math>P \text{ н.мм} = 106.7</math>  <math>P \text{ вн.мм} = 68.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-743</b></p> <p> <math>F \text{ см}^2 = 6.267</math>  <math>Q \text{ кг.} = 1.698</math>  <math>D \text{ оп.мм} = 61.0</math>  <math>P \text{ н.мм} = 190.0</math>  <math>P \text{ вн.мм} = 168.0</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-748</b></p> <p> <math>F \text{ см}^2 = 1.321</math>  <math>Q \text{ кг.} = 0.358</math>  <math>D \text{ оп.мм} = 34.1</math>  <math>P \text{ н.мм} = 94.0</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = III  Точн. = П </p>
			<p><b>БПЗ-749</b></p> <p> <math>F \text{ см}^2 = 4.385</math>  <math>Q \text{ кг.} = 1.188</math>  <math>D \text{ оп.мм} = 48.7</math>  <math>P \text{ н.мм} = 414.7</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-745</b></p> <p> <math>F \text{ см}^2 = 6.660</math>  <math>Q \text{ кг.} = 1.805</math>  <math>D \text{ оп.мм} = 80.7</math>  <math>P \text{ н.мм} = 231.4</math>  <math>P \text{ вн.мм} = 212.6</math>  Гр. сл. = V  Точн. = DIN </p>		<p><b>БПЗ-750</b></p> <p> <math>F \text{ см}^2 = 3.617</math>  <math>Q \text{ кг.} = 0.980</math>  <math>D \text{ оп.мм} = 66.0</math>  <math>P \text{ н.мм} = 354.6</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>











	<p><b>БПЗ-751</b></p> <p> <math>F \text{ см}^2 = 6.032</math>  <math>Q \text{ кг.} = 1.635</math>  <math>D \text{ оп.мм} = 38.0</math>  <math>P \text{ н.мм} = 119.4</math>  <math>P \text{ вн.мм} = 81.7</math>  Гр. сл. = I  Точн. = Н </p>		<p><b>БПЗ-756</b></p> <p> <math>F \text{ см}^2 = 2.820</math>  <math>Q \text{ кг.} = 0.764</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 127.0</math>  <math>P \text{ вн.мм} = 97.4</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-752</b></p> <p> <math>F \text{ см}^2 = 4.260</math>  <math>Q \text{ кг.} = 1.154</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 55.9</math>  <math>P \text{ вн.мм} = 88.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-757</b></p> <p> <math>F \text{ см}^2 = 14.744</math>  <math>Q \text{ кг.} = 3.996</math>  <math>D \text{ оп.мм} = 53.9</math>  <math>P \text{ н.мм} = 152.8</math>  <math>P \text{ вн.мм} = 44.0</math>  Гр. сл. = I  Точн. = Н </p>
	<p><b>БПЗ-753</b></p> <p> <math>F \text{ см}^2 = 10.170</math>  <math>Q \text{ кг.} = 2.756</math>  <math>D \text{ оп.мм} = 48.9</math>  <math>P \text{ н.мм} = 141.6</math>  <math>P \text{ вн.мм} = 77.0</math>  Гр. сл. = II  Точн. = Н </p>		<p><b>БПЗ-758</b></p> <p> <math>F \text{ см}^2 = 2.010</math>  <math>Q \text{ кг.} = 0.545</math>  <math>D \text{ оп.мм} = 53.9</math>  <math>P \text{ н.мм} = 140.0</math>  <math>P \text{ вн.мм} = 128.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>
	<p><b>БПЗ-754</b></p> <p> <math>F \text{ см}^2 = 6.080</math>  <math>Q \text{ кг.} = 1.648</math>  <math>D \text{ оп.мм} = 39.0</math>  <math>P \text{ н.мм} = 120.3</math>  <math>P \text{ вн.мм} = 62.8</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-759</b></p> <p> <math>F \text{ см}^2 = 6.110</math>  <math>Q \text{ кг.} = 1.656</math>  <math>D \text{ оп.мм} = 88.7</math>  <math>P \text{ н.мм} = 313.0</math>  <math>P \text{ вн.мм} = 215.8</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-755</b></p> <p> <math>F \text{ см}^2 = 14.500</math>  <math>Q \text{ кг.} = 3.930</math>  <math>D \text{ оп.мм} = 125.0</math>  <math>P \text{ н.мм} = 485.3</math>  <math>P \text{ вн.мм} = 94.3</math>  Гр. сл. = V  Точн. = П </p>		























			<b>БПЗ-766</b> $F \text{ см}^2 = 2.373$ $Q \text{ кг.} = 0.643$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 223.3$ $P \text{ вн.мм} = 83.0$ $\Gamma \text{р. сл.} = 0 \text{соб.}$ $\text{Точн.} = \Pi$
	<b>БПЗ-762</b> $F \text{ см}^2 = 2.700$ $Q \text{ кг.} = 0.732$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 141.4$ $P \text{ вн.мм} = 121.8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} =$		<b>БПЗ-767</b> $F \text{ см}^2 = 2.744$ $Q \text{ кг.} = 0.744$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 186.7$ $P \text{ вн.мм} = 147.0$ $\Gamma \text{р. сл.} = 0 \text{соб.}$ $\text{Точн.} = \Pi$
	<b>БПЗ-763</b> $F \text{ см}^2 = 2.515$ $Q \text{ кг.} = 0.682$ $D \text{ оп.мм} = 58.9$ $P \text{ н.мм} = 215.8$ $P \text{ вн.мм} = 114.0$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \Pi$		
	<b>БПЗ-764</b> $F \text{ см}^2 = 2.048$ $Q \text{ кг.} = 0.555$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 109.9$ $P \text{ вн.мм} = 99.1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \Pi$		
	<b>БПЗ-765</b> $F \text{ см}^2 = 2.520$ $Q \text{ кг.} = 0.683$ $D \text{ оп.мм} = 56.3$ $P \text{ н.мм} = 225.3$ $P \text{ вн.мм} = 112.0$ $\Gamma \text{р. сл.} = 5$ $\text{Точн.} = \Pi$		<b>БПЗ-770</b> $F \text{ см}^2 = 4.680$ $Q \text{ кг.} = 1.268$ $D \text{ оп.мм} = 63.0$ $P \text{ н.мм} = 257.8$ $P \text{ вн.мм} = 149.0$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \Pi$










	<p><b>БПЗ-771</b></p> <p> <math>F \text{ см}^2 = 3.259</math>  <math>Q \text{ кг.} = 0.883</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 111.8</math>  <math>P \text{ вн.мм} = 105.8</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-776</b></p> <p> <math>F \text{ см}^2 = 7.232</math>  <math>Q \text{ кг.} = 1.960</math>  <math>D \text{ оп.мм} = 108.0</math>  <math>P \text{ н.мм} = 454.0</math>  <math>P \text{ вн.мм} = 273.0</math>  Гр. сл. = VI  Точн. = П </p>
			<p><b>БПЗ-777</b></p> <p> <math>F \text{ см}^2 = 9.458</math>  <math>Q \text{ кг.} = 2.563</math>  <math>D \text{ оп.мм} = 78</math>  <math>P \text{ н.мм} = 321.0</math>  <math>P \text{ вн.мм} = 297.6</math>  Гр. сл. = VI  Точн. = П </p>
			<p><b>БПЗ-778</b></p> <p> <math>F \text{ см}^2 = 2.342</math>  <math>Q \text{ кг.} = 0.635</math>  <math>D \text{ оп.мм} = 68.1</math>  <math>P \text{ н.мм} = 167.9</math>  <math>P \text{ вн.мм} = 164.8</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-774</b></p> <p> <math>F \text{ см}^2 = 11.370</math>  <math>Q \text{ кг.} = 3.081</math>  <math>D \text{ оп.мм} = 165.0</math>  <math>P \text{ н.мм} = 420.0</math>  <math>P \text{ вн.мм} = 658.3</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-779</b></p> <p> <math>F \text{ см}^2 = 18.940</math>  <math>Q \text{ кг.} = 5.133</math>  <math>D \text{ оп.мм} = 81.5</math>  <math>P \text{ н.мм} = 441.7</math>  <math>P \text{ вн.мм} = 207.0</math>  Гр. сл. = 0соб.  Точн. = Н </p>
	<p><b>БПЗ-775</b></p> <p> <math>F \text{ см}^2 = 3.940</math>  <math>Q \text{ кг.} = 1.07</math>  <math>D \text{ оп.мм} = 67.0</math>  <math>P \text{ н.мм} = 291.3</math>  <math>P \text{ вн.мм} = 171.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-780</b></p> <p> <math>F \text{ см}^2 = 1.742</math>  <math>Q \text{ кг.} = 0.472</math>  <math>D \text{ оп.мм} = 56.0</math>  <math>P \text{ н.мм} = 150.0</math>  <math>P \text{ вн.мм} = 140.0</math>  Гр. сл. = 0соб.  Точн. = DIN </p>











			<b>БПЗ-786</b> $F \text{ см}^2 = 44.070$ $Q \text{ кг.} = 11.943$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 323.5$ $P \text{ вн.мм} = 187.9$ Гр. сл. = V Точн. = П
	<b>БПЗ-782</b> $F \text{ см}^2 = 3.200$ $Q \text{ кг.} = 0.867$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 247.0$ $P \text{ вн.мм} = 128.0$ Гр. сл. = VI Точн. = П		<b>БПЗ-787</b> $F \text{ см}^2 = 9.000$ $Q \text{ кг.} = 2.439$ $D \text{ оп.мм} = 71.0$ $P \text{ н.мм} = 200.0$ $P \text{ вн.мм} = 160.0$ Гр. сл. = III Точн. = DIN
	<b>БПЗ-783</b> $F \text{ см}^2 = 2.620$ $Q \text{ кг.} = 0.710$ $D \text{ оп.мм} = 59.3$ $P \text{ н.мм} = 177.0$ $P \text{ вн.мм} = 134.0$ Гр. сл. = V Точн. = П		<b>БПЗ-788</b> $F \text{ см}^2 = 0,400$ $Q \text{ кг.} = 0.108$ $D \text{ оп.мм} = 10.0$ $P \text{ н.мм} = 31,4$ $P \text{ вн.мм} = 22$ Гр. сл. = V Точн. = П
	<b>БПЗ-784</b> $F \text{ см}^2 = 3.260$ $Q \text{ кг.} = 0.883$ $D \text{ оп.мм} = 62.5$ $P \text{ н.мм} = 205.0$ $P \text{ вн.мм} = 164.0$ Гр. сл. = V Точн. = П		<b>БПЗ-789</b> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.084$ $D \text{ оп.мм} = 22.7$ $P \text{ н.мм} = 142.6$ $P \text{ вн.мм} = 123.8$ Гр. сл. = VI Точн. = П
	<b>БПЗ-785</b> $F \text{ см}^2 = 1.710$ $Q \text{ кг.} = 0.463$ $D \text{ оп.мм} = 20.0$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 42.4$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-790</b> $F \text{ см}^2 = 4.620$ $Q \text{ кг.} = 1.252$ $D \text{ оп.мм} = 26$ $P \text{ н.мм} = 163.4$ $P \text{ вн.мм} = 144.5$ Гр. сл. = VI Точн. = П

	<b>БПЗ-791</b> $F \text{ см}^2 = 8.300$ $Q \text{ кг.} = 2.249$ $D \text{ оп.мм} = 168$ $P \text{ н.мм} = 434.2$ $P \text{ вн.мм} = 338.2$ Гр. сл. = 0соб. Точн. = Н		<b>БПЗ-796</b> $F \text{ см}^2 = 2.492$ $Q \text{ кг.} = 0.675$ $D \text{ оп.мм} = 38.3$ $P \text{ н.мм} = 199.3$ $P \text{ вн.мм} = 37.7$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-792</b> $F \text{ см}^2 = 8.648$ $Q \text{ кг.} = 2.344$ $D \text{ оп.мм} = 173$ $P \text{ н.мм} = 418.2$ $P \text{ вн.мм} = 394.1$ Гр. сл. = 0соб. Точн. = Н		<b>БПЗ-797</b> $F \text{ см}^2 = 2.352$ $Q \text{ кг.} = 0.638$ $D \text{ оп.мм} = 38.3$ $P \text{ н.мм} = 185.7$ $P \text{ вн.мм} = 37.7$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-793</b> $F \text{ см}^2 = 9.055$ $Q \text{ кг.} = 2.454$ $D \text{ оп.мм} = 181.4$ $P \text{ н.мм} = 497.6$ $P \text{ вн.мм} = 331.1$ Гр. сл. = 0соб. Точн. = Н		<b>БПЗ-798</b> $F \text{ см}^2 = 8.389$ $Q \text{ кг.} = 2.273$ $D \text{ оп.мм} = 69$ $P \text{ н.мм} = 262.6$ $P \text{ вн.мм} = 140.6$ Гр. сл. = IV Точн. = Н
	<b>БПЗ-794</b> $F \text{ см}^2 = 1.671$ $Q \text{ кг.} = 0.453$ $D \text{ оп.мм} = 40.2$ $P \text{ н.мм} = 136.0$ $P \text{ вн.мм} = 82$ Гр. сл. = III Точн. = П		<b>БПЗ-799</b> $F \text{ см}^2 = 2.287$ $Q \text{ кг.} = 0.620$ $D \text{ оп.мм} = 60.7$ $P \text{ н.мм} = 161.1$ $P \text{ вн.мм} = 112.6$ Гр. сл. = IV Точн. = П
	<b>БПЗ-795</b> $F \text{ см}^2 = 2.143$ $Q \text{ кг.} = 0.581$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 150.1$ $P \text{ вн.мм} = 37.7$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-800</b> $F \text{ см}^2 = 5.040$ $Q \text{ кг.} = 1.366$ $D \text{ оп.мм} = 95.0$ $P \text{ н.мм} = 260.0$ $P \text{ вн.мм} = 244.0$ Гр. сл. = 0соб. Точн. = Н









	<b>БПЗ-811</b> $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 50.7$ $P \text{ н.мм} = 194.3$ $P \text{ вн.мм} = 59.6$ Гр. сл. = V Точн. = Н		<b>БПЗ-816</b> $F \text{ см}^2 = 2.66$ $Q \text{ кг.} = 0.728$ $D \text{ оп.мм} = 39.1$ $P \text{ н.мм} = 147.9$ $P \text{ вн.мм} = 78.9$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-812</b> $F \text{ см}^2 = 2.560$ $Q \text{ кг.} = 0.694$ $D \text{ оп.мм} = 44.8$ $P \text{ н.мм} = 188.7$ $P \text{ вн.мм} = 92.0$ Гр. сл. = IV Точн. = Н		<b>БПЗ-817</b> $F \text{ см}^2 = 4.056$ $Q \text{ кг.} = 1.099$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 148.6$ $P \text{ вн.мм} = 88$ Гр. сл. = III Точн. = П
	<b>БПЗ-813</b> $F \text{ см}^2 = 2.280$ $Q \text{ кг.} = 0.618$ $D \text{ оп.мм} = 51.9$ $P \text{ н.мм} = 188.5$ $P \text{ вн.мм} = 76.2$ Гр. сл. = V Точн. = Н		<b>БПЗ-818</b> $F \text{ см}^2 = 2.534$ $Q \text{ кг.} = 0.687$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 118.2$ $P \text{ вн.мм} = 100.7$ Гр. сл. = V Точн. = П
	<b>БПЗ-814</b> $F \text{ см}^2 = 2.840$ $Q \text{ кг.} = 0.770$ $D \text{ оп.мм} = 44.8$ $P \text{ н.мм} = 215.4$ $P \text{ вн.мм} = 94.5$ Гр. сл. = IV Точн. = Н		<b>БПЗ-819</b> $F \text{ см}^2 = 2.179$ $Q \text{ кг.} = 0.591$ $D \text{ оп.мм} = 32.5$ $P \text{ н.мм} = 121.5$ $P \text{ вн.мм} = 86.4$ Гр. сл. = IV Точн. = П
	<b>БПЗ-815</b> $F \text{ см}^2 = 2.440$ $Q \text{ кг.} = 0.661$ $D \text{ оп.мм} = 66.1$ $P \text{ н.мм} = 232.4$ $P \text{ вн.мм} = 59.6$ Гр. сл. = V Точн. = Н		<b>БПЗ-820</b> $F \text{ см}^2 = 5.869$ $Q \text{ кг.} = 1.590$ $D \text{ оп.мм} = 87$ $P \text{ н.мм} = 207.1$ $P \text{ вн.мм} = 129.6$ Гр. сл. = V Точн. = П











	<p><b>БПЗ-821</b></p> <p> <math>F \text{ см}^2 = 4.106</math>  <math>Q \text{ кг.} = 1.113</math>  <math>D \text{ оп.мм} = 63</math>  <math>P \text{ н.мм} = 231</math>  <math>P \text{ вн.мм} = 69.6</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-826</b></p> <p> <math>F \text{ см}^2 = 5.313</math>  <math>Q \text{ кг.} = 1.440</math>  <math>D \text{ оп.мм} = 48.3</math>  <math>P \text{ н.мм} = 151.7</math>  <math>P \text{ вн.мм} = 127.9</math>  Гр. сл. = II  Точн. = П </p>
	<p><b>БПЗ-822</b></p> <p> <math>F \text{ см}^2 = 2.629</math>  <math>Q \text{ кг.} = 0.712</math>  <math>D \text{ оп.мм} = 40</math>  <math>P \text{ н.мм} = 129.5</math>  <math>P \text{ вн.мм} = 101.8</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-827</b></p> <p> <math>F \text{ см}^2 = 4.241</math>  <math>Q \text{ кг.} = 1.149</math>  <math>D \text{ оп.мм} = 48</math>  <math>P \text{ н.мм} = 150.8</math>  <math>P \text{ вн.мм} = 132</math>  Гр. сл. = II  Точн. = П </p>
	<p><b>БПЗ-823</b></p> <p> <math>F \text{ см}^2 = 6.395</math>  <math>Q \text{ кг.} = 1.733</math>  <math>D \text{ оп.мм} = 79</math>  <math>P \text{ н.мм} = 440.1</math>  <math>P \text{ вн.мм} = 57</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-828</b></p> <p> <math>F \text{ см}^2 = 2.875</math>  <math>Q \text{ кг.} = 0.779</math>  <math>D \text{ оп.мм} = 33.5</math>  <math>P \text{ н.мм} = 105.2</math>  <math>P \text{ вн.мм} = 86.4</math>  Гр. сл. = II  Точн. = П </p>
	<p><b>БПЗ-824</b></p> <p> <math>F \text{ см}^2 = 4.709</math>  <math>Q \text{ кг.} = 1.276</math>  <math>D \text{ оп.мм} = 84</math>  <math>P \text{ н.мм} = 281.1</math>  <math>P \text{ вн.мм} = 202.2</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-829</b></p> <p> <math>F \text{ см}^2 = 2.240</math>  <math>Q \text{ кг.} = 0.607</math>  <math>D \text{ оп.мм} = 45</math>  <math>P \text{ н.мм} = 120</math>  <math>P \text{ вн.мм} = 104</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-825</b></p> <p> <math>F \text{ см}^2 = 5.835</math>  <math>Q \text{ кг.} = 1.581</math>  <math>D \text{ оп.мм} = 161</math>  <math>P \text{ н.мм} = 371.3</math>  <math>P \text{ вн.мм} = 171.3</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-830</b></p> <p> <math>F \text{ см}^2 = 2.750</math>  <math>Q \text{ кг.} = 0.745</math>  <math>D \text{ оп.мм} = 45</math>  <math>P \text{ н.мм} = 120</math>  <math>P \text{ вн.мм} = 100</math>  Гр. сл. = VI  Точн. = П </p>











	<b>БПЗ-831</b> $F \text{ см}^2 = 1.9$ $Q \text{ кг.} = 0.515$ $D \text{ оп.мм} = 70.01$ $P \text{ н.мм} = 199.2$ $P \text{ вн.мм} = 49.8$ Гр. сл. = IV Точн. = Н		<b>БПЗ-836</b> $F \text{ см}^2 = 3.372$ $Q \text{ кг.} = 0.914$ $D \text{ оп.мм} = 61.2$ $P \text{ н.мм} = 174.9$ $P \text{ вн.мм} = 162.3$ Гр. сл. = VI Точн. = DIN
	<b>БПЗ-832</b> $F \text{ см}^2 = 1.790$ $Q \text{ кг.} = 0.485$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 69.1$ $P \text{ вн.мм} = 50.3$ Гр. сл. = II Точн. = Н		<b>БПЗ-837</b> $F \text{ см}^2 = 3.237$ $Q \text{ кг.} = 0.877$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 109.6$ $P \text{ вн.мм} = 105.8$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-833</b> $F \text{ см}^2 = 2.433$ $Q \text{ кг.} = 0.659$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157.1$ $P \text{ вн.мм} = 147$ Гр. сл. = V Точн. = П		<b>БПЗ-838</b> $F \text{ см}^2 = 6.378$ $Q \text{ кг.} = 1.728$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 193.2$ $P \text{ вн.мм} = 171.2$ Гр. сл. = IV Точн. = Н
	<b>БПЗ-834</b> $F \text{ см}^2 = 0.859$ $Q \text{ кг.} = 0.233$ $D \text{ оп.мм} = 17$ $P \text{ н.мм} = 53.4$ $P \text{ вн.мм} = 42.1$ Гр. сл. = VI Точн. = П		<b>БПЗ-839</b> $F \text{ см}^2 = 0.775$ $Q \text{ кг.} = 0.210$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 92.2$ $P \text{ вн.мм} = 10.1$ Гр. сл. = V Точн. = П
	<b>БПЗ-835</b> $F \text{ см}^2 = 4.269$ $Q \text{ кг.} = 1.157$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78.5$ $P \text{ вн.мм} = 32$ Гр. сл. = IV Точн. = П		<b>БПЗ-840</b> $F \text{ см}^2 = 7.270$ $Q \text{ кг.} = 1.970$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 125.7$ $P \text{ вн.мм} = 81.7$ Гр. сл. = II Точн. = П









	<b>БПЗ-841</b> $F \text{ см}^2 = 1.616$ $Q \text{ кг.} = 0.438$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 159$ $P \text{ вн.мм} = 54.8$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-846</b> $F \text{ см}^2 = 1.890$ $Q \text{ кг.} = 0.590$ $D \text{ оп.мм} = 46.4$ $P \text{ н.мм} = 215.5$ $P \text{ вн.мм} = 57.2$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-842</b> $F \text{ см}^2 = 9.137$ $Q \text{ кг.} = 2.476$ $D \text{ оп.мм} = 86.6$ $P \text{ н.мм} = 272.1$ $P \text{ вн.мм} = 250.1$ Гр. сл. = V Точн. = П		<b>БПЗ-847</b> $F \text{ см}^2 = 1.328$ $Q \text{ кг.} = 0.360$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 134$ $P \text{ вн.мм} = 43$ Гр. сл. = VI Точн. = П
	<b>БПЗ-843</b> $F \text{ см}^2 = 4.033$ $Q \text{ кг.} = 1.093$ $D \text{ оп.мм} = 75.8$ $P \text{ н.мм} = 283$ $P \text{ вн.мм} = 170$ Гр. сл. = V Точн. = П		<b>БПЗ-848</b> $F \text{ см}^2 = 1.592$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм} = 45.9$ $P \text{ н.мм} = 192.2$ $P \text{ вн.мм} = 73.0$ Гр. сл. = VI Точн. = П
	<b>БПЗ-844</b> $F \text{ см}^2 = 2.837$ $Q \text{ кг.} = 0.770$ $D \text{ оп.мм} = 51.5$ $P \text{ н.мм} = 282.8$ $P \text{ вн.мм} = 91.7$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-849</b> $F \text{ см}^2 = 1.650$ $Q \text{ кг.} = 0.447$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 141.8$ $P \text{ вн.мм} = 73.5$ Гр. сл. = VI Точн. = П
	<b>БПЗ-845</b> $F \text{ см}^2 = 1.590$ $Q \text{ кг.} = 0,431$ $D \text{ оп.мм} = 37.2$ $P \text{ н.мм} = 155.6$ $P \text{ вн.мм} = 54.3$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-850</b> $F \text{ см}^2 = 9.024$ $Q \text{ кг.} = 2.446$ $D \text{ оп.мм} = 147.0$ $P \text{ н.мм} = 538.6$ $P \text{ вн.мм} = 355.2$ Гр. сл. = VI Точн. = П






















	<b>БПЗ-851</b> $F \text{ см}^2 = 11.920$ $Q \text{ кг.} = 3.23$ $D \text{ оп.мм} = 114$ $P \text{ н.мм} = 402.4$ $P \text{ вн.мм} = 379,6$ Гр. сл. = VI Точн. = П		
	<b>БПЗ-852</b> $F \text{ см}^2 = 3.909$ $Q \text{ кг.} = 1.059$ $D \text{ оп.мм} = 69.3$ $P \text{ н.мм} = 275.6$ $P \text{ вн.мм} = 153.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-857</b> $F \text{ см}^2 = 3.386$ $Q \text{ кг.} = 0.918$ $D \text{ оп.мм} = 66.4$ $P \text{ н.мм} = 254$ $P \text{ вн.мм} = 126$ Гр. сл. = V Точн. = П
	<b>БПЗ-853</b> $F \text{ см}^2 = 4.730$ $Q \text{ кг.} = 1.28$ $D \text{ оп.мм} = 69.6$ $P \text{ н.мм} = 338.1$ $P \text{ вн.мм} = 161.6$ Гр. сл. = VI Точн. = П		<b>БПЗ-858</b> $F \text{ см}^2 = 3.201$ $Q \text{ кг.} = 0.867$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 261$ $P \text{ вн.мм} = 137$ Гр. сл. = V Точн. = П
	<b>БПЗ-854</b> $F \text{ см}^2 = 5.240$ $Q \text{ кг.} = 1.420$ $D \text{ оп.мм} = 62.2$ $P \text{ н.мм} = 392.1$ $P \text{ вн.мм} = 161.6$ Гр. сл. = VI Точн. = П		<b>БПЗ-859</b> $F \text{ см}^2 = 3.920$ $Q \text{ кг.} = 1.061$ $D \text{ оп.мм} = 70$ $P \text{ н.мм} = 336$ $P \text{ вн.мм} = 115$ Гр. сл. = V Точн. = П
	<b>БПЗ-855</b> $F \text{ см}^2 = 3.980$ $Q \text{ кг.} = 1.070$ $D \text{ оп.мм} = 62.1$ $P \text{ н.мм} = 267.4$ $P \text{ вн.мм} = 141.3$ Гр. сл. = VI Точн. = П		











	<p><b>БПЗ-861</b></p> <p> <math>F \text{ см}^2 = 3.867</math>  <math>Q \text{ кг.} = 1.048</math>  <math>D \text{ оп.мм} = 85</math>  <math>P \text{ н.мм} = 270.2</math>  <math>P \text{ вн.мм} = 191.3</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-866-1</b></p> <p> <math>F \text{ см}^2 = 3.867</math>  <math>Q \text{ кг.} = 1.048</math>  <math>D \text{ оп.мм} = 85</math>  <math>P \text{ н.мм} = 270.2</math>  <math>P \text{ вн.мм} = 191.3</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-862</b></p> <p> <math>F \text{ см}^2 = 8.84</math>  <math>Q \text{ кг.} = 2.396</math>  <math>D \text{ оп.мм} = 85.3</math>  <math>P \text{ н.мм} = 304</math>  <math>P \text{ вн.мм} = 239.8</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-867</b></p> <p> <math>F \text{ см}^2 = 22.38</math>  <math>Q \text{ кг.} = 6.065</math>  <math>D \text{ оп.мм} = 57</math>  <math>P \text{ н.мм} = 179.1</math>  <math>P \text{ вн.мм} = 62.8</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-863</b></p> <p> <math>F \text{ см}^2 = 1.414</math>  <math>Q \text{ кг.} = 0.383</math>  <math>D \text{ оп.мм} = 18</math>  <math>P \text{ н.мм} = 56.6</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-868</b></p> <p> <math>F \text{ см}^2 = 18.09</math>  <math>Q \text{ кг.} = 4.902</math>  <math>D \text{ оп.мм} = 52</math>  <math>P \text{ н.мм} = 163.4</math>  <math>P \text{ вн.мм} = 62.8</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-864</b></p> <p> <math>F \text{ см}^2 = 0.346</math>  <math>Q \text{ кг.} = 0.094</math>  <math>D \text{ оп.мм} = 12</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ вн.мм} = 31.4</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-869</b></p> <p> <math>F \text{ см}^2 = 0.352</math>  <math>Q \text{ кг.} = 0.095</math>  <math>D \text{ оп.мм} = 32</math>  <math>P \text{ н.мм} = 100.5</math>  <math>P \text{ вн.мм} = 75.4</math>  Гр. сл. = II  Точн. = Н </p>
	<p><b>БПЗ-865</b></p> <p> <math>F \text{ см}^2 = 2.33</math>  <math>Q \text{ кг.} = 0.631</math>  <math>D \text{ оп.мм} = 42.3</math>  <math>P \text{ н.мм} = 170.6</math>  <math>P \text{ вн.мм} = 131.1</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-870</b></p> <p> <math>F \text{ см}^2 = 4.219</math>  <math>Q \text{ кг.} = 1.119</math>  <math>D \text{ оп.мм} = 66</math>  <math>P \text{ н.мм} = 235.5</math>  <math>P \text{ вн.мм} = 160.6</math>  Гр. сл. = V  Точн. = Н </p>










	<p><b>БПЗ-871</b></p> <p> <math>F \text{ см}^2 = 1.482</math>  <math>Q \text{ кг.} = 0.402</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 87.9</math>  <math>P \text{ вн.мм} = 76.6</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-876</b></p> <p> <math>F \text{ см}^2 = 3.00</math>  <math>Q \text{ кг.} = 0.813</math>  <math>D \text{ оп.мм} = 76.1</math>  <math>P \text{ н.мм} = 290</math>  <math>P \text{ вн.мм} = 60</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-872</b></p> <p> <math>F \text{ см}^2 = 2.212</math>  <math>Q \text{ кг.} = 0.599</math>  <math>D \text{ оп.мм} = 52</math>  <math>P \text{ н.мм} = 187</math>  <math>P \text{ вн.мм} = 59</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-877</b></p> <p> <math>F \text{ см}^2 = 3.14</math>  <math>Q \text{ кг.} = 0.851</math>  <math>D \text{ оп.мм} = 55</math>  <math>P \text{ н.мм} = 212</math>  <math>P \text{ вн.мм} = 109</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-873</b></p> <p> <math>F \text{ см}^2 = 3.029</math>  <math>Q \text{ кг.} = 0.821</math>  <math>D \text{ оп.мм} = 58</math>  <math>P \text{ н.мм} = 241</math>  <math>P \text{ вн.мм} = 92</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-878</b></p> <p> <math>F \text{ см}^2 = 5.42</math>  <math>Q \text{ кг.} = 1.470</math>  <math>D \text{ оп.мм} = 96</math>  <math>P \text{ н.мм} = 361</math>  <math>P \text{ вн.мм} = 217</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-874</b></p> <p> <math>F \text{ см}^2 = 2.487</math>  <math>Q \text{ кг.} = 0.674</math>  <math>D \text{ оп.мм} = 55</math>  <math>P \text{ н.мм} = 223</math>  <math>P \text{ вн.мм} = 60</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-879</b></p> <p> <math>F \text{ см}^2 = 7.70</math>  <math>Q \text{ кг.} = 2.087</math>  <math>D \text{ оп.мм} = 96</math>  <math>P \text{ н.мм} = 400</math>  <math>P \text{ вн.мм} = 251</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-875</b></p> <p> <math>F \text{ см}^2 = 2.27</math>  <math>Q \text{ кг.} = 0.616</math>  <math>D \text{ оп.мм} = 37</math>  <math>P \text{ н.мм} = 172</math>  <math>P \text{ вн.мм} = 69</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-880</b></p> <p> <math>F \text{ см}^2 = 10.20</math>  <math>Q \text{ кг.} = 2.838</math>  <math>D \text{ оп.мм} = 119</math>  <math>P \text{ н.мм} = 500</math>  <math>P \text{ вн.мм} = 351</math>  Гр. сл. = VI  Точн. = П </p>

	<b>БПЗ-881</b> $F \text{ см}^2 = 4.96$ $Q \text{ кг.} = 1.34$ $D \text{ оп.мм} = 76.8$ $P \text{ н.мм} = 299$ $P \text{ вн.мм} = 217$ Гр. сл. = VI Точн. = II		<b>БПЗ-886</b> $F \text{ см}^2 = 2.53$ $Q \text{ кг.} = 0.684$ $D \text{ оп.мм} = 52.5$ $P \text{ н.мм} = 207.9$ $P \text{ вн.мм} = 104.5$ Гр. сл. = VI Точн. = II
	<b>БПЗ-882</b> $F \text{ см}^2 = 7.22$ $Q \text{ кг.} = 1.96$ $D \text{ оп.мм} = 84.3$ $P \text{ н.мм} = 336$ $P \text{ вн.мм} = 251$ Гр. сл. = VI Точн. = II		<b>БПЗ-887</b> $F \text{ см}^2 = 1.50$ $Q \text{ кг.} = 0.407$ $D \text{ оп.мм} = 44$ $P \text{ н.мм} = 161.5$ $P \text{ вн.мм} = 69.4$ Гр. сл. = 0соб. Точн. = DIN
	<b>БПЗ-883</b> $F \text{ см}^2 = 9.71$ $Q \text{ кг.} = 2.63$ $D \text{ оп.мм} = 117.5$ $P \text{ н.мм} = 438$ $P \text{ вн.мм} = 351$ Гр. сл. = VI Точн. = II		<b>БПЗ-888</b> $F \text{ см}^2 = 1.20$ $Q \text{ кг.} = 0.33$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 120.1$ $P \text{ вн.мм} = 64.4$ Гр. сл. = 0соб. Точн. = DIN
	<b>БПЗ-884</b>		<b>БПЗ-889</b> $F \text{ см}^2 = 2.021$ $Q \text{ кг.} = 0.548$ $D \text{ оп.мм} = 52.3$ $P \text{ н.мм} = 222$ $P \text{ вн.мм} = 130.3$ Гр. сл. = 0соб. Точн. = DIN
	<b>БПЗ-885</b>		<b>БПЗ-890</b> $F \text{ см}^2 = 4.45$ $Q \text{ кг.} = 1.20$ $D \text{ оп.мм} = 59.9$ $P \text{ н.мм} = 253.5$ $P \text{ вн.мм} = 217.2$ Гр. сл. = VI Точн. = II










	<b>БПЗ-891</b> $F \text{ см}^2 = 1.081$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 102.5$ $P \text{ вн.мм} = 31.9$ Гр. сл. = 0соб. Точн. = DIN		<b>БПЗ-896</b> $F \text{ см}^2 = 3.345$ $Q \text{ кг.} = 0.906$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 110.4$ $P \text{ вн.мм} = 112.1$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-892</b> $F \text{ см}^2 = 3.102$ $Q \text{ кг.} = 0.841$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 109.2$ $P \text{ вн.мм} = 108.3$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-897</b>
	<b>БПЗ-893</b> $F \text{ см}^2 = 4.812$ $Q \text{ кг.} = 1.304$ $D \text{ оп.мм} = 141$ $P \text{ н.мм} = 394.8$ $P \text{ вн.мм} = 254.6$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-898</b> $F \text{ см}^2 = 4.89$ $Q \text{ кг.} = 1.32$ $D \text{ оп.мм} = 85$ $P \text{ н.мм} = 417$ $P \text{ вн.мм} = 136$ Гр. сл. = VI Точн. = П
	<b>БПЗ-894</b> $F \text{ см}^2 = 19.067$ $Q \text{ кг.} = 5.167$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 284.5$ $P \text{ вн.мм} = 301.2$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-899</b> $F \text{ см}^2 = 8.469$ $Q \text{ кг.} = 2.287$ $D \text{ оп.мм} = 150$ $P \text{ н.мм} = 501$ $P \text{ вн.мм} = 248$ Гр. сл. = VI Точн. = П
	<b>БПЗ-895</b> $F \text{ см}^2 = 4.843$ $Q \text{ кг.} = 1.312$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 146.1$ $P \text{ вн.мм} = 158.8$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-900</b> $F \text{ см}^2 = 4.843$ $Q \text{ кг.} = 1.312$ $D \text{ оп.мм} = 57$ $P \text{ н.мм} = 146.1$ $P \text{ вн.мм} = 158.8$ Гр. сл. = 0соб. Точн. = П


	<p><b>БПЗ-0901</b></p> <p> <math>F \text{ см}^2 = 7.42</math>  <math>Q \text{ кг.} = 2</math>  <math>D \text{ оп.мм} = 88</math>  <math>P \text{ н.мм} = 410.7</math>  <math>P \text{ вн.мм} = 181</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0906</b></p> <p> <math>F \text{ см}^2 = 3.09</math>  <math>Q \text{ кг.} = 0.83</math>  <math>D \text{ оп.мм} = 54</math>  <math>P \text{ н.мм} = 241</math>  <math>P \text{ вн.мм} = 121</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-0902</b></p> <p> <math>F \text{ см}^2 = 7.530</math>  <math>Q \text{ кг.} = 2.041</math>  <math>D \text{ оп.мм} = 106.0</math>  <math>P \text{ н.мм} = 447.5</math>  <math>P \text{ вн.мм} = 224.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0907</b></p> <p> <math>F \text{ см}^2 = 5.07</math>  <math>Q \text{ кг.} = 1.37</math>  <math>D \text{ оп.мм} = 97</math>  <math>P \text{ н.мм} = 357.3</math>  <math>P \text{ вн.мм} = 237.8</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-0903</b></p> <p> <math>F \text{ см}^2 = 9.97</math>  <math>Q \text{ кг.} = 2.69</math>  <math>D \text{ оп.мм} = 136.1</math>  <math>P \text{ н.мм} = 512.9</math>  <math>P \text{ вн.мм} = 283</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0908</b></p> <p> <math>F \text{ см}^2 = 4.38</math>  <math>Q \text{ кг.} = 2.27</math>  <math>D \text{ оп.мм} = 93</math>  <math>P \text{ н.мм} = 285.5</math>  <math>P \text{ вн.мм} = 237.8</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-0904</b></p> <p> <math>F \text{ см}^2 = 11.17</math>  <math>Q \text{ кг.} = 3.02</math>  <math>D \text{ оп.мм} = 159.3</math>  <math>P \text{ н.мм} = 560.9</math>  <math>P \text{ вн.мм} = 331</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0909</b></p> <p> <math>F \text{ см}^2 = 10.200</math>  <math>Q \text{ кг.} = 2.764</math>  <math>D \text{ оп.мм} = 96.0</math>  <math>P \text{ н.мм} = 659.7</math>  <math>P \text{ вн.мм} = 183.6</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-0905</b></p> <p> <math>F \text{ см}^2 = 12.37</math>  <math>Q \text{ кг.} = 3.34</math>  <math>D \text{ оп.мм} = 182.6</math>  <math>P \text{ н.мм} = 608.9</math>  <math>P \text{ вн.мм} = 379</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0910</b></p> <p> <math>F \text{ см}^2 = 2.124</math>  <math>Q \text{ кг.} = 0.576</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 226.7</math>  <math>P \text{ вн.мм} = 59.4</math>  Гр. сл. = VI  Точн. = П </p>

	<p><b>БПЗ-911</b></p> <p> <math>F \text{ см}^2 = 4.813</math>  <math>Q \text{ кг.} = 1.304</math>  <math>D \text{ оп.мм} = 141.0</math>  <math>P \text{ н.мм} = 394.8</math>  <math>P \text{ вн.мм} = 245.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-916</b></p> <p> <math>F \text{ см}^2 = 4.890</math>  <math>Q \text{ кг.} = 1.325</math>  <math>D \text{ оп.мм} = 53.6</math>  <math>P \text{ н.мм} = 156.5</math>  <math>P \text{ вн.мм} = 160.6</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-912</b></p> <p> <math>F \text{ см}^2 = 4.270</math>  <math>Q \text{ кг.} = 1.157</math>  <math>D \text{ оп.мм} = 49.0</math>  <math>P \text{ н.мм} = 186.7</math>  <math>P \text{ вн.мм} = 122.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-917</b></p> <p> <math>F \text{ см}^2 = 1.696</math>  <math>Q \text{ кг.} = 0.460</math>  <math>D \text{ оп.мм} = 29.0</math>  <math>P \text{ н.мм} = 91.1</math>  <math>P \text{ вн.мм} = 78.5</math>  Гр. сл. = II  Точн. = Н </p>
	<p><b>БПЗ-913</b></p> <p> <math>F \text{ см}^2 = 1.137</math>  <math>Q \text{ кг.} = 0.308</math>  <math>D \text{ оп.мм} = 24.0</math>  <math>P \text{ н.мм} = 63.1</math>  <math>P \text{ вн.мм} = 50.6</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-918</b></p> <p> <math>F \text{ см}^2 = 3.950</math>  <math>Q \text{ кг.} = 1.070</math>  <math>D \text{ оп.мм} = 55.9</math>  <math>P \text{ н.мм} = 139.3</math>  <math>P \text{ вн.мм} = 134.3</math>  Гр. сл. =  Точн. = П </p>
	<p><b>БПЗ-914</b></p> <p> <math>F \text{ см}^2 = 1.867</math>  <math>Q \text{ кг.} = 0.506</math>  <math>D \text{ оп.мм} = 31.0</math>  <math>P \text{ н.мм} = 82.6</math>  <math>P \text{ вн.мм} = 66.8</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-919</b></p> <p> <math>F \text{ см}^2 = 6.420</math>  <math>Q \text{ кг.} = 1.740</math>  <math>D \text{ оп.мм} = 109.0</math>  <math>P \text{ н.мм} = 359.4</math>  <math>P \text{ вн.мм} = 251.2</math>  Гр. сл. =  Точн. = П </p>
	<p><b>БПЗ-915</b></p> <p> <math>F \text{ см}^2 = 1.496</math>  <math>Q \text{ кг.} = 0.405</math>  <math>D \text{ оп.мм} = 27.0</math>  <math>P \text{ н.мм} = 72.3</math>  <math>P \text{ вн.мм} = 57.8</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-920</b></p> <p> <math>F \text{ см}^2 = 3.440</math>  <math>Q \text{ кг.} = 0.932</math>  <math>D \text{ оп.мм} = 48.3</math>  <math>P \text{ н.мм} = 199.5</math>  <math>P \text{ вн.мм} = 97.9</math>  Гр. сл. =  Точн. = П </p>


	<p><b>БПЗ-921</b></p> <p> <math>F \text{ см}^2 = 4.600</math>  <math>Q \text{ кг.} = 1.247</math>  <math>D \text{ оп.мм} = 77.1</math>  <math>P \text{ н.мм} = 289.1</math>  <math>P \text{ вн.мм} = 164.2</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-926</b></p> <p> <math>F \text{ см}^2 = 1.511</math>  <math>Q \text{ кг.} = 0.409</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 226.9</math>  <math>P \text{ вн.мм} = 25.1</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-922</b></p> <p> <math>F \text{ см}^2 = 2.262</math>  <math>Q \text{ кг.} = 0.613</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 203.3</math>  <math>P \text{ вн.мм} = 41.2</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-927</b></p> <p> <math>F \text{ см}^2 = 3.202</math>  <math>Q \text{ кг.} = 0.868</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 348.6</math>  <math>P \text{ вн.мм} = 82.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-923</b></p> <p> <math>F \text{ см}^2 = 0.848</math>  <math>Q \text{ кг.} = 0.230</math>  <math>D \text{ оп.мм} = 12.0</math>  <math>P \text{ н.мм} = 37.7</math>  <math>P \text{ вн.мм} = 18.9</math>  Гр. сл. = II  Точн. = Н </p>		<p><b>БПЗ-928</b></p> <p> <math>F \text{ см}^2 = 54.336</math>  <math>Q \text{ кг.} = 14.725</math>  <math>D \text{ оп.мм} = 116.0</math>  <math>P \text{ н.мм} = 388.6</math>  <math>P \text{ вн.мм} = 182.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-924</b></p> <p> <math>F \text{ см}^2 = 1.570</math>  <math>Q \text{ кг.} = 0.425</math>  <math>D \text{ оп.мм} = 44.0</math>  <math>P \text{ н.мм} = 177.9</math>  <math>P \text{ вн.мм} = 77.8</math>  Гр. сл. = 0соб.  Точн. = Н </p>		<p><b>БПЗ-929</b></p> <p> <math>F \text{ см}^2 = 2.500</math>  <math>Q \text{ кг.} = 0.678</math>  <math>D \text{ оп.мм} = 52.3</math>  <math>P \text{ н.мм} = 195.0</math>  <math>P \text{ вн.мм} = 112.3</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-925</b></p> <p> <math>F \text{ см}^2 = 1.198</math>  <math>Q \text{ кг.} = 0.325</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 124.8</math>  <math>P \text{ вн.мм} = 61.5</math>  Гр. сл. = 0соб.  Точн. = П </p>		



	<b>БПЗ-931</b> $F \text{ см}^2 = 1.507$ $Q \text{ кг.} = 0.408$ $D \text{ оп.мм} = 32.5$ $P \text{ н.мм} = 102.1$ $P \text{ вн.мм} = 92.4$ Гр. сл. = III Точн. = П		<b>БПЗ-936</b> $F \text{ см}^2 = 2.070$ $Q \text{ кг.} = 0.561$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 96.4$ $P \text{ вн.мм} = 32.0$ Гр. сл. = V Точн. = П
	<b>БПЗ-932</b> $F \text{ см}^2 = 13.630$ $Q \text{ кг.} = 3.694$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 141.4$ $P \text{ вн.мм} = 53.4$ Гр. сл. = II Точн. = П		<b>БПЗ-937</b> $F \text{ см}^2 = 5.550$ $Q \text{ кг.} = 1.504$ $D \text{ оп.мм} = 86.3$ $P \text{ н.мм} = 232.0$ $P \text{ вн.мм} = 212.0$ Гр. сл. = V Точн. = П
	<b>БПЗ-933</b> $F \text{ см}^2 = 8.359$ $Q \text{ кг.} = 2.265$ $D \text{ оп.мм} = 83.0$ $P \text{ н.мм} = 310.7$ $P \text{ вн.мм} = 103.7$ Гр. сл. = V Точн. = П		<b>БПЗ-938</b> $F \text{ см}^2 = 3.360$ $Q \text{ кг.} = 0.911$ $D \text{ оп.мм} = 75.0$ $P \text{ н.мм} = 180.0$ $P \text{ вн.мм} = 164.0$ Гр. сл. = V Точн. = П
	<b>БПЗ-934</b> $F \text{ см}^2 = 3.324$ $Q \text{ кг.} = 0.901$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 273.6$ $P \text{ вн.мм} = 402.9$ Гр. сл. = V Точн. = П		
	<b>БПЗ-935</b> $F \text{ см}^2 = 3.730$ $Q \text{ кг.} = 1.011$ $D \text{ оп.мм} = 59.5$ $P \text{ н.мм} = 241.6$ $P \text{ вн.мм} = 148.9$ Гр. сл. = V Точн. = П		<b>БПЗ-940</b> $F \text{ см}^2 = 2.770$ $Q \text{ кг.} = 0.751$ $D \text{ оп.мм} = 77.8$ $P \text{ н.мм} = 306.8$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = П




$D_{\text{оп.мм}} = 38.0$   
 $P_{\text{н.мм}} = 119.4$   
 $P_{\text{вн.мм}} = 82.9$   
 Гр. сл. = III  
 Точн. = П




**БПЗ-948**

$F \text{ см}^2 = 30.530$   
 $Q \text{ кг.} = 8.274$   
 $D_{\text{оп.мм}} = 93.0$   
 $P_{\text{н.мм}} = 1289.3$   
 $P_{\text{вн.мм}} = 125.7$   
 Гр. сл. = 0соб.  
 Точн. = П




**БПЗ-949**

$F \text{ см}^2 = 4.830$   
 $Q \text{ кг.} = 1.309$   
 $D_{\text{оп.мм}} = 100.0$   
 $P_{\text{н.мм}} = 416.3$   
 $P_{\text{вн.мм}} = 170.4$   
 Гр. сл. = VI  
 Точн. = П













**БПЗ-945**











$F \text{ см}^2 = 2.150$   
 $Q \text{ кг.} = 0.583$   
 $D_{\text{оп.мм}} = 36.2$   
 $P_{\text{н.мм}} = 95.5$   
 $P_{\text{вн.мм}} = 79.1$   
 Гр. сл. = III  
 Точн. = П























**БПЗ-950**









$F \text{ см}^2 = 3.930$   
 $Q \text{ кг.} = 1.065$   
 $D_{\text{оп.мм}} = 79.0$   
 $P_{\text{н.мм}} = 362.5$   
 $P_{\text{вн.мм}} = 104.6$   
 Гр. сл. = 0соб.  
 Точн. = П







	<b>БПЗ-951</b> $F \text{ см}^2 = 6.680$ $Q \text{ кг.} = 1.810$ $D \text{ оп.мм} = 86.0$ $P \text{ н.мм} = 299.0$ $P \text{ вн.мм} = 213.0$ Гр. сл. = VI Точн. = П		<b>БПЗ-956</b> $F \text{ см}^2 = 8.680$ $Q \text{ кг.} = 2.352$ $D \text{ оп.мм} = 124.0$ $P \text{ н.мм} = 379.0$ $P \text{ вн.мм} = 293.0$ Гр. сл. = VI Точн. = П
	<b>БПЗ-952</b> $F \text{ см}^2 = 4.290$ $Q \text{ кг.} = 1.163$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 364.3$ $P \text{ вн.мм} = 143.2$ Гр. сл. = V Точн. = П		<b>БПЗ-957</b> $F \text{ см}^2 = 4.060$ $Q \text{ кг.} = 1.100$ $D \text{ оп.мм} = 73.3$ $P \text{ н.мм} = 272.6$ $P \text{ вн.мм} = 197.7$ Гр. сл. = VI Точн. = П
	<b>БПЗ-953</b> $F \text{ см}^2 = 3.690$ $Q \text{ кг.} = 1.000$ $D \text{ оп.мм} = 73.3$ $P \text{ н.мм} = 326.3$ $P \text{ вн.мм} = 105.2$ Гр. сл. = V Точн. = П		<b>БПЗ-958</b> $F \text{ см}^2 = 4.200$ $Q \text{ кг.} = 1.138$ $D \text{ оп.мм} = 53.7$ $P \text{ н.мм} = 296.4$ $P \text{ вн.мм} = 0.0$ Гр. сл. = IV Точн. = П
	<b>БПЗ-954</b> $F \text{ см}^2 = 3.230$ $Q \text{ кг.} = 0.875$ $D \text{ оп.мм} = 64.9$ $P \text{ н.мм} = 267.7$ $P \text{ вн.мм} = 105.2$ Гр. сл. = V Точн. = П		<b>БПЗ-959</b> $F \text{ см}^2 = 0.633$ $Q \text{ кг.} = 0.172$ $D \text{ оп.мм} = 16.5$ $P \text{ н.мм} = 88.6$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = П
	<b>БПЗ-955</b> $F \text{ см}^2 = 3.840$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 305.7$ $P \text{ вн.мм} = 143.2$ Гр. сл. = V Точн. = П		<b>БПЗ-960</b> $F \text{ см}^2 = 2.799$ $Q \text{ кг.} = 0.759$ $D \text{ оп.мм} = 61.0$ $P \text{ н.мм} = 275.3$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П

	<p><b>БПЗ-961</b></p> <p> <math>F \text{ см}^2 = 3.860</math>  <math>Q \text{ кг.} = 1.046</math>  <math>D \text{ оп.мм} = 69.3</math>  <math>P \text{ н.мм} = 258.9</math>  <math>P \text{ вн.мм} = 153.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-966</b></p> <p> <math>F \text{ см}^2 = 7.358</math>  <math>Q \text{ кг.} = 1.994</math>  <math>D \text{ оп.мм} = 79.0</math>  <math>P \text{ н.мм} = 335.9</math>  <math>P \text{ вн.мм} = 144.6</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-962</b></p> <p> <math>F \text{ см}^2 = 4.790</math>  <math>Q \text{ кг.} = 1.298</math>  <math>D \text{ оп.мм} = 101.4</math>  <math>P \text{ н.мм} = 375.7</math>  <math>P \text{ вн.мм} = 153.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-967</b></p> <p> <math>F \text{ см}^2 = 2.250</math>  <math>Q \text{ кг.} = 0.610</math>  <math>D \text{ оп.мм} = 76.0</math>  <math>P \text{ н.мм} = 206.0</math>  <math>P \text{ вн.мм} = 146.0</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-963</b></p> <p> <math>F \text{ см}^2 = 2.038</math>  <math>Q \text{ кг.} = 0.552</math>  <math>D \text{ оп.мм} = 40.3</math>  <math>P \text{ н.мм} = 173.4</math>  <math>P \text{ вн.мм} = 76.7</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-968</b></p> <p> <math>F \text{ см}^2 = 1.384</math>  <math>Q \text{ кг.} = 0.375</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 144.4</math>  <math>P \text{ вн.мм} = 60.1</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-964</b></p> <p> <math>F \text{ см}^2 = 7.416</math>  <math>Q \text{ кг.} = 2.010</math>  <math>D \text{ оп.мм} = 71.1</math>  <math>P \text{ н.мм} = 295.3</math>  <math>P \text{ вн.мм} = 154.6</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-969</b></p> <p> <math>F \text{ см}^2 = 1.576</math>  <math>Q \text{ кг.} = 0.427</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 110.6</math>  <math>P \text{ вн.мм} = 59.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-965</b></p> <p> <math>F \text{ см}^2 = 6.558</math>  <math>Q \text{ кг.} = 1.777</math>  <math>D \text{ оп.мм} = 74.0</math>  <math>P \text{ н.мм} = 260.5</math>  <math>P \text{ вн.мм} = 154.6</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-970</b></p> <p> <math>F \text{ см}^2 = 1.665</math>  <math>Q \text{ кг.} = 0.451</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 120.6</math>  <math>P \text{ вн.мм} = 59.6</math>  Гр. сл. = V  Точн. = П </p>










	<p><b>БПЗ-971</b></p> <p> <math>F \text{ см}^2 = 1.789</math>  <math>Q \text{ кг.} = 0.485</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 120.6</math>  <math>P \text{ вн.мм} = 69.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-976</b></p> <p> <math>F \text{ см}^2 = 2.820</math>  <math>Q \text{ кг.} = 0.764</math>  <math>D \text{ оп.мм} = 28.9</math>  <math>P \text{ н.мм} = 99.7</math>  <math>P \text{ вн.мм} = 28.1</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-972</b></p> <p> <math>F \text{ см}^2 = 1.652</math>  <math>Q \text{ кг.} = 0.448</math>  <math>D \text{ оп.мм} = 37.0</math>  <math>P \text{ н.мм} = 172.9</math>  <math>P \text{ вн.мм} = 56.3</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-977</b></p> <p> <math>F \text{ см}^2 = 0.712</math>  <math>Q \text{ кг.} = 0.193</math>  <math>D \text{ оп.мм} = 21.0</math>  <math>P \text{ н.мм} = 78.2</math>  <math>P \text{ вн.мм} = 21.5</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-973</b></p> <p> <math>F \text{ см}^2 = 1.468</math>  <math>Q \text{ кг.} = 0.398</math>  <math>D \text{ оп.мм} = 33.0</math>  <math>P \text{ н.мм} = 140.2</math>  <math>P \text{ вн.мм} = 54.3</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-978</b></p> <p> <math>F \text{ см}^2 = 0.943</math>  <math>Q \text{ кг.} = 0.256</math>  <math>D \text{ оп.мм} = 31.4</math>  <math>P \text{ н.мм} = 44.4</math>  <math>P \text{ вн.мм} = 37.5</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-974</b></p> <p> <math>F \text{ см}^2 = 1.889</math>  <math>Q \text{ кг.} = 0.512</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 130.6</math>  <math>P \text{ вн.мм} = 69.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-979</b></p> <p> <math>F \text{ см}^2 = 0.677</math>  <math>Q \text{ кг.} = 0.183</math>  <math>D \text{ оп.мм} = 23.0</math>  <math>P \text{ н.мм} = 80.5</math>  <math>P \text{ вн.мм} = 31.5</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-975</b></p> <p> <math>F \text{ см}^2 = 1.720</math>  <math>Q \text{ кг.} = 0.466</math>  <math>D \text{ оп.мм} = 38.0</math>  <math>P \text{ н.мм} = 119.4</math>  <math>P \text{ вн.мм} = 110.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-980</b></p> <p> <math>F \text{ см}^2 = 1.330</math>  <math>Q \text{ кг.} = 0.360</math>  <math>D \text{ оп.мм} = 43.0</math>  <math>P \text{ н.мм} = 140.2</math>  <math>P \text{ вн.мм} = 83.7</math>  Гр. сл. = V  Точн. = П </p>









	<p><b>БПЗ-981</b></p> <p> <math>F \text{ см}^2 = 2.270</math>  <math>Q \text{ кг.} = 0.615</math>  <math>D \text{ оп.мм} = 51.2</math>  <math>P \text{ н.мм} = 184.5</math>  <math>P \text{ вн.мм} = 143.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-986</b></p> <p> <math>F \text{ см}^2 = 0.911</math>  <math>Q \text{ кг.} = 0.247</math>  <math>D \text{ оп.мм} = 26.0</math>  <math>P \text{ н.мм} = 92.0</math>  <math>P \text{ вн.мм} = 41.2</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-982</b></p> <p> <math>F \text{ см}^2 = 2.832</math>  <math>Q \text{ кг.} = 0.767</math>  <math>D \text{ оп.мм} = 51.4</math>  <math>P \text{ н.мм} = 257.5</math>  <math>P \text{ вн.мм} = 144.7</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-987</b></p> <p> <math>F \text{ см}^2 = 4.720</math>  <math>Q \text{ кг.} = 1.279</math>  <math>D \text{ оп.мм} = 87.8</math>  <math>P \text{ н.мм} = 337.0</math>  <math>P \text{ вн.мм} = 217.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-983</b></p> <p> <math>F \text{ см}^2 = 0.891</math>  <math>Q \text{ кг.} = 0.241</math>  <math>D \text{ оп.мм} = 26.0</math>  <math>P \text{ н.мм} = 87.2</math>  <math>P \text{ вн.мм} = 49.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-988</b></p> <p> <math>F \text{ см}^2 = 1.269</math>  <math>Q \text{ кг.} = 0.344</math>  <math>D \text{ оп.мм} = 49.0</math>  <math>P \text{ н.мм} = 150.3</math>  <math>P \text{ вн.мм} = 41.2</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-984</b></p> <p> <math>F \text{ см}^2 = 1.185</math>  <math>Q \text{ кг.} = 0.321</math>  <math>D \text{ оп.мм} = 26.0</math>  <math>P \text{ н.мм} = 116.6</math>  <math>P \text{ вн.мм} = 58.4</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-989</b></p> <p> <math>F \text{ см}^2 = 0.935</math>  <math>Q \text{ кг.} = 0.253</math>  <math>D \text{ оп.мм} = 38.0</math>  <math>P \text{ н.мм} = 108.6</math>  <math>P \text{ вн.мм} = 21.5</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-985</b></p> <p> <math>F \text{ см}^2 = 1.169</math>  <math>Q \text{ кг.} = 0.317</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 135.2</math>  <math>P \text{ вн.мм} = 41.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-990</b></p> <p> <math>F \text{ см}^2 = 0.864</math>  <math>Q \text{ кг.} = 0.234</math>  <math>D \text{ оп.мм} = 33.0</math>  <math>P \text{ н.мм} = 97.6</math>  <math>P \text{ вн.мм} = 21.5</math>  Гр. сл. = V  Точн. = П </p>









			<b>БПЗ-996</b> $F \text{ см}^2 = 0.880$ $Q \text{ кг.} = 0.238$ $D \text{ оп.мм} = 16.0$ $P \text{ н.мм} = 50.3$ $P \text{ вн.мм} = 37.7$ Гр. сл. = III Точн. = Н
			<b>БПЗ-997</b> $F \text{ см}^2 = 2.513$ $Q \text{ кг.} = 0.681$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 131.9$ $P \text{ вн.мм} = 119.4$ Гр. сл. = III Точн. = Н
	<b>БПЗ-993</b> $F \text{ см}^2 = 3.308$ $Q \text{ кг.} = 0.896$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 119.7$ $P \text{ вн.мм} = 100.8$ Гр. сл. = IV Точн. = Н		<b>БПЗ-998</b> $F \text{ см}^2 = 1.103$ $Q \text{ кг.} = 0.299$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 132.6$ $P \text{ вн.мм} = 21.5$ Гр. сл. = V Точн. = П
	<b>БПЗ-994</b> $F \text{ см}^2 = 6.240$ $Q \text{ кг.} = 1.691$ $D \text{ оп.мм} = 153.0$ $P \text{ н.мм} = 752.5$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = Н		<b>БПЗ-999</b> $F \text{ см}^2 = 0.928$ $Q \text{ кг.} = 0.251$ $D \text{ оп.мм} = 29.0$ $P \text{ н.мм} = 105.7$ $P \text{ вн.мм} = 21.5$ Гр. сл. = V Точн. = П
	<b>БПЗ-995</b> $F \text{ см}^2 = 5.374$ $Q \text{ кг.} = 1.456$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 379.3$ $P \text{ вн.мм} = 110.8$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-1000</b> $F \text{ см}^2 = 1.019$ $Q \text{ кг.} = 0.276$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 119.7$ $P \text{ вн.мм} = 21.5$ Гр. сл. = V Точн. = П










	<p><b>БПЗ-1001</b></p> <p> <math>F \text{ см}^2 = 3.200</math>  <math>Q \text{ кг.} = 0.867</math>  <math>D \text{ оп.мм} = 92.8</math>  <math>P \text{ н.мм} = 340.2</math>  <math>P \text{ вн.мм} = 154.9</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = П</math> </p>		
	<p><b>БПЗ-1002</b></p> <p> <math>F \text{ см}^2 = 3.260</math>  <math>Q \text{ кг.} = 0.883</math>  <math>D \text{ оп.мм} = 97.7</math>  <math>P \text{ н.мм} = 355.3</math>  <math>P \text{ вн.мм} = 152.3</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-1007</b></p> <p> <math>F \text{ см}^2 = 8.130</math>  <math>Q \text{ кг.} = 2.203</math>  <math>D \text{ оп.мм} = 66.0</math>  <math>P \text{ н.мм} = 168.4</math>  <math>P \text{ вн.мм} = 159.0</math>  <math>\Gamma \text{р. сл.} = 0 \text{соб.}</math>  <math>\text{Точн.} = П</math> </p>
	<p><b>БПЗ-1003</b></p> <p> <math>F \text{ см}^2 = 1.105</math>  <math>Q \text{ кг.} = 0.299</math>  <math>D \text{ оп.мм} = 37.0</math>  <math>P \text{ н.мм} = 106.8</math>  <math>P \text{ вн.мм} = 66.5</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-1008</b></p> <p> <math>F \text{ см}^2 = 5.924</math>  <math>Q \text{ кг.} = 1.605</math>  <math>D \text{ оп.мм} = 66.0</math>  <math>P \text{ н.мм} = 168.4</math>  <math>P \text{ вн.мм} = 188.0</math>  <math>\Gamma \text{р. сл.} = 0 \text{соб.}</math>  <math>\text{Точн.} = П</math> </p>
	<p><b>БПЗ-1004</b></p> <p> <math>F \text{ см}^2 = 1.840</math>  <math>Q \text{ кг.} = 0.499</math>  <math>D \text{ оп.мм} = 53.0</math>  <math>P \text{ н.мм} = 147.9</math>  <math>P \text{ вн.мм} = 123.1</math>  <math>\Gamma \text{р. сл.} = V</math>  <math>\text{Точн.} = П</math> </p>		















	<p><b>БПЗ-1011</b></p> <p> <math>F \text{ см}^2 = 2.870</math>  <math>Q \text{ кг.} = 0.778</math>  <math>D \text{ оп.мм} = 51.2</math>  <math>P \text{ н.мм} = 190.8</math>  <math>P \text{ вн.мм} = 108.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1016</b></p> <p> <math>F \text{ см}^2 = 4.490</math>  <math>Q \text{ кг.} = 1.217</math>  <math>D \text{ оп.мм} = 81.2</math>  <math>P \text{ н.мм} = 294.2</math>  <math>P \text{ вн.мм} = 188.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1012</b></p> <p> <math>F \text{ см}^2 = 3.640</math>  <math>Q \text{ кг.} = 0.986</math>  <math>D \text{ оп.мм} = 90.0</math>  <math>P \text{ н.мм} = 260.0</math>  <math>P \text{ вн.мм} = 104.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1017</b></p> <p> <math>F \text{ см}^2 = 1.006</math>  <math>Q \text{ кг.} = 0.273</math>  <math>D \text{ оп.мм} = 18.0</math>  <math>P \text{ н.мм} = 56.6</math>  <math>P \text{ вн.мм} = 44.0</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-1013</b></p> <p> <math>F \text{ см}^2 = 2.332</math>  <math>Q \text{ кг.} = 0.632</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 138.4</math>  <math>P \text{ вн.мм} = 92.5</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1018</b></p> <p> <math>F \text{ см}^2 = 2.730</math>  <math>Q \text{ кг.} = 0.740</math>  <math>D \text{ оп.мм} = 77.6</math>  <math>P \text{ н.мм} = 302.8</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = V  Точн. = П </p>
			<p><b>БПЗ-1019</b></p> <p> <math>F \text{ см}^2 = 3.370</math>  <math>Q \text{ кг.} = 0.913</math>  <math>D \text{ оп.мм} = 25.0</math>  <math>P \text{ н.мм} = 78.5</math>  <math>P \text{ вн.мм} = 44.0</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-1015</b></p> <p> <math>F \text{ см}^2 = 4.710</math>  <math>Q \text{ кг.} = 1.276</math>  <math>D \text{ оп.мм} = 87.3</math>  <math>P \text{ н.мм} = 306.3</math>  <math>P \text{ вн.мм} = 200.5</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1020</b></p> <p> <math>F \text{ см}^2 = 0.353</math>  <math>Q \text{ кг.} = 0.096</math>  <math>D \text{ оп.мм} = 9.0</math>  <math>P \text{ н.мм} = 28.3</math>  <math>P \text{ вн.мм} = 18.9</math>  Гр. сл. = III  Точн. = Н </p>








	<p><b>БПЗ-1021</b></p> <p> <math>F \text{ см}^2 = 3.371</math>  <math>Q \text{ кг.} = 0.914</math>  <math>D \text{ оп.мм} = 49</math>  <math>P \text{ н.мм} = 257.1</math>  <math>P \text{ вн.мм} = 69.3</math>  Гр. сл. = V  Точн. = особая </p>		<p><b>БПЗ-1026</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1022</b></p> <p> <math>F \text{ см}^2 = 3.933</math>  <math>Q \text{ кг.} = 1.066</math>  <math>D \text{ оп.мм} = 103.9</math>  <math>P \text{ н.мм} = 270</math>  <math>P \text{ вн.мм} = 254.4</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1027</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1023</b></p> <p> <math>F \text{ см}^2 = 0.9</math>  <math>Q \text{ кг.} = 0.244</math>  <math>D \text{ оп.мм} = 27</math>  <math>P \text{ н.мм} = 86.7</math>  <math>P \text{ вн.мм} = 49.2</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1028</b></p> <p> <math>F \text{ см}^2 = 0.641</math>  <math>Q \text{ кг.} = 0.174</math>  <math>D \text{ оп.мм} = 15</math>  <math>P \text{ н.мм} = 142.1</math>  <math>P \text{ вн.мм} = 38.1</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1024</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1029</b></p> <p> <math>F \text{ см}^2 = 2.99</math>  <math>Q \text{ кг.} = 0.807</math>  <math>D \text{ оп.мм} = 53</math>  <math>P \text{ н.мм} = 212.1</math>  <math>P \text{ вн.мм} = 110.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1025</b></p> <p> <math>F \text{ см}^2 = 1.840</math>  <math>Q \text{ кг.} = 0.499</math>  <math>D \text{ оп.мм} = 53.0</math>  <math>P \text{ н.мм} = 147.9</math>  <math>P \text{ вн.мм} = 123.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1030</b></p> <p> <math>F \text{ см}^2 = 2.95</math>  <math>Q \text{ кг.} = 0.798</math>  <math>D \text{ оп.мм} = 54</math>  <math>P \text{ н.мм} = 180.4</math>  <math>P \text{ вн.мм} = 122.7</math>  Гр. сл. = VI  Точн. = П </p>




	<p><b>БПЗ-1031</b></p> <p> <math>F \text{ см}^2 = 0.377</math>  <math>Q \text{ кг.} = 0.102</math>  <math>D \text{ оп.мм} = 8</math>  <math>P \text{ н.мм} = 25.1</math>  <math>P \text{ вн.мм} = 12.6</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-1036</b></p> <p> <math>F \text{ см}^2 = 4.469</math>  <math>Q \text{ кг.} = 1.21</math>  <math>D \text{ оп.мм} = 40</math>  <math>P \text{ н.мм} = 62.8</math>  <math>P \text{ вн.мм} = 159</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1032</b></p> <p> <math>F \text{ см}^2 = 1.25</math>  <math>Q \text{ кг.} = 0.339</math>  <math>D \text{ оп.мм} = 35</math>  <math>P \text{ н.мм} = 90</math>  <math>P \text{ вн.мм} = 75.7</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1037</b></p> <p> <math>F \text{ см}^2 = 1.789</math>  <math>Q \text{ кг.} = 0.485</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 104.4</math>  <math>P \text{ вн.мм} = 25.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1033</b></p> <p> <math>F \text{ см}^2 = 3.016</math>  <math>Q \text{ кг.} = 0.817</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 88</math>  <math>P \text{ вн.мм} = 62.8</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-1038</b></p> <p> <math>F \text{ см}^2 = 2.684</math>  <math>Q \text{ кг.} = 0.727</math>  <math>D \text{ оп.мм} = 51</math>  <math>P \text{ н.мм} = 217</math>  <math>P \text{ вн.мм} = 138.7</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1034</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1039</b></p> <p> <math>F \text{ см}^2 = 12.552</math>  <math>Q \text{ кг.} = 3.402</math>  <math>D \text{ оп.мм} = 130</math>  <math>P \text{ н.мм} = 389.2</math>  <math>P \text{ вн.мм} = 329.9</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1035</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1040</b></p> <p> <math>F \text{ см}^2 = 7.7</math>  <math>Q \text{ кг.} = 2.08</math>  <math>D \text{ оп.мм} = 76</math>  <math>P \text{ н.мм} = 340.4</math>  <math>P \text{ вн.мм} = 160.6</math>  Гр. сл. = V  Точн. = П </p>

	<p><b>БПЗ-1041</b></p> <p> <math>F \text{ см}^2 = 8.060</math>  <math>Q \text{ кг.} = 2.184</math>  <math>D \text{ оп.мм} = 85.2</math>  <math>P \text{ н.мм} = 383.2</math>  <math>P \text{ вн.мм} = 170.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1046</b></p> <p> <math>F \text{ см}^2 = 4.95</math>  <math>Q \text{ кг.} = 1.341</math>  <math>D \text{ оп.мм} = 114.9</math>  <math>P \text{ н.мм} = 298</math>  <math>P \text{ вн.мм} = 281.1</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1042</b></p> <p> <math>F \text{ см}^2 = 3.610</math>  <math>Q \text{ кг.} = 0.978</math>  <math>D \text{ оп.мм} = 59.5</math>  <math>P \text{ н.мм} = 243.1</math>  <math>P \text{ вн.мм} = 93.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1047</b></p> <p> <math>F \text{ см}^2 = 2.814</math>  <math>Q \text{ кг.} = 0.763</math>  <math>D \text{ оп.мм} = 86.0</math>  <math>P \text{ н.мм} = 348.3</math>  <math>P \text{ вн.мм} = 97.2</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1043</b></p> <p> <math>F \text{ см}^2 = 6.270</math>  <math>Q \text{ кг.} = 1.699</math>  <math>D \text{ оп.мм} = 75.6</math>  <math>P \text{ н.мм} = 263.8</math>  <math>P \text{ вн.мм} = 209.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1048</b></p> <p> <math>F \text{ см}^2 = 1.940</math>  <math>Q \text{ кг.} = 0.526</math>  <math>D \text{ оп.мм} = 31.2</math>  <math>P \text{ н.мм} = 82.6</math>  <math>P \text{ вн.мм} = 66.3</math>  Гр. сл. = III  Точн. = П </p>
			<p><b>БПЗ-1049</b></p> <p> <math>F \text{ см}^2 = 18.000</math>  <math>Q \text{ кг.} = 4.878</math>  <math>D \text{ оп.мм} = 85.8</math>  <math>P \text{ н.мм} = 679.8</math>  <math>P \text{ вн.мм} = 105.7</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1045</b></p> <p> <math>F \text{ см}^2 = 3.020</math>  <math>Q \text{ кг.} = 0.818</math>  <math>D \text{ оп.мм} = 48.0</math>  <math>P \text{ н.мм} = 171.9</math>  <math>P \text{ вн.мм} = 128.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1050</b></p> <p> <math>F \text{ см}^2 = 1.920</math>  <math>Q \text{ кг.} = 0.520</math>  <math>D \text{ оп.мм} = 42.6</math>  <math>P \text{ н.мм} = 179.3</math>  <math>P \text{ вн.мм} = 47.8</math>  Гр. сл. = VI  Точн. = П </p>











	<p><b>БПЗ-1051</b></p> <p> <math>F \text{ см}^2 = 4.83</math>  <math>Q \text{ кг.} = 1.309</math>  <math>D \text{ оп.мм} = 77</math>  <math>P \text{ н.мм} = 237.3</math>  <math>P \text{ вн.мм} = 177</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1056</b></p> <p> <math>F \text{ см}^2 = 0.282</math>  <math>Q \text{ кг.} = 0.076</math>  <math>D \text{ оп.мм} = 7.2</math>  <math>P \text{ н.мм} = 22.6</math>  <math>P \text{ вн.мм} = 12.6</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1052</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1057</b></p> <p> <math>F \text{ см}^2 = 21.14</math>  <math>Q \text{ кг.} = 5.729</math>  <math>D \text{ оп.мм} = 112</math>  <math>P \text{ н.мм} = 288.8</math>  <math>P \text{ вн.мм} = 296.3</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1053</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-1058</b></p> <p> <math>F \text{ см}^2 = 5.81</math>  <math>Q \text{ кг.} = 1.574</math>  <math>D \text{ оп.мм} = 57</math>  <math>P \text{ н.мм} = 149.9</math>  <math>P \text{ вн.мм} = 154.6</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1054</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1059</b></p> <p> <math>F \text{ см}^2 = 0.966</math>  <math>Q \text{ кг.} = 0.262</math>  <math>D \text{ оп.мм} = 30</math>  <math>P \text{ н.мм} = 73.4</math>  <math>P \text{ вн.мм} = 64.6</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1055</b></p> <p> <math>F \text{ см}^2 = 1</math>  <math>Q \text{ кг.} = 1</math>  <math>D \text{ оп.мм} = 1</math>  <math>P \text{ н.мм} = 1</math>  <math>P \text{ вн.мм} = 1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1060</b></p> <p> <math>F \text{ см}^2 = 1.351</math>  <math>Q \text{ кг.} = 0.366</math>  <math>D \text{ оп.мм} = 36</math>  <math>P \text{ н.мм} = 124.2</math>  <math>P \text{ вн.мм} = 74.4</math>  Гр. сл. = V  Точн. = П </p>











	<p><b>БПЗ-1061</b></p> <p> <math>F \text{ см}^2 = 23.090</math>  <math>Q \text{ кг.} = 6.257</math>  <math>D \text{ оп.мм} = 64.0</math>  <math>P \text{ н.мм} = 201.1</math>  <math>P \text{ вн.мм} = 106.8</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-1066</b></p> <p> <math>F \text{ см}^2 = 7.637</math>  <math>Q \text{ кг.} = 2.070</math>  <math>D \text{ оп.мм} = 87.0</math>  <math>P \text{ н.мм} = 273.3</math>  <math>P \text{ вн.мм} = 257.6</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-1062</b></p> <p> <math>F \text{ см}^2 = 15.620</math>  <math>Q \text{ кг.} = 4.233</math>  <math>D \text{ оп.мм} = 118.0</math>  <math>P \text{ н.мм} = 494.1</math>  <math>P \text{ вн.мм} = 430.9</math>  Гр. сл. = V  Точн. = П </p>		
	<p><b>БПЗ-1063</b></p> <p> <math>F \text{ см}^2 = 3.016</math>  <math>Q \text{ кг.} = 0.817</math>  <math>D \text{ оп.мм} = 28.0</math>  <math>P \text{ н.мм} = 87.9</math>  <math>P \text{ вн.мм} = 62.8</math>  Гр. сл. = IV  Точн. = П </p>		
	<p><b>БПЗ-1064</b></p> <p> <math>F \text{ см}^2 = 11.110</math>  <math>Q \text{ кг.} = 3.011</math>  <math>D \text{ оп.мм} = 148.0</math>  <math>P \text{ н.мм} = 607.2</math>  <math>P \text{ вн.мм} = 472.6</math>  Гр. сл. = 0соб.  Точн. = П </p>		
	<p><b>БПЗ-1065</b></p> <p> <math>F \text{ см}^2 = 5.430</math>  <math>Q \text{ кг.} = 1.472</math>  <math>D \text{ оп.мм} = 104.5</math>  <math>P \text{ н.мм} = 282.0</math>  <math>P \text{ вн.мм} = 261.2</math>  Гр. сл. = V  Точн. = П </p>		











			БПЗ-1076 $F \text{ см}^2 = 1.490$ $Q \text{ кг.} = 0.404$ $D \text{ оп.мм} = 26.6$ $P \text{ н.мм} = 108.7$ $P \text{ вн.мм} = 38.0$ Гр. сл. = v Точн. = П
	БПЗ-1072 $F \text{ см}^2 = 0.726$ $Q \text{ кг.} = 0.197$ $D \text{ оп.мм} = 22.0$ $P \text{ н.мм} = 74.7$ $P \text{ вн.мм} = 39.5$ Гр. сл. = iv Точн. = П		БПЗ-1077 $F \text{ см}^2 = 1.330$ $Q \text{ кг.} = 0.360$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 78.4$ $P \text{ вн.мм} = 25.1$ Гр. сл. = V Точн. = П
	БПЗ-1073 $F \text{ см}^2 = 4.556$ $Q \text{ кг.} = 1.235$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 158.2$ $P \text{ вн.мм} = 40.0$ Гр. сл. = vi Точн. = П		БПЗ-1078 $F \text{ см}^2 = 8.729$ $Q \text{ кг.} = 2.366$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 246.9$ $P \text{ вн.мм} = 215.7$ Гр. сл. = VI Точн. = П
	БПЗ-1074 $F \text{ см}^2 = 7.657$ $Q \text{ кг.} = 2.075$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 314.2$ $P \text{ вн.мм} = 298.5$ Гр. сл. = v Точн. = П		
	БПЗ-1075 $F \text{ см}^2 = 2.110$ $Q \text{ кг.} = 0.572$ $D \text{ оп.мм} = 29.1$ $P \text{ н.мм} = 114.4$ $P \text{ вн.мм} = 25.1$ Гр. сл. = v Точн. = П		










	БПЗ-1081		БПЗ-1086
	$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 1.6$ $Q \text{ кг.} = 0.434$ $D \text{ оп.мм} = 44.3$ $P \text{ н.мм} = 165.1$ $P \text{ вн.мм} = 0$ Гр. сл. = VI Точн. = П
	БПЗ-1082		БПЗ-1087
	$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = IV Точн. = П
	БПЗ-1083		БПЗ-1088
	$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 1.769$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 94.3$ $P \text{ вн.мм} = 81.7$ Гр. сл. = IV Точн. = П
	БПЗ-1084		БПЗ-1089
	$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = IV Точн. = П
	БПЗ-1085		БПЗ-1090
	$F \text{ см}^2 = 1$ $Q \text{ кг.} = 1$ $D \text{ оп.мм} = 1$ $P \text{ н.мм} = 1$ $P \text{ вн.мм} = 1$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 5.82$ $Q \text{ кг.} = 1.577$ $D \text{ оп.мм} = 87$ $P \text{ н.мм} = 354.4$ $P \text{ вн.мм} = 299.1$ Гр. сл. = особая Точн. = П






















	<p><b>БПЗ-1091</b></p> <p> <math>F \text{ см}^2 = 5.958</math>  <math>Q \text{ кг.} = 1.615</math>  <math>D \text{ оп.мм} = 80.0</math>  <math>P \text{ н.мм} = 205.2</math>  <math>P \text{ вн.мм} = 72.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1096</b></p> <p> <math>F \text{ см}^2 = 0.563</math>  <math>Q \text{ кг.} = 0.153</math>  <math>D \text{ оп.мм} = 20.0</math>  <math>P \text{ н.мм} = 51.0</math>  <math>P \text{ вн.мм} = 41.4</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-1092</b></p> <p> <math>F \text{ см}^2 = 7.358</math>  <math>Q \text{ кг.} = 1.994</math>  <math>D \text{ оп.мм} = 86.0</math>  <math>P \text{ н.мм} = 245.2</math>  <math>P \text{ вн.мм} = 72.0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1097</b></p> <p> <math>F \text{ см}^2 = 46.000</math>  <math>Q \text{ кг.} = 12.466</math>  <math>D \text{ оп.мм} = 111.6</math>  <math>P \text{ н.мм} = 368.7</math>  <math>P \text{ вн.мм} = 193.5</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1093</b></p> <p> <math>F \text{ см}^2 = 4.460</math>  <math>Q \text{ кг.} = 1.209</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 100.8</math>  <math>P \text{ вн.мм} = 40.8</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1098</b></p> <p> <math>F \text{ см}^2 = 2.993</math>  <math>Q \text{ кг.} = 0.811</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 188.6</math>  <math>P \text{ вн.мм} = 31.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1094</b></p> <p> <math>F \text{ см}^2 = 2.152</math>  <math>Q \text{ кг.} = 0.583</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 188.2</math>  <math>P \text{ вн.мм} = 47.5</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1099</b></p> <p> <math>F \text{ см}^2 = 10.210</math>  <math>Q \text{ кг.} = 2.767</math>  <math>D \text{ оп.мм} = 168.0</math>  <math>P \text{ н.мм} = 428.7</math>  <math>P \text{ вн.мм} = 372.0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1095</b></p> <p> <math>F \text{ см}^2 = 21.250</math>  <math>Q \text{ кг.} = 5.759</math>  <math>D \text{ оп.мм} = 120.0</math>  <math>P \text{ н.мм} = 399.3</math>  <math>P \text{ вн.мм} = 260.7</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1100</b></p> <p> <math>F \text{ см}^2 = 6.507</math>  <math>Q \text{ кг.} = 1.763</math>  <math>D \text{ оп.мм} = 102.0</math>  <math>P \text{ н.мм} = 291.7</math>  <math>P \text{ вн.мм} = 34.5</math>  Гр. сл. = VI  Точн. = П </p>




	<b>БПЗ-1101</b> $F \text{ см}^2 = 0.863$ $Q \text{ кг.} = 0.234$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 68.2$ $P \text{ вн.мм} = 59.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-1106</b> $F \text{ см}^2 = 0.825$ $Q \text{ кг.} = 0.224$ $D \text{ оп.мм} = 19$ $P \text{ н.мм} = 59.7$ $P \text{ вн.мм} = 50.3$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1102</b> $F \text{ см}^2 = 1.347$ $Q \text{ кг.} = 0.365$ $D \text{ оп.мм} = 16$ $P \text{ н.мм} = 56$ $P \text{ вн.мм} = 25.8$ Гр. сл. = V Точн. = П		<b>БПЗ-1107</b> $F \text{ см}^2 = 5.266$ $Q \text{ кг.} = 1.427$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 445.2$ $P \text{ вн.мм} = 155.2$ Гр. сл. = V Точн. = П
	<b>БПЗ-1103</b> $F \text{ см}^2 = 3.78$ $Q \text{ кг.} = 1.02$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 315.7$ $P \text{ вн.мм} = 101.5$ Гр. сл. = V Точн. = П		<b>БПЗ-1108</b> $F \text{ см}^2 = 3.684$ $Q \text{ кг.} = 0.998$ $D \text{ оп.мм} = 37$ $P \text{ н.мм} = 116.2$ $P \text{ вн.мм} = 94.2$ Гр. сл. = III Точн. = П
	<b>БПЗ-1104</b> $F \text{ см}^2 = 5.77$ $Q \text{ кг.} = 1.557$ $D \text{ оп.мм} = 97$ $P \text{ н.мм} = 335.3$ $P \text{ вн.мм} = 234.4$ Гр. сл. = V Точн. = П		<b>БПЗ-1109</b> $F \text{ см}^2 = 11.87$ $Q \text{ кг.} = 3.217$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 399.3$ $P \text{ вн.мм} = 305.6$ Гр. сл. = V Точн. = П
	<b>БПЗ-1105</b> $F \text{ см}^2 = 1.65$ $Q \text{ кг.} = 0.45$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 126$ $P \text{ вн.мм} = 42.4$ Гр. сл. = V Точн. = П		<b>БПЗ-1110</b> $F \text{ см}^2 = 3.45$ $Q \text{ кг.} = 0.936$ $D \text{ оп.мм} = 91$ $P \text{ н.мм} = 319.6$ $P \text{ вн.мм} = 69.6$ Гр. сл. = V Точн. = П











	<p><b>БПЗ-1111</b></p> <p> <math>F \text{ см}^2 = 2.598</math>  <math>Q \text{ кг.} = 0.704</math>  <math>D \text{ оп.мм} = 43</math>  <math>P \text{ н.мм} = 196</math>  <math>P \text{ вн.мм} = 79.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1116</b></p> <p> <math>F \text{ см}^2 = 2.356</math>  <math>Q \text{ кг.} = 0.638</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 88</math>  <math>P \text{ вн.мм} = 69.1</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1112</b></p> <p> <math>F \text{ см}^2 = 3.454</math>  <math>Q \text{ кг.} = 0.936</math>  <math>D \text{ оп.мм} = 91</math>  <math>P \text{ н.мм} = 319.6</math>  <math>P \text{ вн.мм} = 69.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1117</b></p> <p> <math>F \text{ см}^2 = 2.04</math>  <math>Q \text{ кг.} = 0.552</math>  <math>D \text{ оп.мм} = 30</math>  <math>P \text{ н.мм} = 94.3</math>  <math>P \text{ вн.мм} = 79.5</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1113</b></p> <p> <math>F \text{ см}^2 = 3.259</math>  <math>Q \text{ кг.} = 0.883</math>  <math>D \text{ оп.мм} = 62</math>  <math>P \text{ н.мм} = 251.4</math>  <math>P \text{ вн.мм} = 102</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1118</b></p> <p> <math>F \text{ см}^2 = 4.12</math>  <math>Q \text{ кг.} = 1.116</math>  <math>D \text{ оп.мм} = 53</math>  <math>P \text{ н.мм} = 146</math>  <math>P \text{ вн.мм} = 122</math>  Гр. сл. = III  Точн. = особая </p>
	<p><b>БПЗ-1114</b></p> <p> <math>F \text{ см}^2 = 2.562</math>  <math>Q \text{ кг.} = 0.694</math>  <math>D \text{ оп.мм} = 41</math>  <math>P \text{ н.мм} = 181.5</math>  <math>P \text{ вн.мм} = 79.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1119</b></p> <p> <math>F \text{ см}^2 = 1.444</math>  <math>Q \text{ кг.} = 0.391</math>  <math>D \text{ оп.мм} = 25</math>  <math>P \text{ н.мм} = 81.6</math>  <math>P \text{ вн.мм} = 69.1</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1115</b></p> <p> <math>F \text{ см}^2 = 2.62</math>  <math>Q \text{ кг.} = 0.71</math>  <math>D \text{ оп.мм} = 57</math>  <math>P \text{ н.мм} = 196.7</math>  <math>P \text{ вн.мм} = 69.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1120</b></p> <p> <math>F \text{ см}^2 = 7.82</math>  <math>Q \text{ кг.} = 2.12</math>  <math>D \text{ оп.мм} = 57</math>  <math>P \text{ н.мм} = 267.4</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = V  Точн. = П </p>

	<p><b>БПЗ-1121</b></p> <p> <math>F \text{ см}^2 = 4.799</math>  <math>Q \text{ кг.} = 1.301</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 264.9</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1126</b></p> <p> <math>F \text{ см}^2 = 24.540</math>  <math>Q \text{ кг.} = 6.650</math>  <math>D \text{ оп.мм} = 75.0</math>  <math>P \text{ н.мм} = 235.6</math>  <math>P \text{ вн.мм} = 157.1</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1122</b></p> <p> <math>F \text{ см}^2 = 13.274</math>  <math>Q \text{ кг.} = 3.597</math>  <math>D \text{ оп.мм} = 78.0</math>  <math>P \text{ н.мм} = 245.0</math>  <math>P \text{ вн.мм} = 227.3</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1127</b></p> <p> <math>F \text{ см}^2 = 32.990</math>  <math>Q \text{ кг.} = 8.940</math>  <math>D \text{ оп.мм} = 85.0</math>  <math>P \text{ н.мм} = 267.0</math>  <math>P \text{ вн.мм} = 172.8</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1123</b></p> <p> <math>F \text{ см}^2 = 5.797</math>  <math>Q \text{ кг.} = 1.571</math>  <math>D \text{ оп.мм} = 101.0</math>  <math>P \text{ н.мм} = 277.0</math>  <math>P \text{ вн.мм} = 165.6</math>  Гр. сл. = 0соб.  Точн. = П </p>		
	<p><b>БПЗ-1124</b></p> <p> <math>F \text{ см}^2 = 82.000</math>  <math>Q \text{ кг.} = 22.222</math>  <math>D \text{ оп.мм} = 43.5</math>  <math>P \text{ н.мм} = 121.3</math>  <math>P \text{ вн.мм} = 53.4</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-1129</b></p> <p> <math>F \text{ см}^2 = 4.074</math>  <math>Q \text{ кг.} = 1.104</math>  <math>D \text{ оп.мм} = 105.0</math>  <math>P \text{ н.мм} = 320.8</math>  <math>P \text{ вн.мм} = 219.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1125</b></p> <p> <math>F \text{ см}^2 = 17.300</math>  <math>Q \text{ кг.} = 4.688</math>  <math>D \text{ оп.мм} = 65.0</math>  <math>P \text{ н.мм} = 204.2</math>  <math>P \text{ вн.мм} = 141.4</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1130</b></p> <p> <math>F \text{ см}^2 = 3.642</math>  <math>Q \text{ кг.} = 0.987</math>  <math>D \text{ оп.мм} = 100.0</math>  <math>P \text{ н.мм} = 319.1</math>  <math>P \text{ вн.мм} = 165.1</math>  Гр. сл. = V  Точн. = П </p>











	<p><b>БПЗ-1131</b></p> <p> <math>F \text{ см}^2 = 4.343</math>  <math>Q \text{ кг.} = 1.177</math>  <math>D \text{ оп.мм} = 42.0</math>  <math>P \text{ н.мм} = 416.2</math>  <math>P \text{ вн.мм} = 43.2</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1136</b></p> <p> <math>F \text{ см}^2 = 10.430</math>  <math>Q \text{ кг.} = 2.827</math>  <math>D \text{ оп.мм} = 61.5</math>  <math>P \text{ н.мм} = 195.2</math>  <math>P \text{ вн.мм} = 125.6</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1132</b></p> <p> <math>F \text{ см}^2 = 3.675</math>  <math>Q \text{ кг.} = 0.996</math>  <math>D \text{ оп.мм} = 102.0</math>  <math>P \text{ н.мм} = 236.0</math>  <math>P \text{ вн.мм} = 251.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1137</b></p> <p> <math>F \text{ см}^2 = 15.440</math>  <math>Q \text{ кг.} = 4.184</math>  <math>D \text{ оп.мм} = 104.5</math>  <math>P \text{ н.мм} = 295.2</math>  <math>P \text{ вн.мм} = 225.6</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1133</b></p> <p> <math>F \text{ см}^2 = 2.175</math>  <math>Q \text{ кг.} = 0.589</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>P \text{ н.мм} = 169.1</math>  <math>P \text{ вн.мм} = 112.6</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1138</b></p> <p> <math>F \text{ см}^2 = 1.729</math>  <math>Q \text{ кг.} = 0.469</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 143.5</math>  <math>P \text{ вн.мм} = 110.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1134</b></p> <p> <math>F \text{ см}^2 = 2.613</math>  <math>Q \text{ кг.} = 0.708</math>  <math>D \text{ оп.мм} = 64.0</math>  <math>P \text{ н.мм} = 152.5</math>  <math>P \text{ вн.мм} = 277.1</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1139</b></p> <p> <math>F \text{ см}^2 = 1.820</math>  <math>Q \text{ кг.} = 0.493</math>  <math>D \text{ оп.мм} = 60.7</math>  <math>P \text{ н.мм} = 176.1</math>  <math>P \text{ вн.мм} = 127.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1135</b></p> <p> <math>F \text{ см}^2 = 8.970</math>  <math>Q \text{ кг.} = 2.431</math>  <math>D \text{ оп.мм} = 49.9</math>  <math>P \text{ н.мм} = 160.0</math>  <math>P \text{ вн.мм} = 57.6</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1140</b></p> <p> <math>F \text{ см}^2 = 4.129</math>  <math>Q \text{ кг.} = 1.119</math>  <math>D \text{ оп.мм} = 61.0</math>  <math>P \text{ н.мм} = 233.6</math>  <math>P \text{ вн.мм} = 197.2</math>  Гр. сл. = VI  Точн. = П </p>











	<p><b>БПЗ-1141</b></p> <p> <math>F \text{ см}^2 = 14.610</math>  <math>Q \text{ кг.} = 3.959</math>  <math>D \text{ оп.мм} = 54.0</math>  <math>P \text{ н.мм} = 165.5</math>  <math>P \text{ вн.мм} = 88.0</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-1146</b></p> <p> <math>F \text{ см}^2 = 13.380</math>  <math>Q \text{ кг.} = 3.626</math>  <math>D \text{ оп.мм} = 145.0</math>  <math>P \text{ н.мм} = 553.6</math>  <math>P \text{ вн.мм} = 166.3</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1142</b></p> <p> <math>F \text{ см}^2 = 17.040</math>  <math>Q \text{ кг.} = 4.618</math>  <math>D \text{ оп.мм} = 58.0</math>  <math>P \text{ н.мм} = 179.4</math>  <math>P \text{ вн.мм} = 99.0</math>  Гр. сл. = III  Точн. = Н </p>		<p><b>БПЗ-1147</b></p> <p> <math>F \text{ см}^2 = 4.050</math>  <math>Q \text{ кг.} = 1.098</math>  <math>D \text{ оп.мм} = 85.0</math>  <math>P \text{ н.мм} = 266.0</math>  <math>P \text{ вн.мм} = 218.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1143</b></p> <p> <math>F \text{ см}^2 = 0.665</math>  <math>Q \text{ кг.} = 0.180</math>  <math>D \text{ оп.мм} = 20.0</math>  <math>P \text{ н.мм} = 78.2</math>  <math>P \text{ вн.мм} = 30.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-1148</b></p> <p> <math>F \text{ см}^2 = 4.720</math>  <math>Q \text{ кг.} = 1.279</math>  <math>D \text{ оп.мм} = 101.0</math>  <math>P \text{ н.мм} = 305.0</math>  <math>P \text{ вн.мм} = 258.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1144</b></p> <p> <math>F \text{ см}^2 = 14.474</math>  <math>Q \text{ кг.} = 3.922</math>  <math>D \text{ оп.мм} = 95.0</math>  <math>P \text{ н.мм} = 248.9</math>  <math>P \text{ вн.мм} = 251.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1149</b></p> <p> <math>F \text{ см}^2 = 7.050</math>  <math>Q \text{ кг.} = 1.911</math>  <math>D \text{ оп.мм} = 130.0</math>  <math>P \text{ н.мм} = 466.9</math>  <math>P \text{ вн.мм} = 317.2</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1145</b></p> <p> <math>F \text{ см}^2 = 4.193</math>  <math>Q \text{ кг.} = 1.136</math>  <math>D \text{ оп.мм} = 57.0</math>  <math>P \text{ н.мм} = 257.9</math>  <math>P \text{ вн.мм} = 80.2</math>  Гр. сл. = VI  Точн. = П </p>		






	<b>БПЗ-1151</b> $F \text{ см}^2 = 2.34$ $Q \text{ кг.} = 0.632$ $D \text{ оп.мм} = 53$ $P \text{ н.мм} = 195.6$ $P \text{ вн.мм} = 65$ Гр. сл. = V Точн. = особой		<b>БПЗ-1156</b> $F \text{ см}^2 = 11.92$ $Q \text{ кг.} = 3.23$ $D \text{ оп.мм} = 127$ $P \text{ н.мм} = 552$ $P \text{ вн.мм} = 552$ Гр. сл. = Точн. = П
	<b>БПЗ-1152</b> $F \text{ см}^2 = 2.59$ $Q \text{ кг.} = 0.699$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 229.5$ $P \text{ вн.мм} = 65.6$ Гр. сл. = V Точн. = особой		<b>БПЗ-1157</b> $F \text{ см}^2 = 11.45$ $Q \text{ кг.} = 3.1$ $D \text{ оп.мм} = 134$ $P \text{ н.мм} = 462$ $P \text{ вн.мм} = 593$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1153</b> $F \text{ см}^2 = 3.1$ $Q \text{ кг.} = 0.837$ $D \text{ оп.мм} = 77$ $P \text{ н.мм} = 295.6$ $P \text{ вн.мм} = 65.6$ Гр. сл. = V Точн. = особой		<b>БПЗ-1158</b> $F \text{ см}^2 = 12.49$ $Q \text{ кг.} = 3.38$ $D \text{ оп.мм} = 134$ $P \text{ н.мм} = 566$ $P \text{ вн.мм} = 593$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1154</b> $F \text{ см}^2 = 1.03$ $Q \text{ кг.} = 0.279$ $D \text{ оп.мм} = 26$ $P \text{ н.мм} = 62.8$ $P \text{ вн.мм} = 51.5$ Гр. сл. = IV Точн. = Н		<b>БПЗ-1159</b> $F \text{ см}^2 = 5.81$ $Q \text{ кг.} = 1.575$ $D \text{ оп.мм} = 83$ $P \text{ н.мм} = 406.3$ $P \text{ вн.мм} = 0$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1155</b> $F \text{ см}^2 = 10.88$ $Q \text{ кг.} = 2.94$ $D \text{ оп.мм} = 127$ $P \text{ н.мм} = 448$ $P \text{ вн.мм} = 552$ Гр. сл. = особая Точн. = П		<b>БПЗ-1160</b> $F \text{ см}^2 = 11.31$ $Q \text{ кг.} = 3.065$ $D \text{ оп.мм} = 144$ $P \text{ н.мм} = 559.6$ $P \text{ вн.мм} = 395.2$ Гр. сл. = особая Точн. = П







	<p><b>БПЗ-1161</b></p> <p> <math>F \text{ см}^2 = 4.252</math>  <math>Q \text{ кг.} = 1.152</math>  <math>D \text{ оп.мм} = 66</math>  <math>P \text{ н.мм} = 234.5</math>  <math>P \text{ вн.мм} = 289.3</math>  Гр. сл. = особой  Точн. = П </p>		<p><b>БПЗ-1166</b></p> <p> <math>F \text{ см}^2 = 2.49</math>  <math>Q \text{ кг.} = 0.673</math>  <math>D \text{ оп.мм} = 57</math>  <math>P \text{ н.мм} = 224.7</math>  <math>P \text{ вн.мм} = 47.6</math>  Гр. сл. = V  Точн. = особой </p>
	<p><b>БПЗ-1162</b></p> <p> <math>F \text{ см}^2 = 2.776</math>  <math>Q \text{ кг.} = 0.752</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 150.6</math>  <math>P \text{ вн.мм} = 158</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1167</b></p> <p> <math>F \text{ см}^2 = 5.561</math>  <math>Q \text{ кг.} = 1.507</math>  <math>D \text{ оп.мм} = 62</math>  <math>P \text{ н.мм} = 194.8</math>  <math>P \text{ вн.мм} = 175.9</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1163</b></p> <p> <math>F \text{ см}^2 = 0.945</math>  <math>Q \text{ кг.} = 0.256</math>  <math>D \text{ оп.мм} = 25</math>  <math>P \text{ н.мм} = 69</math>  <math>P \text{ вн.мм} = 57</math>  Гр. сл. = IV  Точн. = особой </p>		<p><b>БПЗ-1168</b></p> <p> <math>F \text{ см}^2 = 11.942</math>  <math>Q \text{ кг.} = 3.236</math>  <math>D \text{ оп.мм} = 52</math>  <math>P \text{ н.мм} = 160.3</math>  <math>P \text{ вн.мм} = 99</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-1164</b></p> <p> <math>F \text{ см}^2 = 6.67</math>  <math>Q \text{ кг.} = 1.808</math>  <math>D \text{ оп.мм} = 104</math>  <math>P \text{ н.мм} = 274.9</math>  <math>P \text{ вн.мм} = 259.1</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1169</b></p> <p> <math>F \text{ см}^2 = 14.896</math>  <math>Q \text{ кг.} = 4.037</math>  <math>D \text{ оп.мм} = 52</math>  <math>P \text{ н.мм} = 160.3</math>  <math>P \text{ вн.мм} = 99</math>  Гр. сл. = III  Точн. = Н </p>
	<p><b>БПЗ-1165</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм} = 0</math>  <math>P \text{ н.мм} = 0</math>  <math>P \text{ вн.мм} = 0</math>  Гр. сл. = 0  Точн. = 0 </p>		<p><b>БПЗ-1170</b></p> <p> <math>F \text{ см}^2 = 21.553</math>  <math>Q \text{ кг.} = 5.84</math>  <math>D \text{ оп.мм} = 65</math>  <math>P \text{ н.мм} = 201</math>  <math>P \text{ вн.мм} = 110</math>  Гр. сл. = III  Точн. = Н </p>




















	<p><b>БПЗ-1171</b></p> <p> <math>F \text{ см}^2 = 3.300</math>  <math>Q \text{ кг.} = 0.894</math>  <math>D \text{ оп.мм} = 44.0</math>  <math>P \text{ н.мм} = 119.0</math>  <math>P \text{ вн.мм} = 46.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1176</b></p> <p> <math>F \text{ см}^2 = 13.358</math>  <math>Q \text{ кг.} = 3.620</math>  <math>D \text{ оп.мм} = 15.0</math>  <math>P \text{ н.мм} = 175.3</math>  <math>P \text{ вн.мм} = 72.2</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1172</b></p> <p> <math>F \text{ см}^2 = 8.830</math>  <math>Q \text{ кг.} = 2.393</math>  <math>D \text{ оп.мм} = 113.0</math>  <math>P \text{ н.мм} = 213.8</math>  <math>P \text{ вн.мм} = 510.2</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1177</b></p> <p> <math>F \text{ см}^2 = 4.481</math>  <math>Q \text{ кг.} = 1.214</math>  <math>D \text{ оп.мм} = 56.0</math>  <math>P \text{ н.мм} = 269.2</math>  <math>P \text{ вн.мм} = 56.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1173</b></p> <p> <math>F \text{ см}^2 = 4.253</math>  <math>Q \text{ кг.} = 1.153</math>  <math>D \text{ оп.мм} = 78.7</math>  <math>P \text{ н.мм} = 263.0</math>  <math>P \text{ вн.мм} = 108.0</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1178</b></p> <p> <math>F \text{ см}^2 = 3.083</math>  <math>Q \text{ кг.} = 0.835</math>  <math>D \text{ оп.мм} = 35.0</math>  <math>P \text{ н.мм} = 157.9</math>  <math>P \text{ вн.мм} = 86.7</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1174</b></p> <p> <math>F \text{ см}^2 = 4.972</math>  <math>Q \text{ кг.} = 1.347</math>  <math>D \text{ оп.мм} = 66.0</math>  <math>P \text{ н.мм} = 151.7</math>  <math>P \text{ вн.мм} = 142.3</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1179</b></p> <p> <math>F \text{ см}^2 = 9.420</math>  <math>Q \text{ кг.} = 2.553</math>  <math>D \text{ оп.мм} = 92.0</math>  <math>P \text{ н.мм} = 500.2</math>  <math>P \text{ вн.мм} = 124.3</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1175</b></p> <p> <math>F \text{ см}^2 = 9.470</math>  <math>Q \text{ кг.} = 2.566</math>  <math>D \text{ оп.мм} = 51.5</math>  <math>P \text{ н.мм} = 132.6</math>  <math>P \text{ вн.мм} = 31.4</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1180</b></p> <p> <math>F \text{ см}^2 = 1.845</math>  <math>Q \text{ кг.} = 0.500</math>  <math>D \text{ оп.мм} = 55.0</math>  <math>P \text{ н.мм} = 167.3</math>  <math>P \text{ вн.мм} = 140.1</math>  Гр. сл. = VI  Точн. = П </p>




	<p><b>БПЗ-1181</b></p> <p> <math>F \text{ см}^2 = 1.745</math>  <math>Q \text{ кг.} = 0.473</math>  <math>D \text{ оп.мм} = 51</math>  <math>P \text{ н.мм} = 138.7</math>  <math>P \text{ вн.мм} = 127.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1186</b></p> <p> <math>F \text{ см}^2 = 4.124</math>  <math>Q \text{ кг.} = 1.118</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 285.1</math>  <math>P \text{ вн.мм} = 176.6</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1182</b></p> <p> <math>F \text{ см}^2 = 1.589</math>  <math>Q \text{ кг.} = 0.431</math>  <math>D \text{ оп.мм} = 48</math>  <math>P \text{ н.мм} = 127.1</math>  <math>P \text{ вн.мм} = 116</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1187</b></p> <p> <math>F \text{ см}^2 = 4.393</math>  <math>Q \text{ кг.} = 1.19</math>  <math>D \text{ оп.мм} = 86</math>  <math>P \text{ н.мм} = 309.2</math>  <math>P \text{ вн.мм} = 171.2</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1183</b></p> <p> <math>F \text{ см}^2 = 1.416</math>  <math>Q \text{ кг.} = 0.384</math>  <math>D \text{ оп.мм} = 46</math>  <math>P \text{ н.мм} = 114.5</math>  <math>P \text{ вн.мм} = 103.1</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1188</b></p> <p> <math>F \text{ см}^2 = 4.56</math>  <math>Q \text{ кг.} = 1.236</math>  <math>D \text{ оп.мм} = 77</math>  <math>P \text{ н.мм} = 332.7</math>  <math>P \text{ вн.мм} = 137.6</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1184</b></p> <p> <math>F \text{ см}^2 = 4.806</math>  <math>Q \text{ кг.} = 1.302</math>  <math>D \text{ оп.мм} = 54</math>  <math>P \text{ н.мм} = 169.7</math>  <math>P \text{ вн.мм} = 150.8</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1189</b></p> <p> <math>F \text{ см}^2 = 6.017</math>  <math>Q \text{ кг.} = 1.631</math>  <math>D \text{ оп.мм} = 113</math>  <math>P \text{ н.мм} = 329.8</math>  <math>P \text{ вн.мм} = 284.3</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1185</b></p> <p> <math>F \text{ см}^2 = 3.753</math>  <math>Q \text{ кг.} = 1.017</math>  <math>D \text{ оп.мм} = 53.3</math>  <math>P \text{ н.мм} = 198.2</math>  <math>P \text{ вн.мм} = 164.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1190</b></p> <p> <math>F \text{ см}^2 = 1.318</math>  <math>Q \text{ кг.} = 0.357</math>  <math>D \text{ оп.мм} = 29</math>  <math>P \text{ н.мм} = 91.8</math>  <math>P \text{ вн.мм} = 89.6</math>  Гр. сл. = V  Точн. = П </p>





	<p><b>БПЗ-1191</b></p> <p> <math>F \text{ см}^2 = 1.885</math>  <math>Q \text{ кг.} = 0.511</math>  <math>D \text{ оп.мм} = 38.0</math>  <math>P \text{ н.мм} = 145.5</math>  <math>P \text{ вн.мм} = 34.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1196</b></p> <p> <math>F \text{ см}^2 = 3.462</math>  <math>Q \text{ кг.} = 0.938</math>  <math>D \text{ оп.мм} = 90.8</math>  <math>P \text{ н.мм} = 310.0</math>  <math>P \text{ вн.мм} = 79.6</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1192</b></p> <p> <math>F \text{ см}^2 = 3.000</math>  <math>Q \text{ кг.} = 0.813</math>  <math>D \text{ оп.мм} = 65.6</math>  <math>P \text{ н.мм} = 250.5</math>  <math>P \text{ вн.мм} = 79.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1197</b></p> <p> <math>F \text{ см}^2 = 2.237</math>  <math>Q \text{ кг.} = 0.606</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 144.4</math>  <math>P \text{ вн.мм} = 144.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1193</b></p> <p> <math>F \text{ см}^2 = 3.119</math>  <math>Q \text{ кг.} = 0.845</math>  <math>D \text{ оп.мм} = 45.6</math>  <math>P \text{ н.мм} = 241.9</math>  <math>P \text{ вн.мм} = 89.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1198</b></p> <p> <math>F \text{ см}^2 = 3.173</math>  <math>Q \text{ кг.} = 0.860</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 281.8</math>  <math>P \text{ вн.мм} = 117.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1194</b></p> <p> <math>F \text{ см}^2 = 2.855</math>  <math>Q \text{ кг.} = 0.774</math>  <math>D \text{ оп.мм} = 61.0</math>  <math>P \text{ н.мм} = 247.3</math>  <math>P \text{ вн.мм} = 59.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1199</b></p> <p> <math>F \text{ см}^2 = 3.603</math>  <math>Q \text{ кг.} = 0.976</math>  <math>D \text{ оп.мм} = 88.0</math>  <math>P \text{ н.мм} = 323.8</math>  <math>P \text{ вн.мм} = 159.9</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1195</b></p> <p> <math>F \text{ см}^2 = 3.656</math>  <math>Q \text{ кг.} = 0.991</math>  <math>D \text{ оп.мм} = 62.0</math>  <math>P \text{ н.мм} = 291.4</math>  <math>P \text{ вн.мм} = 105.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1200</b></p> <p> <math>F \text{ см}^2 = 3.369</math>  <math>Q \text{ кг.} = 0.913</math>  <math>D \text{ оп.мм} = 50.0</math>  <math>P \text{ н.мм} = 340.7</math>  <math>P \text{ вн.мм} = 117.8</math>  Гр. сл. = VI  Точн. = П </p>

	<p><b>БПЗ-1201</b></p> <p> <math>F \text{ см}^2 = 3.998</math>  <math>Q \text{ кг.} = 1.083</math>  <math>D \text{ оп.мм} = 88</math>  <math>P \text{ н.мм} = 382.7</math>  <math>P \text{ вн.мм} = 159.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1206</b></p> <p> <math>F \text{ см}^2 = 8.398</math>  <math>Q \text{ кг.} = 2.276</math>  <math>D \text{ оп.мм} = 75</math>  <math>P \text{ н.мм} = 196.3</math>  <math>P \text{ вн.мм} = 188.3</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1202</b></p> <p> <math>F \text{ см}^2 = 4.119</math>  <math>Q \text{ кг.} = 1.116</math>  <math>D \text{ оп.мм} = 100</math>  <math>P \text{ н.мм} = 399.7</math>  <math>P \text{ вн.мм} = 178.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1207</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм} = 0</math>  <math>P \text{ н.мм} = 0</math>  <math>P \text{ вн.мм} = 0</math>  Гр. сл. = 0  Точн. = 0 </p>
	<p><b>БПЗ-1203</b></p> <p> <math>F \text{ см}^2 = 3.414</math>  <math>Q \text{ кг.} = 0.925</math>  <math>D \text{ оп.мм} = 82</math>  <math>P \text{ н.мм} = 343.8</math>  <math>P \text{ вн.мм} = 122.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1208</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм} = 0</math>  <math>P \text{ н.мм} = 0</math>  <math>P \text{ вн.мм} = 0</math>  Гр. сл. = 0  Точн. = 0 </p>
	<p><b>БПЗ-1204</b></p> <p> <math>F \text{ см}^2 = 2.865</math>  <math>Q \text{ кг.} = 0.776</math>  <math>D \text{ оп.мм} = 70</math>  <math>P \text{ н.мм} = 365.7</math>  <math>P \text{ вн.мм} = 0</math>  Гр. сл. = особая  Точн. = Н </p>		<p><b>БПЗ-1209</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм} = 0</math>  <math>P \text{ н.мм} = 0</math>  <math>P \text{ вн.мм} = 0</math>  Гр. сл. = 0  Точн. = 0 </p>
	<p><b>БПЗ-1205</b></p> <p> <math>F \text{ см}^2 = 19.419</math>  <math>Q \text{ кг.} = 5.263</math>  <math>D \text{ оп.мм} = 111</math>  <math>P \text{ н.мм} = 292.8</math>  <math>P \text{ вн.мм} = 276</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1210</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм} = 0</math>  <math>P \text{ н.мм} = 0</math>  <math>P \text{ вн.мм} = 0</math>  Гр. сл. = 0  Точн. = 0 </p>






	<p><b>БПЗ-1211</b></p> <p> <math>F \text{ см}^2 = 1.120</math>  <math>Q \text{ кг.} = 0.304</math>  <math>D \text{ оп.мм} = 33.7</math>  <math>P \text{ н.мм} = 90.0</math>  <math>P \text{ вн.мм} = 81.3</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1216</b></p> <p> <math>F \text{ см}^2 = 4.724</math>  <math>Q \text{ кг.} = 1.280</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 259.9</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = V  Точн. = 0соб. </p>
	<p><b>БПЗ-1212</b></p> <p> <math>F \text{ см}^2 = 0.730</math>  <math>Q \text{ кг.} = 0.198</math>  <math>D \text{ оп.мм} = 30.0</math>  <math>P \text{ н.мм} = 72.9</math>  <math>P \text{ вн.мм} = 63.0</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1217</b></p> <p> <math>F \text{ см}^2 = 13.766</math>  <math>Q \text{ кг.} = 3.731</math>  <math>D \text{ оп.мм} = 103.0</math>  <math>P \text{ н.мм} = 340.2</math>  <math>P \text{ вн.мм} = 289.0</math>  Гр. сл. = V  Точн. = Н </p>
	<p><b>БПЗ-1213</b></p> <p> <math>F \text{ см}^2 = 2.248</math>  <math>Q \text{ кг.} = 0.609</math>  <math>D \text{ оп.мм} = 45.0</math>  <math>P \text{ н.мм} = 147.6</math>  <math>P \text{ вн.мм} = 58.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-1218</b></p> <p> <math>F \text{ см}^2 = 7.903</math>  <math>Q \text{ кг.} = 2.142</math>  <math>D \text{ оп.мм} = 140.0</math>  <math>P \text{ н.мм} = 348.3</math>  <math>P \text{ вн.мм} = 387.5</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1214</b></p> <p> <math>F \text{ см}^2 = 27.200</math>  <math>Q \text{ кг.} = 7.371</math>  <math>D \text{ оп.мм} = 133.0</math>  <math>P \text{ н.мм} = 442.9</math>  <math>P \text{ вн.мм} = 72.0</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-1219</b></p> <p> <math>F \text{ см}^2 = 9.704</math>  <math>Q \text{ кг.} = 2.630</math>  <math>D \text{ оп.мм} = 115.0</math>  <math>P \text{ н.мм} = 367.0</math>  <math>P \text{ вн.мм} = 271.8</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1215</b></p> <p> <math>F \text{ см}^2 = 1.610</math>  <math>Q \text{ кг.} = 0.436</math>  <math>D \text{ оп.мм} = 51.0</math>  <math>P \text{ н.мм} = 129.2</math>  <math>P \text{ вн.мм} = 120.3</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1220</b></p> <p> <math>F \text{ см}^2 = 5.683</math>  <math>Q \text{ кг.} = 1.540</math>  <math>D \text{ оп.мм} = 82.0</math>  <math>P \text{ н.мм} = 291.7</math>  <math>P \text{ вн.мм} = 201.3</math>  Гр. сл. = V  Точн. = П </p>









	<b>БПЗ-1221</b> $F \text{ см}^2 = 4.090$ $Q \text{ кг.} = 1.108$ $D \text{ оп.мм} = 70.2$ $P \text{ н.мм} = 329.0$ $P \text{ вн.мм} = 119.6$ Гр. сл. = V Точн. = П		<b>БПЗ-1226</b> $F \text{ см}^2 = 6.154$ $Q \text{ кг.} = 1.668$ $D \text{ оп.мм} = 84.7$ $P \text{ н.мм} = 373.6$ $P \text{ вн.мм} = 199.2$ Гр. сл. = V Точн. = П
			<b>БПЗ-1227</b> $F \text{ см}^2 = 4.187$ $Q \text{ кг.} = 1.135$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 229.3$ $P \text{ вн.мм} = 164.5$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-1223</b> $F \text{ см}^2 = 2.751$ $Q \text{ кг.} = 0.746$ $D \text{ оп.мм} = 45.5$ $P \text{ н.мм} = 191.5$ $P \text{ вн.мм} = 89.2$ Гр. сл. = V Точн. = П		<b>БПЗ-1228</b> $F \text{ см}^2 = 3.374$ $Q \text{ кг.} = 0.914$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 216.0$ $P \text{ вн.мм} = 231.0$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-1224</b> $F \text{ см}^2 = 1.706$ $Q \text{ кг.} = 0.462$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 139.2$ $P \text{ вн.мм} = 141.7$ Гр. сл. = V Точн. = П		<b>БПЗ-1229</b> $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 51.0$ $P \text{ н.мм} = 134.3$ $P \text{ вн.мм} = 81.7$ Гр. сл. = V Точн. = Н
	<b>БПЗ-1225</b> $F \text{ см}^2 = 6.808$ $Q \text{ кг.} = 1.845$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 431.4$ $P \text{ вн.мм} = 187.3$ Гр. сл. = V Точн. = П		<b>БПЗ-1230</b> $F \text{ см}^2 = 15.845$ $Q \text{ кг.} = 4.294$ $D \text{ оп.мм} = 125.0$ $P \text{ н.мм} = 445.4$ $P \text{ вн.мм} = 157.4$ Гр. сл. = 0соб. Точн. = Н


	<p><b>БПЗ-1231</b></p> <p> <math>F \text{ см}^2 = 9.697</math>  <math>Q \text{ кг.} = 2.628</math>  <math>D \text{ оп.мм} = 111</math>  <math>P \text{ н.мм} = 373.4</math>  <math>P \text{ вн.мм} = 84</math>  Гр. сл. = V  Точн. = Н </p>	<p><b>БПЗ-1236</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1232</b></p> <p> <math>F \text{ см}^2 = 25.341</math>  <math>Q \text{ кг.} = 6.867</math>  <math>D \text{ оп.мм} = 100</math>  <math>P \text{ н.мм} = 1371</math>  <math>P \text{ вн.мм} = 78.5</math>  Гр. сл. = Особ.  Точн. = П </p>	<p><b>БПЗ-1237</b></p> <p> <math>F \text{ см}^2 = 8.98</math>  <math>Q \text{ кг.} = 2.434</math>  <math>D \text{ оп.мм} = 164</math>  <math>P \text{ н.мм} = 784.3</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1233</b></p> <p> <math>F \text{ см}^2 = 1.586</math>  <math>Q \text{ кг.} = 0.43</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 97.5</math>  <math>P \text{ вн.мм} = 46.9</math>  Гр. сл. = VI  Точн. = П </p>	<p><b>БПЗ-1238</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1234</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>	<p><b>БПЗ-1239</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1235</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>	<p><b>БПЗ-1240</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>








	БПЗ-1241		БПЗ-1246
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.45$ $Q \text{ кг.} = 0.393$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 146$ $P \text{ вн.мм} = 25.4$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-1242		БПЗ-1247
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.096$ $Q \text{ кг.} = 0.297$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 100$ $P \text{ вн.мм} = 25.4$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПЗ-1243		БПЗ-1248
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$
	БПЗ-1244		БПЗ-1249
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 1.259$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 133.6$ $P \text{ вн.мм} = 16$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
	БПЗ-1245		БПЗ-1250
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\text{Гр. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 3.391$ $Q \text{ кг.} = 0.919$ $D \text{ оп.мм} = 67$ $P \text{ н.мм} = 246.7$ $P \text{ вн.мм} = 177.1$ $\text{Гр. сл.} = \text{Особ.}$ $\text{Точн.} = \text{П}$
















	<p><b>БПЗ-1251</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1256</b></p> <p> <math>F \text{ см}^2 = 21.773</math>  <math>Q \text{ кг.} = 5.9</math>  <math>D \text{ оп.мм} = 120</math>  <math>P \text{ н.мм} = 1106</math>  <math>P \text{ вн.мм} = 245</math>  Гр. сл. = особая  Точн. = особая </p>
	<p><b>БПЗ-1252</b></p> <p> <math>F \text{ см}^2 = 10.833</math>  <math>Q \text{ кг.} = 2.936</math>  <math>D \text{ оп.мм} = 128</math>  <math>P \text{ н.мм} = 337.5</math>  <math>P \text{ вн.мм} = 377.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1257</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1253</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1258</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1254</b></p> <p> <math>F \text{ см}^2 = 3.8</math>  <math>Q \text{ кг.} = 1.03</math>  <math>D \text{ оп.мм} = 96.5</math>  <math>P \text{ н.мм} = 330.6</math>  <math>P \text{ вн.мм} = 99.6</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1259</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1255</b></p> <p> <math>F \text{ см}^2 = 6.808</math>  <math>Q \text{ кг.} = 1.845</math>  <math>D \text{ оп.мм} = 92.0</math>  <math>P \text{ н.мм} = 431.4</math>  <math>P \text{ вн.мм} = 187.3</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1260</b></p> <p> <math>F \text{ см}^2 = 10.062</math>  <math>Q \text{ кг.} = 2.727</math>  <math>D \text{ оп.мм} = 134</math>  <math>P \text{ н.мм} = 480.1</math>  <math>P \text{ вн.мм} = 420.2</math>  Гр. сл. = 0соб.  Точн. = П </p>






	<p><b>БПЗ-1261</b></p> <p> <math>F \text{ см}^2 = 10.578</math>  <math>Q \text{ кг.} = 2.867</math>  <math>D \text{ оп.мм} = 134</math>  <math>P \text{ н.мм} = 609.8</math>  <math>P \text{ вн.мм} = 255.7</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1266</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1262</b></p> <p> <math>F \text{ см}^2 = 2.67</math>  <math>Q \text{ кг.} = 0.723</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 200</math>  <math>P \text{ вн.мм} = 50.4</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1267</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1263</b></p> <p> <math>F \text{ см}^2 = 2.54</math>  <math>Q \text{ кг.} = 0.688</math>  <math>D \text{ оп.мм} = 53</math>  <math>P \text{ н.мм} = 219.8</math>  <math>P \text{ вн.мм} = 43.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1268</b></p> <p> <math>F \text{ см}^2 = 18.24</math>  <math>Q \text{ кг.} = 4.943</math>  <math>D \text{ оп.мм} = 170</math>  <math>P \text{ н.мм} = 783.3</math>  <math>P \text{ вн.мм} = 631.9</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1264</b></p> <p> <math>F \text{ см}^2 = 2.643</math>  <math>Q \text{ кг.} = 0.716</math>  <math>D \text{ оп.мм} = 46</math>  <math>P \text{ н.мм} = 166.3</math>  <math>P \text{ вн.мм} = 93.9</math>  Гр. сл. = VI  Точн. = особая </p>		<p><b>БПЗ-1269</b></p> <p> <math>F \text{ см}^2 = 0.683</math>  <math>Q \text{ кг.} = 0.185</math>  <math>D \text{ оп.мм} = 16</math>  <math>P \text{ н.мм} = 50.3</math>  <math>P \text{ вн.мм} = 40.8</math>  Гр. сл. = II  Точн. = П </p>
	<p><b>БПЗ-1265</b></p> <p> <math>F \text{ см}^2 = 4.98</math>  <math>Q \text{ кг.} = 1.35</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 185.6</math>  <math>P \text{ вн.мм} = 200.2</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1270</b></p> <p> <math>F \text{ см}^2 = 10.447</math>  <math>Q \text{ кг.} = 2.831</math>  <math>D \text{ оп.мм} = 148</math>  <math>P \text{ н.мм} = 367.7</math>  <math>P \text{ вн.мм} = 458.2</math>  Гр. сл. = VI  Точн. = П </p>








			БПЗ-1276
			$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} =$
	БПЗ-1272		БПЗ-1277
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} =$
	БПЗ-1273		БПЗ-1278
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} =$		$F \text{ см}^2 = 5.32$ $Q \text{ кг.} = 1.436$ $D \text{ оп.мм} = 83$ $P \text{ н.мм} = 236.2$ $P \text{ вн.мм} = 204.4$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПЗ-1274		БПЗ-1279
	$F \text{ см}^2 = 2.643$ $Q \text{ кг.} = 0.716$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 166.3$ $P \text{ вн.мм} = 93.9$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{особая}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} =$
	БПЗ-1275		БПЗ-1280
	$F \text{ см}^2 = 2.222$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм} = 19$ $P \text{ н.мм} = 58.5$ $P \text{ вн.мм} = 22$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} =$

	<b>БПЗ-1281</b> $F \text{ см}^2 = 5.529$ $Q \text{ кг.} = 1.498$ $D \text{ оп.мм} = 90$ $P \text{ н.мм} = 282.7$ $P \text{ вн.мм} = 270.2$ Гр. сл. = IV Точн. = Н		<b>БПЗ-1286</b> $F \text{ см}^2 = 5.111$ $Q \text{ кг.} = 1.385$ $D \text{ оп.мм} = 95$ $P \text{ н.мм} = 328.9$ $P \text{ вн.мм} = 181.6$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1282</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =		<b>БПЗ-1287</b> $F \text{ см}^2 = 3.4$ $Q \text{ кг.} = 0.92$ $D \text{ оп.мм} = 83$ $P \text{ н.мм} = 125.1$ $P \text{ вн.мм} = 83$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1283</b> $F \text{ см}^2 = 5.073$ $Q \text{ кг.} = 1.375$ $D \text{ оп.мм} = 70$ $P \text{ н.мм} = 238.2$ $P \text{ вн.мм} = 169.7$ Гр. сл. = V Точн. = П		<b>БПЗ-1288</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =
	<b>БПЗ-1284</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =		<b>БПЗ-1289</b> $F \text{ см}^2 = 1.136$ $Q \text{ кг.} = 0.308$ $D \text{ оп.мм} = 45$ $P \text{ н.мм} = 105.8$ $P \text{ вн.мм} = 63.1$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1285</b> $F \text{ см}^2 = 13.057$ $Q \text{ кг.} = 3.538$ $D \text{ оп.мм} = 152$ $P \text{ н.мм} = 1243$ $P \text{ вн.мм} = 53.4$ Гр. сл. = Особ. Точн. = Н		<b>БПЗ-1290</b> $F \text{ см}^2 = 2.546$ $Q \text{ кг.} = 0.69$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 162.2$ $P \text{ вн.мм} = 156.5$ Гр. сл. = Особ. Точн. = П









	<b>БПЗ-1291</b> $F \text{ см}^2 = 2.535$ $Q \text{ кг.} = 0.687$ $D \text{ оп.мм} = 66$ $P \text{ н.мм} = 162.9$ $P \text{ вн.мм} = 107.3$ Гр. сл. = IV Точн. = П		<b>БПЗ-1296</b> $F \text{ см}^2 = 34.74$ $Q \text{ кг.} = 9.415$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 314.2$ $P \text{ вн.мм} = 232.5$ Гр. сл. = III Точн. = Н
	<b>БПЗ-1292</b> $F \text{ см}^2 = 8.28$ $Q \text{ кг.} = 2.244$ $D \text{ оп.мм} = 159$ $P \text{ н.мм} = 649.4$ $P \text{ вн.мм} = 154.4$ Гр. сл. = VI Точн. = П		<b>БПЗ-1297</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =
	<b>БПЗ-1293</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =		<b>БПЗ-1298</b> $F \text{ см}^2 = 5.761$ $Q \text{ кг.} = 1.561$ $D \text{ оп.мм} = 63$ $P \text{ н.мм} = 316$ $P \text{ вн.мм} = 111.9$ Гр. сл. = V Точн. = П
	<b>БПЗ-1294</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =		<b>БПЗ-1299</b> $F \text{ см}^2 = 6.359$ $Q \text{ кг.} = 1.723$ $D \text{ оп.мм} = 87$ $P \text{ н.мм} = 336.3$ $P \text{ вн.мм} = 251.5$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1295</b> $F \text{ см}^2 = 18.26$ $Q \text{ кг.} = 4.948$ $D \text{ оп.мм} = 85$ $P \text{ н.мм} = 267$ $P \text{ вн.мм} = 219.9$ Гр. сл. = III Точн. = Н		<b>БПЗ-1300</b> $F \text{ см}^2 = 8.53$ $Q \text{ кг.} = 2.312$ $D \text{ оп.мм} = 95$ $P \text{ н.мм} = 379.8$ $P \text{ вн.мм} = 354.7$ Гр. сл. = Особ. Точн. = П





	<p><b>БПЗ-1301</b></p> <p> <math>F \text{ см}^2 = 2.139</math>  <math>Q \text{ кг.} = 0.580</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 150.5</math>  <math>P \text{ вн.мм} = 139.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1306</b></p> <p> <math>F \text{ см}^2 = 0.272</math>  <math>Q \text{ кг.} = 0.074</math>  <math>D \text{ оп.мм} = 9.4</math>  <math>P \text{ н.мм} = 25.7</math>  <math>P \text{ вн.мм} = 17.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1302</b></p> <p> <math>F \text{ см}^2 = 1.894</math>  <math>Q \text{ кг.} = 0.513</math>  <math>D \text{ оп.мм} = 70.0</math>  <math>P \text{ н.мм} = 144.4</math>  <math>P \text{ вн.мм} = 114.2</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1307</b></p> <p> <math>F \text{ см}^2 = 10.400</math>  <math>Q \text{ кг.} = 2.818</math>  <math>D \text{ оп.мм} = 166.0</math>  <math>P \text{ н.мм} = 429.0</math>  <math>P \text{ вн.мм} = 403.0</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1303</b></p> <p> <math>F \text{ см}^2 = 7.231</math>  <math>Q \text{ кг.} = 1.960</math>  <math>D \text{ оп.мм} = 82.0</math>  <math>P \text{ н.мм} = 257.6</math>  <math>P \text{ вн.мм} = 311.2</math>  Гр. сл. = VI  Точн. = П </p>		
			<p><b>БПЗ-1309</b></p> <p> <math>F \text{ см}^2 = 1.441</math>  <math>Q \text{ кг.} = 0.391</math>  <math>D \text{ оп.мм} = 47.0</math>  <math>P \text{ н.мм} = 116.7</math>  <math>P \text{ вн.мм} = 66.6</math>  Гр. сл. = IV  Точн. = П </p>

	<p><b>БПЗ-1311</b></p> <p> <math>F \text{ см}^2 = 4.769</math>  <math>Q \text{ кг.} = 1.292</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 230.1</math>  <math>P \text{ вн.мм} = 65.1</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1316</b></p> <p> <math>F \text{ см}^2 = 7.584</math>  <math>Q \text{ кг.} = 2.055</math>  <math>D \text{ оп.мм} = 120</math>  <math>P \text{ н.мм} = 684.4</math>  <math>P \text{ вн.мм} = 323.7</math>  Гр. сл. = Особ.  Точн. = Особ. </p>
	<p><b>БПЗ-1312</b></p> <p> <math>F \text{ см}^2 = 3.432</math>  <math>Q \text{ кг.} = 0.93</math>  <math>D \text{ оп.мм} = 72</math>  <math>P \text{ н.мм} = 233.9</math>  <math>P \text{ вн.мм} = 197.7</math>  Гр. сл. = Особ.  Точн. = П </p>		<p><b>БПЗ-1317</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1313</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1318</b></p> <p> <math>F \text{ см}^2 = 3.86</math>  <math>Q \text{ кг.} = 1.043</math>  <math>D \text{ оп.мм} = 89.2</math>  <math>P \text{ н.мм} = 329</math>  <math>P \text{ вн.мм} = 126.4</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1314</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1319</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>
	<p><b>БПЗ-1315</b></p> <p> <math>F \text{ см}^2 = 3.78</math>  <math>Q \text{ кг.} = 1.024</math>  <math>D \text{ оп.мм} = 108</math>  <math>P \text{ н.мм} = 253.9</math>  <math>P \text{ вн.мм} = 244.3</math>  Гр. сл. = Особ.  Точн. = П </p>		<p><b>БПЗ-1320</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>

	<p><b>БПЗ-1321</b></p> <p> <math>F \text{ см}^2 = 10.570</math>  <math>Q \text{ кг.} = 2.864</math>  <math>D \text{ оп.мм} = 145.0</math>  <math>P \text{ н.мм} = 554.1</math>  <math>P \text{ вн.мм} = 362.8</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1326</b></p> <p> <math>F \text{ см}^2 = 1.665</math>  <math>Q \text{ кг.} = 0.451</math>  <math>D \text{ оп.мм} = 52.0</math>  <math>P \text{ н.мм} = 128.0</math>  <math>P \text{ вн.мм} = 94.0</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1323</b></p> <p> <math>F \text{ см}^2 = 2.165</math>  <math>Q \text{ кг.} = 0.587</math>  <math>D \text{ оп.мм} = 46.0</math>  <math>P \text{ н.мм} = 219.9</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1328</b></p> <p> <math>F \text{ см}^2 = 2.970</math>  <math>Q \text{ кг.} = 0.805</math>  <math>D \text{ оп.мм} = 54.0</math>  <math>P \text{ н.мм} = 198.8</math>  <math>P \text{ вн.мм} = 99.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1324</b></p> <p> <math>F \text{ см}^2 = 18.980</math>  <math>Q \text{ кг.} = 5.144</math>  <math>D \text{ оп.мм} = 137.0</math>  <math>P \text{ н.мм} = 597.0</math>  <math>P \text{ вн.мм} = 0.0</math>  Гр. сл. = VI  Точн. = Н </p>		<p><b>БПЗ-1329</b></p> <p> <math>F \text{ см}^2 = 2.170</math>  <math>Q \text{ кг.} = 0.588</math>  <math>D \text{ оп.мм} = 38.0</math>  <math>P \text{ н.мм} = 170.4</math>  <math>P \text{ вн.мм} = 69.2</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1325</b></p> <p> <math>F \text{ см}^2 = 3.981</math>  <math>Q \text{ кг.} = 1.079</math>  <math>D \text{ оп.мм} = 78.0</math>  <math>P \text{ н.мм} = 261.0</math>  <math>P \text{ вн.мм} = 159.2</math>  Гр. сл. = V  Точн. = П </p>		




			<b>БПЗ-1336</b> $F \text{ см}^2 = 14.800$ $Q \text{ кг.} = 4.011$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 550.5$ $P \text{ вн.мм} = 388.8$ Гр. сл. = 0соб. Точн. = П
	<b>БПЗ-1332</b> $F \text{ см}^2 = 6.787$ $Q \text{ кг.} = 1.839$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 229.9$ $P \text{ вн.мм} = 147.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-1337</b> $F \text{ см}^2 = 2.540$ $Q \text{ кг.} = 0.688$ $D \text{ оп.мм} = 92.0$ $P \text{ н.мм} = 183.5$ $P \text{ вн.мм} = 174.1$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1333</b> $F \text{ см}^2 = 2.083$ $Q \text{ кг.} = 0.564$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 100.8$ $P \text{ вн.мм} = 54.0$ Гр. сл. = V Точн. = П		<b>БПЗ-1338</b> $F \text{ см}^2 = 9.896$ $Q \text{ кг.} = 2.682$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 163.4$ $P \text{ вн.мм} = 119.4$ Гр. сл. = III Точн. = П
	<b>БПЗ-1334</b> $F \text{ см}^2 = 5.502$ $Q \text{ кг.} = 1.491$ $D \text{ оп.мм} = 99.0$ $P \text{ н.мм} = 479.9$ $P \text{ вн.мм} = 0.0$ Гр. сл. = VI Точн. = П		<b>БПЗ-1339</b> $F \text{ см}^2 = 3.181$ $Q \text{ кг.} = 0.862$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 84.8$ $P \text{ вн.мм} = 56.6$ Гр. сл. = III Точн. = П
	<b>БПЗ-1335</b> $F \text{ см}^2 = 2.160$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 176.8$ $P \text{ вн.мм} = 0.0$ Гр. сл. = V Точн. = П		

	<b>БПЗ-1343</b> $F \text{ см}^2 = 15.538$ $Q \text{ кг.} = 4.211$ $D \text{ оп.мм} = 154.0$ $P \text{ н.мм} = 532.4$ $P \text{ вн.мм} = 452.0$ Гр. сл. = VI Точн. = П		
	<b>БПЗ-1344</b> $F \text{ см}^2 = 5.732$ $Q \text{ кг.} = 1.553$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 227.1$ $P \text{ вн.мм} = 136.4$ Гр. сл. = V Точн. = 0соб.		
	<b>БПЗ-1345</b> $F \text{ см}^2 = 7.830$ $Q \text{ кг.} = 2.122$ $D \text{ оп.мм} = 60.0$ $P \text{ н.мм} = 237.3$ $P \text{ вн.мм} = 69.1$ Гр. сл. = VI Точн. = П		<b>БПЗ-1350</b> $F \text{ см}^2 = 10.310$ $Q \text{ кг.} = 2.794$ $D \text{ оп.мм} = 182.0$ $P \text{ н.мм} = 577.6$ $P \text{ вн.мм} = 424.8$ Гр. сл. = 0соб. Точн. = П


БПЗ-1351

БПЗ-1353




$F \text{ см}^2 = 1.490$   
 $Q \text{ кг.} = 0.404$   
 $D \text{ оп.мм} = 25.0$   
 $P \text{ н.мм} = 107.5$   
 $P \text{ вн.мм} = 86.1$   
 $\text{Гр. сл.} = \text{VI}$   
 $\text{Точн.} = \text{П}$

БПЗ-1354













$F \text{ см}^2 = 1.145$   
 $Q \text{ кг.} = 0.310$   
 $D \text{ оп.мм} = 28.0$   
 $P \text{ н.мм} = 91.4$   
 $P \text{ вн.мм} = 76.2$   
 $\text{Гр. сл.} = \text{VI}$   
 $\text{Точн.} = \text{П}$











БПЗ-1355











БПО-1360








$F \text{ см}^2 = 12.554$   
 $Q \text{ кг.} = 3.402$   
 $D \text{ оп.мм} = 70.0$   
 $P \text{ н.мм} = 186.8$   
 $P \text{ вн.мм} = 59.7$   
 $\text{Гр. сл.} = \text{V}$   
 $\text{Точн.} = \text{П}$

	<b>БПЗ-1361</b> $F \text{ см}^2 = 0.440$ $Q \text{ кг.} = 0.119$ $D \text{ оп.мм} = 9.0$ $P \text{ н.мм} = 28.3$ $P \text{ вн.мм} = 15.7$ Гр. сл. = III Точн. = Н		<b>БПЗ-1366</b> $F \text{ см}^2 = 0.407$ $Q \text{ кг.} = 0.110$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 37.7$ $P \text{ вн.мм} = 30.2$ Гр. сл. = V Точн. = Н
	<b>БПЗ-1362</b> $F \text{ см}^2 = 7.216$ $Q \text{ кг.} = 1.956$ $D \text{ оп.мм} = 153.0$ $P \text{ н.мм} = 492.7$ $P \text{ вн.мм} = 229.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-1367</b> $F \text{ см}^2 = 1.767$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм} = 25.0$ $P \text{ н.мм} = 78.5$ $P \text{ вн.мм} = 62.8$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1363</b> $F \text{ см}^2 = 23.750$ $Q \text{ кг.} = 6.436$ $D \text{ оп.мм} = 132.0$ $P \text{ н.мм} = 414.7$ $P \text{ вн.мм} = 377.0$ Гр. сл. = V Точн. = П		<b>БПЗ-1368</b> $F \text{ см}^2 = 6.665$ $Q \text{ кг.} = 1.806$ $D \text{ оп.мм} = 105.0$ $P \text{ н.мм} = 377.7$ $P \text{ вн.мм} = 120.6$ Гр. сл. = V Точн. = П
	<b>БПЗ-1364</b> $F \text{ см}^2 = 13.934$ $Q \text{ кг.} = 3.776$ $D \text{ оп.мм} = 89.0$ $P \text{ н.мм} = 491.3$ $P \text{ вн.мм} = 140.1$ Гр. сл. = 0соб. Точн. = П		<b>БПЗ-1369</b> $F \text{ см}^2 = 11.230$ $Q \text{ кг.} = 3.043$ $D \text{ оп.мм} = 150.0$ $P \text{ н.мм} = 468.2$ $P \text{ вн.мм} = 453.1$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1365</b> $F \text{ см}^2 = 5.870$ $Q \text{ кг.} = 1.591$ $D \text{ оп.мм} = 34.0$ $P \text{ н.мм} = 96.6$ $P \text{ вн.мм} = 21.1$ Гр. сл. = V Точн. = П		<b>БПЗ-1370</b> $F \text{ см}^2 = 3.214$ $Q \text{ кг.} = 0.871$ $D \text{ оп.мм} = 84.0$ $P \text{ н.мм} = 203.1$ $P \text{ вн.мм} = 188.7$ Гр. сл. = III Точн. = П











	<p><b>БПЗ-1371</b></p> <p> <math>F \text{ см}^2 = 0.909</math>  <math>Q \text{ кг.} = 0.246</math>  <math>D \text{ оп.мм} = 26</math>  <math>R \text{ н.мм} = 99.4</math>  <math>R \text{ вн.мм} = 36.4</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1376</b></p> <p> <math>F \text{ см}^2 = 3.302</math>  <math>Q \text{ кг.} = 0.895</math>  <math>D \text{ оп.мм} = 50.2</math>  <math>R \text{ н.мм} = 140.6</math>  <math>R \text{ вн.мм} = 120.6</math>  Гр. сл. = III  Точн. = П </p>
	<p><b>БПЗ-1372</b></p> <p> <math>F \text{ см}^2 = 0.777</math>  <math>Q \text{ кг.} = 0.211</math>  <math>D \text{ оп.мм} = 25</math>  <math>R \text{ н.мм} = 78.7</math>  <math>R \text{ вн.мм} = 48.9</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1377</b></p> <p> <math>F \text{ см}^2 = 5.1</math>  <math>Q \text{ кг.} = 1.39</math>  <math>D \text{ оп.мм} = 59.6</math>  <math>R \text{ н.мм} = 207.3</math>  <math>R \text{ вн.мм} = 169.2</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1373</b></p> <p> <math>F \text{ см}^2 = 1.193</math>  <math>Q \text{ кг.} = 0.323</math>  <math>D \text{ оп.мм} = 33</math>  <math>R \text{ н.мм} = 101.7</math>  <math>R \text{ вн.мм} = 87.9</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1378</b></p> <p> <math>F \text{ см}^2 = 1.06</math>  <math>Q \text{ кг.} = 0.287</math>  <math>D \text{ оп.мм} = 29</math>  <math>R \text{ н.мм} = 96.4</math>  <math>R \text{ вн.мм} = 67</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1374</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>R \text{ н.мм} =</math>  <math>R \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1379</b></p> <p> <math>F \text{ см}^2 = 1.078</math>  <math>Q \text{ кг.} = 0.292</math>  <math>D \text{ оп.мм} = 33</math>  <math>R \text{ н.мм} = 130.1</math>  <math>R \text{ вн.мм} = 39.4</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1375</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>R \text{ н.мм} =</math>  <math>R \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1380</b></p> <p> <math>F \text{ см}^2 = 1.509</math>  <math>Q \text{ кг.} = 0.409</math>  <math>D \text{ оп.мм} = 40</math>  <math>R \text{ н.мм} = 120.7</math>  <math>R \text{ вн.мм} = 87.8</math>  Гр. сл. = VI  Точн. = П </p>







			БПЗ-1390
			F см <sup>2</sup> = 2.810 Q кг. = 0.762 D оп.мм= 42.0 P н.мм = 116.5 P вн.мм= 111.7 Гр. сл. = 0соб. Точн. = П





	<b>БПЗ-1391</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		<b>БПЗ-1396</b> $F \text{ см}^2 = 8.765$ $Q \text{ кг.} = 2.375$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 301.6$ $P \text{ вн.мм} = 282.7$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	<b>БПЗ-1392</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		<b>БПЗ-1397</b> $F \text{ см}^2 = 1.641$ $Q \text{ кг.} = 0.445$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 193.7$ $P \text{ вн.мм} = 0$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$
	<b>БПЗ-1393</b> $F \text{ см}^2 = 4.7$ $Q \text{ кг.} = 1.274$ $D \text{ оп.мм} = 55.8$ $P \text{ н.мм} = 147.1$ $P \text{ вн.мм} = 139.2$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$		<b>БПЗ-1398</b> $F \text{ см}^2 = 1.004$ $Q \text{ кг.} = 0.272$ $D \text{ оп.мм} = 33.1$ $P \text{ н.мм} = 111.8$ $P \text{ вн.мм} = 47.1$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$
	<b>БПЗ-1394</b> $F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} =$		<b>БПЗ-1399</b> $F \text{ см}^2 = 5.972$ $Q \text{ кг.} = 1.62$ $D \text{ оп.мм} = 83.5$ $P \text{ н.мм} = 348$ $P \text{ вн.мм} = 163$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$
	<b>БПЗ-1395</b> $F \text{ см}^2 = 2.268$ $Q \text{ кг.} = 0.615$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 193.4$ $P \text{ вн.мм} = 109.3$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$		<b>БПЗ-1400</b> $F \text{ см}^2 = 8.878$ $Q \text{ кг.} = 2.406$ $D \text{ оп.мм} = 80.5$ $P \text{ н.мм} = 213.2$ $P \text{ вн.мм} = 211.4$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$







	<p><b>БПЗ-1401</b></p> <p> <math>F \text{ см}^2 = 1.602</math>  <math>Q \text{ кг.} = 0.434</math>  <math>D \text{ оп.мм} = 40.0</math>  <math>P \text{ н.мм} = 177.3</math>  <math>P \text{ вн.мм} = 78.9</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1406</b></p> <p> <math>F \text{ см}^2 = 24.875</math>  <math>Q \text{ кг.} = 6.741</math>  <math>D \text{ оп.мм} = 156</math>  <math>P \text{ н.мм} = 1474.8</math>  <math>P \text{ вн.мм} = 362.9</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1402</b></p> <p> <math>F \text{ см}^2 = 0.872</math>  <math>Q \text{ кг.} = 0.236</math>  <math>D \text{ оп.мм} = 20</math>  <math>P \text{ н.мм} = 62.8</math>  <math>P \text{ вн.мм} = 53.4</math>  Гр. сл. = IV  Точн. = Н </p>		<p><b>БПЗ-1407</b></p> <p> <math>F \text{ см}^2 = 2.474</math>  <math>Q \text{ кг.} = 0.67</math>  <math>D \text{ оп.мм} = 22</math>  <math>P \text{ н.мм} = 69.1</math>  <math>P \text{ вн.мм} = 40.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1403</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1408</b></p> <p> <math>F \text{ см}^2 = 4.147</math>  <math>Q \text{ кг.} = 1.124</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 88</math>  <math>P \text{ вн.мм} = 50.3</math>  Гр. сл. = II  Точн. = П </p>
	<p><b>БПЗ-1404</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1409</b></p> <p> <math>F \text{ см}^2 = 5.937</math>  <math>Q \text{ кг.} = 1.609</math>  <math>D \text{ оп.мм} = 34</math>  <math>P \text{ н.мм} = 106.8</math>  <math>P \text{ вн.мм} = 62.8</math>  Гр. сл. = II  Точн. = П </p>
	<p><b>БПЗ-1405</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1410</b></p> <p> <math>F \text{ см}^2 = 5.462</math>  <math>Q \text{ кг.} = 1.48</math>  <math>D \text{ оп.мм} = 35</math>  <math>P \text{ н.мм} = 110</math>  <math>P \text{ вн.мм} = 72.3</math>  Гр. сл. = II  Точн. = П </p>





















	<p><b>БПЗ-1411</b></p> <p> <math>F \text{ см}^2 = 7.296</math>  <math>Q \text{ кг.} = 1.977</math>  <math>D \text{ оп.мм} = 80</math>  <math>P \text{ н.мм} = 348.2</math>  <math>P \text{ вн.мм} = 199</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1416</b></p> <p> <math>F \text{ см}^2 = 18.445</math>  <math>Q \text{ кг.} = 4.999</math>  <math>D \text{ оп.мм} = 190</math>  <math>P \text{ н.мм} = 593.5</math>  <math>P \text{ вн.мм} = 349.7</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1412</b></p> <p> <math>F \text{ см}^2 = 4.577</math>  <math>Q \text{ кг.} = 1.24</math>  <math>D \text{ оп.мм} = 100</math>  <math>P \text{ н.мм} = 316.5</math>  <math>P \text{ вн.мм} = 245</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1417</b></p> <p> <math>F \text{ см}^2 = 2.391</math>  <math>Q \text{ кг.} = 0.648</math>  <math>D \text{ оп.мм} = 55</math>  <math>P \text{ н.мм} = 251.7</math>  <math>P \text{ вн.мм} = 98.1</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1413</b></p> <p> <math>F \text{ см}^2 = 6.16</math>  <math>Q \text{ кг.} = 1.669</math>  <math>D \text{ оп.мм} = 154</math>  <math>P \text{ н.мм} = 374.5</math>  <math>P \text{ вн.мм} = 293.3</math>  Гр. сл. = 0соб.  Точн. = П </p>		<p><b>БПЗ-1418</b></p> <p> <math>F \text{ см}^2 = 1.778</math>  <math>Q \text{ кг.} = 0.482</math>  <math>D \text{ оп.мм} = 50.3</math>  <math>P \text{ н.мм} = 144.9</math>  <math>P \text{ вн.мм} = 60.3</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1414</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1419</b></p> <p> <math>F \text{ см}^2 = 8.888</math>  <math>Q \text{ кг.} = 2.406</math>  <math>D \text{ оп.мм} = 123</math>  <math>P \text{ н.мм} = 598</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1415</b></p> <p> <math>F \text{ см}^2 = 2.16</math>  <math>Q \text{ кг.} = 0.585</math>  <math>D \text{ оп.мм} = 30</math>  <math>P \text{ н.мм} = 94.3</math>  <math>P \text{ вн.мм} = 78.5</math>  Гр. сл. = II  Точн. = П </p>		<p><b>БПЗ-1420</b></p> <p> <math>F \text{ см}^2 = 3.15</math>  <math>Q \text{ кг.} = 0.853</math>  <math>D \text{ оп.мм} = 103</math>  <math>P \text{ н.мм} = 214.7</math>  <math>P \text{ вн.мм} = 249.9</math>  Гр. сл. = VI  Точн. = П </p>




	<p><b>БПЗ-1421</b></p> <p> <math>F \text{ см}^2 = 22</math>  <math>Q \text{ кг.} = 5.962</math>  <math>D \text{ оп.мм} = 80</math>  <math>P \text{ н.мм} = 251.3</math>  <math>P \text{ вн.мм} = 188.5</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1426</b></p> <p> <math>F \text{ см}^2 = 1.41</math>  <math>Q \text{ кг.} = 0.382</math>  <math>D \text{ оп.мм} = 54</math>  <math>P \text{ н.мм} = 143.6</math>  <math>P \text{ вн.мм} = 84.1</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1422</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = П </p>		<p><b>БПЗ-1427</b></p> <p> <math>F \text{ см}^2 = 14.98</math>  <math>Q \text{ кг.} = 4.06</math>  <math>D \text{ оп.мм} = 132</math>  <math>P \text{ н.мм} = 555.9</math>  <math>P \text{ вн.мм} = 520</math>  Гр. сл. = Особ  Точн. = П </p>
	<p><b>БПЗ-1423</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = П </p>		<p><b>БПЗ-1428</b></p> <p> <math>F \text{ см}^2 = 10.79</math>  <math>Q \text{ кг.} = 2.924</math>  <math>D \text{ оп.мм} = 169</math>  <math>P \text{ н.мм} = 433.4</math>  <math>P \text{ вн.мм} = 349.7</math>  Гр. сл. =  Точн. = П </p>
	<p><b>БПЗ-1424</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = </p>		<p><b>БПЗ-1429</b></p> <p> <math>F \text{ см}^2 = 10.48</math>  <math>Q \text{ кг.} = 2.84</math>  <math>D \text{ оп.мм} = 180.7</math>  <math>P \text{ н.мм} = 427.6</math>  <math>P \text{ вн.мм} = 343.8</math>  Гр. сл. = Особ  Точн. = П </p>
	<p><b>БПЗ-1425</b></p> <p> <math>F \text{ см}^2 = 9.434</math>  <math>Q \text{ кг.} = 2.557</math>  <math>D \text{ оп.мм} = 88</math>  <math>P \text{ н.мм} = 276.2</math>  <math>P \text{ вн.мм} = 194.2</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1430</b></p> <p> <math>F \text{ см}^2 = 5.462</math>  <math>Q \text{ кг.} = 1.48</math>  <math>D \text{ оп.мм} = 35</math>  <math>P \text{ н.мм} = 110</math>  <math>P \text{ вн.мм} = 72.3</math>  Гр. сл. = II  Точн. = П </p>


	БПЗ-1431		БПЗ-1436
	$F \text{ см}^2 = 1.33$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм} = 27.2$ $P \text{ н.мм} = 90.9$ $P \text{ вн.мм} = 84.6$ Гр. сл. = V Точн. = П		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П
	БПЗ-1432		БПЗ-1437
	$F \text{ см}^2 = 2.03$ $Q \text{ кг.} = 0.55$ $D \text{ оп.мм} = 49$ $P \text{ н.мм} = 146.9$ $P \text{ вн.мм} = 112$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П
	БПЗ-1433		БПЗ-1438
	$F \text{ см}^2 = 3.27$ $Q \text{ кг.} = 0.886$ $D \text{ оп.мм} = 49.2$ $P \text{ н.мм} = 206.3$ $P \text{ вн.мм} = 78.3$ Гр. сл. = Особ Точн. = П		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П
	БПЗ-1434		БПЗ-1439
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. =		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П
	БПЗ-1435		БПЗ-1440
	$F \text{ см}^2 = 4.44$ $Q \text{ кг.} = 1.203$ $D \text{ оп.мм} = 76.1$ $P \text{ н.мм} = 302.5$ $P \text{ вн.мм} = 128.9$ Гр. сл. = Особ Точн. = П		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П

	<p><b>БПЗ-1441</b></p> <p> <math>F \text{ см}^2 = 1.4.161</math>  <math>Q \text{ кг.} = 1.128</math>  <math>D \text{ оп.мм} = 101</math>  <math>P \text{ н.мм} = 327</math>  <math>P \text{ вн.мм} = 191</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1446</b></p> <p> <math>F \text{ см}^2 = 24.875</math>  <math>Q \text{ кг.} = 6.741</math>  <math>D \text{ оп.мм} = 156</math>  <math>P \text{ н.мм} = 1474.8</math>  <math>P \text{ вн.мм} = 362.9</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1442</b></p> <p> <math>F \text{ см}^2 = 3.68</math>  <math>Q \text{ кг.} = 0.997</math>  <math>D \text{ оп.мм} = 80.7</math>  <math>P \text{ н.мм} = 319.7</math>  <math>P \text{ вн.мм} = 170.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1447</b></p> <p> <math>F \text{ см}^2 = 7.061</math>  <math>Q \text{ кг.} = 1.914</math>  <math>D \text{ оп.мм} = 65.4</math>  <math>P \text{ н.мм} = 323</math>  <math>P \text{ вн.мм} = 138.5</math>  Гр. сл. = 0соб.  Точн. = П </p>
	<p><b>БПЗ-1443</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = П </p>		<p><b>БПЗ-1448</b></p> <p> <math>F \text{ см}^2 = 1.4</math>  <math>Q \text{ кг.} = 0.38</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 243.7</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1444</b></p> <p> <math>F \text{ см}^2 = 9.35</math>  <math>Q \text{ кг.} = 2.534</math>  <math>D \text{ оп.мм} = 135</math>  <math>P \text{ н.мм} = 398.8</math>  <math>P \text{ вн.мм} = 160.2</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1449</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = П </p>
	<p><b>БПЗ-1445</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = П </p>		<p><b>БПЗ-1450</b></p> <p> <math>F \text{ см}^2 = 18.225</math>  <math>Q \text{ кг.} = 4.939</math>  <math>D \text{ оп.мм} = 58</math>  <math>P \text{ н.мм} = 179.4</math>  <math>P \text{ вн.мм} = 91.1</math>  Гр. сл. = III  Точн. = П </p>






	<p><b>БПЗ-1451</b></p> <p> <math>F \text{ см}^2 = 2.13</math>  <math>Q \text{ кг.} = 0.577</math>  <math>D \text{ оп.мм} = 49</math>  <math>P \text{ н.мм} = 147.7</math>  <math>P \text{ вн.мм} = 111.4</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1456</b></p> <p> <math>F \text{ см}^2 = 1.9</math>  <math>Q \text{ кг.} = 0.515</math>  <math>D \text{ оп.мм} = 46</math>  <math>P \text{ н.мм} = 124.7</math>  <math>P \text{ вн.мм} = 115.3</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1452</b></p> <p> <math>F \text{ см}^2 = 1.744</math>  <math>Q \text{ кг.} = 0.473</math>  <math>D \text{ оп.мм} = 34</math>  <math>P \text{ н.мм} = 93.6</math>  <math>P \text{ вн.мм} = 78.9</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1457</b></p> <p> <math>F \text{ см}^2 = 1.27</math>  <math>Q \text{ кг.} = 0.344</math>  <math>D \text{ оп.мм} = 36</math>  <math>P \text{ н.мм} = 89.4</math>  <math>P \text{ вн.мм} = 80</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1453</b></p> <p> <math>F \text{ см}^2 = 2.875</math>  <math>Q \text{ кг.} = 0.779</math>  <math>D \text{ оп.мм} = 51</math>  <math>P \text{ н.мм} = 237.4</math>  <math>P \text{ вн.мм} = 65.2</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1458</b></p> <p> <math>F \text{ см}^2 = 0.899</math>  <math>Q \text{ кг.} = 0.244</math>  <math>D \text{ оп.мм} = 26</math>  <math>P \text{ н.мм} = 64.6</math>  <math>P \text{ вн.мм} = 56.2</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1454</b></p> <p> <math>F \text{ см}^2 = 4.286</math>  <math>Q \text{ кг.} = 1.161</math>  <math>D \text{ оп.мм} = 44</math>  <math>P \text{ н.мм} = 351.1</math>  <math>P \text{ вн.мм} = 83.9</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1459</b></p> <p> <math>F \text{ см}^2 = 14.28</math>  <math>Q \text{ кг.} = 3.87</math>  <math>D \text{ оп.мм} = 109</math>  <math>P \text{ н.мм} = 309</math>  <math>P \text{ вн.мм} = 352</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1455</b></p> <p> <math>F \text{ см}^2 = 1.36</math>  <math>Q \text{ кг.} = 0.369</math>  <math>D \text{ оп.мм} = 41</math>  <math>P \text{ н.мм} = 95.4</math>  <math>P \text{ вн.мм} = 86</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1460</b></p> <p> <math>F \text{ см}^2 =</math>  <math>Q \text{ кг.} =</math>  <math>D \text{ оп.мм} =</math>  <math>P \text{ н.мм} =</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. =  Точн. = П </p>




	<p><b>БПЗ-1461</b></p> <p> <math>F \text{ см}^2 = 4.092</math>  <math>Q \text{ кг.} = 1.109</math>  <math>D \text{ оп.мм} = 70</math>  <math>P \text{ н.мм} = 241.1</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1466</b></p> <p> <math>F \text{ см}^2 = 4.743</math>  <math>Q \text{ кг.} = 1.285</math>  <math>D \text{ оп.мм} = 79</math>  <math>P \text{ н.мм} = 308.2</math>  <math>P \text{ вн.мм} = 137.6</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1462</b></p> <p> <math>F \text{ см}^2 = 1.435</math>  <math>Q \text{ кг.} = 0.389</math>  <math>D \text{ оп.мм} = 28</math>  <math>P \text{ н.мм} = 79.3</math>  <math>P \text{ вн.мм} = 64</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-1467</b></p> <p> <math>F \text{ см}^2 = 12.2</math>  <math>Q \text{ кг.} = 3.306</math>  <math>D \text{ оп.мм} = 145</math>  <math>P \text{ н.мм} = 464.1</math>  <math>P \text{ вн.мм} = 348.3</math>  Гр. сл. = Особ.  Точн. = П </p>
	<p><b>БПЗ-1463</b></p> <p> <math>F \text{ см}^2 = 4.129</math>  <math>Q \text{ кг.} = 1.119</math>  <math>D \text{ оп.мм} = 62</math>  <math>P \text{ н.мм} = 196.1</math>  <math>P \text{ вн.мм} = 164.2</math>  Гр. сл. = Особ.  Точн. = П </p>		<p><b>БПЗ-1468</b></p> <p> <math>F \text{ см}^2 = 0.899</math>  <math>Q \text{ кг.} = 0.244</math>  <math>D \text{ оп.мм} = 26</math>  <math>P \text{ н.мм} = 64.6</math>  <math>P \text{ вн.мм} = 56.2</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1464</b></p> <p> <math>F \text{ см}^2 = 19.55</math>  <math>Q \text{ кг.} = 5.298</math>  <math>D \text{ оп.мм} = 172</math>  <math>P \text{ н.мм} = 525.2</math>  <math>P \text{ вн.мм} = 520.3</math>  Гр. сл. = Особ.  Точн. = П </p>		<p><b>БПЗ-1469</b></p> <p> <math>F \text{ см}^2 = 13.11</math>  <math>Q \text{ кг.} = 3.553</math>  <math>D \text{ оп.мм} = 55</math>  <math>P \text{ н.мм} = 154.3</math>  <math>P \text{ вн.мм} = 37.7</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1465</b></p> <p> <math>F \text{ см}^2 = 20.154</math>  <math>Q \text{ кг.} = 5.462</math>  <math>D \text{ оп.мм} = 180</math>  <math>P \text{ н.мм} = 529</math>  <math>P \text{ вн.мм} = 470</math>  Гр. сл. = Особ.  Точн. = П </p>		<p><b>БПЗ-1470</b></p> <p> <math>F \text{ см}^2 = 1.061</math>  <math>Q \text{ кг.} = 0.287</math>  <math>D \text{ оп.мм} = 33</math>  <math>P \text{ н.мм} = 131</math>  <math>P \text{ вн.мм} = 20.8</math>  Гр. сл. = VI  Точн. = П </p>








	БПЗ-1471		БПЗ-1476
	$F \text{ см}^2 = 3.565$ $Q \text{ кг.} = 0.966$ $D \text{ оп.мм} = 82$ $P \text{ н.мм} = 240.2$ $P \text{ вн.мм} = 210.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$
	БПЗ-1472		БПЗ-1477
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$
	БПЗ-1473		БПЗ-1478
	$F \text{ см}^2 = 11.61$ $Q \text{ кг.} = 3.146$ $D \text{ оп.мм} = 125$ $P \text{ н.мм} = 353.6$ $P \text{ вн.мм} = 344$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$
	БПЗ-1474		БПЗ-1479
	$F \text{ см}^2 = 1.928$ $Q \text{ кг.} = 0.522$ $D \text{ оп.мм} = 16$ $P \text{ н.мм} = 50.3$ $P \text{ вн.мм} = 18.9$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$
	БПЗ-1475		БПЗ-1480
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$







	БПЗ-1481		БПЗ-1486
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 11.377$ $Q \text{ кг.} = 3.08$ $D \text{ оп.мм} = 138$ $P \text{ н.мм} = 491.7$ $P \text{ вн.мм} = 349.2$ $\Gamma \text{ р. сл.} = \text{Особ.}$ $\text{Точн.} = \Pi$
	БПЗ-1482		БПЗ-1487
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$
	БПЗ-1483		БПЗ-1488
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$
	БПЗ-1484		БПЗ-1489
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$
	БПЗ-1485		БПЗ-1490
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$










	БПЗ-1491		БПЗ-1496
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 2.64$ $Q \text{ кг.} = 0.715$ $D \text{ оп.мм} = 63$ $P \text{ н.мм} = 275$ $P \text{ вн.мм} = 89.9$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = \Pi$
	БПЗ-1492		БПЗ-1497
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 24.17$ $Q \text{ кг.} = 6.55$ $D \text{ оп.мм} = 190$ $P \text{ н.мм} = 430.3$ $P \text{ вн.мм} = 640$ $\Gamma \text{ р. сл.} = \text{Особ.}$ $\text{Точн.} = \Pi$
	БПЗ-1493		БПЗ-1498
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 24.85$ $Q \text{ кг.} = 6.374$ $D \text{ оп.мм} = 120$ $P \text{ н.мм} = 377$ $P \text{ вн.мм} = 333$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = \Pi$
	БПЗ-1494		БПЗ-1499
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 0.542$ $Q \text{ кг.} = 0.147$ $D \text{ оп.мм} = 13$ $P \text{ н.мм} = 40$ $P \text{ вн.мм} = 31.4$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = \Pi$
	БПЗ-1495		БПЗ-1500
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ $\Gamma \text{ р. сл.} =$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 12.548$ $Q \text{ кг.} = 3.4$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 387$ $P \text{ вн.мм} = 129$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = \Pi$






	БПЗ-1501		БПЗ-1506
	$F \text{ см}^2 = 15.49$ $Q \text{ кг.} = 4.19$ $D \text{ оп.мм} = 88$ $P \text{ н.мм} = 179.4$ $P \text{ вн.мм} = 108.4$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм} = 0$ $P \text{ н.мм} = 0$ $P \text{ вн.мм} = 0$ Гр. сл. = Точн. = П
	БПЗ-1502		БПЗ-1507
	$F \text{ см}^2 = 8.26$ $Q \text{ кг.} = 2.24$ $D \text{ оп.мм} = 88$ $P \text{ н.мм} = 532.7$ $P \text{ вн.мм} = 248$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П
	БПЗ-1503		БПЗ-1508
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П		$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П
	БПЗ-1504		БПЗ-1509
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П		$F \text{ см}^2 = 2.592$ $Q \text{ кг.} = 0.702$ $D \text{ оп.мм} = 72$ $P \text{ н.мм} = 250.7$ $P \text{ вн.мм} = 90.7$ Гр. сл. = VI Точн. = П
	БПЗ-1505		БПЗ-1510
	$F \text{ см}^2 =$ $Q \text{ кг.} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ вн.мм} =$ Гр. сл. = Точн. = П		$F \text{ см}^2 = 1.99$ $Q \text{ кг.} = 0.539$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 117.6$ $P \text{ вн.мм} = 126$ Гр. сл. = V Точн. = П








	<p><b>БПЗ-1511</b></p> <p> <math>F \text{ см}^2 = 8.827</math>  <math>Q \text{ кг.} = 2.392</math>  <math>D \text{ оп.мм} = 130</math>  <math>P \text{ н.мм} = 337</math>  <math>P \text{ вн.мм} = 108.4</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1516</b></p> <p> <math>F \text{ см}^2 = 5.934</math>  <math>Q \text{ кг.} = 1.608</math>  <math>D \text{ оп.мм} = 63</math>  <math>P \text{ н.мм} = 314.1</math>  <math>P \text{ вн.мм} = 145.2</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1512</b></p> <p> <math>F \text{ см}^2 = 4.46</math>  <math>Q \text{ кг.} = 1.209</math>  <math>D \text{ оп.мм} = 43</math>  <math>P \text{ н.мм} = 117</math>  <math>P \text{ вн.мм} = 81</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1517</b></p> <p> <math>F \text{ см}^2 = 4.51</math>  <math>Q \text{ кг.} = 1.222</math>  <math>D \text{ оп.мм} = 57</math>  <math>P \text{ н.мм} = 285.6</math>  <math>P \text{ вн.мм} = 107.7</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1513</b></p> <p> <math>F \text{ см}^2 = 5.503</math>  <math>Q \text{ кг.} = 1.491</math>  <math>D \text{ оп.мм} = 96</math>  <math>P \text{ н.мм} = 295.9</math>  <math>P \text{ вн.мм} = 248.4</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1518</b></p>
	<p><b>БПЗ-1514</b></p> <p> <math>F \text{ см}^2 = 0.82</math>  <math>Q \text{ кг.} = 0.222</math>  <math>D \text{ оп.мм} = 31</math>  <math>P \text{ н.мм} = 100.2</math>  <math>P \text{ вн.мм} = 28.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1519</b></p>
	<p><b>БПЗ-1515</b></p> <p> <math>F \text{ см}^2 = 1.11</math>  <math>Q \text{ кг.} = 0.3</math>  <math>D \text{ оп.мм} = 36</math>  <math>P \text{ н.мм} = 147.6</math>  <math>P \text{ вн.мм} = 28.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1520</b></p> <p>2</p>

	<p><b>БПЗ-1521</b></p> <p> <math>F \text{ см}^2 = 21.99</math>  <math>Q \text{ кг.} = 5.96</math>  <math>D \text{ оп.мм} = 55</math>  <math>P \text{ н.мм} = 172.8</math>  <math>P \text{ вн.мм} = 47.1</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-1526</b></p> <p> <math>F \text{ см}^2 = 6.24</math>  <math>Q \text{ кг.} = 1.691</math>  <math>D \text{ оп.мм} = 77</math>  <math>P \text{ н.мм} = 221.3</math>  <math>P \text{ вн.мм} = 102.2</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1522</b></p>		<p><b>БПЗ-1527</b></p> <p> <math>F \text{ см}^2 = 4.99</math>  <math>Q \text{ кг.} = 1.352</math>  <math>D \text{ оп.мм} = 90</math>  <math>P \text{ н.мм} = 278.9</math>  <math>P \text{ вн.мм} = 128.8</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1523</b></p> <p> <math>F \text{ см}^2 = 3.959</math>  <math>Q \text{ кг.} = 1.073</math>  <math>D \text{ оп.мм} = 65</math>  <math>P \text{ н.мм} = 204.2</math>  <math>P \text{ вн.мм} = 191.6</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1528</b></p>
	<p><b>БПЗ-1524</b></p> <p> <math>F \text{ см}^2 = 6.872</math>  <math>Q \text{ кг.} = 1.862</math>  <math>D \text{ оп.мм} = 90</math>  <math>P \text{ н.мм} = 282.7</math>  <math>P \text{ вн.мм} = 267</math>  Гр. сл. = III  Точн. = П </p>		<p><b>БПЗ-1529</b></p> <p>2</p>
	<p><b>БПЗ-1525</b></p> <p> <math>F \text{ см}^2 = 4.475</math>  <math>Q \text{ кг.} = 1.213</math>  <math>D \text{ оп.мм} = 87</math>  <math>P \text{ н.мм} = 253.1</math>  <math>P \text{ вн.мм} = 120.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1530</b></p> <p>2</p>






	БПЗ-1531		БПЗ-1536
	БПЗ-1532	ОРЕЛ	БПЗ-1537
	БПЗ-1533	ОРЕЛ	БПЗ-1538
			F см² = Q кг. = D оп.мм= P н.мм = P вн.мм= Гр. сл. = Точн. = П
	БПЗ-1534	ОРЕЛ	БПЗ-1539
	БПЗ-1535		БПЗ-1540





	БПЗ-1541		БПЗ-1546
			$F \text{ см}^2 = 10.09$ $Q \text{ кг.} = 2.73$ $D \text{ оп.мм} = 131$ $P \text{ н.мм} = 312.6$ $P \text{ вн.мм} = 268.5$ Гр. сл. = VI Точн. = П
	БПЗ-1542		БПЗ-1547
	$F \text{ см}^2 = 2.137$ $Q \text{ кг.} = 0.579$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 113.1$ $P \text{ вн.мм} = 100.6$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 10.329$ $Q \text{ кг.} = 2.799$ $D \text{ оп.мм} = 47$ $P \text{ н.мм} = 144.7$ $P \text{ вн.мм} = 84.8$ Гр. сл. = IV Точн. = Н
	БПЗ-1543		БПЗ-1548
	$F \text{ см}^2 = 1.336$ $Q \text{ кг.} = 0.362$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 73.1$ $P \text{ вн.мм} = 60.6$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 2.825$ $Q \text{ кг.} = 0.766$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 92$ $P \text{ вн.мм} = 22$ Гр. сл. = IV Точн. = П
	БПЗ-1544		БПЗ-1549
	$F \text{ см}^2 = 3.913$ $Q \text{ кг.} = 1.06$ $D \text{ оп.мм} = 60$ $P \text{ н.мм} = 164.5$ $P \text{ вн.мм} = 58.6$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 2.059$ $Q \text{ кг.} = 0.558$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 107.2$ $P \text{ вн.мм} = 31.4$ Гр. сл. = IV Точн. = П
	БПЗ-1545		БПЗ-1550




	БПЗ-1551		БПЗ-1556
	<p>БПЗ-1552</p> <p> <math>F \text{ см}^2 = 5.62</math>  <math>Q \text{ кг.} = 1.523</math>  <math>D \text{ оп.мм} = 85</math>  <math>P \text{ н.мм} = 380.6</math>  <math>P \text{ вн.мм} = 213.7</math>  Гр. сл. = VI  Точн. = П </p>		<p>БПЗ-1557</p> <p> <math>F \text{ см}^2 = 5.52</math>  <math>Q \text{ кг.} = 1.496</math>  <math>D \text{ оп.мм} = 87</math>  <math>P \text{ н.мм} = 254.5</math>  <math>P \text{ вн.мм} = 110.6</math>  Гр. сл. = IV  Точн. = П </p>
	<p>БПЗ-1553</p> <p> <math>F \text{ см}^2 = 10.502</math>  <math>Q \text{ кг.} = 2.846</math>  <math>D \text{ оп.мм} = 147</math>  <math>P \text{ н.мм} = 478.7</math>  <math>P \text{ вн.мм} = 392</math>  Гр. сл. = особая  Точн. = П </p>		<p>БПЗ-1558</p> <p> <math>F \text{ см}^2 = 4.175</math>  <math>Q \text{ кг.} = 1.131</math>  <math>D \text{ оп.мм} = 107</math>  <math>P \text{ н.мм} = 297.3</math>  <math>P \text{ вн.мм} = 252.1</math>  Гр. сл. = VI  Точн. = П </p>
	БПЗ-1554		<p>БПЗ-1559</p> <p> <math>F \text{ см}^2 = 5.2</math>  <math>Q \text{ кг.} = 1.413</math>  <math>D \text{ оп.мм} = 76</math>  <math>P \text{ н.мм} = 367</math>  <math>P \text{ вн.мм} = 167.5</math>  Гр. сл. = VI  Точн. = П </p>
	БПЗ-1555		БПЗ-1560



	БПЗ-1561		БПЗ-1566
	<p>БПЗ-1562</p> <p> <math>F \text{ см}^2 = 14.439</math>  <math>Q \text{ кг.} = 3.913</math>  <math>D \text{ оп.мм} = 175</math>  <math>P \text{ н.мм} = 777.5</math>  <math>P \text{ вн.мм} = 110.3</math>  Гр. сл. = особая  Точн. = П </p>		<p>БПЗ-1567</p> <p> <math>F \text{ см}^2 = 3.37</math>  <math>Q \text{ кг.} = 0.913</math>  <math>D \text{ оп.мм} = 63</math>  <math>P \text{ н.мм} = 401</math>  <math>P \text{ вн.мм} = 83</math>  Гр. сл. = VI  Точн. = П </p>
	<p>БПЗ-1563</p> <p> <math>F \text{ см}^2 = 32.87</math>  <math>Q \text{ кг.} = 8.908</math>  <math>D \text{ оп.мм} = 176</math>  <math>P \text{ н.мм} = 588.9</math>  <math>P \text{ вн.мм} = 441.5</math>  Гр. сл. = особая  Точн. = П </p>		<p>БПЗ-1568</p> <p> <math>F \text{ см}^2 = 2.42</math>  <math>Q \text{ кг.} = 0.66</math>  <math>D \text{ оп.мм} = 45</math>  <math>P \text{ н.мм} = 250</math>  <math>P \text{ вн.мм} = 123</math>  Гр. сл. = VI  Точн. = П </p>
	<p>БПЗ-1564</p> <p> <math>F \text{ см}^2 = 7.355</math>  <math>Q \text{ кг.} = 1.993</math>  <math>D \text{ оп.мм} = 56</math>  <math>P \text{ н.мм} = 204.1</math>  <math>P \text{ вн.мм} = 81.4</math>  Гр. сл. = V  Точн. = П </p>		<p>БПЗ-1569</p> <p> <math>F \text{ см}^2 = 3</math>  <math>Q \text{ кг.} = 0.813</math>  <math>D \text{ оп.мм} = 65</math>  <math>P \text{ н.мм} = 255</math>  <math>P \text{ вн.мм} = 172</math>  Гр. сл. = VI  Точн. = П </p>
	<p>БПЗ-1565</p> <p> <math>F \text{ см}^2 = 3.64</math>  <math>Q \text{ кг.} = 0.986</math>  <math>D \text{ оп.мм} = 45</math>  <math>P \text{ н.мм} = 280</math>  <math>P \text{ вн.мм} = 56</math>  Гр. сл. = VI  Точн. = П </p>		БПЗ-1570















	БПЗ-1571		БПЗ-1576
			$F \text{ см}^2 = 5.08$ $Q \text{ кг.} = 1.377$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 271.6$ $P \text{ вн.мм} = 314.8$ Гр. сл. = особая Точн. = особой
	БПЗ-1572		БПЗ-1577
			$F \text{ см}^2 = 2.506$ $Q \text{ кг.} = 0.679$ $D \text{ оп.мм} = 67$ $P \text{ н.мм} = 173.1$ $P \text{ вн.мм} = 160.6$ Гр. сл. = VI Точн. = П
	БПЗ-1573		БПЗ-1578
			$F \text{ см}^2 = 1.56$ $Q \text{ кг.} = 0.423$ $D \text{ оп.мм} = 41$ $P \text{ н.мм} = 145$ $P \text{ вн.мм} = 113.8$ Гр. сл. = особая Точн. = особой
	БПЗ-1574		БПЗ-1579
	$F \text{ см}^2 = 3.958$ $Q \text{ кг.} = 1.073$ $D \text{ оп.мм} = 48$ $P \text{ н.мм} = 130$ $P \text{ вн.мм} = 102$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 1.521$ $Q \text{ кг.} = 0.412$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 130.8$ $P \text{ вн.мм} = 122.1$ Гр. сл. = особая Точн. = особой
	БПЗ-1575		БПЗ-1580








	БПЗ-1581		БПЗ-1586
	БПЗ-1582 $F \text{ см}^2 = 1.015$ $Q \text{ кг.} = 0.275$ $D \text{ оп.мм} = 23$ $P \text{ н.мм} = 76.6$ $P \text{ вн.мм} = 35.1$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$		БПЗ-1587
	БПЗ-1583		БПЗ-1588 $F \text{ см}^2 = 1.126$ $Q \text{ кг.} = 0.305$ $D \text{ оп.мм} = 33$ $P \text{ н.мм} = 131.2$ $P \text{ вн.мм} = 51.2$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = Н$
	БПЗ-1584 $F \text{ см}^2 = 1.26$ $Q \text{ кг.} = 0.341$ $D \text{ оп.мм} = 44$ $P \text{ н.мм} = 202.7$ $P \text{ вн.мм} = 29.2$ $\text{Гр. сл.} = IV$ $\text{Точн.} = П$		БПЗ-1589
	БПЗ-1585 $F \text{ см}^2 = 7.32$ $Q \text{ кг.} = 1.984$ $D \text{ оп.мм} = 63$ $P \text{ н.мм} = 192$ $P \text{ вн.мм} = 120$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$		БПЗ-1590







	БПЗ-1591		БПЗ-1596
			<p> <math>F \text{ см}^2 = 3.52</math>  <math>Q \text{ кг.} = 0.954</math>  <math>D \text{ оп.мм} = 32</math>  <math>P \text{ н.мм} = 100.5</math>  <math>P \text{ вн.мм} = 75.4</math>  Гр. сл. = IV  Точн. = особой </p>
	БПЗ-1592		БПЗ-1597
			<p> <math>F \text{ см}^2 = 5.457</math>  <math>Q \text{ кг.} = 1.479</math>  <math>D \text{ оп.мм} = 76.3</math>  <math>P \text{ н.мм} = 372.5</math>  <math>P \text{ вн.мм} = 45.7</math>  Гр. сл. = особая  Точн. = П </p>
	БПЗ-1593		БПЗ-1598
			<p> <math>F \text{ см}^2 = 2.005</math>  <math>Q \text{ кг.} = 0.543</math>  <math>D \text{ оп.мм} = 42</math>  <math>P \text{ н.мм} = 204.5</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = VI  Точн. = П </p>
	БПЗ-1594		БПЗ-1599
	БПЗ-1595		БПЗ-1600

	БПЗ-1601		БПЗ-1606
			$F \text{ см}^2 = 3.44$ $Q \text{ кг.} = 0.932$ $D \text{ оп.мм} = 55$ $P \text{ н.мм} = 190.2$ $P \text{ вн.мм} = 113.1$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПЗ-1602		БПЗ-1607
			$F \text{ см}^2 = 1.299$ $Q \text{ кг.} = 0.352$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 135.6$ $P \text{ вн.мм} = 18$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$
	БПЗ-1603		БПЗ-1608
	БПЗ-1604		БПЗ-1609
	БПЗ-1605		БПЗ-1610



	<b>БПЗ-1611</b> $F \text{ см}^2 = 15.93$ $Q \text{ кг.} = 4.317$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 160.3$ $P \text{ вн.мм} = 69.1$ Гр. сл. = III Точн. = П		<b>БПЗ-1616</b> $F \text{ см}^2 = 7.672$ $Q \text{ кг.} = 2.079$ $D \text{ оп.мм} = 56$ $P \text{ н.мм} = 153.1$ $P \text{ вн.мм} = 110.3$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1612</b> $F \text{ см}^2 = 18.23$ $Q \text{ кг.} = 4.94$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 179.4$ $P \text{ вн.мм} = 99.1$ Гр. сл. = III Точн. = П		<b>БПЗ-1617</b> $F \text{ см}^2 = 8.14$ $Q \text{ кг.} = 2.206$ $D \text{ оп.мм} = 73$ $P \text{ н.мм} = 261.3$ $P \text{ вн.мм} = 126.3$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1613</b>		<b>БПЗ-1618</b> $F \text{ см}^2 = 4.991$ $Q \text{ кг.} = 1.353$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 118.3$ $P \text{ вн.мм} = 80$ Гр. сл. = IV Точн. = Н
	<b>БПЗ-1614</b> $F \text{ см}^2 = 2.819$ $Q \text{ кг.} = 0.764$ $D \text{ оп.мм} = 81$ $P \text{ н.мм} = 297.4$ $P \text{ вн.мм} = 170$ Гр. сл. = VI Точн. = П		<b>БПЗ-1619</b> $F \text{ см}^2 = 6.74$ $Q \text{ кг.} = 1.827$ $D \text{ оп.мм} = 57$ $P \text{ н.мм} = 204.1$ $P \text{ вн.мм} = 108.2$ Гр. сл. = V Точн. = П
	<b>БПЗ-1615</b> $F \text{ см}^2 = 5.82$ $Q \text{ кг.} = 1.577$ $D \text{ оп.мм} = 100$ $P \text{ н.мм} = 189.2$ $P \text{ вн.мм} = 350.4$ Гр. сл. = VI Точн. = П		<b>БПЗ-1620</b> $F \text{ см}^2 = 3.339$ $Q \text{ кг.} = 0.905$ $D \text{ оп.мм} = 124$ $P \text{ н.мм} = 291.4$ $P \text{ вн.мм} = 98.1$ Гр. сл. = VI Точн. = П







	БПЗ-1621		БПЗ-1626
	БПЗ-1622		БПЗ-1627 $F \text{ см}^2 = 4.522$ $Q \text{ кг.} = 1.225$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 139.1$ $P \text{ вн.мм} = 112.1$ Гр. сл. = V Точн. = П
	БПЗ-1623 $F \text{ см}^2 = 20.11$ $Q \text{ кг.} = 5.45$ $D \text{ оп.мм} = 191$ $P \text{ н.мм} = 450.9$ $P \text{ вн.мм} = 530.9$ Гр. сл. = особая Точн. = П		БПЗ-1628
	БПЗ-1624		БПЗ-1629
	БПЗ-1625		БПЗ-1630 $F \text{ см}^2 = 4.108$ $Q \text{ кг.} = 1.113$ $D \text{ оп.мм} = 67$ $P \text{ н.мм} = 295$ $P \text{ вн.мм} = 227.5$ Гр. сл. = VI Точн. = П











	<p><b>БПЗ-1631</b></p> <p> <math>F \text{ см}^2 = 4.42</math>  <math>Q \text{ кг.} = 1.198</math>  <math>D \text{ оп.мм} = 100</math>  <math>P \text{ н.мм} = 323.7</math>  <math>P \text{ вн.мм} = 229.3</math>  Гр. сл. = III  Точн. = особая </p>		<p><b>БПЗ-1636</b></p>
	<p><b>БПЗ-1632</b></p> <p> <math>F \text{ см}^2 = 4.51</math>  <math>Q \text{ кг.} = 1.222</math>  <math>D \text{ оп.мм} = 95</math>  <math>P \text{ н.мм} = 249</math>  <math>P \text{ вн.мм} = 307.5</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1637</b></p>
	<p><b>БПЗ-1633</b></p>		<p><b>БПЗ-1638</b></p> <p> <math>F \text{ см}^2 = 2.555</math>  <math>Q \text{ кг.} = 0.692</math>  <math>D \text{ оп.мм} = 67</math>  <math>P \text{ н.мм} = 244.6</math>  <math>P \text{ вн.мм} = 153.9</math>  Гр. сл. = IV  Точн. = Н </p>
	<p><b>БПЗ-1634</b></p> <p> <math>F \text{ см}^2 = 5.396</math>  <math>Q \text{ кг.} = 1.462</math>  <math>D \text{ оп.мм} = 87</math>  <math>P \text{ н.мм} = 355.9</math>  <math>P \text{ вн.мм} = 153.7</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1639</b></p> <p> <math>F \text{ см}^2 = 1.17</math>  <math>Q \text{ кг.} = 0.317</math>  <math>D \text{ оп.мм} = 24</math>  <math>P \text{ н.мм} = 100.4</math>  <math>P \text{ вн.мм} =</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-1635</b></p> <p> <math>F \text{ см}^2 = 21.303</math>  <math>Q \text{ кг.} = 5.773</math>  <math>D \text{ оп.мм} = 137</math>  <math>P \text{ н.мм} = 382.6</math>  <math>P \text{ вн.мм} = 106.9</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1640</b></p> <p> <math>F \text{ см}^2 = 16.365</math>  <math>Q \text{ кг.} = 4.435</math>  <math>D \text{ оп.мм} = 61</math>  <math>P \text{ н.мм} = 240</math>  <math>P \text{ вн.мм} = 157</math>  Гр. сл. = III  Точн. = П </p>







	БПЗ-1641		БПЗ-1646
	$F \text{ см}^2 = 8,641$ $Q \text{ кг.} = 2,342$ $D \text{ оп.мм.} = 131$ $P \text{ н.} = 416,5$ $P_{\text{вн.}} = 446,9$ Гр. сл. = особая Точн. = П		
	БПЗ-1642		БПЗ-1647
	$F \text{ см}^2 = 13.504$ $Q \text{ кг.} = 3.66$ $D \text{ оп.мм.} = 116$ $P \text{ н.} = 446.8$ $P_{\text{вн.}} = 168.3$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0.306$ $Q \text{ кг.} = 0.083$ $D \text{ оп.мм.} = 8$ $P \text{ н.} = 25.1$ $P_{\text{вн.}} = 15.7$ Гр. сл. = VI Точн. = П
	БПЗ-1643		БПЗ-1648
	$F \text{ см}^2 = 3.786$ $Q \text{ кг.} = 1.026$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 82.8$ $P_{\text{вн.}} = 45.2$ Гр. сл. = IV Точн. = Н		$F \text{ см}^2 = 1.95$ $Q \text{ кг.} = 0.528$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 103.7$ $P_{\text{вн.}} = 91.1$ Гр. сл. = IV Точн. = П
	БПЗ-1644		БПЗ-1649
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см}^2 = 1.38$ $Q \text{ кг.} = 0.374$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 115.1$ $P_{\text{вн.}} = 53.5$ Гр. сл. = V Точн. = П
	БПЗ-1645		БПЗ-1650
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = 0 Точн. = 0		$F \text{ см} = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ Гр. сл. = 0 Точн. = 0












	БПЗ-1651		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-1657
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.893$ $Q \text{ кг.} = 0.784$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 260.2$ $P_{вн.} = 72.4$ Гр. сл. = VI Точн. = П
	БПЗ-0		БПЗ-1658
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 5.333$ $Q \text{ кг.} = 1.445$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 163.4$ $P_{вн.} = 141.4$ Гр. сл. = IV Точн. = Н
	БПЗ-0		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П




	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1666</b> $F \text{ см}^2 = 5.049$ $Q \text{ кг.} = 1.368$ $D \text{ оп.мм.} = 89$ $P \text{ н.} = 248.7$ $P_{\text{вн.}} = 208.4$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1667</b> $F \text{ см}^2 = 3.22$ $Q \text{ кг.} = 0.873$ $D \text{ оп.мм.} = 73$ $P \text{ н.} = 223.9$ $P_{\text{вн.}} = 209.4$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1664</b> $F \text{ см}^2 = 44.183$ $Q \text{ кг.} = 11.974$ $D \text{ оп.мм.} = 106$ $P \text{ н.} = 359.3$ $P_{\text{вн.}} = 185.8$ Гр. сл. = особая Точн. = П		<b>БПЗ-1669</b> $F \text{ см}^2 = 30.96$ $Q \text{ кг.} = 8.39$ $D \text{ оп.мм.} = 140$ $P \text{ н.} = 458$ $P_{\text{вн.}} = 163.4$ Гр. сл. = V Точн. = П
	<b>БПЗ-1665</b> $F \text{ см}^2 = 6.951$ $Q \text{ кг.} = 1.884$ $D \text{ оп.мм.} = 91$ $P \text{ н.} = 285.9$ $P_{\text{вн.}} = 270.2$ Гр. сл. = IV Точн. = П		<b>БПЗ-1670</b> $F \text{ см}^2 = 6.59$ $Q \text{ кг.} = 1.786$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 138$ $P_{\text{вн.}} = 135.2$ Гр. сл. = особая Точн. = П









	<b>БПЗ-1671</b> $F \text{ см}^2 = 3.322$ $Q \text{ кг.} = 0.9$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 88$ $P_{Вн.} = 59.7$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		<b>БПЗ-1676</b> $F \text{ см}^2 = 6.122$ $Q \text{ кг.} = 1.66$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 171.9$ $P_{Вн.} = 104.6$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1672</b> $F \text{ см}^2 = 4.241$ $Q \text{ кг.} = 1.149$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 100.5$ $P_{Вн.} = 69.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		<b>БПЗ-1677</b> $F \text{ см}^2 = 6.327$ $Q \text{ кг.} = 1.715$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 275.1$ $P_{Вн.} = 31.2$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1673</b> $F \text{ см}^2 = 5.655$ $Q \text{ кг.} = 1.533$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 113.1$ $P_{Вн.} = 75.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		<b>БПЗ-1678</b> $F \text{ см}^2 = 3.661$ $Q \text{ кг.} = 0.992$ $D \text{ оп.мм.} = 68$ $P \text{ н.} = 323$ $P_{Вн.} = 0$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1674</b> $F \text{ см}^2 = 11.624$ $Q \text{ кг.} = 3.15$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 147.7$ $P_{Вн.} = 84.8$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		<b>БПЗ-1679</b> $F \text{ см}^2 = 3.12$ $Q \text{ кг.} = 0.846$ $D \text{ оп.мм.} = 93$ $P \text{ н.} = 233.8$ $P_{Вн.} = 238.5$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1675</b> $F \text{ см}^2 = 12.987$ $Q \text{ кг.} = 3.519$ $D \text{ оп.мм.} = 104$ $P \text{ н.} = 423.5$ $P_{Вн.} = 91.6$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1680</b> $F \text{ см}^2 = 0.66$ $Q \text{ кг.} = 0.179$ $D \text{ оп.мм.} = 18$ $P \text{ н.} = 56.6$ $P_{Вн.} = 48.7$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$

	<b>БПЗ-1681</b> $F \text{ см}^2 = 0.5$ $Q \text{ кг.} = 0.136$ $D \text{ оп.мм.} = 14$ $P \text{ н.} = 44$ $P_{вн.} = 36.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1687</b> $F \text{ см}^2 = 1.42$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм.} = 16$ $P \text{ н.} = 50.3$ $P_{вн.} = 27.3$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1688</b> $F \text{ см}^2 = 1.01$ $Q \text{ кг.} = 0.275$ $D \text{ оп.мм.} = 15$ $P \text{ н.} = 47.8$ $P_{вн.} = 28.3$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1684</b> $F \text{ см}^2 = 1.755$ $Q \text{ кг.} = 0.476$ $D \text{ оп.мм.} = 36.2$ $P \text{ н.} = 129.5$ $P_{вн.} = 34.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1685</b> $F \text{ см}^2 = 2.267$ $Q \text{ кг.} = 0.614$ $D \text{ оп.мм.} = 71$ $P \text{ н.} = 199.1$ $P_{вн.} = 101.1$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1690</b> $F \text{ см}^2 = 10.313$ $Q \text{ кг.} = 2.795$ $D \text{ оп.мм.} = 95$ $P \text{ н.} = 270.9$ $P_{вн.} = 102$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$





	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1692</b> $F \text{ см}^2 = 1.34$ $Q \text{ кг.} = 0.364$ $D \text{ оп.мм.} = 23$ $P \text{ н.} = 68.8$ $P_{\text{вн.}} = 18.9$ Гр. сл. = V Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1693</b> $F \text{ см}^2 = 4.273$ $Q \text{ кг.} = 1.158$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 341.2$ $P_{\text{вн.}} = 0$ Гр. сл. = VI Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1694</b> $F \text{ см}^2 = 6.08$ $Q \text{ кг.} = 1.648$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 99.4$ $P_{\text{вн.}} = 31.4$ Гр. сл. = IV Точн. = П		<b>БПЗ-1699</b> $F \text{ см}^2 = 7.924$ $Q \text{ кг.} = 2.147$ $D \text{ оп.мм.} = 94$ $P \text{ н.} = 380.6$ $P_{\text{вн.}} = 249.5$ Гр. сл. = V Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П











	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1702</b> $F \text{ см}^2 = 7.47$ $Q \text{ кг.} = 2.025$ $D \text{ оп.мм.} = 100$ $P \text{ н.} = 273.9$ $P_{\text{вн.}} = 223.9$ Гр. сл. = особая Точн. = П		<b>БПЗ-1707</b> $F \text{ см}^2 = 5.305$ $Q \text{ кг.} = 1.438$ $D \text{ оп.мм.} = 99$ $P \text{ н.} = 298.4$ $P_{\text{вн.}} = 257.9$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1703</b> $F \text{ см}^2 = 1.53$ $Q \text{ кг.} = 0.415$ $D \text{ оп.мм.} = 49$ $P \text{ н.} = 126.4$ $P_{\text{вн.}} = 115.6$ Гр. сл. = IV Точн. = П		<b>БПЗ-1708</b> $F \text{ см}^2 = 3.27$ $Q \text{ кг.} = 0.886$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 260.2$ $P_{\text{вн.}} = 171.3$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1710</b> $F \text{ см}^2 = 2.918$ $Q \text{ кг.} = 0.791$ $D \text{ оп.мм.} = 59$ $P \text{ н.} = 291.8$ $P_{\text{вн.}} = 54.9$ Гр. сл. = VI Точн. = П









	БПЗ-1711		БПЗ-1715
	F см <sup>2</sup> = 5.93 Q кг. = 1.607 D оп.мм.= 77 P н. = 224.1 Pвн. = 31.4 Гр. сл. = V Точн. = П		F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П
	БПЗ-1712		БПЗ-0
	F см <sup>2</sup> = 3.464 Q кг. = 0.939 D оп.мм.= 29 P н. = 91.1 Pвн. = 62.8 Гр. сл. = III Точн. = Н		F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П
	БПЗ-1713		БПЗ-0
	F см <sup>2</sup> = 5.938 Q кг. = 1.609 D оп.мм.= 34 P н. = 106.8 Pвн. = 62.8 Гр. сл. = III Точн. = Н		F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-0
	F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П		F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-0
	F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П		F см <sup>2</sup> = 0 Q кг. = 0 D оп.мм.= 0 P н. = 0 Pвн. = 0 Гр. сл. = особая Точн. = П







	<b>БПЗ-1721</b> $F \text{ см}^2 = 2.823$ $Q \text{ кг.} = 0.765$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 281.9$ $P_{вн.} = 92$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$		<b>БПЗ-1726</b> $F \text{ см}^2 = 24.711$ $Q \text{ кг.} = 6.697$ $D \text{ оп.мм.} = 130$ $P \text{ н.} = 1001$ $P_{вн.} = 253.4$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
	<b>БПЗ-1722</b> $F \text{ см}^2 = 1.225$ $Q \text{ кг.} = 0.332$ $D \text{ оп.мм.} = 16$ $P \text{ н.} = 50.3$ $P_{вн.} = 31.4$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = \text{особая}$		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$
	<b>БПЗ-1723</b> $F \text{ см}^2 = 4.001$ $Q \text{ кг.} = 1.084$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 192.6$ $P_{вн.} = 27.4$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$		<b>БПЗ-1728</b> $F \text{ см}^2 = 11.74$ $Q \text{ кг.} = 3.182$ $D \text{ оп.мм.} = 163$ $P \text{ н.} = 472.4$ $P_{вн.} = 466.6$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = П$
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$		<b>БПЗ-1729</b> $F \text{ см}^2 = 7.186$ $Q \text{ кг.} = 1.947$ $D \text{ оп.мм.} = 75$ $P \text{ н.} = 462.3$ $P_{вн.} = 196.7$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$
	<b>БПЗ-1725</b> $F \text{ см}^2 = 0.314$ $Q \text{ кг.} = 0.085$ $D \text{ оп.мм.} = 11$ $P \text{ н.} = 34.6$ $P_{вн.} = 28.3$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = H$		<b>БПЗ-1730</b> $F \text{ см}^2 = 5.338$ $Q \text{ кг.} = 1.447$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 303.2$ $P_{вн.} = 217.8$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = П$















	БПЗ-1731		БПЗ-0
	<p> <math>F \text{ см}^2 = 4.65</math>  <math>Q \text{ кг.} = 1.26</math>  <math>D \text{ оп.мм.} = 52</math>  <math>P \text{ н.} = 173.8</math>  <math>P_{\text{вн.}} = 15.7</math>  Гр. сл. = V  Точн. = П </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	БПЗ-1732		БПЗ-0
	<p> <math>F \text{ см}^2 = 11.148</math>  <math>Q \text{ кг.} = 3.021</math>  <math>D \text{ оп.мм.} = 82</math>  <math>P \text{ н.} = 207.2</math>  <math>P_{\text{вн.}} = 164.2</math>  Гр. сл. = IV  Точн. = П </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	БПЗ-1733		БПЗ-0
	<p> <math>F \text{ см}^2 = 4.54</math>  <math>Q \text{ кг.} = 1.23</math>  <math>D \text{ оп.мм.} = 103</math>  <math>P \text{ н.} = 403.5</math>  <math>P_{\text{вн.}} = 147.5</math>  Гр. сл. = VI  Точн. = П </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	БПЗ-0		БПЗ-0
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	БПЗ-0		БПЗ-1740
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p> <math>F \text{ см}^2 = 2.451</math>  <math>Q \text{ кг.} = 0.664</math>  <math>D \text{ оп.мм.} = 49.8</math>  <math>P \text{ н.} = 184.5</math>  <math>P_{\text{вн.}} = 192.8</math>  Гр. сл. = VI  Точн. = П </p>




	<p><b>БПЗ-1741</b></p> <p> <math>F \text{ см}^2 = 4.18</math>  <math>Q \text{ кг.} = 1.133</math>  <math>D \text{ оп.мм.} = 91.5</math>  <math>P \text{ н.} = 196.6</math>  <math>P_{\text{вн.}} = 211.5</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1746</b></p> <p> <math>F \text{ см}^2 = 1.41</math>  <math>Q \text{ кг.} = 0.383</math>  <math>D \text{ оп.мм.} = 60</math>  <math>P \text{ н.} = 143.5</math>  <math>P_{\text{вн.}} = 24.2</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1742</b></p> <p> <math>F \text{ см}^2 = 9.125</math>  <math>Q \text{ кг.} = 2.473</math>  <math>D \text{ оп.мм.} = 184</math>  <math>P \text{ н.} = 388.9</math>  <math>P_{\text{вн.}} = 430.3</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1747</b></p> <p> <math>F \text{ см}^2 = 14.7</math>  <math>Q \text{ кг.} = 3.98</math>  <math>D \text{ оп.мм.} = 122</math>  <math>P \text{ н.} = 370.7</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1748</b></p> <p> <math>F \text{ см}^2 = 1.762</math>  <math>Q \text{ кг.} = 0.478</math>  <math>D \text{ оп.мм.} = 25</math>  <math>P \text{ н.} = 102.8</math>  <math>P_{\text{вн.}} = 71.9</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-1744</b></p> <p> <math>F \text{ см}^2 = 3.298</math>  <math>Q \text{ кг.} = 0.894</math>  <math>D \text{ оп.мм.} = 60</math>  <math>P \text{ н.} = 181.9</math>  <math>P_{\text{вн.}} = 152.1</math>  Гр. сл. = V  Точн. = особая </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-1750</b></p> <p> <math>F \text{ см}^2 = 5.704</math>  <math>Q \text{ кг.} = 1.546</math>  <math>D \text{ оп.мм.} = 49</math>  <math>P \text{ н.} = 199.7</math>  <math>P_{\text{вн.}} = 108</math>  Гр. сл. = особая  Точн. = П </p>





	<p><b>БПЗ-1751</b></p> <p> <math>F \text{ см}^2 = 3.526</math>  <math>Q \text{ кг.} = 0.955</math>  <math>D \text{ оп.мм.} = 58</math>  <math>P \text{ н.} = 175.5</math>  <math>P_{\text{вн.}} = 91</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1752</b></p> <p> <math>F \text{ см}^2 = 6.01</math>  <math>Q \text{ кг.} = 1.628</math>  <math>D \text{ оп.мм.} = 54</math>  <math>P \text{ н.} = 214.6</math>  <math>P_{\text{вн.}} = 100.4</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-1753</b></p> <p> <math>F \text{ см}^2 = 3.211</math>  <math>Q \text{ кг.} = 0.87</math>  <math>D \text{ оп.мм.} = 41</math>  <math>P \text{ н.} = 182</math>  <math>P_{\text{вн.}} = 42.1</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-1758</b></p> <p> <math>F \text{ см}^2 = 0.917</math>  <math>Q \text{ кг.} = 0.249</math>  <math>D \text{ оп.мм.} = 31</math>  <math>P \text{ н.} = 116.6</math>  <math>P_{\text{вн.}} = 28.6</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1754</b></p> <p> <math>F \text{ см}^2 = 0.391</math>  <math>Q \text{ кг.} = 0.106</math>  <math>D \text{ оп.мм.} = 12.4</math>  <math>P \text{ н.} = 39</math>  <math>P_{\text{вн.}} = 32</math>  Гр. сл. = особая  Точн. = особой </p>		<p><b>БПЗ-1759</b></p> <p> <math>F \text{ см}^2 = 2.36</math>  <math>Q \text{ кг.} = 0.64</math>  <math>D \text{ оп.мм.} = 32</math>  <math>P \text{ н.} = 153.7</math>  <math>P_{\text{вн.}} = 78.5</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-1755</b></p> <p> <math>F \text{ см}^2 = 2.78</math>  <math>Q \text{ кг.} = 0.753</math>  <math>D \text{ оп.мм.} = 33</math>  <math>P \text{ н.} = 102.1</math>  <math>P_{\text{вн.}} = 83.3</math>  Гр. сл. = IV  Точн. = особой </p>		<p><b>БПЗ-1760</b></p> <p> <math>F \text{ см}^2 = 3.484</math>  <math>Q \text{ кг.} = 0.944</math>  <math>D \text{ оп.мм.} = 71</math>  <math>P \text{ н.} = 285.5</math>  <math>P_{\text{вн.}} = 143.1</math>  Гр. сл. = VI  Точн. = П </p>

	<b>БПЗ-1761</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1766</b> $F \text{ см}^2 = 35.94$ $Q \text{ кг.} = 9.74$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 219.9$ $P_{\text{вн.}} = 56.6$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1762</b> $F \text{ см}^2 = 4.816$ $Q \text{ кг.} = 1.305$ $D \text{ оп.мм.} = 66$ $P \text{ н.} = 319.3$ $P_{\text{вн.}} = 216.2$ Гр. сл. = VI Точн. = П		<b>БПЗ-1767</b> $F \text{ см}^2 = 32.95$ $Q \text{ кг.} = 8.929$ $D \text{ оп.мм.} = 150$ $P \text{ н.} = 913$ $P_{\text{вн.}} = 246.4$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1763</b> $F \text{ см}^2 = 31.04$ $Q \text{ кг.} = 8.42$ $D \text{ оп.мм.} = 141$ $P \text{ н.} = 375.4$ $P_{\text{вн.}} = 128.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1764</b> $F \text{ см}^2 = 1.343$ $Q \text{ кг.} = 0.364$ $D \text{ оп.мм.} = 14$ $P \text{ н.} = 44$ $P_{\text{вн.}} = 15.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1765</b> $F \text{ см}^2 = 0.872$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 62.8$ $P_{\text{вн.}} = 53.4$ Гр. сл. = V Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П








	БПЗ-1771		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1773		БПЗ-1778
	$F \text{ см}^2 = 2.112$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм.} = 49.8$ $P \text{ н.} = 184.5$ $P_{\text{вн.}} = 147$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 5.616$ $Q \text{ кг.} = 1.522$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 119.4$ $P_{\text{вн.}} = 84.8$ Гр. сл. = V Точн. = П
	БПЗ-1774		БПЗ-1779
	$F \text{ см}^2 = 5.28$ $Q \text{ кг.} = 1.431$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 106.8$ $P_{\text{вн.}} = 69.1$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 3.035$ $Q \text{ кг.} = 0.822$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 219.4$ $P_{\text{вн.}} = 179.1$ Гр. сл. = VI Точн. = П
	БПЗ-0		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П








	<b>БПЗ-1781</b> $F \text{ см}^2 = 2.689$ $Q \text{ кг.} = 0.729$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 98.3$ $P_{\text{вн.}} = 62$ Гр. сл. = IV Точн. = П		<b>БПЗ-1786</b> $F \text{ см}^2 = 0.872$ $Q \text{ кг.} = 0.236$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 62.8$ $P_{\text{вн.}} = 53.4$ Гр. сл. = V Точн. = П
	<b>БПЗ-1782</b> $F \text{ см}^2 = 23.91$ $Q \text{ кг.} = 6.48$ $D \text{ оп.мм.} = 147$ $P \text{ н.} = 333.1$ $P_{\text{вн.}} = 364$ Гр. сл. = особая Точн. = Н		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1783</b> $F \text{ см}^2 = 2.226$ $Q \text{ кг.} = 0.603$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 178.1$ $P_{\text{вн.}} = 121$ Гр. сл. = VI Точн. = П		<b>БПЗ-1788</b> $F \text{ см}^2 = 2.267$ $Q \text{ кг.} = 0.614$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 240.1$ $P_{\text{вн.}} = 138.6$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1784</b> $F \text{ см}^2 = 2.06$ $Q \text{ кг.} = 0.558$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 175.7$ $P_{\text{вн.}} = 99$ Гр. сл. = VI Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = 0 Точн. = П
	<b>БПЗ-1785</b> $F \text{ см}^2 = 0.73$ $Q \text{ кг.} = 0.198$ $D \text{ оп.мм.} = 17$ $P \text{ н.} = 53.4$ $P_{\text{вн.}} = 44$ Гр. сл. = IV Точн. = П		<b>БПЗ-1790</b> $F \text{ см}^2 = 5.183$ $Q \text{ кг.} = 1.405$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 378.9$ $P_{\text{вн.}} = 110.8$ Гр. сл. = особая Точн. = П




	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1796</b> $F \text{ см}^2 = 7.19$ $Q \text{ кг.} = 1.95$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 274.9$ $P_{\text{вн.}} = 491.3$ Гр. сл. = V Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1799</b> $F \text{ см}^2 = 1.54$ $Q \text{ кг.} = 0.417$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 208$ $P_{\text{вн.}} = 0$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1795</b> $F \text{ см}^2 = 2.425$ $Q \text{ кг.} = 0.657$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 225.7$ $P_{\text{вн.}} = 251.2$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П










	<p><b>БПЗ-1801</b></p> <p> <math>F \text{ см}^2 = 18.85</math>  <math>Q \text{ кг.} = 5.108</math>  <math>D \text{ оп.мм.} = 70</math>  <math>P \text{ н.} = 219.9</math>  <math>P_{\text{вн.}} = 157.1</math>  <math>\Gamma \text{ р. сл.} = \text{I}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-1802</b></p> <p> <math>F \text{ см}^2 = 21.18</math>  <math>Q \text{ кг.} = 5.74</math>  <math>D \text{ оп.мм.} = 110</math>  <math>P \text{ н.} = 282.5</math>  <math>P_{\text{вн.}} = 237.8</math>  <math>\Gamma \text{ р. сл.} = \text{V}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-1803</b></p> <p> <math>F \text{ см}^2 = 17.51</math>  <math>Q \text{ кг.} = 4.745</math>  <math>D \text{ оп.мм.} = 81</math>  <math>P \text{ н.} = 218.1</math>  <math>P_{\text{вн.}} = 294.5</math>  <math>\Gamma \text{ р. сл.} = \text{V}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-1810</b></p> <p> <math>F \text{ см}^2 = 2.47</math>  <math>Q \text{ кг.} = 0.669</math>  <math>D \text{ оп.мм.} = 51</math>  <math>P \text{ н.} = 167.2</math>  <math>P_{\text{вн.}} = 93.2</math>  <math>\Gamma \text{ р. сл.} = \text{V}</math>  <math>\text{Точн.} = \text{П}</math> </p>




















	<p><b>БПЗ-1811</b></p> <p> <math>F \text{ см}^2 = 3.016</math>  <math>Q \text{ кг.} = 0.817</math>  <math>D \text{ оп.мм.} = 50</math>  <math>P \text{ н.} = 157.1</math>  <math>P_{\text{вн.}} = 144.5</math>  <math>\Gamma \text{ р. сл.} = V</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = П</math> </p>
	<p><b>БПЗ-1812</b></p> <p> <math>F \text{ см}^2 = 1.882</math>  <math>Q \text{ кг.} = 0.51</math>  <math>D \text{ оп.мм.} = 48</math>  <math>P \text{ н.} = 141.5</math>  <math>P_{\text{вн.}} = 135.4</math>  <math>\Gamma \text{ р. сл.} = VI</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-1817</b></p> <p> <math>F \text{ см}^2 = 1.107</math>  <math>Q \text{ кг.} = 0.291</math>  <math>D \text{ оп.мм.} = 29</math>  <math>P \text{ н.} = 89.9</math>  <math>P_{\text{вн.}} = 77.2</math>  <math>\Gamma \text{ р. сл.} = VI</math>  <math>\text{Точн.} = П</math> </p>
	<p><b>БПЗ-1813</b></p> <p> <math>F \text{ см}^2 = 1.874</math>  <math>Q \text{ кг.} = 0.508</math>  <math>D \text{ оп.мм.} = 54</math>  <math>P \text{ н.} = 141.7</math>  <math>P_{\text{вн.}} = 129.3</math>  <math>\Gamma \text{ р. сл.} = V</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-1818</b></p> <p> <math>F \text{ см}^2 = 2.676</math>  <math>Q \text{ кг.} = 0.725</math>  <math>D \text{ оп.мм.} = 58</math>  <math>P \text{ н.} = 193.3</math>  <math>P_{\text{вн.}} = 132.7</math>  <math>\Gamma \text{ р. сл.} = VI</math>  <math>\text{Точн.} = П</math> </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-1819</b></p> <p> <math>F \text{ см}^2 = 2.601</math>  <math>Q \text{ кг.} = 0.705</math>  <math>D \text{ оп.мм.} = 58</math>  <math>P \text{ н.} = 182.3</math>  <math>P_{\text{вн.}} = 138.4</math>  <math>\Gamma \text{ р. сл.} = VI</math>  <math>\text{Точн.} = П</math> </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{ р. сл.} = \text{особая}</math>  <math>\text{Точн.} = П</math> </p>		<p><b>БПЗ-1820</b></p> <p> <math>F \text{ см}^2 = 3.386</math>  <math>Q \text{ кг.} = 0.918</math>  <math>D \text{ оп.мм.} = 78</math>  <math>P \text{ н.} = 234.4</math>  <math>P_{\text{вн.}} = 206.2</math>  <math>\Gamma \text{ р. сл.} = VI</math>  <math>\text{Точн.} = П</math> </p>





	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1822</b> $F \text{ см}^2 = 2.807$ $Q \text{ кг.} = 0.761$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 204.4$ $P_{\text{вн.}} = 138.4$ Гр. сл. = VI Точн. = П		<b>БПЗ-1827</b> $F \text{ см}^2 = 47.31$ $Q \text{ кг.} = 12.8$ $D \text{ оп.мм.} = 115$ $P \text{ н.} = 361.3$ $P_{\text{вн.}} = 284.2$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1823</b> $F \text{ см}^2 = 3.797$ $Q \text{ кг.} = 1.03$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 180.8$ $P_{\text{вн.}} = 212.5$ Гр. сл. = V Точн. = П		<b>БПЗ-1828</b> $F \text{ см}^2 = 2.16$ $Q \text{ кг.} = 0.585$ $D \text{ оп.мм.} = 81$ $P \text{ н.} = 336.2$ $P_{\text{вн.}} = 0$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1824</b> $F \text{ см}^2 = 4.131$ $Q \text{ кг.} = 1.12$ $D \text{ оп.мм.} = 86$ $P \text{ н.} = 337.4$ $P_{\text{вн.}} = 75.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1825</b> $F \text{ см}^2 = 4.745$ $Q \text{ кг.} = 1.286$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 268.8$ $P_{\text{вн.}} = 201.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-1830</b> $F \text{ см}^2 = 6.316$ $Q \text{ кг.} = 1.712$ $D \text{ оп.мм.} = 72$ $P \text{ н.мм} = 286.6$ $P_{\text{вн.мм}} = 168.8$ Гр. сл. = IV Точн. = П







	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1836</b> $F \text{ см}^2 = 1.354$ $Q \text{ кг.} = 0.367$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 220.5$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1833</b> $F \text{ см}^2 = 1.76$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 162$ $P_{вн.} = 62$ Гр. сл. = IV Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1834</b> $F \text{ см}^2 = 1.767$ $Q \text{ кг.} = 0.479$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 78.5$ $P_{вн.} = 62.8$ Гр. сл. = IV Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П

	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1846</b> $F \text{ см}^2 = 5.466$ $Q \text{ кг.} = 1.481$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 403.9$ $P_{\text{вн.}} = 269.1$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1842</b> $F \text{ см}^2 = 7.625$ $Q \text{ кг.} = 2.066$ $D \text{ оп.мм.} = 137$ $P \text{ н.} = 379.9$ $P_{\text{вн.}} = 266.8$ Гр. сл. = VI Точн. = П		<b>БПЗ-1847</b> $F \text{ см}^2 = 0.702$ $Q \text{ кг.} = 0.19$ $D \text{ оп.мм.} = 15.4$ $P \text{ н.} = 48.4$ $P_{\text{вн.}} = 40.7$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1843</b> $F \text{ см}^2 = 10.481$ $Q \text{ кг.} = 2.84$ $D \text{ оп.мм.} = 127$ $P \text{ н.} = 508.4$ $P_{\text{вн.}} = 422.1$ Гр. сл. = особая Точн. = П		<b>БПЗ-1848</b> $F \text{ см}^2 = 2.011$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 106.8$ $P_{\text{вн.}} = 94.3$ Гр. сл. = V Точн. = П
	<b>БПЗ-1844</b> $F \text{ см}^2 = 3.24$ $Q \text{ кг.} = 0.88$ $D \text{ оп.мм.} = 29$ $P \text{ н.} = 81.7$ $P_{\text{вн.}} = 36.1$ Гр. сл. = V Точн. = П		<b>БПЗ-1849</b> $F \text{ см}^2 = 2.474$ $Q \text{ кг.} = 0.67$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 106.8$ $P_{\text{вн.}} = 91.1$ Гр. сл. = V Точн. = П
	<b>БПЗ-1845</b> $F \text{ см}^2 = 0.725$ $Q \text{ кг.} = 0.196$ $D \text{ оп.мм.} = 13.5$ $P \text{ н.} = 42.4$ $P_{\text{вн.}} = 98.1$ Гр. сл. = VI Точн. = П		<b>БПЗ-1850</b> $F \text{ см}^2 = 3.564$ $Q \text{ кг.} = 0.966$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 106.8$ $P_{\text{вн.}} = 83.3$ Гр. сл. = IV Точн. = П







	<b>БПЗ-1851</b> $F \text{ см}^2 = 5.0$ $Q \text{ кг.} = 1.36$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 348.3$ $P_{\text{вн.}} = 110.8$ Гр. сл. = особая Точн. = П		<b>БПЗ-1856</b> $F \text{ см}^2 = 2.998$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм.} = 99$ $P \text{ н.} = 242.4$ $P_{\text{вн.}} = 230.7$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1852</b> $F \text{ см}^2 =$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1857</b> $F \text{ см}^2 = 6.39$ $Q \text{ кг.} = 1.73$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 100.5$ $P_{\text{вн.}} = 68.7$ Гр. сл. = V Точн. = П
	<b>БПЗ-1853</b> $F \text{ см}^2 = 2.76$ $Q \text{ кг.} = 0.747$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 196.3$ $P_{\text{вн.}} = 74.4$ Гр. сл. = особая Точн. = П		<b>БПЗ-1858</b> $F \text{ см}^2 = 1.94$ $Q \text{ кг.} = 0.526$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 152.3$ $P_{\text{вн.}} = 147.2$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1854</b> $F \text{ см}^2 = 3.3$ $Q \text{ кг.} = 0.894$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 162.3$ $P_{\text{вн.}} = 104.3$ Гр. сл. = V Точн. = П		<b>БПЗ-1859</b> $F \text{ см}^2 = 1.176$ $Q \text{ кг.} = 0.319$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 101.8$ $P_{\text{вн.}} = 94.2$ Гр. сл. = V Точн. = П
	<b>БПЗ-1855</b> $F \text{ см}^2 = 4.44$ $Q \text{ кг.} = 1.2$ $D \text{ оп.мм.} = 79$ $P \text{ н.} = 324.7$ $P_{\text{вн.}} = 232.5$ Гр. сл. = V Точн. = П		<b>БПЗ-1860</b> $F \text{ см}^2 = 3.98$ $Q \text{ кг.} = 1.079$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 205.1$ $P_{\text{вн.}} = 192.5$ Гр. сл. = V Точн. = П




	<b>БПЗ-1851</b> $F \text{ см}^2 = 5$ $Q \text{ кг.} = 1.36$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 348.3$ $P_{\text{вн.}} = 110.8$ Гр. сл. = особая Точн. = П		<b>БПЗ-1856</b> $F \text{ см}^2 = 2.998$ $Q \text{ кг.} = 0.813$ $D \text{ оп.мм.} = 99$ $P \text{ н.} = 242.4$ $P_{\text{вн.}} = 230.7$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1852</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1857</b> $F \text{ см}^2 = 6.39$ $Q \text{ кг.} = 1.73$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 100.5$ $P_{\text{вн.}} = 68.7$ Гр. сл. = V Точн. = П
	<b>БПЗ-1853</b> $F \text{ см}^2 = 2.76$ $Q \text{ кг.} = 0.747$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 196.3$ $P_{\text{вн.}} = 74.4$ Гр. сл. = особая Точн. = П		<b>БПЗ-1858</b> $F \text{ см}^2 = 1.94$ $Q \text{ кг.} = 0.526$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 152.3$ $P_{\text{вн.}} = 147.2$ Гр. сл. = VI Точн. = П
	<b>БПЗ-1854</b> $F \text{ см}^2 = 3.3$ $Q \text{ кг.} = 0.894$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 162.3$ $P_{\text{вн.}} = 104.9$ Гр. сл. = V Точн. = П		<b>БПЗ-1859</b> $F \text{ см}^2 = 1.176$ $Q \text{ кг.} = 0.319$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 101.8$ $P_{\text{вн.}} = 94.2$ Гр. сл. = V Точн. = П
	<b>БПЗ-1855</b> $F \text{ см}^2 = 4.44$ $Q \text{ кг.} = 1.2$ $D \text{ оп.мм.} = 79$ $P \text{ н.} = 324.7$ $P_{\text{вн.}} = 232.5$ Гр. сл. = V Точн. = П		<b>БПЗ-1860</b> $F \text{ см}^2 = 3.98$ $Q \text{ кг.} = 1.079$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 205.1$ $P_{\text{вн.}} = 192.5$ Гр. сл. = V Точн. = П



	<b>БПЗ-1861</b> $F \text{ см}^2 = 3.495$ $Q \text{ кг.} = 0.947$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 180.8$ $P_{\text{вн.}} = 167.4$ Гр. сл. = V Точн. = П		<b>БПЗ-1866</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1862</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1867</b> $F \text{ см}^2 = 10.2$ $Q \text{ кг.} = 2.76$ $D \text{ оп.мм.} = 97$ $P \text{ н.} = 323.1$ $P_{\text{вн.}} = 115.8$ Гр. сл. = IV Точн. = П
	<b>БПЗ-1863</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1868</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1864</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1869</b> $F \text{ см}^2 = 7.986$ $Q \text{ кг.} = 2.164$ $D \text{ оп.мм.} = 136$ $P \text{ н.} = 403.5$ $P_{\text{вн.}} = 335.2$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1865</b> $F \text{ см}^2 = 8.254$ $Q \text{ кг.} = 2.24$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 233$ $P_{\text{вн.}} = 31.4$ Гр. сл. = особая Точн. = П		<b>БПЗ-1870</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П





	<b>БПЗ-1871</b> $F \text{ см}^2 = 5.145$ $Q \text{ кг.} = 1.394$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 198.2$ $P_{вн.} = 157.7$ Гр. сл. = особая Точн. = П		<b>БПЗ-1876</b> $F \text{ см}^2 = 6.434$ $Q \text{ кг.} = 1.744$ $D \text{ оп.мм.} = 86$ $P \text{ н.} = 367.9$ $P_{вн.} = 261.8$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1872</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1877</b> $F \text{ см}^2 = 1.08$ $Q \text{ кг.} = 0.293$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 116.6$ $P_{вн.} = 44$ Гр. сл. = V Точн. = П
	<b>БПЗ-1873</b> $F \text{ см}^2 = 7.633$ $Q \text{ кг.} = 2.07$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 250.2$ $P_{вн.} = 195.3$ Гр. сл. = VI Точн. = П		<b>БПЗ-1878</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1874</b> $F \text{ см}^2 = 5.83$ $Q \text{ кг.} = 1.58$ $D \text{ оп.мм.} = 108$ $P \text{ н.} = 309.4$ $P_{вн.} = 0$ Гр. сл. = V Точн. = П		<b>БПЗ-1879</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1875</b> $F \text{ см}^2 = 4.351$ $Q \text{ кг.} = 1.18$ $D \text{ оп.мм.} = 100.5$ $P \text{ н.} = 297.7$ $P_{вн.} = 161.5$ Гр. сл. = особая Точн. = П		<b>БПЗ-1880</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П













	БПЗ-1881		БПЗ-1886
	$F \text{ см}^2 = 1.885$ $Q \text{ кг.} = 0.511$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 154.4$ $P_{\text{вн.}} = 133.7$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1882		БПЗ-1887
	$F \text{ см}^2 = 1.06$ $Q \text{ кг.} = 0.287$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 75.4$ $P_{\text{вн.}} = 66$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 3.18$ $Q \text{ кг.} = 0.862$ $D \text{ оп.мм.} = 27$ $P \text{ н.} = 84.8$ $P_{\text{вн.}} = 56.6$ Гр. сл. = IV Точн. = П
	БПЗ-1883		БПЗ-1888
	$F \text{ см}^2 = 2.116$ $Q \text{ кг.} = 0.573$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 94.2$ $P_{\text{вн.}} = 78.5$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 7.838$ $Q \text{ кг.} = 2.124$ $D \text{ оп.мм.} = 126$ $P \text{ н.} = 555.2$ $P_{\text{вн.}} = 307.4$ Гр. сл. = V Точн. = П
	БПЗ-1884		БПЗ-1889
	$F \text{ см}^2 = 5.737$ $Q \text{ кг.} = 1.555$ $D \text{ оп.мм.} = 77$ $P \text{ н.} = 312.9$ $P_{\text{вн.}} = 209$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1885		БПЗ-1890
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П






	БПЗ-1891		БПЗ-1896
	$F \text{ см}^2 = 1.579$ $Q \text{ кг.} = 0.428$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 110$ $P_{\text{вн.}} = 100.5$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПЗ-1892		БПЗ-1897
	$F \text{ см}^2 = 18$ $Q \text{ кг.} = 4.88$ $D \text{ оп.мм.} = 121$ $P \text{ н.} = 374.8$ $P_{\text{вн.}} = 198.5$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПЗ-1893		БПЗ-1898
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПЗ-1894		БПЗ-1899
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 2.82$ $Q \text{ кг.} = 0.764$ $D \text{ оп.мм.} = 77$ $P \text{ н.} = 192.6$ $P_{\text{вн.}} = 182.8$ $\text{Гр. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
	БПЗ-1895		БПЗ-1900
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 1.866$ $Q \text{ кг.} = 0.506$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 169.2$ $P_{\text{вн.}} = 64$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$








	БПЗ-1901		БПЗ-1906
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1902		БПЗ-1907
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1903		БПЗ-1908
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1904		БПЗ-1909
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1905		БПЗ-1910
	$F \text{ см}^2 = 5.019$ $Q \text{ кг.} = 1.36$ $D \text{ оп.мм.} = 63$ $P \text{ н.} = 351.2$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.695$ $Q \text{ кг.} = 0.73$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 251.5$ $P_{\text{вн.}} = 50.5$ Гр. сл. = VI Точн. = П

	<p><b>БПЗ-1911</b></p> <p> <math>F \text{ см}^2 = 3</math>  <math>Q \text{ кг.} = 0.813</math>  <math>D \text{ оп.мм.} = 43</math>  <math>P \text{ н.} = 119</math>  <math>P_{\text{вн.}} = 99.2</math>  <math>\Gamma \text{р. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{особой}</math> </p>		<p><b>БПЗ-1916</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-1912</b></p> <p> <math>F \text{ см}^2 = 1.933</math>  <math>Q \text{ кг.} = 0.54</math>  <math>D \text{ оп.мм.} = 29</math>  <math>P \text{ н.} = 81</math>  <math>P_{\text{вн.}} = 62.6</math>  <math>\Gamma \text{р. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{особой}</math> </p>		<p><b>БПЗ-1917</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-1913</b></p> <p> <math>F \text{ см}^2 = 3.03</math>  <math>Q \text{ кг.} = 0.82</math>  <math>D \text{ оп.мм.} = 44</math>  <math>P \text{ н.} = 183.7</math>  <math>P_{\text{вн.}} = 35</math>  <math>\Gamma \text{р. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-1918</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-1914</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-1919</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	<p><b>БПЗ-1915</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p><b>БПЗ-1920</b></p> <p> <math>F \text{ см}^2 = 6.722</math>  <math>Q \text{ кг.} = 1.822</math>  <math>D \text{ оп.мм.} = 106</math>  <math>P \text{ н.} = 352.8</math>  <math>P_{\text{вн.}} = 343.2</math>  <math>\Gamma \text{р. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>




	БПЗ-1921		БПЗ-1926
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 4.096$ $Q \text{ кг.} = 1.11$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 307.8$ $P_{\text{вн.}} = 99.6$ Гр. сл. = IV Точн. = П
	БПЗ-1922		БПЗ-1927
	$F \text{ см}^2 = 2.596$ $Q \text{ кг.} = 0.703$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 229.8$ $P_{\text{вн.}} = 23.9$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1923		БПЗ-1928
	$F \text{ см}^2 = 2.105$ $Q \text{ кг.} = 0.57$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 130.7$ $P_{\text{вн.}} = 94.2$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1924		БПЗ-1929
	$F \text{ см}^2 = 4.071$ $Q \text{ кг.} = 1.1$ $D \text{ оп.мм.} = 44$ $P \text{ н.} = 331.3$ $P_{\text{вн.}} = 63.1$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1925		БПЗ-1930
	$F \text{ см}^2 = 4.11$ $Q \text{ кг.} = 1.114$ $D \text{ оп.мм.} = 46$ $P \text{ н.} = 333.6$ $P_{\text{вн.}} = 63.14$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П









	БПЗ-1931		БПЗ-1936
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.206$ $Q \text{ кг.} = 0.598$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 130.3$ $P_{\text{вн.}} = 58.4$ Гр. сл. = V Точн. = П
	БПЗ-1932		БПЗ-1937
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 3.338$ $Q \text{ кг.} = 0.905$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 141.4$ $P_{\text{вн.}} = 125.7$ Гр. сл. = V Точн. = П
	БПЗ-1933		БПЗ-1938
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.58$ $Q \text{ кг.} = 0.7$ $D \text{ оп.мм.} = 49$ $P \text{ н.} = 181$ $P_{\text{вн.}} = 93.1$ Гр. сл. = V Точн. = П
	БПЗ-1934		БПЗ-1939
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 3.957$ $Q \text{ кг.} = 1.07$ $D \text{ оп.мм.} = 84$ $P \text{ н.} = 280.9$ $P_{\text{вн.}} = 243.8$ Гр. сл. = особая Точн. = П
	БПЗ-1935		БПЗ-1940
	$F \text{ см}^2 = 4.77$ $Q \text{ кг.} = 1.293$ $D \text{ оп.мм.} = 78$ $P \text{ н.} = 245$ $P_{\text{вн.}} = 232.5$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П





	БПЗ-1941		БПЗ-1946
	$F \text{ см}^2 = 1.659$ $Q \text{ кг.} = 0.45$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 89.1$ $P_{\text{вн.}} = 76$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1942		БПЗ-1947
	$F \text{ см}^2 = 3.136$ $Q \text{ кг.} = 0.85$ $D \text{ оп.мм.} = 27$ $P \text{ н.} = 78.4$ $P_{\text{вн.}} = 43.8$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1943		БПЗ-1948
	$F \text{ см}^2 = 2.946$ $Q \text{ кг.} = 0.798$ $D \text{ оп.мм.} = 89$ $P \text{ н.} = 217.4$ $P_{\text{вн.}} = 172.9$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1944		БПЗ-1949
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 5.499$ $Q \text{ кг.} = 1.49$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 282.9$ $P_{\text{вн.}} = 248.4$ Гр. сл. = VI Точн. = П
	БПЗ-1945		БПЗ-1950
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.223$ $Q \text{ кг.} = 0.602$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 176.1$ $P_{\text{вн.}} = 123$ Гр. сл. = VI Точн. = П








	<b>БПЗ-1951</b> $F \text{ см}^2 = 17.84$ $Q \text{ кг.} = 4.835$ $D \text{ оп.мм.} = 103$ $P \text{ н.} = 569.7$ $P_{вн.} = 0$ Гр. сл. = V Точн. = П		<b>БПЗ-1956</b> $F \text{ см}^2 = 2.649$ $Q \text{ кг.} = 0.718$ $D \text{ оп.мм.} = 57$ $P \text{ н.} = 181.3$ $P_{вн.} = 171.9$ Гр. сл. = V Точн. = П
	<b>БПЗ-1952</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-1957</b> $F \text{ см}^2 = 57.42$ $Q \text{ кг.} = 15.56$ $D \text{ оп.мм.} = 114$ $P \text{ н.} = 358.1$ $P_{вн.} = 236.9$ Гр. сл. = V Точн. = П
	<b>БПЗ-1953</b> $F \text{ см}^2 = 4.286$ $Q \text{ кг.} = 1.162$ $D \text{ оп.мм.} = 91$ $P \text{ н.} = 255.1$ $P_{вн.} = 316$ Гр. сл. = VI Точн. = П		<b>БПЗ-1958</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1954</b> $F \text{ см}^2 = 17.81$ $Q \text{ кг.} = 4.827$ $D \text{ оп.мм.} = 72$ $P \text{ н.} = 241.7$ $P_{вн.} = 157$ Гр. сл. = V Точн. = П		<b>БПЗ-1959</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-1955</b> $F \text{ см}^2 = 29.69$ $Q \text{ кг.} = 8.045$ $D \text{ оп.мм.} = 114$ $P \text{ н.} = 358.1$ $P_{вн.} = 301.6$ Гр. сл. = V Точн. = П		<b>БПЗ-1960</b> $F \text{ см}^2 = 3.095$ $Q \text{ кг.} = 0.839$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 108.8$ $P_{вн.} = 105.8$ Гр. сл. = особая Точн. = П











	БПЗ-1961		БПЗ-1966
	<p> <math>F \text{ см}^2 = 9.038</math>  <math>Q \text{ кг.} = 2.449</math>  <math>D \text{ оп.мм.} = 161.1</math>  <math>P \text{ н.} = 467</math>  <math>P_{\text{вн.}} = 376</math>  <math>\text{Гр. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 12.839</math>  <math>Q \text{ кг.} = 3.479</math>  <math>D \text{ оп.мм.} = 130</math>  <math>P \text{ н.} = 532.8</math>  <math>P_{\text{вн.}} = 288.3</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	БПЗ-1962		БПЗ-1967
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	БПЗ-1963		БПЗ-1968
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	БПЗ-1964		БПЗ-1969
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	БПЗ-1965		БПЗ-1970
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 1.33</math>  <math>Q \text{ кг.} = 0.36</math>  <math>D \text{ оп.мм.} = 31</math>  <math>P \text{ н.} = 134.8</math>  <math>P_{\text{вн.}} = 55.2</math>  <math>\text{Гр. сл.} = \text{VI}</math>  <math>\text{Точн.} = \text{П}</math> </p>





	<b>БПЗ-1971</b> $F \text{ см}^2 = 0.682$ $Q \text{ кг.} = 0.185$ $D \text{ оп.мм.} = 12$ $P \text{ н.} = 37.7$ $P_{вн.} = 24.1$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1976</b> $F \text{ см}^2 = 0.814$ $Q \text{ кг.} = 0.221$ $D \text{ оп.мм.} = 16.5$ $P \text{ н.} = 51.5$ $P_{вн.} = 40.5$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1972</b> $F \text{ см}^2 = 0.654$ $Q \text{ кг.} = 0.177$ $D \text{ оп.мм.} = 18$ $P \text{ н.} = 48$ $P_{вн.} = 46$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1977</b> $F \text{ см}^2 = 4.166$ $Q \text{ кг.} = 1.129$ $D \text{ оп.мм.} = 105$ $P \text{ н.} = 401.4$ $P_{вн.} = 106.4$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{особая}$
	<b>БПЗ-1973</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1978</b> $F \text{ см}^2 = 8.547$ $Q \text{ кг.} = 2.316$ $D \text{ оп.мм.} = 173$ $P \text{ н.} = 643.9$ $P_{вн.} = 307.9$ $\text{Гр. сл.} = \text{VI}$ $\text{Точн.} = \text{особая}$
	<b>БПЗ-1974</b> $F \text{ см}^2 = 0.796$ $Q \text{ кг.} = 0.216$ $D \text{ оп.мм.} = 19.5$ $P \text{ н.} = 61.3$ $P_{вн.} = 52.5$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1979</b> $F \text{ см}^2 = 0.818$ $Q \text{ кг.} = 0.222$ $D \text{ оп.мм.} = 14$ $P \text{ н.} = 44$ $P_{вн.} = 31$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-1975</b> $F \text{ см}^2 = 0.866$ $Q \text{ кг.} = 0.235$ $D \text{ оп.мм.} = 16.5$ $P \text{ н.} = 51.5$ $P_{вн.} = 39.6$ $\text{Гр. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		<b>БПЗ-1980</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\text{Гр. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$





	БПЗ-1981		БПЗ-1986
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1982		БПЗ-1987
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1983		БПЗ-1988
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 6.96$ $Q \text{ кг.} = 1.886$ $D \text{ оп.мм.} = 71$ $P \text{ н.} = 312$ $P_{\text{вн.}} = 152$ Гр. сл. = IV Точн. = П
	БПЗ-1984		БПЗ-1989
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 3.5$ $Q \text{ кг.} = 0.949$ $D \text{ оп.мм.} = 91$ $P \text{ н.} = 260.6$ $P_{\text{вн.}} = 84.5$ Гр. сл. = VI Точн. = П
	БПЗ-1985		БПЗ-1990
	$F \text{ см}^2 = 0.715$ $Q \text{ кг.} = 0.194$ $D \text{ оп.мм.} = 12.5$ $P \text{ н.} = 39.3$ $P_{\text{вн.}} = 85.3$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.527$ $Q \text{ кг.} = 0.685$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 296.1$ $P_{\text{вн.}} = 77.3$ Гр. сл. = VI Точн. = П

	БПЗ-1991		БПЗ-1996
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 6.34$ $Q \text{ кг.} = 1.718$ $D \text{ оп.мм.} = 81$ $P \text{ н.} = 378$ $P_{\text{вн.}} = 207$ Гр. сл. = VI Точн. = П
	БПЗ-1992		БПЗ-1997
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 5.556$ $Q \text{ кг.} = 1.507$ $D \text{ оп.мм.} = 112$ $P \text{ н.} = 319$ $P_{\text{вн.}} = 281$ Гр. сл. = VI Точн. = П
	БПЗ-1993		БПЗ-1998
	$F \text{ см}^2 = 12.04$ $Q \text{ кг.} = 3.263$ $D \text{ оп.мм.} = 101$ $P \text{ н.} = 396.2$ $P_{\text{вн.}} = 260.4$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 7.44$ $Q \text{ кг.} = 2.016$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 328$ $P_{\text{вн.}} = 211$ Гр. сл. = V Точн. = П
	БПЗ-1994		БПЗ-1999
	$F \text{ см}^2 = 6.22$ $Q \text{ кг.} = 1.686$ $D \text{ оп.мм.} = 112$ $P \text{ н.} = 344$ $P_{\text{вн.}} = 278$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-1995		БПЗ-2000
	$F \text{ см}^2 = 7.2$ $Q \text{ кг.} = 1.951$ $D \text{ оп.мм.} = 90$ $P \text{ н.} = 424$ $P_{\text{вн.}} = 224$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 7.72$ $Q \text{ кг.} = 1.496$ $D \text{ оп.мм.} = 108$ $P \text{ н.} = 376$ $P_{\text{вн.}} = 265$ Гр. сл. = VI Точн. = П








	БПЗ-2001		БПЗ-2006
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2002		БПЗ-2007
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2003		БПЗ-2008
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2004		БПЗ-2009
	$F \text{ см}^2 = 35.34$ $Q \text{ кг.} = 9.577$ $D \text{ оп.мм.} = 90$ $P \text{ н.} = 282.7$ $P_{\text{вн.}} = 188.5$ Гр. сл. = III Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2005		БПЗ-2010
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П









	<b>БПЗ-2011</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2016</b> $F \text{ см}^2 = 2.9$ $Q \text{ кг.} = 0.786$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 214$ $P_{\text{вн.}} = 91$ Гр. сл. = IV Точн. = П
	<b>БПЗ-2012</b> $F \text{ см}^2 = 0.979$ $Q \text{ кг.} = 0.265$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 95.2$ $P_{\text{вн.}} = 45.4$ Гр. сл. = V Точн. = П		<b>БПЗ-2017</b> $F \text{ см}^2 = 13.37$ $Q \text{ кг.} = 3.623$ $D \text{ оп.мм.} = 99$ $P \text{ н.} = 373.4$ $P_{\text{вн.}} = 361$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2013</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2018</b> $F \text{ см}^2 = 1.207$ $Q \text{ кг.} = 0.327$ $D \text{ оп.мм.} = 34$ $P \text{ н.} = 136.8$ $P_{\text{вн.}} = 64.4$ Гр. сл. = V Точн. = П
	<b>БПЗ-2014</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2019</b> $F \text{ см}^2 = 7.19$ $Q \text{ кг.} = 1.948$ $D \text{ оп.мм.} = 143$ $P \text{ н.} = 538$ $P_{\text{вн.}} = 265.8$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2015</b> $F \text{ см}^2 = 10.479$ $Q \text{ кг.} = 2.84$ $D \text{ оп.мм.} = 129$ $P \text{ н.} = 830.1$ $P_{\text{вн.}} = 182$ Гр. сл. = VI Точн. = П		<b>БПЗ-2020</b> $F \text{ см}^2 = 2.935$ $Q \text{ кг.} = 0.795$ $D \text{ оп.мм.} = 66$ $P \text{ н.} = 255.3$ $P_{\text{вн.}} = 83.7$ Гр. сл. = VI Точн. = П








	БПЗ-2021		БПЗ-2026
	$F \text{ см}^2 = 6.87$ $Q \text{ кг.} = 1.862$ $D \text{ оп.мм.} = 150$ $P \text{ н.} = 462$ $P_{\text{вн.}} = 282.2$ Гр. сл. = VI Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2022		БПЗ-2027
	$F \text{ см}^2 = 5.68$ $Q \text{ кг.} = 1.54$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 214.5$ $P_{\text{вн.}} = 125.5$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2023		БПЗ-2028
	$F \text{ см}^2 = 4.843$ $Q \text{ кг.} = 1.312$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 235.2$ $P_{\text{вн.}} = 71.5$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2024		БПЗ-2029
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.655$ $Q \text{ кг.} = 0.72$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 173.3$ $P_{\text{вн.}} = 32.2$ Гр. сл. = VI Точн. = П
	БПЗ-2025		БПЗ-2030
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П






	БПЗ-2031		БПЗ-2036
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2032		БПЗ-2037
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 11.37$ $Q \text{ кг.} = 3.08$ $D \text{ оп.мм.} = 162$ $P \text{ н.} = 505.7$ $P_{\text{вн.}} = 500.4$ Гр. сл. = особая Точн. = П
	БПЗ-2033		БПЗ-2038
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 9.16$ $Q \text{ кг.} = 2.48$ $D \text{ оп.мм.} = 128$ $P \text{ н.} = 651.8$ $P_{\text{вн.}} = 115.5$ Гр. сл. = особая Точн. = П
	БПЗ-2034		БПЗ-2039
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 11.107$ $Q \text{ кг.} = 3.001$ $D \text{ оп.мм.} = 171$ $P \text{ н.} = 425.9$ $P_{\text{вн.}} = 300.9$ Гр. сл. = особая Точн. = П
	БПЗ-2035		БПЗ-2040
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 1.968$ $Q \text{ кг.} = 0.533$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 180.2$ $P_{\text{вн.}} = 74.4$ Гр. сл. = VI Точн. = П













	<p><b>БПЗ-2041</b></p> <p> <math>F \text{ см}^2 = 3.297</math>  <math>Q \text{ кг.} = 0.894</math>  <math>D \text{ оп.мм.} = 48</math>  <math>P \text{ н.} = 180.2</math>  <math>P_{\text{вн.}} = 96.7</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2046</b></p> <p> <math>F \text{ см}^2 = 3.951</math>  <math>Q \text{ кг.} = 1.07</math>  <math>D \text{ оп.мм.} = 86</math>  <math>P \text{ н.} = 335.1</math>  <math>P_{\text{вн.}} = 38</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-2042</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2047</b></p> <p> <math>F \text{ см}^2 = 9.106</math>  <math>Q \text{ кг.} = 2.468</math>  <math>D \text{ оп.мм.} = 131</math>  <math>P \text{ н.} = 344.6</math>  <math>P_{\text{вн.}} = 196.8</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-2043</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2048</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2044</b></p> <p> <math>F \text{ см}^2 = 3.07</math>  <math>Q \text{ кг.} = 0.832</math>  <math>D \text{ оп.мм.} = 63</math>  <math>P \text{ н.} = 190.6</math>  <math>P_{\text{вн.}} = 63.8</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2049</b></p> <p> <math>F \text{ см}^2 = 1.984</math>  <math>Q \text{ кг.} = 0.538</math>  <math>D \text{ оп.мм.} = 40</math>  <math>P \text{ н.} = 124.6</math>  <math>P_{\text{вн.}} = 22</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-2045</b></p> <p> <math>F \text{ см}^2 = 3.963</math>  <math>Q \text{ кг.} = 1.074</math>  <math>D \text{ оп.мм.} = 55</math>  <math>P \text{ н.} = 242.9</math>  <math>P_{\text{вн.}} = 68</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2050</b></p> <p> <math>F \text{ см}^2 = 7.797</math>  <math>Q \text{ кг.} = 2.113</math>  <math>D \text{ оп.мм.} = 180</math>  <math>P \text{ н.} = 608.2</math>  <math>P_{\text{вн.}} = 488.1</math>  Гр. сл. = особая  Точн. = П </p>






	<p><b>БПЗ-2051</b></p> <p> <math>F \text{ см}^2 = 2.22</math>  <math>Q \text{ кг.} = 0.602</math>  <math>D \text{ оп.мм.} = 59</math>  <math>P \text{ н.} = 227</math>  <math>P_{\text{вн.}} = 69</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2056</b></p> <p> <math>F \text{ см}^2 = 2.437</math>  <math>Q \text{ кг.} = 0.66</math>  <math>D \text{ оп.мм.} = 60</math>  <math>P \text{ н.} = 197.1</math>  <math>P_{\text{вн.}} = 127.7</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-2052</b></p> <p> <math>F \text{ см}^2 = 8.88</math>  <math>Q \text{ кг.} = 2.406</math>  <math>D \text{ оп.мм.} = 89</math>  <math>P \text{ н.} = 363</math>  <math>P_{\text{вн.}} = 361</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-2057</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2053</b></p> <p> <math>F \text{ см}^2 = 7.42</math>  <math>Q \text{ кг.} = 2.011</math>  <math>D \text{ оп.мм.} = 88</math>  <math>P \text{ н.} = 360</math>  <math>P_{\text{вн.}} = 324</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-2058</b></p> <p> <math>F \text{ см}^2 = 0.79</math>  <math>Q \text{ кг.} = 0.214</math>  <math>D \text{ оп.мм.} = 27</math>  <math>P \text{ н.} = 83.3</math>  <math>P_{\text{вн.}} = 44.8</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-2054</b></p> <p> <math>F \text{ см}^2 = 2.606</math>  <math>Q \text{ кг.} = 0.706</math>  <math>D \text{ оп.мм.} = 59</math>  <math>P \text{ н.} = 279.2</math>  <math>P_{\text{вн.}} = 63.3</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2059</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2055</b></p> <p> <math>F \text{ см}^2 = 2.49</math>  <math>Q \text{ кг.} = 0.675</math>  <math>D \text{ оп.мм.} = 61</math>  <math>P \text{ н.} = 215</math>  <math>P_{\text{вн.}} = 111.6</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2060</b></p> <p> <math>F \text{ см}^2 = 4.992</math>  <math>Q \text{ кг.} = 1.353</math>  <math>D \text{ оп.мм.} = 58</math>  <math>P \text{ н.} = 228.9</math>  <math>P_{\text{вн.}} = 74.6</math>  Гр. сл. = V  Точн. = Н </p>








	БПЗ-2071		БПЗ-2076
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 1.55$ $Q \text{ кг.} = 0.42$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 92$ $P_{\text{вн.}} = 40.8$ Гр. сл. = VI Точн. = П
	БПЗ-2072		БПЗ-2077
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 1.616$ $Q \text{ кг.} = 0.438$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 97.5$ $P_{\text{вн.}} = 81.9$ Гр. сл. = III Точн. = П
	БПЗ-2073		БПЗ-2078
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 14.134$ $Q \text{ кг.} = 3.83$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 270.4$ $P_{\text{вн.}} = 236$ Гр. сл. = V Точн. = П
	БПЗ-2074		БПЗ-2079
	$F \text{ см}^2 = 9.605$ $Q \text{ кг.} = 2.603$ $D \text{ оп.мм.} = 158$ $P \text{ н.} = 613.7$ $P_{\text{вн.}} = 307.3$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 1.78$ $Q \text{ кг.} = 0.483$ $D \text{ оп.мм.} = 44.4$ $P \text{ н.} = 134.24$ $P_{\text{вн.}} = 99.14$ Гр. сл. = V Точн. = П
	БПЗ-2075		БПЗ-2080
	$F \text{ см}^2 = 7.301$ $Q \text{ кг.} = 1.978$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 373.6$ $P_{\text{вн.}} = 175.7$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 3.24$ $Q \text{ кг.} = 0.878$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 139.4$ $P_{\text{вн.}} = 119.1$ Гр. сл. = IV Точн. = П

	БПЗ-2061		БПЗ-2066
	$F \text{ см}^2 = 4.2$ $Q \text{ кг.} = 1.14$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 300.7$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2062		БПЗ-2067
	$F \text{ см}^2 = 10.53$ $Q \text{ кг.} = 2.854$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 380.7$ $P_{\text{вн.}} = 130.2$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2063		БПЗ-2068
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 9.087$ $Q \text{ кг.} = 2.463$ $D \text{ оп.мм.} = 132$ $P \text{ н.} = 317.9$ $P_{\text{вн.}} = 260.6$ Гр. сл. = особая Точн. = П
	БПЗ-2064		БПЗ-2069
	$F \text{ см}^2 = 1.352$ $Q \text{ кг.} = 0.366$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 63.3$ $P_{\text{вн.}} = 31.3$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2065		БПЗ-2070
	$F \text{ см}^2 = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм.} = 32.3$ $P \text{ н.} = 93.6$ $P_{\text{вн.}} = 32$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П











	БПЗ-2061		БПЗ-2066
	$F \text{ см}^2 = 4.2$ $Q \text{ кг.} = 1.14$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 300.7$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2062		БПЗ-2067
	$F \text{ см}^2 = 10.53$ $Q \text{ кг.} = 2.854$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 380.7$ $P_{\text{вн.}} = 130.2$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2063		БПЗ-2068
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 9.087$ $Q \text{ кг.} = 2.463$ $D \text{ оп.мм.} = 132$ $P \text{ н.} = 317.9$ $P_{\text{вн.}} = 260.6$ Гр. сл. = особая Точн. = П
	БПЗ-2064		БПЗ-2069
	$F \text{ см}^2 = 1.352$ $Q \text{ кг.} = 0.366$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 63.3$ $P_{\text{вн.}} = 31.3$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2065		БПЗ-2070
	$F \text{ см}^2 = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм.} = 32.3$ $P \text{ н.} = 93.6$ $P_{\text{вн.}} = 32$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П










	БПЗ-2061		БПЗ-2066
	$F \text{ см}^2 = 4.2$ $Q \text{ кг.} = 1.14$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 300.7$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2062		БПЗ-2067
	$F \text{ см}^2 = 10.53$ $Q \text{ кг.} = 2.854$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 380.7$ $P_{\text{вн.}} = 130.2$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2063		БПЗ-2068
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 9.087$ $Q \text{ кг.} = 2.463$ $D \text{ оп.мм.} = 132$ $P \text{ н.} = 317.9$ $P_{\text{вн.}} = 260.6$ Гр. сл. = особая Точн. = П
	БПЗ-2064		БПЗ-2069
	$F \text{ см}^2 = 1.352$ $Q \text{ кг.} = 0.366$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 63.3$ $P_{\text{вн.}} = 31.3$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2065		БПЗ-2070
	$F \text{ см}^2 = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм.} = 32.3$ $P \text{ н.} = 93.6$ $P_{\text{вн.}} = 32$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П








	БПЗ-2061		БПЗ-2066
	$F \text{ см}^2 = 4.2$ $Q \text{ кг.} = 1.14$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 300.7$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2062		БПЗ-2067
	$F \text{ см}^2 = 10.53$ $Q \text{ кг.} = 2.854$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 380.7$ $P_{\text{вн.}} = 130.2$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2063		БПЗ-2068
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 9.087$ $Q \text{ кг.} = 2.463$ $D \text{ оп.мм.} = 132$ $P \text{ н.} = 317.9$ $P_{\text{вн.}} = 260.6$ Гр. сл. = особая Точн. = П
	БПЗ-2064		БПЗ-2069
	$F \text{ см}^2 = 1.352$ $Q \text{ кг.} = 0.366$ $D \text{ оп.мм.} = 20$ $P \text{ н.} = 63.3$ $P_{\text{вн.}} = 31.3$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2065		БПЗ-2070
	$F \text{ см}^2 = 1.64$ $Q \text{ кг.} = 0.444$ $D \text{ оп.мм.} = 32.3$ $P \text{ н.} = 93.6$ $P_{\text{вн.}} = 32$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П










	<div>БПЗ-2071</div> <div><div><div><math>F \text{ см}^2 = 0</math></div><div><math>Q \text{ кг.} = 0</math></div><div><math>D \text{ оп.мм.} = 0</math></div><div><math>P \text{ н.} = 0</math></div><div><math>P_{\text{вн.}} = 0</math></div><div>Гр. сл. = особая</div><div>Точн. = П</div></div></div>	<div></div>	<div>БПЗ-2076</div> <div><div><div><math>F \text{ см}^2 = 1.55</math></div><div><math>Q \text{ кг.} = 0.42</math></div><div><math>D \text{ оп.мм.} = 30</math></div><div><math>P \text{ н.} = 92</math></div><div><math>P_{\text{вн.}} = 40.8</math></div><div>Гр. сл. = VI</div><div>Точн. = П</div></div></div>
	<div>БПЗ-2072</div> <div><div><div><math>F \text{ см}^2 = 0</math></div><div><math>Q \text{ кг.} = 0</math></div><div><math>D \text{ оп.мм.} = 0</math></div><div><math>P \text{ н.} = 0</math></div><div><math>P_{\text{вн.}} = 0</math></div><div>Гр. сл. = особая</div><div>Точн. = П</div></div></div>	<div></div>	<div>БПЗ-2077</div> <div><div><div><math>F \text{ см}^2 = 1.616</math></div><div><math>Q \text{ кг.} = 0.438</math></div><div><math>D \text{ оп.мм.} = 36</math></div><div><math>P \text{ н.} = 97.5</math></div><div><math>P_{\text{вн.}} = 81.9</math></div><div>Гр. сл. = III</div><div>Точн. = П</div></div></div>
	<div>БПЗ-2073</div> <div><div><div><math>F \text{ см}^2 = 0</math></div><div><math>Q \text{ кг.} = 0</math></div><div><math>D \text{ оп.мм.} = 0</math></div><div><math>P \text{ н.} = 0</math></div><div><math>P_{\text{вн.}} = 0</math></div><div>Гр. сл. = особая</div><div>Точн. = П</div></div></div>	<div></div>	<div>БПЗ-2078</div> <div><div><div><math>F \text{ см}^2 = 14.134</math></div><div><math>Q \text{ кг.} = 3.83</math></div><div><math>D \text{ оп.мм.} = 80</math></div><div><math>P \text{ н.} = 270.4</math></div><div><math>P_{\text{вн.}} = 236</math></div><div>Гр. сл. = V</div><div>Точн. = П</div></div></div>
<div></div>	<div>БПЗ-2074</div> <div><div><div><math>F \text{ см}^2 = 9.605</math></div><div><math>Q \text{ кг.} = 2.603</math></div><div><math>D \text{ оп.мм.} = 158</math></div><div><math>P \text{ н.} = 613.7</math></div><div><math>P_{\text{вн.}} = 307.3</math></div><div>Гр. сл. = особая</div><div>Точн. = П</div></div></div>	<div></div>	<div>БПЗ-2079</div> <div><div><div><math>F \text{ см}^2 = 1.78</math></div><div><math>Q \text{ кг.} = 0.483</math></div><div><math>D \text{ оп.мм.} = 44.4</math></div><div><math>P \text{ н.} = 134.24</math></div><div><math>P_{\text{вн.}} = 99.14</math></div><div>Гр. сл. = V</div><div>Точн. = П</div></div></div>
<div></div>	<div>БПЗ-2075</div> <div><div><div><math>F \text{ см}^2 = 7.301</math></div><div><math>Q \text{ кг.} = 1.978</math></div><div><math>D \text{ оп.мм.} = 87</math></div><div><math>P \text{ н.} = 373.6</math></div><div><math>P_{\text{вн.}} = 175.7</math></div><div>Гр. сл. = V</div><div>Точн. = П</div></div></div>	<div></div>	<div>БПЗ-2080</div> <div><div><div><math>F \text{ см}^2 = 3.24</math></div><div><math>Q \text{ кг.} = 0.878</math></div><div><math>D \text{ оп.мм.} = 50</math></div><div><math>P \text{ н.} = 139.4</math></div><div><math>P_{\text{вн.}} = 119.1</math></div><div>Гр. сл. = IV</div><div>Точн. = П</div></div></div>

















	<b>БПЗ-2081</b> $F \text{ см}^2 = 2.866$ $Q \text{ кг.} = 0.777$ $D \text{ оп.мм.} = 23$ $P \text{ н.} = 78.3$ $P_{\text{вн.}} = 26.7$ Гр. сл. = IV Точн. = П		<b>БПЗ-2086</b> $F \text{ см}^2 = 12.162$ $Q \text{ кг.} = 3.296$ $D \text{ оп.мм.} = 108$ $P \text{ н.} = 833.9$ $P_{\text{вн.}} = 179.3$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2082</b> $F \text{ см}^2 = 1.39$ $Q \text{ кг.} = 0.377$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 105$ $P_{\text{вн.}} = 77.5$ Гр. сл. = VI Точн. = П		<b>БПЗ-2087</b> $F \text{ см}^2 = 7.52$ $Q \text{ кг.} = 2.038$ $D \text{ оп.мм.} = 104$ $P \text{ н.} = 412.4$ $P_{\text{вн.}} = 314.7$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2083</b> $F \text{ см}^2 = 44.365$ $Q \text{ кг.} = 12.02$ $D \text{ оп.мм.} = 170$ $P \text{ н.} = 1543$ $P_{\text{вн.}} = 286.3$ Гр. сл. = особая Точн. = П		<b>БПЗ-2088</b> $F \text{ см}^2 = 2.661$ $Q \text{ кг.} = 0.721$ $D \text{ оп.мм.} = 83$ $P \text{ н.} = 287$ $P_{\text{вн.}} = 128.8$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2084</b> $F \text{ см}^2 = 4.09$ $Q \text{ кг.} = 1.108$ $D \text{ оп.мм.} = 51$ $P \text{ н.} = 120.6$ $P_{\text{вн.}} = 82$ Гр. сл. = VI Точн. = П		<b>БПЗ-2089</b> $F \text{ см}^2 = 2.767$ $Q \text{ кг.} = 0.75$ $D \text{ оп.мм.} = 78$ $P \text{ н.} = 318.6$ $P_{\text{вн.}} = 113.8$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2085</b> $F \text{ см}^2 = 0.864$ $Q \text{ кг.} = 0.234$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 72.3$ $P_{\text{вн.}} = 60.7$ Гр. сл. = V Точн. = П		<b>БПЗ-2090</b> $F \text{ см}^2 = 1.149$ $Q \text{ кг.} = 0.311$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 97.5$ $P_{\text{вн.}} = 86.4$ Гр. сл. = IV Точн. = П






	<b>БПЗ-2091</b> $F \text{ см}^2 = 1.508$ $Q \text{ кг.} = 0.409$ $D \text{ оп.мм.} = 38$ $P \text{ н.} = 179.2$ $P_{\text{вн.}} = 0$ Гр. сл. = VI Точн. = П		<b>БПЗ-2096</b> $F \text{ см}^2 = 6.384$ $Q \text{ кг.} = 1.73$ $D \text{ оп.мм.} = 71$ $P \text{ н.} = 312.7$ $P_{\text{вн.}} = 129.4$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2092</b> $F \text{ см}^2 = 12.06$ $Q \text{ кг.} = 3.269$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 219.9$ $P_{\text{вн.}} = 182.2$ Гр. сл. = IV Точн. = Н		<b>БПЗ-2097</b> $F \text{ см}^2 = 5.368$ $Q \text{ кг.} = 1.455$ $D \text{ оп.мм.} = 136$ $P \text{ н.} = 437.9$ $P_{\text{вн.}} = 288.3$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2093</b> $F \text{ см}^2 = 2.929$ $Q \text{ кг.} = 0.794$ $D \text{ оп.мм.} = 53$ $P \text{ н.} = 275.5$ $P_{\text{вн.}} = 0$ Гр. сл. = VI Точн. = П		<b>БПЗ-2098</b> $F \text{ см}^2 = 2.553$ $Q \text{ кг.} = 0.692$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 257.3$ $P_{\text{вн.}} = 124.8$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2094</b> $F \text{ см}^2 = 14.99$ $Q \text{ кг.} = 4.064$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 273.2$ $P_{\text{вн.}} = 50.3$ Гр. сл. = VI Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2095</b> $F \text{ см}^2 = 11.31$ $Q \text{ кг.} = 3.07$ $D \text{ оп.мм.} = 103$ $P \text{ н.} = 272.5$ $P_{\text{вн.}} = 25.1$ Гр. сл. = IV Точн. = П		<b>БПЗ-2100</b> $F \text{ см}^2 = 2.926$ $Q \text{ кг.} = 0.793$ $D \text{ оп.мм.} = 73$ $P \text{ н.} = 318.5$ $P_{\text{вн.}} = 122.4$ Гр. сл. = VI Точн. = П







	<p><b>БПЗ-2101</b></p> <p> <math>F \text{ см}^2 = 4.132</math>  <math>Q \text{ кг.} = 1.12</math>  <math>D \text{ оп.мм.} = 97</math>  <math>P \text{ н.} = 383.8</math>  <math>P_{\text{вн.}} = 177.7</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = 0  Точн. = П </p>
	<p><b>БПЗ-2102</b></p> <p> <math>F \text{ см}^2 = 1.954</math>  <math>Q \text{ кг.} = 0.53</math>  <math>D \text{ оп.мм.} = 41</math>  <math>P \text{ н.} = 108.3</math>  <math>P_{\text{вн.}} = 86</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = 0  Точн. = П </p>
	<p><b>БПЗ-2103</b></p> <p> <math>F \text{ см}^2 = 10.42</math>  <math>Q \text{ кг.} = 2.82</math>  <math>D \text{ оп.мм.} = 183</math>  <math>P \text{ н.} = 595.7</math>  <math>P_{\text{вн.}} = 389</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-2108</b></p> <p> <math>F \text{ см}^2 = 5.11</math>  <math>Q \text{ кг.} = 1.385</math>  <math>D \text{ оп.мм.} = 52</math>  <math>P \text{ н.} = 186.1</math>  <math>P_{\text{вн.}} = 119.2</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2104</b></p> <p> <math>F \text{ см}^2 = 2.964</math>  <math>Q \text{ кг.} = 0.803</math>  <math>D \text{ оп.мм.} = 55</math>  <math>P \text{ н.} = 166.5</math>  <math>P_{\text{вн.}} = 131</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = 0  Точн. = П </p>
	<p><b>БПЗ-2105</b></p> <p> <math>F \text{ см}^2 = 1.434</math>  <math>Q \text{ кг.} = 0.389</math>  <math>D \text{ оп.мм.} = 26</math>  <math>P \text{ н.} = 135.4</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = IV  Точн. = П </p>		<p><b>БПЗ-2110</b></p> <p> <math>F \text{ см}^2 = 5.12</math>  <math>Q \text{ кг.} = 1.388</math>  <math>D \text{ оп.мм.} = 60</math>  <math>P \text{ н.} = 344.8</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = VI  Точн. = П </p>

	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2116</b> $F \text{ см}^2 = 2.746$ $Q \text{ кг.} = 0.744$ $D \text{ оп.мм.} = 48.5$ $P \text{ н.} = 206.8$ $P_{\text{вн.}} = 34.6$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2112</b> $F \text{ см}^2 = 2.603$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм.} = 45$ $P \text{ н.} = 169.6$ $P_{\text{вн.}} = 97.8$ Гр. сл. = V Точн. = П		<b>БПЗ-2117</b> $F \text{ см}^2 = 8.78$ $Q \text{ кг.} = 2.38$ $D \text{ оп.мм.} = 161$ $P \text{ н.} = 491$ $P_{\text{вн.}} = 316$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2113</b> $F \text{ см}^2 = 3.041$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 223.6$ $P_{\text{вн.}} = 238$ Гр. сл. = VI Точн. = П		<b>БПЗ-2118</b> $F \text{ см}^2 = 7.552$ $Q \text{ кг.} = 2.05$ $D \text{ оп.мм.} = 161$ $P \text{ н.} = 617.5$ $P_{\text{вн.}} = 69.6$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2114</b> $F \text{ см}^2 = 3.58$ $Q \text{ кг.} = 0.97$ $D \text{ оп.мм.} = 66$ $P \text{ н.} = 226$ $P_{\text{вн.}} = 128$ Гр. сл. = VI Точн. = П		<b>БПЗ-2119</b> $F \text{ см}^2 = 4.6$ $Q \text{ кг.} = 1.247$ $D \text{ оп.мм.} = 68$ $P \text{ н.} = 214$ $P_{\text{вн.}} = 94$ Гр. сл. = V Точн. = П
	<b>БПЗ-2115</b> $F \text{ см}^2 = 1.992$ $Q \text{ кг.} = 0.539$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 138$ $P_{\text{вн.}} = 34.8$ Гр. сл. = IV Точн. = П		<b>БПЗ-2120</b> $F \text{ см}^2 = 3.604$ $Q \text{ кг.} = 0.977$ $D \text{ оп.мм.} = 79.5$ $P \text{ н.} = 357.8$ $P_{\text{вн.}} = 120$ Гр. сл. = VI Точн. = П





	<b>БПЗ-2121</b> $F \text{ см}^2 = 1.72$ $Q \text{ кг.} = 0.466$ $D \text{ оп.мм.} = 42.8$ $P \text{ н.} = 143.4$ $P_{вн.} = 116$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2126</b> $F \text{ см}^2 = 1.319$ $Q \text{ кг.} = 0.357$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 166.7$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-2122</b> $F \text{ см}^2 = 2.82$ $Q \text{ кг.} = 0.765$ $D \text{ оп.мм.} = 77.1$ $P \text{ н.} = 386.9$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2127</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-2123</b> $F \text{ см}^2 = 1.76$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм.} = 38.9$ $P \text{ н.} = 145.6$ $P_{вн.} = 81.5$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2128</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-2124</b> $F \text{ см}^2 = 1.79$ $Q \text{ кг.} = 0.485$ $D \text{ оп.мм.} = 43.3$ $P \text{ н.} = 148.7$ $P_{вн.} = 100.1$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2129</b> $F \text{ см}^2 = 9.06$ $Q \text{ кг.} = 2.455$ $D \text{ оп.мм.} = 190$ $P \text{ н.} = 437.4$ $P_{вн.} = 369.4$ $\Gamma \text{ р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-2125</b> $F \text{ см}^2 = 2.195$ $Q \text{ кг.} = 0.595$ $D \text{ оп.мм.} = 65.4$ $P \text{ н.} = 293.5$ $P_{вн.} = 0$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2130</b> $F \text{ см}^2 = 1.213$ $Q \text{ кг.} = 0.329$ $D \text{ оп.мм.} = 35$ $P \text{ н.} = 100.1$ $P_{вн.} = 88.7$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$








	БПЗ-2131		БПЗ-2136
	<p> <math>F \text{ см}^2 = 1.33</math>  <math>Q \text{ кг.} = 0.36</math>  <math>D \text{ оп.мм.} = 33</math>  <math>P \text{ н.} = 84</math>  <math>P_{\text{вн.}} = 36</math>  <math>\text{Гр. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 11.349</math>  <math>Q \text{ кг.} = 3.08</math>  <math>D \text{ оп.мм.} = 84</math>  <math>P \text{ н.} = 296.7</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = \text{IV}</math>  <math>\text{Точн.} = \text{Н}</math> </p>
	БПЗ-2132		БПЗ-2137
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = 0</math>  <math>\text{Точн.} = 0</math> </p>		<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = 0</math>  <math>\text{Точн.} = 0</math> </p>
	БПЗ-2133		БПЗ-2138
	<p> <math>F \text{ см}^2 = 0.84</math>  <math>Q \text{ кг.} = 0.228</math>  <math>D \text{ оп.мм.} = 32</math>  <math>P \text{ н.} = 122</math>  <math>P_{\text{вн.}} = 25.1</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>		<p> <math>F \text{ см}^2 = 1.19</math>  <math>Q \text{ кг.} = 0.322</math>  <math>D \text{ оп.мм.} = 33</math>  <math>P \text{ н.} = 121.3</math>  <math>P_{\text{вн.}} = 42.8</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	БПЗ-2134		БПЗ-2139
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = 0</math>  <math>\text{Точн.} = 0</math> </p>		<p> <math>F \text{ см}^2 = 1.248</math>  <math>Q \text{ кг.} = 0.338</math>  <math>D \text{ оп.мм.} = 33</math>  <math>P \text{ н.} = 125.9</math>  <math>P_{\text{вн.}} = 34.6</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>
	БПЗ-2135		БПЗ-2140
	<p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  <math>\text{Гр. сл.} = 0</math>  <math>\text{Точн.} = 0</math> </p>		<p> <math>F \text{ см}^2 = 0.992</math>  <math>Q \text{ кг.} = 0.269</math>  <math>D \text{ оп.мм.} = 32</math>  <math>P \text{ н.} = 122</math>  <math>P_{\text{вн.}} = 46.3</math>  <math>\text{Гр. сл.} = \text{особая}</math>  <math>\text{Точн.} = \text{П}</math> </p>





	БПЗ-2141		БПЗ-2146
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 2.513$ $Q \text{ кг.} = 0.681$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 114.4$ $P_{\text{вн.}} = 25.1$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$
	БПЗ-2142		БПЗ-2147
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 6.225$ $Q \text{ кг.} = 1.687$ $D \text{ оп.мм.} = 124$ $P \text{ н.} = 298.3$ $P_{\text{вн.}} = 306.5$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$
	БПЗ-2143		БПЗ-2148
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2144		БПЗ-2149
	$F \text{ см}^2 = 7.6$ $Q \text{ кг.} = 2.06$ $D \text{ оп.мм.} = 157$ $P \text{ н.} = 680$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 7.75$ $Q \text{ кг.} = 2.1$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 200$ $P_{\text{вн.}} = 158.5$ $\text{Гр. сл.} = V$ $\text{Точн.} = П$
	БПЗ-2145		БПЗ-2150
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\text{Гр. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 12.07$ $Q \text{ кг.} = 3.271$ $D \text{ оп.мм.} = 150$ $P \text{ н.} = 337.7$ $P_{\text{вн.}} = 350.9$ $\text{Гр. сл.} = IV$ $\text{Точн.} = П$






	<p><b>БПЗ-2151</b></p> <p> <math>F \text{ см}^2 = 2.93</math>  <math>Q \text{ кг.} = 0.794</math>  <math>D \text{ оп.мм.} = 33</math>  <math>P \text{ н.} = 88.6</math>  <math>P_{\text{вн.}} = 72.3</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-2156</b></p> <p> <math>F \text{ см}^2 = 7.78</math>  <math>Q \text{ кг.} = 2.108</math>  <math>D \text{ оп.мм.} = 93</math>  <math>P \text{ н.} = 669.3</math>  <math>P_{\text{вн.}} = 94</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-2152</b></p> <p> <math>F \text{ см}^2 = 13.11</math>  <math>Q \text{ кг.} = 3.55</math>  <math>D \text{ оп.мм.} = 73</math>  <math>P \text{ н.} = 220.8</math>  <math>P_{\text{вн.}} = 178</math>  Гр. сл. = особая  Точн. = Н </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2153</b></p> <p> <math>F \text{ см}^2 = 7.823</math>  <math>Q \text{ кг.} = 2.12</math>  <math>D \text{ оп.мм.} = 64</math>  <math>P \text{ н.} = 179.2</math>  <math>P_{\text{вн.}} = 132.3</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2154</b></p> <p> <math>F \text{ см}^2 = 16.875</math>  <math>Q \text{ кг.} = 4.573</math>  <math>D \text{ оп.мм.} = 79</math>  <math>P \text{ н.} = 261.7</math>  <math>P_{\text{вн.}} = 232.5</math>  Гр. сл. = особая  Точн. = Н </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2155</b></p> <p> <math>F \text{ см}^2 = 8.851</math>  <math>Q \text{ кг.} = 2.399</math>  <math>D \text{ оп.мм.} = 72</math>  <math>P \text{ н.} = 198.9</math>  <math>P_{\text{вн.}} = 32</math>  Гр. сл. = V  Точн. = Н </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>















	БПЗ-0		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-2162		БПЗ-2167
	$F \text{ см}^2 = 11.662$ $Q \text{ кг.} = 3.16$ $D \text{ оп.мм.} = 132$ $P \text{ н.} = 720.9$ $P_{\text{вн.}} = 497$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 2.92$ $Q \text{ кг.} = 0.792$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 283.2$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-0
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-2169
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 2.673$ $Q \text{ кг.} = 0.724$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 166$ $P_{\text{вн.}} = 167.6$ Гр. сл. = особая Точн. = П
	БПЗ-0		БПЗ-2170
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		$F \text{ см}^2 = 11.84$ $Q \text{ кг.} = 3.21$ $D \text{ оп.мм.} = 100$ $P \text{ н.} = 411.2$ $P_{\text{вн.}} = 187.7$ Гр. сл. = особая Точн. = П



	<p><b>БПЗ-2171</b></p> <p> <math>F \text{ см}^2 = 6.382</math>  <math>Q \text{ кг.} = 1.73</math>  <math>D \text{ оп.мм.} = 114</math>  <math>P \text{ н.} = 285.2</math>  <math>P_{вн.} = 173.9</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2176</b></p> <p> <math>F \text{ см}^2 = 8.305</math>  <math>Q \text{ кг.} = 2.251</math>  <math>D \text{ оп.мм.} = 78</math>  <math>P \text{ н.} = 227.5</math>  <math>P_{вн.} = 296.9</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{вн.} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2177</b></p> <p> <math>F \text{ см}^2 = 38.2</math>  <math>Q \text{ кг.} = 10.352</math>  <math>D \text{ оп.мм.} = 116</math>  <math>P \text{ н.} = 328.8</math>  <math>P_{вн.} = 224.8</math>  Гр. сл. = IV  Точн. = П </p>
	<p><b>БПЗ-2173</b></p> <p> <math>F \text{ см}^2 = 1.781</math>  <math>Q \text{ кг.} = 0.483</math>  <math>D \text{ оп.мм.} = 38</math>  <math>P \text{ н.} = 185.3</math>  <math>P_{вн.} = 0</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2178</b></p> <p> <math>F \text{ см}^2 = 1.064</math>  <math>Q \text{ кг.} = 0.288</math>  <math>D \text{ оп.мм.} = 30</math>  <math>P \text{ н.} = 115.8</math>  <math>P_{вн.} = 52.4</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-2174</b></p> <p> <math>F \text{ см}^2 = 1.935</math>  <math>Q \text{ кг.} = 0.525</math>  <math>D \text{ оп.мм.} = 131</math>  <math>P \text{ н.} = 292.1</math>  <math>P_{вн.} = 89.85</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2179</b></p> <p> <math>F \text{ см}^2 = 1.665</math>  <math>Q \text{ кг.} = 0.451</math>  <math>D \text{ оп.мм.} = 39</math>  <math>P \text{ н.} = 147</math>  <math>P_{вн.} = 75</math>  Гр. сл. = V  Точн. = П </p>
	<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{вн.} = 0</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-0</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{вн.} = 0</math>  Гр. сл. = особая  Точн. = П </p>






	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2186</b> $F \text{ см}^2 = 1.506$ $Q \text{ кг.} = 0.408$ $D \text{ оп.мм.} = 39.9$ $P \text{ н.} = 105.1$ $P_{\text{вн.}} = 95.7$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2183</b> $F \text{ см}^2 = 3.357$ $Q \text{ кг.} = 0.91$ $D \text{ оп.мм.} = 39$ $P \text{ н.} = 96.8$ $P_{\text{вн.}} = 50.3$ Гр. сл. = особая Точн. = Н		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2184</b> $F \text{ см}^2 = 5.418$ $Q \text{ кг.} = 1.468$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 193.4$ $P_{\text{вн.}} = 37$ Гр. сл. = VI Точн. = Н		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2185</b> $F \text{ см}^2 = 1.33$ $Q \text{ кг.} = 0.36$ $D \text{ оп.мм.} = 33.3$ $P \text{ н.} = 93.8$ $P_{\text{вн.}} = 84.4$ Гр. сл. = VI Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ Гр. сл. = особая Точн. = П

	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2192</b> $F \text{ см}^2 = 5.534$ $Q \text{ кг.} = 1.5$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 485.8$ $P_{вн.} = 163.4$ Гр. сл. = особая Точн. = П		<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П
	<b>БПЗ-2193</b> $F \text{ см}^2 = 2.044$ $Q \text{ кг.} = 0.554$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 192.8$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2198</b> $F \text{ см}^2 = 7.146$ $Q \text{ кг.} = 1.937$ $D \text{ оп.мм.} = 160$ $P \text{ н.} = 394.2$ $P_{вн.} = 311.7$ Гр. сл. = особая Точн. = Н
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2199</b> $F \text{ см}^2 = 5.92$ $Q \text{ кг.} = 1.6$ $D \text{ оп.мм.} = 85$ $P \text{ н.} = 517.5$ $P_{вн.} = 275.2$ Гр. сл. = VI Точн. = П
	<b>БПЗ-0</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = особая Точн. = П		<b>БПЗ-2200</b> $F \text{ см}^2 = 5.84$ $Q \text{ кг.} = 1.58$ $D \text{ оп.мм.} = 124$ $P \text{ н.} = 300$ $P_{вн.} = 284$ Гр. сл. = особая Точн. = Н






	<p><b>БПЗ-2201</b></p> <p> <math>F \text{ см}^2 = 2.416</math>  <math>Q \text{ кг.} = 0.655</math>  <math>D \text{ оп.мм.} = 68</math>  <math>P \text{ н.} = 279.3</math>  <math>P_{\text{вн.}} = 65.7</math>  Гр. сл. = VI  Точн. = П </p>		<p><b>БПЗ-2206</b></p> <p> <math>F \text{ см}^2 = 19.15</math>  <math>Q \text{ кг.} = 5.19</math>  <math>D \text{ оп.мм.} = 149</math>  <math>P \text{ н.} = 413.4</math>  <math>P_{\text{вн.}} = 393.2</math>  Гр. сл. = особая  Точн. = V </p>
	<p><b>БПЗ-2202</b></p> <p> <math>F \text{ см}^2 = 2.529</math>  <math>Q \text{ кг.} = 0.685</math>  <math>D \text{ оп.мм.} = 70</math>  <math>P \text{ н.} = 265.9</math>  <math>P_{\text{вн.}} = 176.6</math>  Гр. сл. = особая  Точн. = П </p>		<p><b>БПЗ-2207</b></p> <p> <math>F \text{ см}^2 = 4.344</math>  <math>Q \text{ кг.} = 1.177</math>  <math>D \text{ оп.мм.} = 67</math>  <math>P \text{ н.} = 343</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2203</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = 0 </p>		<p><b>БПЗ-2208</b></p> <p> <math>F \text{ см}^2 = 7.795</math>  <math>Q \text{ кг.} = 2.112</math>  <math>D \text{ оп.мм.} = 100</math>  <math>P \text{ н.} = 234.2</math>  <math>P_{\text{вн.}} = 291.8</math>  Гр. сл. = особая  Точн. = П </p>
	<p><b>БПЗ-2204</b></p> <p> <math>F \text{ см}^2 = 0.903</math>  <math>Q \text{ кг.} = 0.245</math>  <math>D \text{ оп.мм.} = 14</math>  <math>P \text{ н.} = 44</math>  <math>P_{\text{вн.}} = 28.3</math>  Гр. сл. = V  Точн. = П </p>		<p><b>БПЗ-2209</b></p> <p> <math>F \text{ см}^2 = 2.242</math>  <math>Q \text{ кг.} = 0.608</math>  <math>D \text{ оп.мм.} = 62</math>  <math>P \text{ н.} = 145</math>  <math>P_{\text{вн.}} = 151</math>  Гр. сл. = VI  Точн. = П </p>
	<p><b>БПЗ-2205</b></p> <p> <math>F \text{ см}^2 = 0</math>  <math>Q \text{ кг.} = 0</math>  <math>D \text{ оп.мм.} = 0</math>  <math>P \text{ н.} = 0</math>  <math>P_{\text{вн.}} = 0</math>  Гр. сл. = особая  Точн. = 0 </p>		<p><b>БПЗ-2210</b></p> <p> <math>F \text{ см}^2 = 2.47</math>  <math>Q \text{ кг.} = 0.67</math>  <math>D \text{ оп.мм.} = 66</math>  <math>P \text{ н.} = 147.3</math>  <math>P_{\text{вн.}} = 175</math>  Гр. сл. = VI  Точн. = П </p>




	БПЗ-2211		БПЗ-2216
	$F \text{ см}^2 = 3.21$ $Q \text{ кг.} = 0.87$ $D \text{ оп.мм.} = 90$ $P \text{ н.} = 219.1$ $P_{\text{вн.}} = 130.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2212		БПЗ-2217
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2213		БПЗ-2218
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2214		БПЗ-2219
	$F \text{ см}^2 = 1.353$ $Q \text{ кг.} = 0.367$ $D \text{ оп.мм.} = 33$ $P \text{ н.} = 130.8$ $P_{\text{вн.}} = 63.7$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2215		БПЗ-2220
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$






	БПЗ-2221		БПЗ-2226
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2222		БПЗ-2227
	$F \text{ см}^2 = 3.13$ $Q \text{ кг.} = 0.848$ $D \text{ оп.мм.} = 57$ $P \text{ н.} = 184.8$ $P_{\text{вн.}} = 121$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2223		БПЗ-2228
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2224		БПЗ-2229
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2225		БПЗ-2230
	$F \text{ см}^2 = 2.397$ $Q \text{ кг.} = 0.65$ $D \text{ оп.мм.} = 62$ $P \text{ н.} = 163.1$ $P_{\text{вн.}} = 128$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$







	БПЗ-2231		БПЗ-2236
	$F \text{ см}^2 = 0.768$ $Q \text{ кг.} = 0.208$ $D \text{ оп.мм.} = 14$ $P \text{ н.} = 41.6$ $P_{\text{вн.}} = 15.7$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0.72$ $Q \text{ кг.} = 0.195$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 76.8$ $P_{\text{вн.}} = 52.8$ $\Gamma \text{ р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2232		БПЗ-2237
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0.649$ $Q \text{ кг.} = 0.176$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 81.5$ $P_{\text{вн.}} = 44.8$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПЗ-2233		БПЗ-2238
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 4.241$ $Q \text{ кг.} = 1.149$ $D \text{ оп.мм.} = 78$ $P \text{ н.} = 237.5$ $P_{\text{вн.}} = 99$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПЗ-2234		БПЗ-2239
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2235		БПЗ-2240
	$F \text{ см}^2 = 1.04$ $Q \text{ кг.} = 0.282$ $D \text{ оп.мм.} = 30$ $P \text{ н.} = 94.7$ $P_{\text{вн.}} = 76.7$ $\Gamma \text{ р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{ р. сл.} = 0$ $\text{Точн.} = 0$












	БПЗ-2241		БПЗ-2246
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 2.208$ $Q \text{ кг.} = 0.598$ $D \text{ оп.мм.} = 36$ $P \text{ н.} = 200.4$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$
	БПЗ-2242		БПЗ-2247
	$F \text{ см}^2 = 5.112$ $Q \text{ кг.} = 1.385$ $D \text{ оп.мм.} = 114$ $P \text{ н.} = 327.8$ $P_{\text{вн.}} = 276.7$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 2.869$ $Q \text{ кг.} = 0.774$ $D \text{ оп.мм.} = 73$ $P \text{ н.} = 305.2$ $P_{\text{вн.}} = 89.9$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$
	БПЗ-2243		БПЗ-2248
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2244		БПЗ-2249
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 2.81$ $Q \text{ кг.} = 0.762$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 227.3$ $P_{\text{вн.}} = 83.9$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2245		БПЗ-2250
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 5.364$ $Q \text{ кг.} = 1.454$ $D \text{ оп.мм.} = 87$ $P \text{ н.} = 367.3$ $P_{\text{вн.}} = 158.5$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$








	БПЗ-2251		БПЗ-2256
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 3.04$ $Q \text{ кг.} = 0.824$ $D \text{ оп.мм.} = 60$ $P \text{ н.} = 173.8$ $P_{\text{вн.}} = 167.5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	БПЗ-2252		БПЗ-2257
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2253		БПЗ-2258
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0.813$ $Q \text{ кг.} = 0.22$ $D \text{ оп.мм.} = 16$ $P \text{ н.} = 50.3$ $P_{\text{вн.}} = 172.6$ $\Gamma \text{р. сл.} = \text{Особая}$ $\text{Точн.} = П$
	БПЗ-2254		БПЗ-2259
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2255		БПЗ-2260
	$F \text{ см}^2 = 5.204$ $Q \text{ кг.} = 1.41$ $D \text{ оп.мм.} = 47$ $P \text{ н.} = 156.1$ $P_{\text{вн.}} = 67.2$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$




	<b>БПЗ-2261</b> $F \text{ см}^2 = 3.94$ $Q \text{ кг.} = 1.07$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 182.1$ $P_{вн.} = 168.1$ Гр. сл. = IV Точн. = П		<b>БПЗ-2266</b> $F \text{ см}^2 = 1.304$ $Q \text{ кг.} = 0.353$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 176.9$ $P_{вн.} = 0$ Гр. сл. = VI Точн. = Н
	<b>БПЗ-2262</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0		<b>БПЗ-2267</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2263</b> $F \text{ см}^2 = 14.71$ $Q \text{ кг.} = 3.99$ $D \text{ оп.мм.} = 102$ $P \text{ н.} = 392.8$ $P_{вн.} = 213.2$ Гр. сл. = V Точн. = П		<b>БПЗ-2268</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2264</b> $F \text{ см}^2 = 13.123$ $Q \text{ кг.} = 3.56$ $D \text{ оп.мм.} = 89$ $P \text{ н.} = 352.8$ $P_{вн.} = 174.8$ Гр. сл. = V Точн. = П		<b>БПЗ-2269</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2265</b> $F \text{ см}^2 = 8.05$ $Q \text{ кг.} = 2.182$ $D \text{ оп.мм.} = 105$ $P \text{ н.} = 329.9$ $P_{вн.} = 314.2$ Гр. сл. = IV Точн. = П		<b>БПЗ-2270</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0

	<b>БПЗ-2271</b> $F \text{ см}^2 = 32.31$ $Q \text{ кг.} = 8.756$ $D \text{ оп.мм.} = 192$ $P \text{ н.} = 594.5$ $P_{вн.} = 513.3$ Гр. сл. = 0 Точн. = Н		<b>БПЗ-2276</b> $F \text{ см}^2 = 6.281$ $Q \text{ кг.} = 1.7$ $D \text{ оп.мм.} = 52$ $P \text{ н.} = 163.3$ $P_{вн.} = 71.3$ Гр. сл. = V Точн. = Н
	<b>БПЗ-2272</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0		<b>БПЗ-2277</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2273</b> $F \text{ см}^2 = 2.296$ $Q \text{ кг.} = 0.622$ $D \text{ оп.мм.} = 54$ $P \text{ н.} = 184$ $P_{вн.} = 167$ Гр. сл. = VI Точн. = П		<b>БПЗ-2278</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2274</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0		<b>БПЗ-2279</b> $F \text{ см}^2 = 12.955$ $Q \text{ кг.} = 3.511$ $D \text{ оп.мм.} = 80$ $P \text{ н.} = 392.3$ $P_{вн.} = 52$ Гр. сл. = V Точн. = П
	<b>БПЗ-2275</b> $F \text{ см}^2 = 24.44$ $Q \text{ кг.} = 6.63$ $D \text{ оп.мм.} = 133$ $P \text{ н.} = 491.2$ $P_{вн.} = 301.8$ Гр. сл. = V Точн. = П		<b>БПЗ-2280</b> $F \text{ см}^2 = 10.76$ $Q \text{ кг.} = 2.92$ $D \text{ оп.мм.} = 55$ $P \text{ н.} = 169.1$ $P_{вн.} = 131.3$ Гр. сл. = VI Точн. = П





	БПЗ-2281		БПЗ-2286
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2282		БПЗ-2287
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2283		БПЗ-2288
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2284		БПЗ-2289
	$F \text{ см}^2 = 1.468$ $Q \text{ кг.} = 0.398$ $D \text{ оп.мм.} = 37$ $P \text{ н.} = 198.6$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 5.445$ $Q \text{ кг.} = 1.476$ $D \text{ оп.мм.} = 82$ $P \text{ н.} = 225.7$ $P_{\text{вн.}} = 209.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = 0$
	БПЗ-2285		БПЗ-2290
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 3.365$ $Q \text{ кг.} = 0.912$ $D \text{ оп.мм.} = 78$ $P \text{ н.} = 174.5$ $P_{\text{вн.}} = 161.9$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = 0$


	<b>БПЗ-2291</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		<b>БПЗ-2296</b> $F \text{ см}^2 = 0.825$ $Q \text{ кг.} = 0.224$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 86.01$ $P_{\text{вн.}} = 25.13$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-2292</b> $F \text{ см}^2 = 1.577$ $Q \text{ кг.} = 0.427$ $D \text{ оп.мм.} = 24$ $P \text{ н.} = 83.97$ $P_{\text{вн.}} = 41.6$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2297</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	<b>БПЗ-2293</b> $F \text{ см}^2 = 12.482$ $Q \text{ кг.} = 3.383$ $D \text{ оп.мм.} = 120$ $P \text{ н.} = 443.4$ $P_{\text{вн.}} = 495.4$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2298</b> $F \text{ см}^2 = 5.668$ $Q \text{ кг.} = 1.536$ $D \text{ оп.мм.} = 100$ $P \text{ н.} = 441.9$ $P_{\text{вн.}} = 122.2$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	<b>БПЗ-2294</b> $F \text{ см}^2 = 8.846$ $Q \text{ кг.} = 2.397$ $D \text{ оп.мм.} = 154$ $P \text{ н.} = 385$ $P_{\text{вн.}} = 336$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2299</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	<b>БПЗ-2295</b> $F \text{ см}^2 = 9.973$ $Q \text{ кг.} = 2.7$ $D \text{ оп.мм.} = 114$ $P \text{ н.} = 394.4$ $P_{\text{вн.}} = 399.6$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		<b>БПЗ-2300</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$




	<b>БПЗ-2301</b> $F \text{ см}^2 = 5.473$ $Q \text{ кг.} = 1.483$ $D \text{ оп.мм.} = 118$ $P \text{ н.} = 360$ $P_{вн.} = 276.7$ Гр. сл. = П Точн. = особая		<b>БПЗ-2306</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2302</b> $F \text{ см}^2 = 2.55$ $Q \text{ кг.} = 0.691$ $D \text{ оп.мм.} = 61$ $P \text{ н.} = 237.1$ $P_{вн.} = 39.4$ Гр. сл. = V Точн. = П		<b>БПЗ-2307</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0
	<b>БПЗ-2303</b> $F \text{ см}^2 = 2.74$ $Q \text{ кг.} = 0.743$ $D \text{ оп.мм.} = 64$ $P \text{ н.} = 249.1$ $P_{вн.} = 52.5$ Гр. сл. = V Точн. = П		<b>БПЗ-2308</b> $F \text{ см}^2 = 1.278$ $Q \text{ кг.} = 0.346$ $D \text{ оп.мм.} = 40$ $P \text{ н.} = 122.6$ $P_{вн.} = 62$ Гр. сл. = VI Точн. = П
	<b>БПЗ-2304</b> $F \text{ см}^2 = 7.263$ $Q \text{ кг.} = 1.97$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 237.35$ $P_{вн.} = 0$ Гр. сл. = IV Точн. = Н		<b>БПЗ-2309</b> $F \text{ см}^2 = 11.838$ $Q \text{ кг.} = 3.208$ $D \text{ оп.мм.} = 175$ $P \text{ н.} = 476.1$ $P_{вн.} = 504.5$ Гр. сл. = VI Точн. = особая
	<b>БПЗ-2305</b> $F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{вн.} = 0$ Гр. сл. = 0 Точн. = 0		<b>БПЗ-2310</b> $F \text{ см}^2 = 3.063$ $Q \text{ кг.} = 0.83$ $D \text{ оп.мм.} = 28$ $P \text{ н.} = 160.9$ $P_{вн.} = 40.3$ Гр. сл. = IV Точн. = П




	БПЗ-2311		БПЗ-2316
	$F \text{ см}^2 = 5.592$ $Q \text{ кг.} = 1.515$ $D \text{ оп.мм.} = 95$ $P \text{ н.} = 460.3$ $P_{\text{вн.}} = 227.5$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2312		БПЗ-2317
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2313		БПЗ-2318
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 5,247$ $Q \text{ кг.} = 1,422$ $D \text{ оп.мм.} = 67$ $P \text{ н.} = 304,9$ $P_{\text{вн.}} = 207,8$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПЗ-2314		БПЗ-2319
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2315		БПЗ-2320
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 1.624$ $Q \text{ кг.} = 0.44$ $D \text{ оп.мм.} = 43$ $P \text{ н.} = 160.1$ $P_{\text{вн.}} = 56.2$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$












	БПЗ-2321		БПЗ-2326
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2322		БПЗ-2327
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 13.818$ $Q \text{ кг.} = 3.745$ $D \text{ оп.мм.} = 141$ $P \text{ н.} = 382.2$ $P_{\text{вн.}} = 647.8$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{П}$
	БПЗ-2323		БПЗ-2328
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 9.912$ $Q \text{ кг.} = 2.686$ $D \text{ оп.мм.} = 98$ $P \text{ н.} = 310.2$ $P_{\text{вн.}} = 336$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2324		БПЗ-2329
	$F \text{ см}^2 = 1.37$ $Q \text{ кг.} = 0.371$ $D \text{ оп.мм.} = 41$ $P \text{ н.} = 96$ $P_{\text{вн.}} = 88$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2325		БПЗ-2330
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 2.607$ $Q \text{ кг.} = 0.706$ $D \text{ оп.мм.} = 98$ $P \text{ н.} = 263$ $P_{\text{вн.}} = 189.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$








	БПЗ-2331		БПЗ-2336
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2332		БПЗ-2337
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2333		БПЗ-2338
	$F \text{ см}^2 = 2.541$ $Q \text{ кг.} = 0.689$ $D \text{ оп.мм.} = 58$ $P \text{ н.} = 185.4$ $P_{\text{вн.}} = 90.9$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2334		БПЗ-2339
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2335		БПЗ-2340
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$


	БПЗ-2341		БПЗ-2346
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2342		БПЗ-2347
	$F \text{ см}^2 = 6.509$ $Q \text{ кг.} = 1.764$ $D \text{ оп.мм.} = 116$ $P \text{ н.} = 347.8$ $P_{\text{вн.}} = 295.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2343		БПЗ-2348
	$F \text{ см}^2 = 5.709$ $Q \text{ кг.} = 1.547$ $D \text{ оп.мм.} = 96$ $P \text{ н.} = 307.8$ $P_{\text{вн.}} = 255.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2344		БПЗ-2349
	$F \text{ см}^2 = 26.12$ $Q \text{ кг.} = 7.08$ $D \text{ оп.мм.} = 65$ $P \text{ н.} = 204.2$ $P_{\text{вн.}} = 94.3$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2345		БПЗ-2350
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$

	БПЗ-2351		БПЗ-2356
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 1.6$ $Q \text{ кг.} = 0.44$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 120.8$ $P_{\text{вн.}} = 43.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2352		БПЗ-2357
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2353		БПЗ-2358
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2354		БПЗ-2359
	$F \text{ см}^2 = 2.66$ $Q \text{ кг.} = 0.73$ $D \text{ оп.мм.} = 50$ $P \text{ н.} = 189.9$ $P_{\text{вн.}} = 165.2$ $\Gamma \text{р. сл.} = \text{особая}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2355		БПЗ-2360
	$F \text{ см}^2 = 0.86$ $Q \text{ кг.} = 0.24$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 94.8$ $P_{\text{вн.}} = 48.4$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$

	БПЗ-2361		БПЗ-2366
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2362		БПЗ-2367
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2363		БПЗ-2368
	$F \text{ см}^2 = 2.317$ $Q \text{ кг.} = 0.628$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 803.8$ $P_{\text{вн.}} = 572.3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2364		БПЗ-2369
	$F \text{ см}^2 = 4.4$ $Q \text{ кг.} = 1.2$ $D \text{ оп.мм.} = 68$ $P \text{ н.} = 270.7$ $P_{\text{вн.}} = 291.6$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2365		БПЗ-2370
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$

	БПЗ-2371		БПЗ-2376
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 3.166$ $Q \text{ кг.} = 0.858$ $D \text{ оп.мм.} = 74$ $P \text{ н.} = 289.1$ $P_{\text{вн.}} = 179.8$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2372		БПЗ-2377
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 2.844$ $Q \text{ кг.} = 0.771$ $D \text{ оп.мм.} = 72$ $P \text{ н.} = 263.2$ $P_{\text{вн.}} = 159.7$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2373		БПЗ-2378
	$F \text{ см}^2 = 5.267$ $Q \text{ кг.} = 1.427$ $D \text{ оп.мм.} = 56$ $P \text{ н.} = 161.5$ $P_{\text{вн.}} = 58.6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.01$ $Q \text{ кг.} = 0.816$ $D \text{ оп.мм.} = 70$ $P \text{ н.} = 281.4$ $P_{\text{вн.}} = 149.9$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2374		БПЗ-2379
	$F \text{ см}^2 = 2.72$ $Q \text{ кг.} = 0.74$ $D \text{ оп.мм.} = 84$ $P \text{ н.} = 388$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 4.377$ $Q \text{ кг.} = 1.19$ $D \text{ оп.мм.} = 94$ $P \text{ н.} = 385.7$ $P_{\text{вн.}} = 255.3$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$
	БПЗ-2375		БПЗ-2380
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 3.77$ $Q \text{ кг.} = 1.022$ $D \text{ оп.мм.} = 76$ $P \text{ н.} = 266.9$ $P_{\text{вн.}} = 291.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{П}$

	БПЗ-2381		БПЗ-2386
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 5.91$ $Q \text{ кг.} = 1.61$ $D \text{ оп.мм.} = 91$ $P \text{ н.} = 345.8$ $P_{\text{вн.}} = 99$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \Pi$
	БПЗ-2382		БПЗ-2387
	$F \text{ см}^2 = 2.168$ $Q \text{ кг.} = 0.588$ $D \text{ оп.мм.} = 26$ $P \text{ н.} = 81.7$ $P_{\text{вн.}} = 62.8$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2383		БПЗ-2388
	$F \text{ см}^2 = 1.885$ $Q \text{ кг.} = 0.511$ $D \text{ оп.мм.} = 32$ $P \text{ н.} = 100.5$ $P_{\text{вн.}} = 88$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 1.66$ $Q \text{ кг.} = 0.46$ $D \text{ оп.мм.} = 42$ $P \text{ н.} = 171.9$ $P_{\text{вн.}} = 83.3$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = \Pi$
	БПЗ-2384		БПЗ-2389
	$F \text{ см}^2 = 3.03$ $Q \text{ кг.} = 0.82$ $D \text{ оп.мм.} = 57$ $P \text{ н.} = 302.4$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 8.47$ $Q \text{ кг.} = 2.295$ $D \text{ оп.мм.} = 113$ $P \text{ н.} = 321.5$ $P_{\text{вн.}} = 368.1$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = \Pi$
	БПЗ-2385		БПЗ-2390
	$F \text{ см}^2 = 8.59$ $Q \text{ кг.} = 2.33$ $D \text{ оп.мм.} = 90$ $P \text{ н.} = 273.6$ $P_{\text{вн.}} = 270.3$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$

	БПЗ-2391		БПЗ-2396
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2392		БПЗ-2397
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2393		БПЗ-2398
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2394		БПЗ-2399
	$F \text{ см}^2 = 1.119$ $Q \text{ кг.} = 0.303$ $D \text{ оп.мм.} = 25$ $P \text{ н.} = 97.2$ $P_{\text{вн.}} = 83.5$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \Pi$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$
	БПЗ-2395		БПЗ-2400
	$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$		$F \text{ см}^2 = 0$ $Q \text{ кг.} = 0$ $D \text{ оп.мм.} = 0$ $P \text{ н.} = 0$ $P_{\text{вн.}} = 0$ $\Gamma \text{р. сл.} = 0$ $\text{Точн.} = 0$