



















































	ЗН-1	(П39.022)	ЗН-6
	$F \text{ см}^2 = 0.542$ $Q \text{ кг} = 0.147$ $D \text{ оп.мм} = 13$ $P \text{ н.мм} = 40.84$ $P \text{ в.мм} = 31.42$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 2.092$ $Q \text{ кг} = 0.567$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 136.9$ $P \text{ в.мм} = 56.6$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$
(ЛА-240)	ЗН-2	(П39.029)	ЗН-7
	$F \text{ см}^2 = 2.24$ $Q \text{ кг} = 0.607$ $D \text{ оп.мм} = 44.4$ $P \text{ н.мм} = 119.2$ $P \text{ в.мм} = 104$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см}^2 = 1.71$ $Q \text{ кг} = 0.463$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 62.83$ $P \text{ в.мм} = 42.41$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = П$
(ЭЛ-01)	ЗН-3	(П39.034)	ЗН-8
	$F \text{ см}^2 = 1.72$ $Q \text{ кг} = 0.466$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119.4$ $P \text{ в.мм} = 110$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F \text{ см}^2 = 3.52$ $Q \text{ кг} = 0.954$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 100.5$ $P \text{ в.мм} = 75.4$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = Н$
(П39.019)	ЗН-4	(П39.044)	ЗН-9
	$F \text{ см}^2 = 4.3$ $Q \text{ кг} = 1.17$ $D \text{ оп.мм} = 65$ $P \text{ н.мм} = 182$ $P \text{ в.мм} = 162$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$		$F \text{ см}^2 = 0.82$ $Q \text{ кг} = 0.223$ $D \text{ оп.мм} = 15$ $P \text{ н.мм} = 47.12$ $P \text{ в.мм} = 34.56$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$
(П39.020)	ЗН-5	(П39.049)	ЗН-10
	$F \text{ см}^2 = 9.41$ $Q \text{ кг} = 2.55$ $D \text{ оп.мм} = 128.2$ $P \text{ н.мм} = 415$ $P \text{ в.мм} = 344$ $\Gamma \text{р. сл.} = VII$ $\text{Точн.} = Н$		$F \text{ см}^2 = 17.01$ $Q \text{ кг} = 4.54$ $D \text{ оп.мм} = 107$ $P \text{ н.мм} = 364.7$ $P \text{ в.мм} = 251.33$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$











(П39.055)	ЗН-11	(П39.068)	ЗН-16
	$F \text{ см}^2 = 26.1$ $Q \text{ кг} = 7.021$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 1754$ $P \text{ в.мм} = 157.1$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 5.56$ $Q \text{ кг} = 1.507$ $D \text{ оп.мм} = 62$ $P \text{ н.мм} = 194.8$ $P \text{ в.мм} = 175.9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$
(П39.056)	ЗН-12	(П39.005)	ЗН-17
	$F \text{ см}^2 = 32.65$ $Q \text{ кг} = 8.783$ $D \text{ оп.мм} = 96$ $P \text{ н.мм} = 1348$ $P \text{ в.мм} = 132$ $\Gamma \text{р. сл.} = \text{ОСОБ}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.57$ $Q \text{ кг} = 0.97$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 268.6$ $P \text{ в.мм} = 116$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$
(П39.060)	ЗН-13	(П39.006)	ЗН-18
	$F \text{ см}^2 = 1.41$ $Q \text{ кг} = 0.382$ $D \text{ оп.мм} = 18$ $P \text{ н.мм} = 56.55$ $P \text{ в.мм} = 37.7$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4.027$ $Q \text{ кг} = 1.092$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 263.2$ $P \text{ в.мм} = 140.1$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{Н}$
(П39.064)	ЗН-14	(П39.008)	ЗН-19
	$F \text{ см}^2 = 5.44$ $Q \text{ кг} = 1.47$ $D \text{ оп.мм} = 37$ $P \text{ н.мм} = 116.2$ $P \text{ в.мм} = 81.68$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 4.444$ $Q \text{ кг} = 1.204$ $D \text{ оп.мм} = 57.5$ $P \text{ н.мм} = 166.3$ $P \text{ в.мм} = 37.7$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$
(П39.067)	ЗН-15	(П39.009)	ЗН-20
	$F \text{ см}^2 = 1.29$ $Q \text{ кг} = 0.35$ $D \text{ оп.мм} = 20.5$ $P \text{ н.мм} = 64.4$ $P \text{ в.мм} = 50.27$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3.66$ $Q \text{ кг} = 0.992$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 113.89$ $P \text{ в.мм} = 22.93$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$











(П39.013)	ЗН-21	(П39.004)	ЗН-26
	$F \text{ см}^2 = 3,584$ $Q \text{ кг} = 0,971$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 263,6$ $P \text{ в.мм} = 116$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3,849$ $Q \text{ кг} = 1,043$ $D \text{ оп.мм} = 71$ $P \text{ н.мм} = 268,6$ $P \text{ в.мм} = 132$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
(П39.064-01)	ЗН-22	(П39.012)	ЗН-27
	$F \text{ см}^2 = 6,64$ $Q \text{ кг} = 1,799$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 122,5$ $P \text{ в.мм} = 81,68$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 3,54$ $Q \text{ кг} = 0,96$ $D \text{ оп.мм} = 66,6$ $P \text{ н.мм} = 255,6$ $P \text{ в.мм} = 116$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$
(П39.001)	ЗН-23		ЗН-28
	$F \text{ см}^2 = 3,079$ $Q \text{ кг} = 0,8344$ $D \text{ оп.мм} = 55,5$ $P \text{ н.мм} = 221,6$ $P \text{ в.мм} = 108$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 6,472$ $Q \text{ кг} = 1,754$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 122,5$ $P \text{ в.мм} = 82,9$ $\Gamma \text{р. сл.} = \text{I}$ $\text{Точн.} = \text{H}$
(П39.002)	ЗН-24		ЗН-29
	$F \text{ см}^2 = 3,354$ $Q \text{ кг} = 0,909$ $D \text{ оп.мм} = 55,5$ $P \text{ н.мм} = 221,6$ $P \text{ в.мм} = 124$ $\Gamma \text{р. сл.} = \text{VI}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3,02$ $Q \text{ кг} = 0,82$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 88$ $P \text{ в.мм} = 62,8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$
(П39.003)	ЗН-25		ЗН-30
	$F \text{ см}^2 = 6,347$ $Q \text{ кг} = 1,72$ $D \text{ оп.мм} = 121$ $P \text{ н.мм} = 379,3$ $P \text{ в.мм} = 256,1$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 1,382$ $Q \text{ кг} = 0,375$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75,4$ $P \text{ в.мм} = 62,8$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{H}$











	<p>ЗН-31</p>		<p>ЗН-36</p>
<p> $F \text{ см}^2 = 1.34$ $Q \text{ кг} = 0.375$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 94.3$ $P \text{ в.мм} = 84.8$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>		<p> $F \text{ см}^2 = 0.88$ $Q \text{ кг} = 0.239$ $D \text{ оп.мм} = 16$ $P \text{ н.мм} = 50.3$ $P \text{ в.мм} = 37.7$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$ </p>	
	<p>ЗН-32</p>		<p>ЗН-37</p>
<p> $F \text{ см}^2 = 2.388$ $Q \text{ кг} = 0.6472$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 125.7$ $P \text{ в.мм} = 113.1$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>		<p> $F \text{ см}^2 = 1.225$ $Q \text{ кг} = 0.332$ $D \text{ оп.мм} = 16$ $P \text{ н.мм} = 50.3$ $P \text{ в.мм} = 31.4$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$ </p>	
	<p>ЗН-33</p>		<p>ЗН-38</p>
<p> $F \text{ см}^2 = 3.64$ $Q \text{ кг} = 0.986$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 111.6$ $P \text{ в.мм} = 105.6$ $\Gamma \text{ р. сл.} = VII$ $\text{Точн.} = П$ </p>		<p> $F \text{ см}^2 = 0.495$ $Q \text{ кг} = 0.134$ $D \text{ оп.мм} = 12$ $P \text{ н.мм} = 37.7$ $P \text{ в.мм} = 28.27$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>	
	<p>ЗН-34</p>		<p>ЗН-39</p>
<p> $F, \text{ см}^2 = 54.336$ $Q, \text{ кг} = 14.725$ $D \text{ оп.,мм} = 116$ $P \text{ н.,мм} = 388.6$ $P \text{ в.,мм} = 182.1$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>		<p> $F \text{ см}^2 = 0.746$ $Q \text{ кг} = 0.2022$ $D \text{ оп.мм} = 12$ $P \text{ н.мм} = 37.7$ $P \text{ в.мм} = 21.99$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>	
	<p>ЗН-35</p>		<p>ЗН-40</p>
<p> $F \text{ см}^2 = 15.2$ $Q \text{ кг} = 4.12$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 179.4$ $P \text{ в.мм} = 110$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$ </p>		<p> $F \text{ см}^2 = 10.272$ $Q \text{ кг} = 2.783$ $D \text{ оп.мм} = 113.4$ $P \text{ н.мм} = 659.9$ $P \text{ в.мм} = 259.8$ $\Gamma \text{ р. сл.} = VII$ $\text{Точн.} = П$ </p>	











	ЗН-41 $F \text{ см}^2 = 2,29$ $Q \text{ кг} = 0,621$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 147,7$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$		ЗН-46 $F \text{ см}^2 = 10,556$ $Q \text{ кг} = 2,85$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 106,8$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗН-42 $F \text{ см}^2 = 2,433$ $Q \text{ кг} = 0,659$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 147$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$		ЗН-47 $F \text{ см}^2 = 0,589$ $Q \text{ кг} = 0,16$ $D \text{ оп.мм} = 14$ $P \text{ н.мм} = 44$ $P \text{ в.мм} = 34,6$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$
	ЗН-43 $F \text{ см}^2 = 3,016$ $Q \text{ кг} = 0,818$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 144,5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$		ЗН-48 $F \text{ см}^2 = 4,123$ $Q \text{ кг} = 1,117$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,54$ $P \text{ в.мм} = 31,4$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗН-44 $F \text{ см}^2 = 3,731$ $Q \text{ кг} = 1,011$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 141,4$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$		ЗН-49 $F \text{ см}^2 = 2,77$ $Q \text{ кг} = 0,751$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,54$ $P \text{ в.мм} = 51,84$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$
	ЗН-45 $F \text{ см}^2 = 4,43$ $Q \text{ кг} = 1,2$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 157,1$ $P \text{ в.мм} = 138,2$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$		ЗН-50 $F \text{ см}^2 = 3,61$ $Q \text{ кг} = 0,978$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 87,96$ $P \text{ в.мм} = 56,55$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$











	3Н-51		3Н-56
	$F \text{ см}^2 = 2.1$ $Q \text{ кг} = 0.569$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 62.8$ $P \text{ в.мм} = 36.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 4.742$ $Q \text{ кг} = 1.285$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 100.5$ $P \text{ в.мм} = 64.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
	3Н-52		3Н-57
	$F \text{ см}^2 = 2.262$ $Q \text{ кг} = 0.613$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 69.12$ $P \text{ в.мм} = 44$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 5.78$ $Q \text{ кг} = 1.566$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 106.8$ $P \text{ в.мм} = 64.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
	3Н-53		3Н-58
	$F \text{ см}^2 = 1.131$ $Q \text{ кг} = 0.307$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 62.83$ $P \text{ в.мм} = 50.27$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 4.273$ $Q \text{ кг} = 1.16$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78.54$ $P \text{ в.мм} = 28.27$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
	3Н-54		3Н-59
	$F \text{ см}^2 = 1.257$ $Q \text{ кг} = 0.341$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 69.12$ $P \text{ в.мм} = 56.55$ $\Gamma \text{ р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 5.655$ $Q \text{ кг} = 1.532$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 113.1$ $P \text{ в.мм} = 75.4$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
	3Н-55		3Н-60
	$F \text{ см}^2 = 1.154$ $Q \text{ кг} = 0.313$ $D \text{ оп.мм} = 14$ $P \text{ н.мм} = 44$ $P \text{ в.мм} = 23$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 5.94$ $Q \text{ кг} = 1.61$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 106.8$ $P \text{ в.мм} = 62.8$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$










	<p>ЗН-61</p> <p> $F \text{ см}^2 = 4,9$ $Q \text{ кг} = 1,328$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 100,5$ $P \text{ в.мм} = 62,8$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>		<p>ЗН-66</p> <p> $F \text{ см}^2 = 88$ $Q \text{ кг} = 2,385$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119,4$ $P \text{ в.мм} = 56,6$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>
	<p>ЗН-62</p> <p> $F \text{ см}^2 = 3,14$ $Q \text{ кг} = 0,851$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 78,54$ $P \text{ в.мм} = 47,12$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>		<p>ЗН-67</p> <p> $F \text{ см}^2 = 10,33$ $Q \text{ кг} = 2,8$ $D \text{ оп.мм} = 47$ $P \text{ н.мм} = 144,8$ $P \text{ в.мм} = 84,8$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>
	<p>ЗН-63</p> <p> $F \text{ см}^2 = 2,948$ $Q \text{ кг} = 0,8$ $D \text{ оп.мм} = 44,2$ $P \text{ н.мм} = 117$ $P \text{ в.мм} = 112$ $\Gamma \text{р. сл.} = \text{II}$ $\text{Точн.} = \text{П}$ </p>		<p>ЗН-68</p> <p> $F \text{ см}^2 = 8,55$ $Q \text{ кг} = 2,32$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 131,9$ $P \text{ в.мм} = 81,7$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>
	<p>ЗН-64</p> <p> $F \text{ см}^2 =$ $Q \text{ кг} =$ $D \text{ оп.мм} =$ $P \text{ н.мм} =$ $P \text{ в.мм} =$ $\Gamma \text{р. сл.} =$ $\text{Точн.} = \text{Н}$ </p>		<p>ЗН-69</p> <p> $F \text{ см}^2 = 7,52$ $Q \text{ кг} = 2,038$ $D \text{ оп.мм} = 104$ $P \text{ н.мм} = 412,4$ $P \text{ в.мм} = 314,7$ $\Gamma \text{р. сл.} = \text{VII}$ $\text{Точн.} = \text{П}$ </p>
	<p>ЗН-65</p> <p> $F \text{ см}^2 = 8,04$ $Q \text{ кг} = 2,18$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119,4$ $P \text{ в.мм} = 64,4$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>		<p>ЗН-70</p> <p> $F \text{ см}^2 = 2,04$ $Q \text{ кг} = 0,553$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 69,1$ $P \text{ в.мм} = 47,1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p>

	<p>ЗН-71</p> <p> $F \text{ см}^2 = 10.05$ $Q \text{ кг} = 2.724$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 131.9$ $P \text{ в.мм} = 69.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>ЗН-76</p> <p> $F \text{ см}^2 = 4.233$ $Q \text{ кг} = 1.147$ $D \text{ оп.мм} = 42$ $P \text{ н.мм} = 132$ $P \text{ в.мм} = 110$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>ЗН-72</p> <p> $F \text{ см}^2 = 5.28$ $Q \text{ кг} = 1.431$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 106.8$ $P \text{ в.мм} = 69.1$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>ЗН-77</p> <p> $F \text{ см}^2 = 3.3$ $Q \text{ кг} = 0.894$ $D \text{ оп.мм} = 37$ $P \text{ н.мм} = 116.2$ $P \text{ в.мм} = 96.7$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>ЗН-73</p> <p> $F \text{ см}^2 = 6.03$ $Q \text{ кг} = 1.634$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119.4$ $P \text{ в.мм} = 81.7$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>ЗН-78</p> <p> $F \text{ см}^2 = 3.5$ $Q \text{ кг} = 0.95$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 122.5$ $P \text{ в.мм} = 103$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>ЗН-74</p> <p> $F \text{ см}^2 = 2.513$ $Q \text{ кг} = 0.681$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75.4$ $P \text{ в.мм} = 50.3$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>ЗН-79</p> <p> $F \text{ см}^2 = 2.4$ $Q \text{ кг} = 0.65$ $D \text{ оп.мм} = 32$ $P \text{ н.мм} = 100.5$ $P \text{ в.мм} = 84.2$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>
	<p>ЗН-75</p> <p> $F \text{ см}^2 = 2.015$ $Q \text{ кг} = 0.546$ $D \text{ оп.мм} = 20$ $P \text{ н.мм} = 75.4$ $P \text{ в.мм} = 50.3$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>ЗН-80</p> <p> $F \text{ см}^2 = 2.07$ $Q \text{ кг} = 0.561$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 88$ $P \text{ в.мм} = 71.6$ $\Gamma \text{ р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$ </p>

	3Н-81		3Н-86
	$F \text{ см}^2 = 1.56$ $Q \text{ кг} = 0.423$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75.4$ $P \text{ в.мм} = 61$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.168$ $Q, \text{ кг} = 0.587$ $D \text{ оп.мм} = 26$ $P \text{ н.мм} = 81.68$ $P \text{ в.мм} = 62.83$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-82		3Н-87
	$F \text{ см}^2 = 5.18$ $Q \text{ кг} = 1.404$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 94.25$ $P \text{ в.мм} = 48.69$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 2.63$ $Q \text{ кг} = 0.713$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 113.1$ $P \text{ в.мм} = 97.4$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-83		3Н-88
	$F \text{ см}^2 = 4.215$ $Q \text{ кг} = 1.142$ $D \text{ оп.мм} = 25$ $P \text{ н.мм} = 29.53$ $P \text{ в.мм} = 78.54$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3.927$ $Q \text{ кг} = 1.064$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 94.25$ $P \text{ в.мм} = 62.83$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-84		3Н-89
	$F \text{ см}^2 = 2.254$ $Q \text{ кг} = 0.611$ $D \text{ оп.мм} = 24$ $P \text{ н.мм} = 75.4$ $P \text{ в.мм} = 53.41$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 5.184$ $Q \text{ кг} = 1.405$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 119.4$ $P \text{ в.мм} = 87.96$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$
	3Н-85		3Н-90
	$F \text{ см}^2 = 10.23$ $Q \text{ кг} = 2.771$ $D \text{ оп.мм} = 53.5$ $P \text{ н.мм} = 168.1$ $P \text{ в.мм} = 124.1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$		$F \text{ см}^2 = 3.322$ $Q \text{ кг} = 0.9$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 87.96$ $P \text{ в.мм} = 59.69$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{H}$

	ЗН-91		ЗН-96
	$F, \text{ см}^2 = 3.888$ $Q, \text{ кг} = 1.053$ $D_{\text{оп.мм}} = 28$ $P_{\text{н.мм}} = 87.96$ $P_{\text{вн.мм}} = 53.41$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 9.29$ $Q, \text{ кг} = 2.518$ $D_{\text{оп.мм}} = 52$ $P_{\text{н.мм}} = 163.4$ $P_{\text{вн.мм}} = 122.5$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-92		ЗН-97
	$F, \text{ см}^2 = 3.605$ $Q, \text{ кг} = 0.977$ $D_{\text{оп.мм}} = 30$ $P_{\text{н.мм}} = 94.25$ $P_{\text{вн.мм}} = 65.97$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.529$ $Q, \text{ кг} = 1.498$ $D_{\text{оп.мм}} = 90$ $P_{\text{н.мм}} = 282.7$ $P_{\text{вн.мм}} = 270.2$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-93		ЗН-98
	$F, \text{ см}^2 = 6.48$ $Q, \text{ кг} = 1.756$ $D_{\text{оп.мм}} = 35$ $P_{\text{н.мм}} = 109.95$ $P_{\text{вн.мм}} = 62.83$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.073$ $Q, \text{ кг} = 0.562$ $D_{\text{оп.мм}} = 35$ $P_{\text{н.мм}} = 110$ $P_{\text{вн.мм}} = 97.4$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-94		ЗН-99
	$F, \text{ см}^2 = 0.903$ $Q, \text{ кг} = 0.245$ $D_{\text{оп.мм}} = 14$ $P_{\text{н.мм}} = 47.98$ $P_{\text{вн.мм}} = 28.27$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 0.858$ $Q, \text{ кг} = 0.233$ $D_{\text{оп.мм}} = 12$ $P_{\text{н.мм}} = 37.7$ $P_{\text{вн.мм}} = 18.85$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-95		ЗН-100
	$F, \text{ см}^2 = 1.532$ $Q, \text{ кг} = 0.415$ $D_{\text{оп.мм}} = 22$ $P_{\text{н.мм}} = 69.12$ $P_{\text{вн.мм}} = 53.41$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.87$ $Q, \text{ кг} = 1.32$ $D_{\text{оп.мм}} = 36$ $P_{\text{н.мм}} = 113.1$ $P_{\text{вн.мм}} = 81.68$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$

	ЗН-101		ЗН-106
	$F, \text{ см}^2 = 6.715$ $Q, \text{ кг} = 1.82$ $D_{\text{оп, мм}} = 32$ $P_{\text{н, мм}} = 100.5$ $P_{\text{вн, мм}} = 40.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 5.867$ $Q, \text{ кг} = 1.59$ $D_{\text{оп, мм}} = 38$ $P_{\text{н, мм}} = 119.4$ $P_{\text{вн, мм}} = 82.9$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{Н}$
	ЗН-102		ЗН-107
	$F, \text{ см}^2 = 4.273$ $Q, \text{ кг} = 1.158$ $D_{\text{оп, мм}} = 38$ $P_{\text{н, мм}} = 119.4$ $P_{\text{вн, мм}} = 94.25$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 5.374$ $Q, \text{ кг} = 1.456$ $D_{\text{оп, мм}} = 83.65$ $P_{\text{н, мм}} = 379.3$ $P_{\text{вн, мм}} = 110.8$ $\Gamma_{\text{р. сл.}} = \text{ОС.}$ $\text{Точн.} = \text{Н}$
	ЗН-103		ЗН-108
	$F, \text{ см}^2 = 48.95$ $Q, \text{ кг} = 13.51$ $D_{\text{оп, мм}} = 112$ $P_{\text{н, мм}} = 377.8$ $P_{\text{вн, мм}} = 182.3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$		$F, \text{ см}^2 = 1.602$ $Q, \text{ кг} = 0.434$ $D_{\text{оп, мм}} = 20$ $P_{\text{н, мм}} = 62.83$ $P_{\text{вн, мм}} = 43.98$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{Н}$
	ЗН-104		ЗН-109
	$F, \text{ см}^2 = 1.814$ $Q, \text{ кг} = 0.492$ $D_{\text{оп, мм}} = 20$ $P_{\text{н, мм}} = 62.8$ $P_{\text{вн, мм}} = 40.8$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 6.296$ $Q, \text{ кг} = 1.706$ $D_{\text{оп, мм}} = 95.83$ $P_{\text{н, мм}} = 373.9$ $P_{\text{вн, мм}} = 223.1$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$
	ЗН-105		ЗН-110
	$F, \text{ см}^2 = 2.724$ $Q, \text{ кг} = 0.738$ $D_{\text{оп, мм}} = 64$ $P_{\text{н, мм}} = 152.2$ $P_{\text{вн, мм}} = 317.7$ $\Gamma_{\text{р. сл.}} = \text{ОС.}$ $\text{Точн.} = \text{Н}$		$F, \text{ см}^2 = 9.766$ $Q, \text{ кг} = 2.647$ $D_{\text{оп, мм}} = 114$ $P_{\text{н, мм}} = 578$ $P_{\text{вн, мм}} = 294.2$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$

	ЗН-111		ЗН-116
	$F, \text{ см}^2 = 4.318$ $Q, \text{ кг} = 1.17$ $D_{\text{оп, мм}} = 66.3$ $P_{\text{н, мм}} = 257.2$ $P_{\text{вн, мм}} = 154.87$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 1.759$ $Q, \text{ кг} = 0.477$ $D_{\text{оп, мм}} = 30$ $P_{\text{н, мм}} = 94.3$ $P_{\text{вн, мм}} = 81.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-112		ЗН-117
	$F, \text{ см}^2 = 6.841$ $Q, \text{ кг} = 1.854$ $D_{\text{оп, мм}} = 40$ $P_{\text{н, мм}} = 126$ $P_{\text{вн, мм}} = 85$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = -$ $Q, \text{ кг} = -$ $D_{\text{оп, мм}} = -$ $P_{\text{н, мм}} = -$ $P_{\text{вн, мм}} = -$ $\Gamma_{\text{р. сл.}} = -$ $\text{Точн.} = -$
	ЗН-113		ЗН-118
	$F, \text{ см}^2 = 13.95$ $Q, \text{ кг} = 3.78$ $D_{\text{оп, мм}} = 80$ $P_{\text{н, мм}} = 251.3$ $P_{\text{вн, мм}} = 213.6$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 3.3$ $Q, \text{ кг} = 0.894$ $D_{\text{оп, мм}} = 55$ $P_{\text{н, мм}} = 162.3$ $P_{\text{вн, мм}} = 104.9$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$
	ЗН-114		ЗН-119
	$F, \text{ см}^2 = 7.257$ $Q, \text{ кг} = 1.967$ $D_{\text{оп, мм}} = 40$ $P_{\text{н, мм}} = 125.7$ $P_{\text{вн, мм}} = 81.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 1.013$ $Q, \text{ кг} = 0.274$ $D_{\text{оп, мм}} = 15$ $P_{\text{н, мм}} = 47.1$ $P_{\text{вн, мм}} = 30.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	ЗН-115		ЗН-120
	$F, \text{ см}^2 = 2.478$ $Q, \text{ кг} = 0.672$ $D_{\text{оп, мм}} = 30.1$ $P_{\text{н, мм}} = 94.6$ $P_{\text{вн, мм}} = 76.3$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.799$ $Q, \text{ кг} = 1.3$ $D_{\text{оп, мм}} = 30$ $P_{\text{н, мм}} = 94.2$ $P_{\text{вн, мм}} = 53.4$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$